

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8247S

DATE 25/5/2018 12:18

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 1,480.00 ✓
	Front Bumper Cover ✓			\$ 1,052.20 ✓
	Front Bumper Sponge ✓			\$ 142.20
	Front Bumper Reinforcement ✓			\$ 526.10
	Front Bumper Bracket Top (LH/RH) ✓		\$ 22.40	\$ 44.80
	Front Bumper Side Bracket (LH/RH) ✓		\$ 14.30	\$ 28.60
	SUB TOTAL			\$ 3,273.90
	LESS 20%			\$ 654.78
	DISCOUNTED TOTAL			\$ 2,619.12
	Front Number Plate ✓			\$ 25.00 Nett ✓
	Front No Plate Trim Cover ✓			\$ 30.00 Nett ✓
				\$ 55.00
	Labour Charge			200
	Panel Beating			\$ 280.00
	Spray Painting Charge			\$ 250.00
				200
	TOTAL LABOUR			\$ 530.00
	ESTIMATE TOTAL			\$ 3,204.12
Ka/ur 11/11/14 25/5/18 12:15h 2 Ryz. P/P Before Paint phh				LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company Acknowledged by Repairer Signature: Date:
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				