

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 8247S

DATE 25/5/2018 14:10

H24

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓ <i>or</i>			\$ 1,480.00 ✓
	Front Bumper Cover ✓ <i>ahh</i>			\$ 1,052.20 ✓
	Front Bumper Sponge <i>Xme</i>			\$ 142.20
	Front Bumper Reinforcement <i>Xme</i>			\$ 526.10
	Front Bumper Bracket Top (LH/RH) <i>Xme</i>		\$ 22.40	\$ 44.80
	Front Bumper Side Bracket (LH/RH) <i>Xme</i>		\$ 14.30	\$ 28.60
	<b>SUB TOTAL</b>			<b>\$ 3,273.90</b>
	<b>LESS 20%</b>			<b>\$ 654.78</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,619.12</b>
	Front Number Plate ✓ <i>am</i>			\$ 25.00 <b>Nett ✓</b>
	Front No Plate Trim Cover ✓ <i>am</i>			\$ 30.00 <b>Nett ✓</b>
				<b>\$ 55.00</b>
	<b>Labour Charge</b>			<b>200</b>
	Panel Beating			\$ 280.00
	Spray Painting Charge			\$ 250.00
				<b>200</b>
	<b>TOTAL LABOUR</b>			<b>\$ 530.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 3,204.12</b>
<i>Kaluz 11/11/14</i> <i>25/5/18 1215h</i> <i>2 Rys.</i> <i>P/P</i> <i>Before Paint phh</i>				
<b>LKK Auto Consultants hence notify the Repairer of the following:</b> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul>				
Acknowledged by Repairer				
Signature:				
Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				