

Surveyor:

ASSIGNMENT (Office)

From (Person): Grice Teo

of

8MO

Date/Time:

28/5/2018 @ 11:23am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KQ 4895M

Insured:

FS72884

at Workshop in/s

Optima Werkz

Tel:

6484 9919

of

9A Seungoon North Ave 5

Policy No:

Claim No:

CMTD1802249/NSW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/05/2018CA / REV / REP. / REV 24 HRS ^{lup}

H.O.D. Endorsement:

Date/Time:

11:59am @ 28/5/18

Person Contacted:

Riza

Vehicle IN/

OUT

Date/Time	Action/Instruction (✓) Estimate
	8KQ 4895M - NBA/INC18009406/Y DOA: 23/5/2018
	FS72884 - NBA/INC18009406/Y DOA: 23/5/2018
04/06/18	@ 10:52am. revised PA to shown via email.

ASS. REC. BY:

REF: SON /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Optima

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: 5 Consistent? : Yes or NoEst. Repairs: 04 days Res.: Yes or NoLum Sum: 1.13.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKG 4895 Regn: 12, 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda A F.T c.c. 1317Colour: Red A/C: Insured / Std / NI / NASp. Reading 63993 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK3 3003958Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 7 mmL/Bal. 9 mmL/Bal. 7 mmD.O.A. 23/5/18D.O.I. 30/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/5 File pass to Customer, car not readyC\$ 1,013.20 Red - 24%

RECEIVED 24 AUG 2018

24/8 confirmed with Kenneth days of repair (5 days)

Date/Time, File Pass to?

24/8/18

1) Type

Date/Time, File Return to?

2)

☐ : Prell. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + F.S. \$

Photos

Others

250

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I.: (\$ 3,137.52 P/P)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1802249/NSW

Date: 04 June 2018

Our Ref: CS/SMO18009623/Ksd3

The Motor Claims Department
Tenet Sampo Insurance Pte Ltd

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SKQ 4895M

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/05/2018 at the premises of M/s Optima Werkz Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,150.72</u>
Revised Estimate Amount	: S\$ <u>1,656.80</u>
"Check" Items Amount	: S\$ <u>700.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 4 June 2018 10:52 AM
To: 'Ngo, Sau Wei Shawn'; 'Teo, Grace'; 'Sharon Ten'; 'Ye, Yong Kang Melvin'
Cc: sur@lkkauto.com; assignments@lkkauto.com; 'Nivitha (LKK Auto)'
Subject: RE: CMTD1802249/NSW - SUV(LKK)/ Accident involving FS7288U & SKQ4895M on 23/05/18
Attachments: SKQ 4895M- Preli Advise.pdf

Dear Shawn,

Enclosed herewith preliminary advice of SKQ 4895M.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 28 May 2018 12:02 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments@lkkauto.com
Cc: 'Sharon Ten' <sharon@ow.sg>; 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; sur@lkkauto.com
Subject: RE: CMTD1802249/NSW - SUV(LKK)/ Accident involving FS7288U & SKQ4895M on 23/05/18

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Monday, 28 May 2018 11:23 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Riza <riza@ow.sg>; winson@ow.sg; lily.loi@ow.sg; Sharon Ten <sharon@ow.sg>; Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1802249/NSW - SUV(LKK)/ Accident involving FS7288U & SKQ4895M on 23/05/18

Our Reference: CMTD1802249/NSW

Dear LKK AUTO,

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 28 May 2018 11:23 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Riza; winson@ow.sg; lily.loi@ow.sg; Sharon Ten; Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin
Subject: CMTD1802249/NSW - SUV(LKK)/ Accident involving FS7288U & SKQ4895M on 23/05/18
Attachments: 25052018181202.pdf

Our Reference: CMTD1802249/NSW

Dear LKK AUTO,

Please make arrangement to conduct the survey for SKQ4895M.

Please be informed that Shawn Ngo the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Riza [mailto:riza@ow.sg]
Sent: Monday, May 28, 2018 11:13 AM
To: Teo, Grace
Cc: winson@ow.sg; lily.loi@ow.sg; Sharon Ten; Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin
Subject: Re: CMTD1802249/NSW - Accident involving FS7288U & SKQ4895M on 23/05/18

Dear Grace,

We chose LKK to survey the above mentioned vehicle.

Thanks

--

Best Regards,

Riza (Ms)

Claims Executive

Tel: +65 6484-9919 (ext.105)

Fax: +65 6481-1011

OPTIMA WERKZ PTE LTD

Head office: 6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472 1313 | Fax:
(+65) 6472 2112 |

Branch: 9A Serangoon North Ave 5 Singapore 554500 | Tel: (+65) 6484 9919 | Fax:
(+65) 6481 1011 |

Branch: 551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452 6868 | Fax:
(+65) 6452 9223 |

www.ow.sg

www.facebook.com/optimawerkz

On 5/28/2018 10:06 AM, Teo, Grace wrote:

Our Reference : CMTD1802249/NSW

Your Reference: SKQ4895M

Without Prejudice

Date: 28th May 2018

Attention:

M/S OPTIMA WERKZ PTE LTD

Dear Riza,

ACCIDENT INVOLVING FS7288U & SKQ4895M ON 23.05.18

We refer to your Notice of Accident dated 25/05/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey		Surveyor	Selection (Indicate as tick)
	Motor Surveyor		
1	Raleigh Services	Andrew Ow Yong Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area) Marcus Chua (East area) Mohd Rasul (West area) Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee Lawrence Ng Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Riza [<mailto:riza@ow.sg>]

Sent: Friday, May 25, 2018 6:23 PM

To: Claims - Motor Survey

Cc: winson@ow.sg; lily.loi@ow.sg; Sharon Ten

Subject: Arrange survey - Accident involving SKQ4895M and FS7288U on 23/05/18

Without Prejudice

Your Ref: FS7288U

Our Ref: SKQ4895M

Hi all,

Please arrange for survey as soon as possible. Vehicle is inside our premises.

Location: 9A Serangoon North Avenue 5

***Please avoid 1-2PM*

Thanks

--

Best Regards,

Riza (Ms)

Claims Executive

Tel: +65 6484-9919 (ext.105)

Fax: +65 6481-1011

OPTIMA WERKZ PTE LTD

Head office: 6 Kung Chong Road Singapore 159143 | Tel: (+65) 6472
1313 | Fax: (+65) 6472 2112 |
Branch: 9A Serangoon North Ave 5 Singapore 554500 | Tel: (+65) 6484
9919 | Fax: (+65) 6481 1011 |
Branch: 551 Upp Thomson Road Singapore 574415 | Tel: (+65) 6452
6868 | Fax: (+65) 6452 9223 |
www.ow.sg
www.facebook.com/optimawerkz

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 25 MAY 2018

Third Party Insurer: SOMPO

Vehicle No: SKQ 4895 M

Third Party Veh No: FS7288U

Model: HONDA FIT 1.3

Date of Accident: 23/05/18

Chassis: GK3-3003958

ESTIMATE

QTY	DESCRIPTION	UNIT	S\$	AMOUNT	S\$
1	REAR TAILGATE LOGO EMBLEM			<i>na</i>	\$24.60
1	REAR TAILGATE FIT EMBLEM			<i>na</i>	\$34.60
1	REAR TAILLAMP LH				\$493.30
2	REAR TAILLAMP CLIPS LH		\$5.80		\$11.60
1	REAR TAILLAMP INNER PANEL LH			<i>R</i>	\$109.70
1	REAR BUMPER		<i>cm / Bn</i>		\$803.60
1	REAR BUMPER GARNISH LH			<i>sn</i>	\$29.50
14	REAR BUMPER CLIPS		\$6.80	<i>na</i>	\$95.20
2	REAR BUMPER SIDE RETAINER L/R		<i>also 1</i> \$25.50		\$51.00
1	REAR BUMPER INNER SIDE SHIELD LH			<i>sn</i>	\$49.20
3	REAR BUMPER INNER SIDE SHIELD CLIPS LH		\$6.80	<i>na</i>	\$20.40
1	REAR END PANEL				\$370.10
1	REAR END PANEL INNER TOP GARNISH			<i>sn</i>	\$98.60
4	REAR END PANEL INNER TOP GARNISH CLIPS		\$5.50	<i>na</i>	\$22.00
SUB TOTAL					\$2,213.40
Less 20%					-\$442.68
PARTS TOTAL					\$1,770.72

*Not Attached
Resurvey B & paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 25 MAY 2018

Third Party Insurer: SOMPO

Vehicle No: SKQ 4895 M

Third Party Veh No: FS7288U

Model: HONDA FIT 1.3

Date of Accident: 23/05/18

Chassis: GK3-3003958

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR		Short \$280.00
		S/N TOTAL	\$280.00

✓ 200sn

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$800.00 4000 600

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$800.00 4000 600

TO TUFF KOTE / ANTI-RUST

na \$60.00 x 40

TO CHECK WIRING, LIGHTING & WATER LEAKAGE

\$80.00 200

TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR

na \$280.00 x 150

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$80.00 500

LABOUR TOTAL \$2,100.00

WINSON

TOTAL \$4,150.72

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 25 MAY 2018

Third Party Insurer: SOMPO

Vehicle No: SKQ 4895 M

Third Party Veh No: FS7288U

Model: HONDA FIT 1.3

Date of Accident: 23/05/18

Chassis: GK3-3003958

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE LOGO EMBLEM		24.60
1	REAR TAILGATE FIT EMBLEM		34.60
1	REAR TAILLAMP LH		493.30
2	REAR TAILLAMP CLIPS LH	\$5.80	11.60
1	REAR TAILLAMP INNER PANEL LH		109.70
1	REAR BUMPER		803.60
1	REAR BUMPER GARNISH LH		29.50
14	REAR BUMPER CLIPS	\$6.80	95.20
2	REAR BUMPER SIDE RETAINER L/R	\$25.50	51.00
1	REAR BUMPER INNER SIDE SHIELD LH		49.20
3	REAR BUMPER INNER SIDE SHIELD CLIPS LH	\$6.80	20.40
1	REAR END PANEL		370.10
1	REAR END PANEL INNER TOP GARNISH		98.60
4	REAR END PANEL INNER TOP GARNISH CLIPS	\$5.50	22.00
SUB TOTAL			\$2,213.40
Less 20%			-\$442.68
PARTS TOTAL			\$1,770.72

—
 —
 7✓
 ✗
 ✗
 —
 ✗
 ✓
 ✗
 ✗
 ✗
 ✗
 ✗
 ✗
 ✗
 ✗
 1967.50
 393.50
 1574.00

Not Authorized
Repair B4 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

5 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 25 MAY 2018

Third Party Insurer: SOMPO

Vehicle No: SKQ 4895 M

Third Party Veh No: FS7288U

Model: HONDA FIT 1.3

Date of Accident: 23/05/18

Chassis: GK3-3003958

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR	Shan 200p	\$280.00 ✓ 200.00
		S/N TOTAL	\$280.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

600p
\$800.00 400p

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

600p
\$800.00 400p

TO TUFF KOTE / ANTI-RUST

now \$60.00 40p

TO CHECK WIRING, LIGHTING & WATER LEAKAGE

\$80.00 20p

TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR

now \$280.00 150p

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$80.00 50p

LABOUR TOTAL \$2,100.00 1460.00

WINSON TOTAL \$4,150.72

p - 1574.00

shn - 200.00

L - 1460.00

plp - \$ 3234.00 &
3137.52



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18009623/Ksd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 24-08-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FS 7288U	Veh. Inspected	SKQ 4895M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802249/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	28/05/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT (A)	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	GK33003958	Colour	RED
Odometer	63993	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	YOKOHAMA	9 mm
L/H Front Tyre	175/70 R14	YOKOHAMA	9 mm
R/H Rear Tyre	175/70 R14	YOKOHAMA	7 mm
L/H Rear Tyre	175/70 R14	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/05/2018	Inspection Date	30/05/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 4895M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE LOGO EMBLEM	NECESSARY	24.60	24.60
1	REAR TAILGATE FIT EMBLEM	NECESSARY	34.60	34.60
1	REAR TAILLAMP LH	MTG CRACKED	493.30	493.30
2	REAR TAILLAMP CLIPS LH @\$5.80	NOT NECESSARY	11.60	-
1	REAR TAILLAMP INNER PANEL LH	TO REPAIR SEE LABOUR	109.70	-
1	REAR BUMPER	CRACKED / BUCKLED	803.60	803.60
1	REAR BUMPER GARNISH LH	SERVICEABLE	29.50	-
14	REAR BUMPER CLIPS @\$6.80	NECESSARY	95.20	95.20
2	REAR BUMPER SIDE RETAINER L/R @\$25.50	N/S DISTORTED	51.00	25.50
1	REAR BUMPER INNER SIDE SHIELD LH	SERVICEABLE	49.20	-
3	REAR BUMPER INNER SIDE SHIELD CLIPS LH @\$6.80	NOT NECESSARY	20.40	-
1	REAR END PANEL	BENT	370.10	370.10
1	REAR END PANEL INNER TOP GARNISH	SERVICEABLE	98.60	-
4	REAR END PANEL INNER TOP GARNISH CLIPS @\$5.50	NOT NECESSARY	22.00	-
	LESS 20% DISCOUNT		-442.68	-369.38
			1,770.72	1,477.52
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
<u>LABOUR</u>				
	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION.INCLUSIVE OF THE REPAIR OF REAR TAILLAMP INNER PANEL LH.		800.00	600.00
	TO PUTTY & SPRAY PAINTING WIL SEALANT ALL ACCIDENT PORTION.		800.00	600.00
	TO TUFF KOTE/ANTI-RUST.		60.00	40.00
	TO CHECK WIRING,LIGHTING & WATER LEAKAGE.		80.00	20.00
	TO DISMANTLE & REINSTALL REAR INTERIOR CARPET COMPONENT TO FACILITATE REPAIR.		280.00	150.00
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR.		80.00	50.00
			2,100.00	1,460.00
GRAND TOTAL			4,150.72	3,137.52

Report Ref No. CS/SMO18009623/Ksd3n2



RECOMMENDED COST OF REPAIRS			3,137.52
-----------------------------	--	--	----------

Report Ref No. CS/SMO18009623/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.