

ASS. REC. BY:

REF:

CS/AGI18009624/Uvd3nz

Special Instruction:

Surveyor:

Matrus

ASSIGNMENT (Office)

From (Person):

Julie Mergubert

of

AGI

Date/Time:

28/5/2018 @ 10:08am

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 6559P

Insured:

SLB 2037D

at Workshop n/s

Pegasus Engineering

Tel:

6858 1846

of

51 Deftu Lane 10

Policy No:

Claim No:

C10001624/JM

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:20am @ 28/5/18

Person Contacted:

Alvin

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLP 6559P-x

SLB 2037D-x

AG1/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 65592at Workshop m/s Reg-suof SLB 2037D

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLP 65592 Yr Regn: 6.17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota v40s C.C. 1496Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 1-3839 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MM/FB29F38 0 2012317

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / 8/Rim / STD A/Rim or

Tyre Size: F: 195/50 R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 28/5/18

Survey held at: _____

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 28/5/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision: Rear

Date / Time Action / Instruction

28/5/18 cont. ind 2/5 of \$600 with willian. (Red 5818.87, 519)

RECEIVED 31 MAY 2018

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 30/5- typistDays Of Repair: 8Resurvey No. of Trip: -

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ - RS, \$1

Photos

Others

TOTAL

350

Report Format: TPLump Sum / I.B.I. (\$) 5600/-

Nivitha (LKK Auto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Monday, 28 May 2018 10:08 AM
To: SUR; assignments
Cc: admin-d@lkkauto.com
Subject: FW: Third party survey SLP6559P Your insured SLB2037D on 25.05.2018 | Our ref: C10001624/JM
Attachments: 26052018141243.tif

Hi Team

Please accept TPPD survey request and survey on a without prejudice basis.

Vehicle is in please liaise with Alvin Low @ 6858 1846.

Thank you,
-Julie

From: Pegasus Engineering <claims@pegasusengrg.com.sg>
Sent: Saturday, 26 May, 2018 2:08 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: Re: Third party survey SLP6559P Your insured SLB2037D on 25.05.2018

Dear Sir/Mdm,

Enclose the estimate for your perusal.

Please arrange for survey as soon as possible.

Thanks & Regards,

Wee

Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846
Fax : 6487 6070
Email : claims@pegasusengrg.com.sg

On Sat, May 26, 2018 at 2:03 PM, Pegasus Engineering <claims@pegasusengrg.com.sg> wrote:

Your Ref: SLB2037D

Our Ref: SLP6559P

DOA: 25.05.2018

Without Prejudice

Dear All,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 2.3 of Pre-Action Protocol for NIMA Cases, please let us have a **list of 10 motor surveyors** for our selection and please let us know within **2 working days** whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In the event that you request for post repair inspection pursuant to paragraph 4.1 under the NIMA Protocol, you must compensate our client for the loss of use of his/her vehicle for the day that the inspection is conducted.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

**Vehicle is currently grounded in our premises.
Please arrange for survey as soon as possible.**

Thanks & Regards,

Alvin Low
Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846
Fax : 6487 6070
Email : claims@pegasusengrg.com.sg

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended De-registration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

7200G

SLP6559P

Yes

25 May 2018

TOYOTA

VIOS 1.5E CVT

Silver

2017

2NRX161320

MHFB29F3802012317

79.0 kW (105 bhp)

\$12,744.00

14 Jun 2017

14 Jun 2017

0

\$7,744.00

Yes

13 Jun 2027

\$5,808.00

13 Jun 2027

A - Car up to 1600cc & 97kW (130bhp)

10

\$51,600.00

\$41,280.00

\$47,088.00

The information contained herein is correct as at 25 May 2018

OK

Enquire Vehicle & Owner Information (Vehicle No. SLB2037D As At 25 May 2018 / 09:38:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: PET(WEE)SLP0337P

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S7909886H
Owner Name: MARTIN LIM JONG THUAN

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 42

Registered Street Name: LORONG ENG KAP

Registered Unit No.: # 03-04

Registered Building Name: -

Registered Postal Code: 534412

Current Vehicle Details

Vehicle No.: SLB2037D
Make Description/Model: CHEVROLET / ORLANDO 1.4AT TURBO
Insurance Company Name: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/05/2018 18:03
Date Of Accident	25/05/2018 09:35
Exact Location Of Accident	JUNCTION OF ANG MO KIO AVENUE 1 & BOUNDARY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP6559P
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68014188

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

Driver

Name of Driver	SYED MOHD HAIRULNIZAM BIN SYED MOHD HAMZAH
NRIC No	S1740751A
Date Of Birth	22/08/1966
Occupation	OUTDOOR
Date Of Driving Pass	07/07/2009
Driving Experience	8 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98765432
Fax Number	
Contact Number	
Email Address	UNCLE_BRADER@YAHOO.COM

Address	BLOCK 335 WOODLANDS STREET 32 #09-37
Postcode	730335
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 25.05.2018 at about 0938 hours, I was driving my vehicle (A: SLP6559P) along the junction of Ang Mo Kio Avenue 1 and Boundary Road. Upon reaching the junction I stopped my vehicle due to traffic light turned "amber" to "red". While stationary, I felt an impact from the rear and realized a vehicle (B: SLB2037D) had hit onto the rear portion of my vehicle. Vehicle A: 1 passenger onboard. Vehicle B: 1 passenger onboard.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB2037D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 25/5/18 16:55 Hrs.



Reporting Centre Personnel's Signature
Name: Shirley Chua
NRIC/FIN No.: S817740

Sketch Plan Pg. 2

SKETCH PLAN

Junction of
Any No 10 Avenue
X Boundary Road

A: SLP659P

B: 3LB2037D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: 25/5/18
1655 hrs

Reporting Centre Personnel's signature
Name: *[Signature]*
NRIC/FIN No.: *98mm wj*

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn : *Confirmed*
Tel :
Fax : *on 28/05/18*

28/5/18

Not Added

note

2/5 \$5600

T. the photo after repair
sdg.

Quotation No : QO18/05-1277	Quotation Date : 25/05/2018	Terms : 30 DAYS
Vehicle No : SLP6559P	Chassis No : MHFB29F3802012317	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEH NO: SLB2037D, DATE OF ACCIDENT: 25.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>762.47 30/500</i>	1	1,662.4000	1,662.40 ✓
2	BOOTLID LOCK <i>twi</i>	1	90.4000	90.40 ✓
3	BOOTLID LOCK STRIKER <i>11</i>	1	18.5000	18.50 X
4	BOOTLID WEATHERSTRIP <i>twi</i>	1	188.8000	188.80 ✓
5	BOOTLID E BADGE <i>nu</i>	1	34.4000	34.40 ✓
6	BOOTLID CENTRE LOGO BADGE <i>nu</i>	1	59.8000	59.80 ✓
7	BOOTLID VIOS BADGE <i>nu</i>	1	44.1000	44.10 ✓
8	BOOTLID HINGE <i>n</i>	2	57.8000	115.60 X
9	BOOTLID INNER TRIM COVER <i>11</i>	1	234.3000	234.30 X
10	BOOTLID INNER TRIM COVER CLIPS <i>11</i>	4	4.3000	17.20 X
11	BOOTLID LOCK CABLE CLIPS <i>11</i>	3	4.3000	12.90 X
12	BOOTLID OUTER GARNISH <i>3ent/twi</i>	1	164.7000	164.70 ✓
13	BOOTLID OUTER GARNISH CLIPS <i>11</i>	3	4.3000	12.90 X
14	FRONT LICENCE PLATE LAMP <i>11</i>	2	64.1000	128.20 X
15	REAR END PANEL <i>30/500</i>	1	694.7000	694.70 ✓
16	REAR END PANEL INNER TRIM <i>twi</i>	1	234.3000	234.30 ✓
17	REAR END PANEL INNER TRIM CLIPS <i>nu</i>	4	4.3000	17.20 ✓
18	REAR LUGGAGE FLOOR PANEL <i>crumpled/guc</i>	1	678.7000	678.70 ✓
19	REAR LUGGAGE FLOOR PANEL INSULATOR CLIPS <i>11</i>	4	4.3000	17.20 X
20	REAR LAMP <i>one</i>	2	375.8000	751.60 ✓
21	REAR LAMP PANEL <i>n</i>	2	124.0000	248.00 X
22	REAR LAMP CLIP HOLDER <i>11</i>	4	4.3000	17.20 X
23	REAR LUGGAGE FLOOR SIDE COMPARTMENT FOAM <i>11</i>	2	108.2000	216.40 X

C/F 0.00

Page 1 of 3

3721.17

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 570000 Attn : Tel : Fax :
---	---

Quotation No : QO18/05-1277	Quotation Date : 25/05/2018	Terms : 30 DAYS
Vehicle No : SLP6559P	Chassis No : MHFB29F3802012317	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: AGI, INSURED'S VEH NO: SLB2037D, DATE OF ACCIDENT: 25.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR BUMPER <i>dis</i>	1	504.9000	504.90
25	REAR BUMPER REINFORCEMENT <i>DD</i>	1	379.2000	379.20
26	REAR BUMPER SIDE RETAINER <i>set</i>	2	115.1000	230.20
27	REAR BUMPER SIDE HOLDER <i>set</i>	2	22.3000	44.60
28	REAR BUMPER REFLECTOR <i>2 set</i>	2	130.5000	130.50
29	REAR BUMPER CLIPS <i>set</i>	6	4.3000	25.80
30	REAR BUMPER END SPLASHIELD COVER <i>11</i>	2	59.1000	118.20
31	REAR EXHAUST BOX <i>1</i>	1	512.7000	512.70
32	REAR EXHAUST BOX HEAT SHIELD <i>11</i>	1	155.1000	155.10
33	REAR EXHAUST BOX MOUNT <i>11</i>	2	78.9000	157.80
34	LESS 25% (ITEM 1 - 33)	1	-1,979.6300	-1,979.63
35	REAR LICENSE PLATE <i>set</i>	1	50.0000	50.00
36	REAR LUGGAGE FLOOR PANEL INSULATOR <i>set</i>	1	250.0000	250.00
37	REAR BUMPER PARKING SENSOR <i>set</i>	1	450.0000	450.00
38	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	2,000.0000	2,000.00
39	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,400.0000	1,400.00
40	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00
41	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	180.0000	180.00
42	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	1	150.0000	150.00
43	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00

C/F 0.00

Page 2 of 3

P- 5036.37
3777.28
3230 7007.48

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MIING LANE #01-08 MIDVIEW CITY SINGAPORE 570666 Attn : Tel : Email :
--	--

Quotation No : QO18/05-1277	Quotation Date : 25/05/2018	Terms : 30 DAYS
Vehicle No : SLP6559P	Chassis No : MHFB29F3802012317	Third Party Insurer :
Model : VIOS		Date of Accident :
Remarks : TP INSURER: AGI, INSURED'S VEH NO: SLB2037D, DATE OF ACCIDENT: 25.05.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)	
				B/F	0.00
44	TO TRANSFER BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	1	120.0000	60	120.00
45	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND DIAGNOSTIC MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	1	500.0000	11X	500.00
46	TO RUST PROOFING OF THE AFFECTED PORTION	1	200.0000	100	200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total	11,418.87
GST(7.00%)	799.32
Total (SGD)	12,218.19

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18009624/Uvd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 07-06-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 2037D	Veh. Inspected	SLP 6559P
Policy No.		Coverage (\$)	0.00
Claim No.	C10001624/JM	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	28/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MHFB29F3802012317	Colour	SILVER
Odometer	53839	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R16	BRIDGESTONE	7 mm
L/H Front Tyre	195/50 R16	BRIDGESTONE	7 mm
R/H Rear Tyre	195/50 R16	BRIDGESTONE	7 mm
L/H Rear Tyre	195/50 R16	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/05/2018	Inspection Date	28/05/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 6559P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	BADLY DENTED	1,662.40	762.47
1	BOOTLID LOCK	TWISTED	90.40	90.40
1	BOOTLID LOCK STRIKER	NOT NECESSARY	18.50	-
1	BOOTLID WEATHERSTRIP	TWISTED	188.80	188.80
1	BOOTLID E BADGE	NECESSARY	34.40	34.40
1	BOOTLID CENTRE LOGO BADGE	NECESSARY	59.80	59.80
1	BOOTLID VIOS EMBLEM	NECESSARY	44.10	44.10
2	BOOTLID HINGE @\$57.80	TO REPAIR SEE LABOUR	115.60	-
1	BOOTLID INNER TRIM COVER	NOT NECESSARY	234.30	-
4	BOOTLID INNER TRIM COVER CLIPS @\$4.30	NOT NECESSARY	17.20	-
3	BOOTLID LOCK CABLE CLIPS @\$4.30	NOT NECESSARY	12.90	-
1	BOOTLID OUTER GARNISH	BENT / TWISTED	164.70	164.70
3	BOOTLID OUTER GARNISH CLIPS @\$4.30	NOT NECESSARY	12.90	-
2	FRONT LICENCE PLATE LAMP @\$64.10	NOT NECESSARY	128.20	-
1	REAR END PANEL	BADLY DENTED	694.70	694.70
1	REAR END PANEL INNER TRIM	TWISTED	234.30	234.30
4	REAR END PANEL INNER TRIM CLIPS @\$4.30	NECESSARY	17.20	17.20
1	REAR LUGGAGE FLOOR PANEL	CRUMPLED / BUCKLED	678.70	678.70
4	REAR LUGGAGE FLOOR PANEL INSULATOR CLIPS @\$4.30	NOT NECESSARY	17.20	-
2	REAR LAMP @\$375.80	CRACKED	751.60	751.60
2	REAR LAMP PANEL @\$124.00	TO REPAIR SEE LABOUR	248.00	-
4	REAR LAMP CLIP HOLDER @\$4.30	NOT NECESSARY	17.20	-
2	REAR LUGGAGE FLOOR SIDE COMPARTMENT FOAM @\$108.20	NOT NECESSARY	216.40	-
1	REAR BUMPER	DISTORTED	504.90	504.90
1	REAR BUMPER REINFORCEMENT	DENTED	379.20	379.20
2	REAR BUMPER SIDE RETAINER @\$115.10	BENT	230.20	230.20
2	REAR BUMPER SIDE HOLDER @\$22.30	BENT	44.60	44.60
2	REAR BUMPER REFLECTOR	CRACKED	130.50	130.50
6	REAR BUMPER CLIPS @\$4.30	NECESSARY	25.80	25.80
2	REAR BUMPER END SPLASHIELD COVER @\$59.10	NOT NECESSARY	118.20	-

Report Ref No. CS/AGI18009624/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	512.70	-
1	REAR EXHAUST BOX HEAT SHIELD	NOT NECESSARY	155.10	-
2	REAR EXHAUST BOX MOUNT @\$78.90	NOT NECESSARY	157.80	-
	LESS 25% DISCOUNT		-1,979.63	-1,259.09
			5,938.87	3,777.28
	<u>SPECIAL NETT ITEMS</u>			
1	REAR LUGGAGE FLOOR PANEL INSULATOR (SN)	NECESSARY	250.00	120.00
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	450.00	200.00
1	REAR LICENSE PLATE (SN)	BENT	50.00	40.00
			750.00	360.00
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BOOTLID HINGE,REAR LAMP PANEL AND REAR EXHAUST BOX.		2,000.00	1,400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	1,100.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMMINGS,GARNISH AND OTHER,TO ENABLE REPAIR.		180.00	80.00
	TO DROP REAR EXHAUST BOX AND RENEW THE SAME.		150.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO TRANSFER BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		120.00	60.00
	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND DIAGNOSTIC MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC JACK.	NOT NECESSARY	500.00	-
	TO RUST PROOFING OF THE AFFECTED PORTION.		200.00	100.00
	-		-	-
	-		-	-
	-		-	-
			4,730.00	2,870.00
	GRAND TOTAL		11,418.87	7,007.28
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,600.00

Report Ref No. CS/AGI18009624/Uvd3n2



Report Ref No. CS/AGI18009624/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.