

ASS. REC. BY:

REF: CS/EGI18009633/8/03 n2 Special Instruction:

Surveyor: Sebastian

ASSIGNMENT (Office)

From (Person): Yee Pui Li

of EGI

Date/Time: 28/5/18 @ 8:44am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8HF 1003J

Insured:

GBD 7944K

at Workshop m/s

SMRT

Tel:

6866 2672

of

60 Woodlands Ind. Park E &

Policy No:

Claim No:

DSMCV1801048

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/05/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time: 9:15am @ 28/5/18

Person Contacted:

Shanti

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	8HF 1003J -X
	GBD 7944K -
31/05/18 @ 15:28 pm.	revised PA to Pui Li via email.
20/06/18 @ 11:59 a.m.	Confirmed L/S amount \$1,500.00/4 days with
	Poh Suan Greener) via email
	(\$5,626.59 Red - 79%)

REF: EGI

ASSIGNMENT

From:

Date: 28/5/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHF 1003J
8MRT

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ¹wp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHF 1003J

Yr Regn:

30/7/14.

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c. 1798.

Colour:

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

532387.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN364605752018

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

V

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Palky

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/5/18

D.O.I.

28/5/18

Survey held at

SMART

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Tax / 05/18/2110

LKK

Eigo

G507944R

RECEIVED 20 JUN 2018

Date/Time: File Pass to?



: Preli. Report

1)

20/6/18
Typist

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) \$ - RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$ 1500/- 4/s)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

TOTAL

250

Shirley Hiew (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 20 June 2018 1:50 PM
To: 'Shirley Hiew (LKK Auto)'; assignments@lkkauto.com
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'
Subject: RE: GBD7944K / TP : SHF1003J/LKK / DOA : 26/05/2018

Claim no. : DSMCV1801048

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 20 June, 2018 11:50 AM
To: Survey Report (ERGO Insurance Pte. Ltd.); assignments@lkkauto.com
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'
Subject: RE: GBD7944K / TP : SHF1003J/LKK / DOA : 26/05/2018

Dear Pei Li,

Kindly provide us the claim no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Thursday, 31 May 2018 3:28 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments@lkkauto.com
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>
Subject: RE: GBD7944K / TP : SHF1003J/LKK / DOA : 26/05/2018

Dear Pei Li,

Enclosed herewith preliminary advice of SHF 1003J.

Kindly provide us the claim no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 28 May 2018 9:18 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments@lkkauto.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 31 May 2018 3:28 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments@lkkauto.com
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'
Subject: RE: GBD7944K / TP : SHF1003J/LKK / DOA : 26/05/2018
Attachments: SHF 1003J - Preli Advise.pdf

Dear Pei Li,

Enclosed herewith preliminary advice of SHF 1003J.

Kindly provide us the claim no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 28 May 2018 9:18 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments@lkkauto.com
Cc: sur@lkkauto.com
Subject: RE: GBD7944K / TP : SHF1003J/LKK / DOA : 26/05/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Monday, 28 May 2018 8:44 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GBD7944K / TP : SHF1003J/LKK / DOA : 26/05/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 28 May 2018 8:44 AM
To: 'admin-d@lkkauto.com'
Subject: OI : GBD7944K / TP : SHF1003J/LKK / DOA : 26/05/2018
Attachments: SHF1003J - SAS.pdf; SHF1003J - ESTIMATE.pdf; RE: SHF1003J - Survey (Ergo) (738 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**.

ADDRESS : WOODLANDS SMRT DEPOT
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

PERSON TO CONTACT : SHANTI @ 6866 2671/2

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate and third party's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Nivitha (LKK Auto)

From: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
<BThaiyalN@smrt.com.sg>
Sent: Monday, 28 May 2018 8:13 AM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Subject: RE: SHF1003J - Survey (Ergo)
Attachments: SHF1003J.pdf; 2110 - 1003.pdf

Dear Sir /Mdm,

Kindly arrange to survey the vehicle **SHF1003J** within 48 hours according to GIA guide line, involving your insured **GBD7944K**

Insurance Company : **ERGO**
Vehicle in **Woodlands. SMRT Depot**

**Please arrange LKK to survey our taxi*

Regards
Shanti
SMRT Automotive Services PTE LTD
Accident Reporting Center (Claims Dept)
6866 2671/2 | bthaiyaln@smrt.com.sg



Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 20 June 2018 2:29 PM
To: Shirley Hiew (LKK Auto)
Cc: SUR; CS A Team; Sebastian Yeang (LKK Auto)
Subject: RE: SHF1003J

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, 20 June 2018 11:59 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: 'SUR'; 'CS A Team'; 'Sebastian Yeang (LKK Auto)'
Subject: RE: SHF1003J

Hi Poh Suan,

kindly confirmed finalised L/S amount \$ 1,500.00 and 4 repair days.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 19 June 2018 3:38 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>
Subject: RE: SHF1003J

Hi

FYI.

Regards
Poh Suan

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 19 June 2018 3:35 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 20 June 2018 11:59 AM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'
Cc: SUR; CS A Team; Sebastian Yeang (LKK Auto)
Subject: RE: SHF1003J

Hi Poh Suan,

kindly confirmed finalised L/S amount \$ 1,500.00 and 4 repair days.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 19 June 2018 3:38 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>
Subject: RE: SHF1003J

Hi

FYI.

Regards

Poh Suan

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 19 June 2018 3:35 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: "SUR"; cs-a@lkkauto.com; SebastianYeang@lkkauto.com
Subject: FW: SHF1003J

Dear Poh Suan,

Please forward us resurvey photos.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Friday, 8 June 2018 7:21 PM
To: Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHF1003J

Hi Sebastian,

Attached herewith the repair estimate of SHF 1003J having Case No:
TAX/05/18/2110.

There is no change to the approved amount of \$1,500 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Friday, 8 June 2018 1:48 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 31 May 2018

Our Ref: CS/EG118009633/Ssd3

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SHF 1003J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/05/2018 at the premises of M/s SMRT Automotive Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 7,126.59 .
Revised Estimate Amount	: S\$ 1,297.44 .
"Check" Items Amount	: S\$ 2,040.14 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Sebastian Yeang
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHF1003J
Vehicle to be Exported:	No
Intended De-registration Date:	30 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1443032
Chassis No.:	JTDKN36U605752018
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$27,464.00
Total Rebate Amount:	\$33,530.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 May 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF1003J
 Ref. No : TAX/05/18/2110
 Reg. Date : 30/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : SUDIRMAN BIN MARJAN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 26/05/2018 06:55:00 AM
 Accident Reported Date / Time : 26/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096280
 Special Instruction to ARC, if any :
 GBD7944K
 Prepared Date : 26/05/2018 09:06:56 AM



Sebastian.
 28/5/18.
 - Lump Sum Repair.
 - Question Mark Item
 Photo
 - Photo After Repair.

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605752018

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,476.00	0.00
Total Material Charges	: 4,185.59	4,185.59
Other Charges	: 620.00	0.00
TOTAL	: 7,126.59	0.00
Lum Sum Total	: 7,150.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	3 days
Arc / Surveyor Sign Off Date	: 26/05/2018 11:22:19 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/05/2018 11:22:19 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00	0.00 400
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 X
TO RESPRAY REAR PANEL	180.00	0.00 X
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 X
TO RESPRAY REAR SPOILER	180.00	0.00 X
Total Spray Painting & Panel Beating	1,476.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 X
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	620.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
90467-07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace	No
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace	No
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No
76801-47070-B0			TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.67	Replace	Replace	No
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace	No
75441-47031			NAME PLATE (TOYOTA)	1	49.40	25.00	37.05	Replace	Replace	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No
81006-47011		6505464	3RD BRAKE LAMP	1	231.30	10.00	208.17	Replace	Replace	No
76085-47910		6505620	SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace	No
TOTAL MATERIALS								5,232.06	5,231.99	
TOTAL MATERIALS(Discounted)								4,185.59	4,185.59	

Added Spare Parts / Material Usage After Surveyor Signed off


Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

28-5-18 / 14:52

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF1003J
 Ref. No : TAX/05/18/2110
 Reg. Date : 30/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : SUDIRMAN BIN MARJAN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 26/05/2018 06:55:00 AM
 Accident Reported Date / Time : 26/05/2018 12:00:00 AM
 Surveyor Is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096280
 Special Instruction to ARC, if any :
 GBD7944K (ERGO) HS
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP: 90036121
 Prepared Date : 26/05/2018 09:06:56 AM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date

28-5-18

2nd witness

Date

532387

1 1 1
1/4 1/2 3/4

QC 2/6/18 11:42 PM

Supplementary
& Refer to the Supplementary part 1/6

532449

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

2-6-2018

Vehicle Return Time:

11:00 am

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605752018

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	400.00
Total Spray Painting Charges	: 1,476.00	400.00
Total Material Charges	: 1,792.26	610.97
Other Charges	: 620.00	80.00
TOTAL	: 4,733.26	1,490.97
Lump Sum Total	: 4,750.00	1,500.00
No. of Repair Days	: 6.00	4.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 26/05/2018 11:22:19 AM	28/05/2018 02:52:25 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/05/2018 11:22:19 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1806-0124
Quotation Date : 6/6
Invoice Amount :

Invoice No :
Invoice Date :
Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00	400.00
Total Labour	845.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY TAIL GATE	378.00	200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00
TO RESPRAY REAR SPOILER	180.00	0.00
Total Spray Painting & Panel Beating	1,476.00	400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	620.00	80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
52159-47905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No <i>R</i>	
90467-07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace	No <i>/</i>	rec
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>/</i>	rec
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Replace <i>S</i>	No <i>/</i>	DD
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Check	No <i>X</i>	{
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No <i>X</i>	
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Check	No <i>X</i>	
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Check	No <i>X</i>	{
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Check	No <i>X</i>	
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>S</i>	No <i>/</i>	
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace	No <i>/</i>	cut
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.58	Replace	Replace <i>S</i>	No <i>/</i>	dis
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace <i>S</i>	No <i>/</i>	Def
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No <i>/</i>	Dis
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.88	Replace	Check	No <i>X</i>	{
58307-47060		6505522	END PANEL	1	602.10	25.00	451.58	Replace	Check	No <i>X</i>	
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	0	46.10	25.00	0.00	Replace	Not given	No <i>X</i>	
64716-47031B0			END PANEL COVER, DECK TRIM, RR	0	121.10	25.00	0.00	Replace	Not given	No <i>X</i>	{
67881-47022			TAILGATE DOOR WEATHER STRIP	0	353.40	25.00	0.00	Replace	Not given	No <i>X</i>	
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No <i>X</i>	
67005-47241			TAILGATE ASY	1	1,007.90	100.00	0.00	Replace	Repair	No <i>R</i>	
76801-47070-B0			TAILGATE OUTSIDE GARNISH	0	504.90	25.00	0.00	Replace	Not given	No <i>X</i>	{
75310-47020		6505639	EMBLEM REAR	0	60.30	25.00	0.00	Replace	Not given	No <i>X</i>	
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>/</i>	rec
75442-47030			NAME PLATE (PRIUS)	0	60.80	25.00	0.00	Replace	Not given	No <i>X</i>	{
75441-47031			NAME PLATE (TOYOTA)	0	49.40	25.00	0.00	Replace	Not given	No <i>X</i>	
			STICKER DECAL SMRT	0	7.80	0.00	0.00	Replace	Not given	No <i>X</i>	
	COMMO N		STICKER DECAL 6555 8888	0	21.60	0.00	0.00	Replace	Not given	No <i>X</i>	{
	REAR		NUMBER PLATE	0	30.00	0.00	0.00	Replace	Not given	No <i>X</i>	

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
			NUMBER PLATE FRAME	0	12.00	0.00	0.00	Replace	Not given	No X
81006-47011		6505464	3RD BRAKE LAMP	0	231.30	10.00	0.00	Replace	Not given	No X
76085-47910		6505620	SPOILER REAR	0	953.70	25.00	0.00	Replace	Not given	No X
TOTAL MATERIALS							2,240.34	763.71		
TOTAL MATERIALS(Discounted)							1,792.26	610.97		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

763.71

- 20%

610.98

+ 400.00

+ 480.00

1490.98

4S \$1500/-

9703.20

REQUEST FOR SUPPLYMENT PARTS

Contractor:			
Accident Case Number	TAX/05/18/2/10	Date of Collection	/ /
Vehicle No	S4F 1003 J	Date of Request	30/05/2018
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	2 1 day

S/N	Part Number	Part Description	Quantity	Unit Price
		REAR BUMPER REINFORCEMENT	1pc	✓ DT
		REAR BUMPER RETAINER RH	1pc	✓ BR
		REAR BUMPER LIP RH	1pc	✓ CUT
		REAR BUMPER LIP	1pc	✓ DT

<<<Please submit photographs for damaged parts>>>

Sebastian
1/6/2018

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted	YES / NO	Date of submission



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18009633/Ssd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 21-06-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 7944K	Veh. Inspected	SHF 1003J	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1801048	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	28/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U605752018	Colour	MAROON	
Odometer	532387	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/05/2018	Inspection Date	28/05/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 1003J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	BUMPER CLIPS @\$2.10 (DISC 25%)	NECESSARY	21.00	15.75
1	BUMPER REINFORCEMENT REAR (DISC 25%)	DENTED	205.70	154.27
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	CRACKED	94.80	71.10
1	BUMPER SEAL,RR RH (DISC 25%)	CUT	65.70	49.27
1	BUMPER LIP COVER RR/RH (DISC 25%)	DISTORTED	118.10	88.57
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.67
1	BUMPER LIP COVER RR/LH (DISC 25%)	DISTORTED	72.20	54.15
1	NAME PLATE (HYBRID)(DISC 25%)	NECESSARY	51.90	38.92
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	ARM SUB-ASSY,RR BUMPER LH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY,RR BUMPER RH	NOT NECESSARY	139.60	-
1	ANTENNA,ELECTRICAL LOWER REAR	NOT NECESSARY	157.40	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	UNDER COVER SUB-ASSY,RR FLOOR	NOT NECESSARY	514.50	-
1	END PANEL	NOT NECESSARY	602.10	-
1	END PANEL COVER,DECK TRIM HOLE	NOT NECESSARY	46.10	-
1	END PANEL COVER,DECK TRIM,RR	NOT NECESSARY	121.10	-
1	TAILGATE DOOR WEATHER STRIP	NOT NECESSARY	353.40	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	TAILGATE OUTSIDE GARNISH	NOT NECESSARY	504.90	-
1	EMBLEM REAR	NOT NECESSARY	60.30	-
1	NAME PLATE (PRIUS)	NOT NECESSARY	60.80	-
1	NAME PLATE (TOYOTA)	NOT NECESSARY	49.40	-
1	STICKER DECAL SMRT	NOT NECESSARY	7.80	-
1	STICKER DECAL 65558888	NOT NECESSARY	21.60	-
1	NUMBER PLATE	NOT NECESSARY	30.00	-
1	NUMBER PLATE FRAME	NOT NECESSARY	12.00	-
1	3RD BRAKE LAMP	NOT NECESSARY	231.30	-
1	SPOILER REAR	NOT NECESSARY	953.70	-

Report Ref No. CS/EGI18009633/Ssd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
1	TAILGATE ASY	TO REPAIR SEE LABOUR	1,007.90	-
			6,762.20	763.70
	LABOUR			
	PANEL BEATING & BODY WORKS.INCLUSIVE OF THE REPAIR OF BUMPER REAR AND TAILGATE ASY.		845.00	400.00
	SPRAY PAINT.		1,476.00	400.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO INSPECT RR LIGHTING,MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	NOT NECESSARY	120.00	-
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	50.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,941.00	880.00
	GRAND TOTAL		9,703.20	1,643.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/EG18009633/Ssd3n2

YEANG WAI KEEN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.