

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9604H**AAD1805-056***Not Authenticated
11 Sep @ 2700h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9604H

KL1LA69RJB100125

CHEVROLET

EPICA 2.0

7.5.2018

III**PART****LIST**

1	1	Front Fender LH	\$	R 837.60 X
2	1	Front Fender Liner LH	\$	SL 47.00 X
3	1	Fender Insulation LH	\$	SL 39.00 X
4	1	Front Fender Inner Wheel House Panel LH	\$	R 1,437.00 X
5	1	Front Door LH	\$	B 1,133.00 ✓
6	1	Front Door Glass Guide RH Chrome Moulding	\$	L 60.00 X
7	1	Front Door Outer Moulding	\$	NR 220.00 ✓
8	1	Front Door Outer Handle	\$	BR 125.00 ✓
9	1	Front Door Handle Support	\$	. 3.00 ✓
10	1	Front Door outer handle inner seal	\$	NR 89.15 ✓
11	1	Front Door outer key lock	\$	SL 25.00 X
12	1	Front Door Hinge Upper	\$	R 65.00 X
13	1	Front Door Hinge Lower	\$	R 65.00 X
14	1	Front Door inner lock	\$	R 586.00 X
15	1	Front Door Inner Lock Latch LH	\$	R 206.00 X
16	1	Front Door Check / Arrestor	\$	SL 67.50 X
17	1	Front Door Weatherstrip LH	\$	SL 138.79 X
18	1	Front Door glass channel weatherstrip	\$	SL 160.00 X
19	1	Front Door inner trim board	\$	SL 455.69 X
20	1	Front Door window glass	\$	SL 456.12 X
21	1	Front Door Power Window Motor (Master) LH	\$	SL 284.97 X
22	1	Front Door power window motor switch	\$	SL 145.00 X
23	1	Front Door Window Regulator Gear LH	\$	B 84.58 ✓
24	1	Front Door Outer Pillar Panel LH	\$	R 715.00 X
25	1	Front Door Pillar Inner Panel LH	\$	R 850.00 X
26	1	Front Door Center Pillar Panel LH	\$	R 698.15 X
27	1	Front Side View Mirror Assy LH	\$	BR 1,191.00 ✓

Trans-cab Auto Services Pte Ltd

AAD1805-056

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9604H

28	1	Rear Door RH (Panel A-RR DR LH)	\$	<i>12</i> 1,133.00 <i>X</i>
----	---	---------------------------------	----	-----------------------------

TOTAL	\$	11,317.55
10%	\$	1,131.76
	\$	10,185.80

Specical Nett

1 Set	Front Bumper Fastener Clip	\$	<i>nn</i> 24.00 <i>X</i>
1 Set	Front licence plate with holder	\$	<i>nn</i> 192.00 <i>X</i>
1 Set	Radiator Grille clip	\$	<i>nn</i> 35.00 <i>X</i>
1 Set	Front Fender Liner clip	\$	<i>nn</i> 30.00 <i>X</i>
1	Front Fender RR Bracket RH	\$	<i>12</i> 7.10 <i>X</i>

TOTAL	\$	288.10
--------------	-----------	---------------

TOTAL PARTS	\$	10,473.90
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	<i>201</i> 170.00
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <i>2501</i>
Putty and spray painting of the affected portion.	\$	4,000.00 <i>4001</i>
Towing Fees.	\$	120.00 <i>501</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1805-056

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9604H

To rust-proofing of the affected areas.	\$	170.00	30%
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	60%
To transfer of fender fittings, attachment and perform water seepage test.	\$	~ 170.00	X

TOTAL	\$	10,460.00
--------------	-----------	------------------

Over All Total	\$	20,933.90
-----------------------	-----------	------------------

Repair Days (Lump Sum)~~15 days~~

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: