

22/04/2018

ASS. REC. BY:

REF: CS3/AIC18009647/G24dB^{on}

Special Instruction:

Surveyor: 90 ASSIGNMENT (Office)

From (Person): Winnie Fan of AIG Date/Time: 11:25am @ 28/5/2018

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDH 66 99F Insured: SJR 3637E

at Workshop m/s: Verve motor clinic Tel: 9159 5951

of No 25 Kaki Bukit Rd 4 #03-39 Synergy

Policy No: 2100505524 Claim No: 754635951696

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26/5/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: _____

Date/Time: 12:05pm @ 28/5/18 Person Contacted: Mr. Jaron Vehicle: IN / OUT


Date/Time	Action/Instruction (X) Estimate
	SDH 66 99F - X
	SJR 3637E - X
31/5/18	dismantled

PRS
Kee

REF: A16

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s Verve Motorclinic
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SDH6699 Yr Regn: - /
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Volkswagen Golf c.c. -
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 136814 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WUWZZZIK8AW367197
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/45R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 28-05-18
 Survey held at w/s 4pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1/6/18	Submit DAR report.

RECEIVED 01 JUN 2018

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)) \$ + RS. \$
 : Interview (\$ _____)) Photos
 : Tech. Invs (\$ _____)) Others
 : Weekend (\$ _____))
 TOTAL _____

- PRI AIG Insured SJR3637E(2ND) [EAL.2018.5692.MK.ya - SDH6699F(1ST)]

From: Fan, Winnie-LW
To:
Cc: Fong, Andy-SY, Chin, Lee-Ying
Sent: 28/5/2018 11:25:13 AM

Hi LKK,

Kindly assist to survey, car is in.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Fax +(65) 6835 7416
winnie-lw.fan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Yvonne [mailto:yvonne@ealc.com.sg]
Sent: Monday, May 28, 2018 11:18 AM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Fan, Winnie-LW
Subject: PRI AIG Insured SJR3637E(2ND) [EAL.2018.5692.MK.ya - SDH6699F(1ST)]

Our ref : 2018.5692.MK.ya - **SDH6699F(1ST)**
Your ref : **SJR3637E(2ND)**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

AIG Asia Pacific Insurance Pte Ltd
No. 78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s AIG Asia Pacific Insurance Pte Ltd		
Vehicle SDH6699F(1ST) inspected as follows by Name:		
Before repair	Parts removed	After repair
_____	_____	_____
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE
CLAIMANT: WONG CHUEN YUE MARCUS

ACCIDENT INVOLVING SDH6699F(1ST) & SJR3637E(2ND) & SLA1874R(3RD) ON 26 MAY 2018 ALONG PIE BEFORE PAYA LEBAR EXIT AT ABOUT 1554 HOURS

We refer to the above matter wherein we are instructed to act for **WONG CHUEN YUE MARCUS**, the owner of vehicle no. **SDH6699F(1ST)**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SDH6699F(1ST)** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Verve Motorclinic Pte Ltd
No. 25 Kaki Bukit Road 4,
#03-39 Synergy@KB,
Singapore 417800
Tel: 91595951 (Mr Jaron)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

5) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)

Aug 2005
 (1) Replace (✓) (2) Repair (X) (3) Check (✓)
 (4) Not Consistent (NC)

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BR	✓	
1138	993627	Rear Number Plate Base	BR	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	CRA	✓	2
1141	992958	Rear Bumper	RE	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	RE	✓	1
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket	RE	✓	
1148	993068	Rear Bumper Side Retainer	RE	✓	2
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DMG	✓	
1159	993327	Rear End Panel	DT	✓	
1160	993339	Rear End Panel Top Garnish	BR	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	Cut	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CUT	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH	SCR	✓	
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber	BT	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	BT	✓	
1182	991328	Tailgate Emblem	NBC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	CRA	✓	2
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NBC	✓	
1196	994607	Tailgate Glass Sealant	MC	✓	
1197	994629	Tailgate Lock	DT	✓	
1198	994651	Tailgate Rubber	WIP	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Inner Board	RE	✓	

Vehicle No: SDH 6699 F

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			repair
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	RE	✓	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim	RE	✓	
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 May 2018 Edit Reg		28 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	SHI YING , ID: S7966366B		
Main Claimant:	WONG CHUEN YUE MARCUS		
Vehicle Reg. No.:	SDH6699F	Date of Loss:	26/05/2018 15:00 - :59 [340 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7546359516SG	Policy/Cover Note No.:	2100505524 (Comprehensive)
Vehicle Reg. No. (Insured):	SJR3637E	Policy No. (Claimant):	
		Excess:	
Repairer:	Verve Autoclinic (HQ) 1 KAKI BUKIT AVENUE 6 #02-22, 417883 Kaki Bukit - Tel: 9159 5951		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/06/2018]		
Claimant's Solicitor:	EAST ASIA LAW CORPORATION - Tel: 63232565		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (05/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDH6699F (7546359516SG)**
[SJR3637E]
TP
WONG CHUEN YUE MARCUS
May 26 2018 3:00PM
[SHI YING]
Verve Autoclinic

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value=""/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
2	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
3	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
4	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
5	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
6	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
7	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
8	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
9	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
10	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
11	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
12	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
13	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
14	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
15	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
16	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
17	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
18	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
19	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
20	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
21	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
22	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
23	01/06/18 11:45	General View	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
24	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
25	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
26	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
27	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
28	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
29	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
30	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
31	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
32	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
33	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
34	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>
35	01/06/18 11:46	Dismantled Parts	<input type="button" value="1"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
36	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
37	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
38	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
39	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
40	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
41	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
42	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
43	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
44	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
45	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
46	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
47	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
48	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
49	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
50	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
51	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
52	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
53	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
54	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
55	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
56	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
57	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
58	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
59	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
60	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
61	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
62	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
63	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
64	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
65	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
66	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
67	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
68	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
69	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
70	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
71	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
72	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
73	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
74	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
75	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
76	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
77	01/06/18 11:46	Dismantled Parts	1	Load JPG ✓
78	29/06/18 12:46	Photo After Spray	1	Load JPG ✓
79	29/06/18 12:46	Photo After Spray	1	Load JPG ✓
80	29/06/18 12:46	Photo After Spray	1	Load JPG ✓
81	29/06/18 12:46	Photo After Spray	1	Load JPG ✓
82	29/06/18 12:46	Photo After Spray	1	Load JPG ✓
83	29/06/18 12:46	Photo After Spray	1	Load JPG ✓

Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
84	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
85	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
86	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
87	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
88	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
89	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
90	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
91	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
92	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
93	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
94	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
95	29/06/18 12:46	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	05/06/18 14:35	OI GIA REPORT		Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009647/GZ4D3S2

Date: 06/07/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100505524
Claimant Vehicle No :	SDH6699F	Insured Vehicle No :	SJR3637E
Date of Loss:	26/05/2018	Nature of Claim:	TP
		Claim No:	7546359516SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDH6699F	Engine No:	HIDDEN
Make & Model:	VOLKSWAGEN GOLF A7, 1.4 (A)	Chassis No:	WVWZZZ1KZAW367197
Reg. Date:	01/01/1990 (Man. Year: 1990)	Odometer:	136814 km
Colour:	Black		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	28/05/2018		
Date Inspected:	28/05/2018	Inspected At:	No.25 Kaki Bukit Rd4 #03-39 Synergy Repairer: Verve Motor Clinic 10 Kaki Bukit Rd 2 Singapore 417868
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR NUMBER PLATE	Broken	0.00 F	*-F	
2	1		*REAR NUMBER PLATE BASE	Broken	0.00 F	*-F	
3	1		*REAR BUMPER	Deformed	0.00 F	*-F	
4	1		*REAR BUMPER LOWER	Deformed	0.00 F	*-F	
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F	
6	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*-F	
7	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*-F	
8	1		*REVERSE SENSOR	Damaged	0.00 F	*-F	
9	1		*REAR END PANEL	Dented	0.00 F	*-F	
10	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*-F	
11	1		*REAR RH TAILLAMP	Cut	0.00 F	*-F	
12	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*-F	
13	1		*REAR BUMPER BRACKET	Deformed	0.00 F	*-F	
14	1		*REAR LH TAILLAMP	Cut	0.00 F	*-F	
15	1		*TAILGATE	Bent	0.00 F	*-F	
16	1		*TAILGATE EMBLEM	Necessary	0.00 F	*-F	
17	2		*TAILGATE LAMP	Cracked	0.00 F	*-F	
18	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*-F	
19	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*-F	
20	1		*TAILGATE LOCK	Dented	0.00 F	*-F	
21	1		*TAILGATE RUBBER	Twisted	0.00 F	*-F	
22	1		*TAILGATE INNER BOARD	Deformed	0.00 F	*-F	
23	1		*SPARE TYRE PANEL	Repair	0.00 F	*-F	
24	1		*REAR LH FENDER INNER TRIM	Deformed	0.00 F	*-F	
25	1		*REAR RH FENDER INNER TRIM	Deformed	0.00 F	*-F	
					Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >