

威利摩多 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455 3986

Business Regn No : 269436/00J

*Not Authorised
L1Lp @ 2050/
Penny After Paint
4 days*

22, May 2018

EQ Insurance Company Ltd
5 Maxwell Road #17-00
Tower Block MND Complex
S 069110

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle No: SJH5838G
Accident involving vehicle No: SJH7067B/SJH5838G
DOA: 09/05/2018 AT Jurong East Central To Jurong East 24

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SJH7067B

To supply--

Description	Qty	Amount
Front fender, Rh	1	723.40 ✓
Headlamp, Rh	1	853.60 ✓
Front bumper	1	472.80 ✓
Front bumper retainer, Rh	1	53.60 ✓
Rim, Rh	1	280.00 ✓
Tyre	1	220.00 X
	Parts	2,603.40
	Less 25%	650.85
		1,952.55

To remove damaged parts and attachments.

Repair/reshape dented areas.

Replace/align above parts into position

To spray paint

700.00

600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: