

ASS. REC. BY:

REP:

CS/18009057/11sd302

did not receive

SURVEYOR

CWS

From (Person)

Taufik
Lurere jaw

ASSIGNMENT (Office)

of FCI

Date/Time: 28/5/18 @ 4-04pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SID 8503A

Insured:

SHC 7187M

at Workshop to:

Vermogen Ace

Tel:

6368 3031

of

6 Benvi sefor

Policy No:

Claim No:

D18004232 MPSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 26/5/2018

CA / REV / REP. / REV 24 HRS

1wpr

30/05/2018

R.O.D. Endorsement:

Date/Time:

433pm 28/5/18

Person Contacted:

eze

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SID 8503A - C3/E6I/601722/Dv/bq2

D.O.A: 15/9/18

SHC 7187M - C03/1A/1G/60C500S/H/ub3q2

D.O.A: 15/3/16

05/06/18

@ 14:36 p.m. revised PA to Lurere v.9 email.

11/09/18

Confirmed 1/5 \$ 18,600/- @ 11 days with Taufik

(\$ 23,229.82 Red - 56%)

ASS. REC. BY:

REF:

CS/18009057/T1sd302

Estimate:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Taufik
Lurene Jaw

of

FPI

Date/Time: 28/5/18 @ 4-04pm

Estimated Cost:

Bill to:

OD (TP/WS/TP RES / OD RES / EVA / INV / MV / CS)

To Inspect Vehicle No:

STD 8503A

Insured:

SHC 7187M

at Workshop n/s:

Vermogen Ace

Tel:

6368 3031

of

6 Benoi scfor

Policy No:

Claim No:

D18004232 MPSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26/5/2018

CA / REV / REP. / REV 24 HRS 'wpi

30/05/2018

Date/Time:

4:33pm 28/5/18

Person Contacted:

eze1

H.O.D. Endorsement:

Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate
	✓) Estimate	
	SLD 8503A - C3/EGT/6017222/Dubay 2	D.O.A. 15/9/18
	SHC 7187M - CC3/1A/IG/6005005/H/ub3q2	D.O.A. 15/3/16
05/06/18	@ 14:36 p.m. revised PA to Lurene via email.	
11/09/18	Confirmed L/S \$ 18,600/- @ 11 days with Taufik.	
	(\$ 23,229.82 Red - 56%)	

Signature: *Tanjin*

REF:


FCI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
QD / TP / WS / TP RES / QD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 84k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR. Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
WP

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SUD8503A Yr Regn: 2016 June
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Sienta CC: 1496
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 180292 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NSP 170 7020922
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: " "
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Achilles
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. _____ D.O.I: 1/6/18
 Survey held at: Venue
 Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

Rebate: 50212
Repair Limit: 930K

RECEIVED 12 SEP 2018

Cum/Term. File Pass to? 12/09/18
 Typist
 Cum/Term. File Return to?

☐ : Prel. Report
☒ : Final Report

Days Of Repair: 11
 Resurvey No. of Trip: 3

Add Fee: ☐ Site Insp (S)
☐ Interview (S)
☐ Tech Insp (S)
☐ Weekend (S)

Survey Fee:
 Transportation

580
13/09/18

31x15 = 465

170+465
50
50+50+50
159

994

Report Format :

Lump Sum / I.B.I: (S) 18,600/- 4/5

MOTOR SURVEY ASSIGNMENT

Date	28-05-2018	Our Ref No. D18004232MFSH
Accident Date	26-05-2018	Claim Type. Third Party
Insured Vehicle	SHC7187M	Third Party Vehicle. SLD8503A
Survey Location	6 BENOI SECTOR.	
Contact Person.	PILA	
Contact No.	63583031/ 0	Fax No. 66944929
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VERMOGEN ACE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240811)



PRI Documents



Close



PRI Header Details

Claim No	D18004232MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & VERMOGE
Workshop Name	VERMOGEN ACE PTE LTD (Contact Person : PILA)	Survey Location & Contact Details	6 BENOI SECTOR. Mobile: 0 , Phone: 63583031 , Fax: 66944929 EmailId: PILA@VERMOGEN-GROUP.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7187M	TP Vehicle No	SLD8503A
PRI Recieved Date	28-05-2018 04:54:12 PM	Surveyor Appointed Date	28-05-2018 04:03:04 PM	Surveyor Accept Date	

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-05-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18009657/T1sd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7187M	Veh. Inspected	SLD 8503A
Policy No.		Coverage (\$)	0.00
Claim No.	D18004232MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	28/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/05/2018	Inspection Date
Survey held at	6 BENOI SECTOR	
Repairer	VERMOGEN ACE PTE LTD	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 4597K

Vehicle Details

Vehicle No.: SLD8503A

Vehicle to be Exported: No

Intended De-registration Date: 04 Jun 2018

Vehicle Make: TOYOTA

Vehicle Model: SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 2NR8581033

Chassis No.: NSP1707020922

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$19,160.00

Original Registration Date: 29 Jun 2016

First Registration Date: 29 Jun 2016

Transfer Count: 1

Actual ARF Paid: \$9,160.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Jun 2026

PARF Rebate Amount: \$6,870.00

Intended COE Rebate Details

COE Expiry Date: 28 Jun 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$53,694.00

COE Rebate Amount: \$43,313.00

Total Rebate Amount: \$50,183.00

The information contained herein is correct as at 04 Jun 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement
Sell it yourself. Advertise it at just
\$58 until it's SOLD!

New 5 Years Car Renewal Honda Stream 1.8A



\$2800 Downpayment Monthly
From \$888 Onwards. Lowest
3.88%APR. Apply Cars Financing
Or Credit For Life. [View More](#)

Like View
& Credit Pte Ltd

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

How to Buy Advertiser Login Ways of Selling

Browse by Category

5 vehicles

Toyota Sienta

Sort by Date Posted 20 results/page

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Van Type	Status
Search Selection	Toyota Sienta	Price	Depreciation	Reg Date	Eng Cap	Mileage	Van Type	Status
	Toyota Sienta Hybrid 1.5A X	\$42,888	\$9,981 /yr	17-Jun-2018	1,496 cc	46,555 km	MPV	Available
Fuel Type: Petrol-Electric Signature MPV Toyota Sienta Comes With Certified Warranty! Very Well Maintained By 1 Owner Only! As Good As New! 17" Yokohama Blue Earth Trail Full Servicing Records Provided In Free Possessing... Extra Performance Also For UOT Posted: 03-Jun-2018 Tags: 2018 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota								
	Toyota Sienta 1.5A X	\$79,888	\$9,432 /yr	20-May-2018	1,496 cc	25,104 km	MPV	Available
Most Popular Japanese Reliable Mid-Size 7 Seaters With Comfortable Leg Room And Sliding Door For Easy Access. Superb Fuel Efficiency Without Compromising Power. Non-Uber/Grab Limit. High Loan Available... Car (S) Pte Ltd Posted: 04-May-2018 Tags: 2018 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota								
	Toyota Sienta 1.5A G	\$66,888	\$10,000 /yr	23-Aug-2018	1,496 cc	24,332 km	MPV	Available
1 Owner Only! 100% Accident Free! Super Low Fuel Consumption. Very Well Maintained By the Owner. Evaluation Welcome! Selling Cheap. Up To 80% Loan Available. All Trade In Welcome. We Welcome Buyer's In... Creative Auto Posted: 22-May-2018 Tags: 2018 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota								
	Toyota Sienta 1.5A X	\$79,888	\$9,882 /yr	02-Mar-2018	1,496 cc	25,122 km	MPV	Available
1 Owner Only And The Most Popular Mid-Size 7 Seaters With Comfortable Leg Room And Auto Sliding Doors For Easy Access. Superb Fuel Efficiency Without Compromising Power. Best Selling MPV! Keyless ETC... Creative Auto Posted: 18-May-2018 Tags: 2018 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota								
Car Buying	Car Selling	Car Ownership						
Car Aftermarket	On The Move	Offshore						
	Toyota Sienta 1.5A G	\$79,888	\$9,582 /yr	14-Jan-2018	1,496 cc	32,000 km	MPV	Available
The Toyota Sienta, Ever Popular Entry-Level MPV In The Market, Being A Fun-to-Drive, Stylish Car That Suits The Young Crowd With Big Families. Dual Sliding Door Model With Generous Interior Cabin Space To Fit... Posted: 28-Apr-2018 Tags: 2018 Toyota Sienta, Toyota Sienta, Toyota, Sienta, Used Toyota								

Save the search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Van Type	Status
No old advertisements, view Expired ads								
20 results/page								

sgCarmart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or minivans, SUV, MPV, hatchback, to CDE cars & CPC cars. You can also buy from a car auction, low up car loans, low mileage cars, car brands, compare rates & car insurance. And buy used Toyota Sienta, Toyota Sienta Singapore, used Toyota Sienta Singapore, used Toyota Sienta, used vehicles Singapore or even buy used Toyota Sienta Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarmart.com are gathered from sources and based on algorithms that are believed by sgCarmart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarmart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarmart.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 12 September 2018 12:16 PM
To: 'Baldoz Juan Paulo Bongon'
Cc: 'Asher Sng (LKKAuto)'; 'Admin-D (LKKAuto)'; 'Janice Lee (LKKAuto)'; 'Hsiao Tong (LKKAuto)'; 'Veron Chen (LKKAuto)'; 'Taufikh (LKKAuto)'; 'Vmg admin'; 'Glorioso Eric Paul Patambang'; 'Tejano Exequiel Dawal'; 'Minoko Chan'; 'Pila Ng'; 'Desmond Kor'; 'Edmond Lim'; 'Lina Rosli'; 'Luis Tan'; 'Paul Tan'
Subject: RE: SLD 8503A REPAIR LIMIT

Hi Paulo Baldoz,

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Baldoz Juan Paulo Bongon [mailto:paulo.b@vermogen-group.com]
Sent: Wednesday, 12 September 2018 12:02 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tejano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>; Pila Ng <pila@vermogen-group.com>; Desmond Kor <desmond@vermogen-group.com>; Edmond Lim <edmond@vermogen-group.com>; Lina Rosli <linarosli@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>
Subject: Re: SLD 8503A REPAIR LIMIT

Dear Shirley,

We Confirmed COR @ **\$18,600** bef gst (lump sum) 11 working days.

Thank you

Best Regards,

Paulo Baldoz
Vermogen Ace Pte Ltd
Operation Address:
6 Benoi Sector Singapore 629904
Tel: 6358 3031
Fax: 6694 4929

Mailing Address:
1 Bukit Batok Crescent #04-54

On Wed, Sep 12, 2018 at 11:14 AM, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Paulo Baldoz,

As spoken, please re-confirm final fig of \$18,600.00 (lump sum) @ 11 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Baldoz Juan Paulo Bongon [<mailto:paulo.b@vermogen-group.com>]

Sent: Thursday, 6 September 2018 2:28 PM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tejano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>; Pila Ng <pila@vermogen-group.com>; Desmond Kor <desmond@vermogen-group.com>; Edmond Lim <edmond@vermogen-group.com>; Lina Rosli <linarosli@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>

Subject: Fwd: SLD 8503A REPAIR LIMIT

3rd REMINDER

Dear Officer-in-charge,

SLD8503A DOA: 26/05/2018

Kindly check & revert to us as soon as possible, to expedite the claim.

Please send us your calculation.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

----- Forwarded message -----

From: **Baldoz Juan Paulo Bongon** <paulo.b@vermogen-group.com>

Date: Wed, Aug 1, 2018 at 10:16 AM

Subject: Fwd: SLD 8503A REPAIR LIMIT

To: "Catherine Chong (LKK Auto)" <admin-d@lkkauto.com>, "Janice Lee (LKKAuto)" <JaniceLee@lkkauto.com>, "Asher Sng (LKKAuto)" <AsherSng@lkkauto.com>, "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>, "Veron Chen (LKKAuto)" <veronchen@lkkauto.com>, "Taufikh (LKK Auto)" <taufikh@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>, Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>, Tezano Exequiel Dawal <ezel.t@vermogen-group.com>, Minoko Chan <minoko@vermogen-group.com>, assignments <assignments@lkkauto.com>, Pila Ng <pila@vermogen-group.com>, Edmond Lim <edmond@vermogen-group.com>, Desmond Kor <desmond@vermogen-group.com>, Lina Rosli <linarosli@vermogen-group.com>, Luis Tan <luis@vermogen-group.com>, Paul Tan <paul@vermogen-group.com>

Dear Officer-in-charge,

Kindly check & revert to us as soon as possible, to expedite the claim.

Please send us your calculation.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

----- Forwarded message -----

From: **Baldoz Juan Paulo Bongon** <paulo.b@vermogen-group.com>

Date: Wed, Jun 20, 2018 at 1:30 PM

Subject: Re: SLD 8503A REPAIR LIMIT

To: "Catherine Chong (LKK Auto)" <admin-d@lkkauto.com>, "Janice Lee (LKKAuto)" <JaniceLee@lkkauto.com>, "Asher Sng (LKKAuto)" <AsherSng@lkkauto.com>, "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>, "Veron Chen (LKKAuto)" <veronchen@lkkauto.com>, "Taufikh (LKK Auto)" <taufikh@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>, Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>, Tezano Exequiel Dawal <ezel.t@vermogen-group.com>, Minoko Chan <minoko@vermogen-group.com>

pila@vermogen-group.com>, Pila Ng <pila@vermogen-group.com>, Edmond Lim <edmond@vermogen-group.com>, Lina Rosli <linarosli@vermogen-group.com>, Luis Tan <luis@vermogen-group.com>, Paul Tan <paul@vermogen-group.com>

Dear Officer in-charge,

Please check and confirm finalise COR @ **\$18,950** bef gst (lump sum) 11 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

On Tue, Jun 5, 2018 at 10:06 AM, Catherine Chong (LKK Auto) <admin-d@lkkauto.com> wrote:

Dear Paulo,

Rasul will resurvey by today.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Baldoz Juan Paulo Bongon [<mailto:paulo.b@vermogen-group.com>]

Sent: Tuesday, 5 June, 2018 10:02 AM

To: Taufikh (LKK Auto) <taufikh@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Nivitha (LKK Auto) <admin-d@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tezano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>; Pila Ng <pila@vermogen-group.com>; Edmond Lim <edmond@vermogen-group.com>; Lina Rosli <linarosli@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>

Subject: Fwd: SLD 8503A REPAIR LIMIT

REMINDER..

----- Forwarded message -----

From: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>

Date: Mon, Jun 4, 2018 at 5:17 PM

Subject: Re: SLD 8503A REPAIR LIMIT

To: "Taufikh (LKK Auto)" <taufikh@lkkauto.com>, "Asher Sng (LKKAuto)" <AsherSng@lkkauto.com>, "Nivitha (LKK Auto)" <admin-d@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>, Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>, Tezano Exequiel Dawal <ezel.t@vermogen-group.com>, Minoko Chan <minoko@vermogen-group.com>, Pila Ng <pila@vermogen-group.com>, Edmond Lim <edmond@vermogen-group.com>, Lina Rosli <linarosli@vermogen-group.com>, Luis Tan <luis@vermogen-group.com>, Paul Tan <paul@vermogen-group.com>

Hi Taufikh,

Kindly Re-survey the vehicle SLD8503A tomorrow morning 05/06/2018 for the check items & supplementary.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

On Mon, Jun 4, 2018 at 12:01 PM, Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com> wrote:

Hi Taufikh,

We will undertake under lumpsum at \$30,000 repair limit.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

On Mon, Jun 4, 2018 at 10:18 AM, Taufikh (LKK Auto) <taufikh@lkkauto.com> wrote:

Hi Paulo,

Please take note repair limit is \$30,000.

Regards

Taufikh

Lkk Auto

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 5 June 2018 2:36 PM
To: 'Nivitha (LKK Auto)'; 'Claim Workflow System'; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18004232MFSH/1
Attachments: SLD 8503A - Preli Advise.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLD 8503A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 28 May 2018 4:35 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18004232MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 28 May 2018 4:03 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004232MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004232MFSH

Date: 05 June 2018

Our Ref: CS/FCI18009657/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLD 8503A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/06/2018 at the premises of M/s Vermogen Ace Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 41,156.99</u>
Revised Estimate Amount	: <u>S\$ 18,251.33</u>
"Check" Items Amount	: <u>S\$ 5,788.33</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the front & rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 11 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/05/2018 14:35
Date Of Accident	26/05/2018 11:25
Exact Location Of Accident	KPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD8503A
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201504621K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995063
Cover Note Number	

Driver

Name of Driver	ERWIN SOH CHEE MON
NRIC No	S1433531E
Date Of Birth	09/08/1960
Occupation	OUTDOOR
Date Of Driving Pass	13/10/1980
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 44 BENOI ROAD BLOCK B (ENTTRANCE B) ENTRANCE 6 BENOI SECTOR

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1 NAME: UNKNOWN

GENDER: FEMALE

Passenger 2 NAME: UNKNOWN

GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO PHOTOS ATTACHED. THANK YOU.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC7187M

Vehicle Make/Model/Colour

Details Of Properties VEH. B

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SFH1993P

Vehicle Make/Model/Colour

Details Of Properties

VEH. C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SLN6043X

Vehicle Make/Model/Colour

Details Of Properties

VEH. D

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SFP4344B

Vehicle Make/Model/Colour

Details Of Properties

VEH. E

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false statement may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) Any insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulation, laws or court orders.

  Policyholder's Signature Date & Time:	 Driver's Signature (If driver is not the policyholder) Date & Time:	 Reporting Centre Personnel's Signature Name: RRIC/PN No.:
--	--	---

SKETCH PLAN

KFE

- (A) SLD 8503A
- (B) SHC 7187M
- (C) SPH 193P
- (D) SLN 6043X
- (E) SFP 4344B



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along KFE at the most extremely right lane. However I did not manage to stop in time when the car ahead of me stopped. And I collided into vehicle E rear portion. A few seconds later I felt an impact coming from the rear of my car. I went out to check and realise I was involved in chain collision involving 5 cars, I am the 3rd car.

DECLARATION

I/We declare the foregoing particulars are true to every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

YIRA RAHMAN
Reporting Centre Personnel's Signature
Name:
NRIC/PPN No.:

Accident Sketch Plan

Land Transport Authority

VMG USE ONLY

Serial No. A 32000

Name: Edwin See Chee Mon

NRIC: S1433531E

TEMPORARY PRIVATE HIRE CAR DRIVER'S VOCATIONAL LICENCE

You have passed the vocational licence competency test and have been granted a Private Hire Car Driver's Vocational Licence (PDVL).

PDVL Commencement Date: 17 MAY 2025

You must display this Temporary PDVL in your car at all times while driving a chauffeured private hire car.

TA will subsequently inform you to collect your Vocational Licence Card that will replace this Temporary PDVL. You must collect your Vocational Licence Card within 6 months of the PDVL Commencement Date and display it in your car thereafter. Otherwise, your PDVL may be revoked.

Mei Fong
Assistant Registrar of Vehicles
Land Transport Authority of Singapore



Temporary PDVL is handed to you by _____ (centre officer name),
(officer designation), of _____ (centre name).



SLD8503A

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : FCI
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 26/5/2018

Vehicle Reg. No. : SLD8503A
Vehicle Reg. Date: 29-Jun-2016
Make / Model : T. SIENTA 1.5X HYBRID A1
Engine No. : 2NR8581033
Chassis No. : NSP1707020922

COST OF CLAIMS

Parts Cost / List Items : \$ 40,502.65
Plus/Less 25% \$ 10,125.66
Total Cost / List : \$ 30,376.99
Special Nett Items : \$ 1,730.00
Total Parts Amount : \$ 32,106.99
Total Labour Amount : \$ 9,050.00
Gross Total : \$ 41,156.99
GST % : 7% \$ 2,880.99
Nett Amount : \$ 44,037.98

Surveyor Name and Company :

Taufik 97495744
Date of survey : 01/6/18
Part by Part / Lump Sum : 11 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur@lkkauto.com
Fax No :
HP No :

This claim is handled by : PAULO BALDOZ

* To check repair limit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD8503A**
 Vehicle Reg. Date: **29/6/2016**
 Make / Model : **T. SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2V**
 Engine No. : **2NR8581033**
 Chassis No. : **NSP1707020922**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Bonnet	bt	\$ 706.00		
2	1	Bonnet lock	bt	\$ 122.00		
3	1	Bonnet hinge LH	bt	\$ 84.00		
4	1	Bonnet hinge RH	bt	\$ 84.00		
5	1	Bonnet heat insulator	X nn	\$ 88.00		
6	1set	Bonnet heat insulator clips	X nn	\$ 50.00		
7	1	Bonnet seal	ac	\$ 54.00		
8	1	Headlamp LH	ac	\$ 2,300.00		
9	1	Headlamp RH	ac	\$ 2,300.00		
10	1	Headlamp panel LH	bt	\$ 130.00		
11	1	Headlamp panel RH	bt	\$ 130.00		
12	1	Front support panel	bt	\$ 1,197.00		
13	1	Brace panel	bt	\$ 215.00		
14	1	Radiator	bt	\$ 2,188.00		
15	1	Front grille chrome moulding	ac	\$ 947.00		
16	1set	Front grille clips	ac	\$ 50.00		
17	1	Front top cover	de	\$ 92.00		
18	1	Front bumper	de	\$ 679.00		
19	1set	Front bumper clips	na	\$ 50.00		
20	1	Front bumper logo	na	\$ 500.00		
21	1	Front bumper base logo	de	\$ 500.00		
22	1	Front bumper sponge	ac	\$ 97.60		
23	1	Front bumper reinforcement	bt	\$ 489.00		
24	2	Front reinforcement support bracket LH/RH	X nn	\$ 190.00		
25	1	Front bumper upper retainer	na	\$ 92.00		
26	2	Front bumper side retainer LH/RH	ac	\$ 192.00		
27	1	Front bumper grille	X nn	\$ 750.00		
28	1	Front bumper tow cover	X nn	\$ 32.00		
29	2	Front radiator air guide lower/upper	ac	\$ 256.00		
30	1	Fog lamp garnish RH	X nn	\$ 148.00		
31	1	Fog lamp garnish LH	X nn	\$ 148.00		
32	1	Front fender RH	bt	\$ 690.00		
33	1	Front fender inner shield RH	X nn	\$ 163.00		
34	1set	Front fender inner shield clips RH	X nn	\$ 40.00		
35	1	Front fender LH	bt	\$ 690.00		
36	1	Front fender inner shield LH	X nn	\$ 163.00		
37	1set	Front fender inner shield clips LH	X nn	\$ 40.00		
38	1	Washer tank	X nn	\$ 140.00		
39	1	Washer tank pump	X nn	\$ 150.00		
40	1	Air duct assy	X nn	\$ 797.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD8503A**
 Vehicle Reg. Date: **29/6/2016**
 Make / Model : **T. SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2V**
 Engine No. : **2NR8581033**
 Chassis No. : **NSP1707020922**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Condenser	bt ✓	\$ 2,022.00		
42	1	Condenser side cover	de ✓	\$ 95.00		
43	1	Radiator fan motor	7 ✓ 300	\$ 457.00		
44	1	Radiator fan blade	2 ✓ 02	\$ 180.00		
45	1	Radiator fan cowl	2 ✓ 04	\$ 250.00		
46	1	Radiator hose top	2 X 00	\$ 60.00		
47	1	Radiator bottom top	2 X 00	\$ 60.00		
48	2	Horn (high/low)	2 X 00	\$ 180.00		
49	1	Aircon discharge	2 X 00	\$ 370.00		
50	1	Aircon liquid pipe	2 X 00	\$ 211.10		
51	1	Aircon Suction pipe	2 ✓ 00	\$ 484.00		
52	2	Front chassis member LH/RH	Ryo	\$ 1,305.20		
53	1	Rear windscreen moulding	we ✓	\$ 168.40		
54	1	Rear number plate lamp assy	X 00	\$ 158.00		
55	1	Rear bumper	de ✓	\$ 838.80		
56	1	Rear bumper cover center	200 out	\$ 182.40		
57	2	Rear bumper cover LH/RH	LH-Y, RH-out	\$ 391.00		
58	1set	Rear bumper clips	we ✓	\$ 50.00		
59	2	Rear bumper side retainer LH/RH	2 ✓ 00	\$ 164.00		
60	2	Rear bumper bracket LH/RH	X 00	\$ 164.00		
61	1	Rear bumper sponge	2 ✓ 00	\$ 98.00		
62	2	Rear bumper reflector LH/RH	X 00	\$ 216.00		
63	2	Rear bumper splash shield LH/RH	X 00	\$ 340.00		
64	1	Tail gate	bt ✓	\$ 1,360.00		
65	1	Tail gate lock	bt ✓	\$ 246.60		
66	1	Tail gate striker	bt ✓	\$ 48.00		
67	2	Tail gate stay LH/RH	X 00	\$ 320.00		
68	1	Tail gate logo	we ✓	\$ 50.00		
69	1	Tail gate emblem	we ✓	\$ 59.40		
70	1	Tail gate outer garnish	X 00	\$ 84.50		
71	1	Tail gate weatherstrip	ut ✓	\$ 145.00		
72	2	Tail gate lamp LH/RH	X 00	\$ 720.00		
73	1	Tail door trim	X 00	\$ 280.00		
74	1set	Tail door trim clips	X 00	\$ 60.00		
75	2	Tail lamp LH/RH	2 ✓ 00	\$ 780.00		
76	2	Tail lamp bracket LH/RH	2 X 00	\$ 180.00		
77	1	Tail gate inner handle	de ✓	\$ 90.00		
78	1	Antenna sensor	2 ✓ 00	\$ 190.00		
79	1	Rear wiper motor	X 00	\$ 387.60		
80	1	Rear wiper motor link	X 00	\$ 245.10		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD8503A**
 Vehicle Reg. Date: **29/6/2016**
 Make / Model : **T. SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2V**
 Engine No. : **2NR8581033**
 Chassis No. : **N5P1707020922**

PAGE 3

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
81	1	Rear wiper arm	X 00	\$ 187.50		
82	1	Rear wiper blade	X 00	\$ 98.40		
83	1	Rear end panel outer	gt	\$ 498.20		
84	1	Rear end panel inner	Ry	\$ 498.20		
85	1	Rear end panel garnish	de	\$ 195.20		
86	1	Spare tyre well panel	Ry	\$ 822.60		
87	1	Spare tyre board	X 00	\$ 256.00		
88	1	Spare tyre bracket	X 00	\$ 60.00		
89	1	Spare tyre insulator	X 00	\$ 280.00		
90	1	Spare tyre tool tray	X 00	\$ 758.10		
91	1	Exhaust muffler	X 00	\$ 700.00		
92	1	Exhaust muffler mounting	X 00	\$ 70.10		
93	1	Exhaust heat shield	X 00	\$ 90.00		
94	2	Rear fender LH/RH	X 00	\$ 2,682.00		
95	2	Rear fender inner lower trim LH/RH	X 00	\$ 1,214.50		
96	2	Rear fender garnish lower LH/RH	X 00	\$ 157.60		
97	2	Rear fender garnish upper LH/RH	X 00	\$ 360.00		
98	2	Rear fender air duct LH/RH	X 00	\$ 149.55		
99	1	Rear end panel sealant	de	\$ 80.00		
100	1	Spare tyre panel sealant	X 00	\$ 80.00		
101	1	Spare tyre sound damper	X 00	\$ 250.00		
102	1	Sundries		\$ 60.00		
103	1	Tail gate seal		\$ 60.00		
104	1	Rear fender sealant	X 00	\$ 80.00		
105	1	Reverse sensor		\$ 300.00		
106	1	Reverse camera	X 00	\$ 550.00		
107	1	Rear number plate with frame	X 00	\$ 45.00		
108	1	Front number plate with frame		\$ 45.00		
109	1	Radiator coolant		\$ 80.00		
110	1	Aircon gas		\$ 100.00		
111	0	0				
112	0	0				
113	0	0				
114	0	0				
115	0	0				
116	0	0				
117	0	0				
118	0	0				
119	0	0				
120	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLD8503A
Vehicle Reg. Date: 29/6/2016
Make / Model : T. SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2v
Engine No. : 2NR8581033
Chassis No. : NSP1707020922

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To remove and replace damaged parts and to panel beating accident area. BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT SUPPORT PANEL, FRT FENDER LH/RH,	\$ 1,800.00	1800 700
2	To remove and refit radiator, condenser and top up A/C gas	\$ 250.00	150
3	To mount chassis member to reset alignment.	\$ 350.00	200 2 photos ✓
4	To rustproof accident repair area. Front portion.	\$ 100.00	50
5	To putty and respray replaced parts and accident repair area. BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT SUPPORT PANEL, FRT FENDER LH/RH,	\$ 1,800.00	1800 1000
6	To remove and replace damaged parts and to panel beating accident area. TAILGATE, TAILGATE GARNISH, RR BUMPER, RR END PANEL, SPARETYRE PANEL, RR FENDER LH/RH, RR FENDER GARNISH UPPER LH/RH.	\$ 1,800.00	700
7	To check and rectify wiring after disconnect and connect.	\$ 150.00	30
8	To remove and replace reverse sensor.	\$ 150.00	30
9	To remove and refit inner trim, inner seat, trim board, to assist repair.	\$ 200.00	60
10	To rustproof accident repair area. Rear portion.	\$ 150.00	50
11	To transfer tailgate mechanism to new tailgate.	\$ 150.00	60
12	To remove and refit rear windscreen.	\$ 150.00	120

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 2

[illegible]

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLD8503A
Vehicle Reg. Date: 29/6/2016
Make / Model : T. SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2V
Engine No. : 2NR8581033
Chassis No. : NSP1707020922

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Air Filter Housing Assy	<i>OK</i> ✓	\$ 897.10		
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

P = 897.10



SLD8503A

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : FCI
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 26/5/2018

Vehicle Reg. No. : SLD8503A
Vehicle Reg. Date: 29-Jun-2016
Make / Model : T. SIENTA 1.5X HYBRID A1
Engine No. : 2NR8581033
Chassis No. : NSP1707020922

COST OF CLAIMS

Parts Cost / List Items : \$ 40,502.65
Plus/Less 25% \$ 10,125.66
Total Cost / List : \$ 30,376.99
Special Nett Items : \$ 1,730.00
Total Parts Amount : \$ 32,106.99
Total Labour Amount : \$ 9,050.00
Gross Total : \$ 41,156.99
GST % : 7% \$ 2,880.99
Nett Amount : \$ 44,037.98

Surveyor Name and Company :

Tanfer 97495749

Date of survey : 01/6/18

Part by Part / Lump Sum : 11 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : surc@kanto.com

Fax No : _____

HP No : _____

This claim is handled by : PAULO BALDOZ

14/5-18950

* To check repair limit
P= 25078.30
-25%

19258.73

SN= 525

L= 3950

23733.73

-20%

18986.98

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLD8503A
 Vehicle Reg. Date: 29/6/2016
 Make / Model : T. SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2v
 Engine No. : 2NR8581033
 Chassis No. : NSP1707020922

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Bonnet	ht	\$ 706.00		
2	1	Bonnet lock	ht	\$ 122.00		
3	1	Bonnet hinge LH	ht	\$ 84.00		
4	1	Bonnet hinge RH	ht	\$ 84.00		
5	1	Bonnet heat insulator	x nn	\$ 88.00		
6	1set	Bonnet heat insulator clips	x nn	\$ 50.00		
7	1	Bonnet seal	ht	\$ 54.00		
8	1	Headlamp LH	ht	\$ 2,300.00		
9	1	Headlamp RH	ht	\$ 2,300.00		
10	1	Headlamp panel LH	ht	\$ 130.00		
11	1	Headlamp panel RH	ht	\$ 130.00		
12	1	Front support panel	ht	\$ 1,197.00		
13	1	Brace panel	ht	\$ 215.00		
14	1	Radiator	ht	\$ 2,188.00		
15	1	Front grille chrome moulding	ht	\$ 947.00		
16	1set	Front grille clips	ht	\$ 50.00		
17	1	Front top cover	ht	\$ 92.00		
18	1	Front bumper	ht	\$ 679.00		
19	1set	Front bumper clips	ht	\$ 50.00		
20	1	Front bumper logo	ht	\$ 500.00	75	
21	1	Front bumper base logo	ht	\$ 500.00	157	
22	1	Front bumper sponge	ht	\$ 97.60		
23	1	Front bumper reinforcement	ht	\$ 489.00		
24	2	Front reinforcement support bracket LH/RH	nn	\$ 190.00		
25	1	Front bumper upper retainer	ht	\$ 92.00		
26	2	Front bumper side retainer LH/RH	ht	\$ 192.00		
27	1	Front bumper grille REPORT	nn	\$ 750.00		
28	1	Front bumper tow cover	nn	\$ 32.00		
29	2	Front radiator air guide lower/upper	CPA	\$ 256.00		
30	1	Fog lamp garnish RH	nn	\$ 148.00		
31	1	Fog lamp garnish LH	nn	\$ 148.00		
32	1	Front fender RH	ht	\$ 690.00		
33	1	Front fender inner shield RH	nn	\$ 163.00		
34	1set	Front fender inner shield clips RH	nn	\$ 40.00		
35	1	Front fender LH	ht	\$ 690.00		
36	1	Front fender inner shield LH	nn	\$ 163.00		
37	1set	Front fender inner shield clips LH	nn	\$ 40.00		
38	1	Washer tank	ht	\$ 148.00		
39	1	Washer tank pump	ht	\$ 150.00		
40	1	Air duct assy	ht	\$ 797.00		

P= 14066.60

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLD8503A
 Vehicle Reg. Date: 29/6/2016
 Make / Model : T. SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2V
 Engine No. : 2NR8581033
 Chassis No. : NSP1707020922

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Condenser	bt	\$ 2,022.00		
42	1	Condenser side cover	de	\$ 95.00		
43	1	Radiator fan motor	? 3A	\$ 457.00		
44	1	Radiator fan blade	? 05	\$ 180.00		
45	1	Radiator fan cowling	? CAA	\$ 250.00		
46	1	Radiator hose top	? X nh	\$ 60.00		
47	1	Radiator bottom top	? X nh	\$ 60.00		
48	2	Horn (high/low)	? X nh	\$ 180.00		
49	1	Aircon discharge	? X nh	\$ 370.00		
50	1	Aircon liquid pipe	? X nh	\$ 211.10		
51	1	Aircon Suction pipe	? PA	\$ 484.00		
52	1 2	Front chassis member LH/RH	Ryo	\$ 1,205.20	652.60	
53	1	Rear windscreen moulding	ue	\$ 168.40		
54	1	Rear number plate lamp assy	X nh	\$ 158.00		
55	1	Rear bumper	de	\$ 838.80		
56	1	Rear bumper cover center	part	\$ 182.40		
57	2	Rear bumper cover LH/RH	LH-Y, RH-ue	\$ 391.00	105.50	
58	1set	Rear bumper clips	ue	\$ 50.00		
59	2	Rear bumper side retainer LH/RH	? ne	\$ 164.00		
60	2	Rear bumper bracket LH/RH	X nh	\$ 164.00		
61	1	Rear bumper sponge	? CAA	\$ 98.00		
62	2	Rear bumper reflector LH/RH	X nh	\$ 216.00		
63	2	Rear bumper splash shield LH/RH	X nh	\$ 340.00		
64	1	Tail gate	bt	\$ 1,360.00		
65	1	Tail gate lock	bt	\$ 246.60		
66	1	Tail gate striker	bt	\$ 48.00		
67	2	Tail gate stay LH/RH	X nh	\$ 320.00		
68	1	Tail gate logo	ue	\$ 50.00		
69	1	Tail gate emblem	ue	\$ 59.40		
70	1	Tail gate outer garnish	X nh	\$ 84.50		
71	1	Tail gate weatherstrip	ue	\$ 145.00		
72	2	Tail gate lamp LH/RH	X } X	\$ 720.00		
73	1	Tail door trim	X } nh	\$ 280.00		
74	1set	Tail door trim clips	X }	\$ 60.00		
75	2	Tail lamp LH/RH	? CAA	\$ 780.00		
76	2	Tail lamp bracket LH/RH	nh ? X	\$ 180.00		
77	1	Tail gate inner handle	de	\$ 90.00		
78	1	Antenna sensor	? CAA	\$ 190.00		
79	1	Rear wiper motor	X nh	\$ 387.60		
80	1	Rear wiper motor link	X nh	\$ 245.10		

F = 8806.70

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD8503A**
 Vehicle Reg. Date: **29/6/2016**
 Make / Model : **T. SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2V**
 Engine No. : **2NR8581033**
 Chassis No. : **NSP1707020922**

PAGE 3

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
81	1	Rear wiper arm	X NH	\$ 167.50		
82	1	Rear wiper blade	X NH	\$ 98.40		
83	1	Rear end panel outer	bt	\$ 498.20		
84	1	Rear end panel inner	Ry	\$ 498.20		
85	1	Rear end panel garnish	de	\$ 195.20		
86	1	Spare tyre well panel	Ry	\$ 822.60		
87	1	Spare tyre board	X	\$ 256.00		
88	1	Spare tyre bracket	X	\$ 60.00		
89	1	Spare tyre insulator	X	\$ 280.00		
90	1	Spare tyre tool tray	X	\$ 758.10		
91	1	Exhaust muffler	X	\$ 700.00		
92	1	Exhaust muffler mounting	X	\$ 70.10		
93	1	Exhaust heat shield	X	\$ 90.00		
94	2	Rear fender LH/RH	X	\$2,682.00		
95	2	Rear fender inner lower trim LH/RH	X CRA	\$1,214.50		
96	2	Rear fender garnish lower LH/RH	X	\$ 157.60		
97	2	Rear fender garnish upper LH/RH	X	\$ 360.00		
98	2	Rear fender air duct LH/RH	X	\$ 149.55		
99	1	Rear end panel sealant	de	40	\$ 80.00	
100	1	Spare tyre panel sealant	NH X		\$ 80.00	
101	1	Spare tyre sound damper	NH X		\$ 250.00	
102	1	Sundries		30	\$ 60.00	
103	1	Tail gate seal		30	\$ 60.00	
104	1	Rear fender sealant	NH X		\$ 80.00	
105	1	Reverse sensor		200 NH	\$ 300.00	
106	1	Reverse camera	X NH		\$ 550.00	
107	1	Rear number plate with frame	X NH		\$ 45.00	
108	1	Front number plate with frame		200	\$ 45.00	
109	1	Radiator coolant		200	\$ 80.00	
110	1	Aircon gas		200	\$ 100.00	
111	0	0				
112	0	0				
113	0	0				
114	0	0				
115	0	0				
116	0	0				
117	0	0				
118	0	0				
119	0	0				
120	0	0				

* AIR FILTER HOUSING ASSY
 \$ 897.10

P=2815

S/N= 525

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLD8503A
 Vehicle Reg. Date: 29/6/2016
 Make / Model : T. SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2V
 Engine No. : 2NR8581033
 Chassis No. : NSP1707020922

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To remove and replace damaged parts and to panel beating accident area. BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT SUPPORT PANEL, FRT FENDER LH/RH,	\$ 1,800.00	1800 700
2	To remove and refit radiator, condenser and top up A/C gas	\$ 250.00	150
3	To mount chassis member to reset alignment.	\$ 350.00	200? photo ✓
4	To rustproof accident repair area. Front portion.	\$ 100.00	50
5	To putty and respray replaced parts and accident repair area. BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT SUPPORT PANEL, FRT FENDER LH/RH,	\$ 1,800.00	1800 1000
6	To remove and replace damaged parts and to panel beating accident area. TAILGATE, TAILGATE GARNISH, RR BUMPER, RR END PANEL, SPARETYRE PANEL, RR FENDER LH/RH, RR FENDER GARNISH UPPER LH/RH.	\$ 1,800.00	700
7	To check and rectify wiring after disconnect and connect.	\$ 150.00	30
8	To remove and replace reverse sensor.	\$ 150.00	30
9	To remove and refit inner trim, inner seat, trim board, to assist repair.	\$ 200.00	60
10	To rustproof accident repair area. Rear portion.	\$ 150.00	50
11	To transfer tailgate mechanism to new tailgate.	\$ 150.00	60
12	To remove and refit rear windscreen.	\$ 150.00	120

L = 3950

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 2

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18009657/T1sd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 21-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7187M	Veh. Inspected	SLD 8503A
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18004232MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	28/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1707020922	Colour	WHITE
Odometer	180292	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	ACHILLES	6 mm
L/H Front Tyre	185/60 R15	ACHILLES	6 mm
R/H Rear Tyre	185/60 R15	ACHILLES	6 mm
L/H Rear Tyre	185/60 R15	ACHILLES	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/05/2018	Inspection Date	01/06/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 8503A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BENT	706.00	706.00
1	BONNET LOCK	BENT	122.00	122.00
1	BONNET HINGE LH	BENT	84.00	84.00
1	BONNET HINGE RH	BENT	84.00	84.00
1	BONNET HEAT INSULATOR	NOT NECESSARY	88.00	-
1	SET BONNET HEAT INSULATOR CLIPS	NOT NECESSARY	50.00	-
1	BONNET SEAL	NECESSARY	54.00	54.00
1	HEADLAMP LH	CRACKED	2,300.00	2,300.00
1	HEADLAMP RH	CRACKED	2,300.00	2,300.00
1	HEADLAMP PANEL LH	BENT	130.00	130.00
1	HEADLAMP PANEL RH	BENT	130.00	130.00
1	FRONT SUPPORT PANEL	BENT	1,197.00	1,197.00
1	BRACE PANEL	BENT	215.00	215.00
1	RADIATOR	BENT	2,188.00	2,188.00
1	FRONT GRILLE CHROME MOULDING	CRACKED	947.00	947.00
1	SET FRONT GRILLE CLIPS	NECESSARY	50.00	50.00
1	FRONT TOP COVER	DEFORMED	92.00	92.00
1	FRONT BUMPER	DEFORMED	679.00	679.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER LOGO	NECESSARY	500.00	75.00
1	FRONT BUMPER BASE LOGO	DEFORMED	500.00	157.00
1	FRONT BUMPER SPONGE	CRACKED	97.60	97.60
1	FRONT BUMPER REINFORCEMENT	BENT	489.00	489.00
2	FRONT REINFORCEMENT SUPPORT BRACKET LH/RH	NOT NECESSARY	190.00	-
1	FRONT BUMPER UPPER RETAINER	NECESSARY	92.00	92.00
2	FRONT BUMPER SIDE RETAINER LH/RH	NECESSARY	192.00	192.00
1	FRONT BUMPER GRILLE	NOT NECESSARY	750.00	-
1	FRONT BUMPER TOW COVER	NOT NECESSARY	32.00	-
2	FRONT RADIATOR AIR GUIDE LOWER / UPPER	CRACKED	256.00	256.00
1	FOG LAMP GARNISH RH	NOT NECESSARY	148.00	-
1	FOG LAMP GARNISH LH	NOT NECESSARY	148.00	-

Report Ref No. CS/FCI18009657/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER RH	BENT	690.00	690.00
1	FRONT FENDER INNER SHIELD RH	NOT NECESSARY	163.00	-
1	SET FRONT FENDER INNER SHIELD CLIPS RH	NOT NECESSARY	40.00	-
1	FRONT FENDER LH	BENT	690.00	690.00
1	FRONT FENDER INNER SHIELD LH	NOT NECESSARY	163.00	-
1	SET FRONT FENDER INNER SHIELD CLIPS LH	NOT NECESSARY	40.00	-
1	WASHER TANK	NOT NECESSARY	140.00	-
1	WASHER TANK PUMP	NOT NECESSARY	150.00	-
1	AIR DUCT ASSY	NOT NECESSARY	797.00	-
1	CONDENSER	BENT	2,022.00	2,022.00
1	CONDENSER SIDE COVER	DEFORMED	95.00	95.00
1	RADIATOR FAN MOTOR	JAMMED	457.00	457.00
1	RADIATOR FAN BLADE	DEFORMED	180.00	180.00
1	RADIATOR FAN COWLING	CRACKED	250.00	250.00
1	RADIATOR HOSE TOP	NOT NECESSARY	60.00	-
1	RADIATOR BOTTOM TOP	NOT NECESSARY	60.00	-
2	HORN (HIGH/LOW)	NOT NECESSARY	180.00	-
1	AIRCON DISCHARGE	NOT NECESSARY	370.00	-
1	AIRCON LIQUID PIPE	NOT NECESSARY	211.10	-
1	AIRCON SUCTION PIPE	BENT	484.00	484.00
2	FRONT CHASSIS MEMBER LH/RH	TO REPAIR SEE LABOUR	1,305.20	-
1	REAR WINDSCREEN MOULDING	NECESSARY	168.40	168.40
1	REAR NUMBER PLATE LAMP ASSY	NOT NECESSARY	158.00	-
1	REAR BUMPER	DEFORMED	838.80	838.80
1	REAR BUMPER COVER CENTER	CUT	182.40	182.40
2	REAR BUMPER COVER LH/RH	N/S NOT NECESSARY / O/S CUT	391.00	195.50
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE RETAINER LH/RH	NECESSARY	164.00	164.00
2	REAR BUMPER BRACKET LH / RH	NOT NECESSARY	164.00	-
1	REAR BUMPER SPONGE	CRACKED	98.00	98.00
2	REAR BUMPER REFLECTOR LH/RH	NOT NECESSARY	216.00	-

Report Ref No. CS/FCI18009657/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER SPLASH SHIELD LH/RH	NOT NECESSARY	340.00	-
1	TAIL GATE	BENT	1,360.00	1,360.00
1	TAIL GATE LOCK	BENT	246.60	246.60
1	TAIL GATE STRIKER	BENT	48.00	48.00
2	TAIL GATE STAY LH/RH	NOT NECESSARY	320.00	-
1	TAIL GATE LOGO	NECESSARY	50.00	50.00
1	TAIL GATE EMBLEM	NECESSARY	59.40	59.40
1	TAIL GATE OUTER GARNISH	NOT NECESSARY	84.50	-
1	TAIL GATE WEATHERSTRIP	CUT	145.00	145.00
2	TAIL GATE LAMP LH/RH	NOT NECESSARY	720.00	-
1	TAIL DOOR TRIM	NOT NECESSARY	280.00	-
1	SET TAIL DOOR TRIM CLIPS	NOT NECESSARY	60.00	-
2	TAIL LAMP LH/RH	CRACKED	780.00	780.00
2	TAIL LAMP BRACKET LH/RH	NOT NECESSARY	180.00	-
1	TAIL GATE INNER HANDLE	DEFORMED	90.00	90.00
1	ANTENNA SENSOR	CRACKED	190.00	190.00
1	REAR WIPER MOTOR	NOT NECESSARY	387.60	-
1	REAR WIPER MOTOR LINK	NOT NECESSARY	245.10	-
1	REAR WIPER ARM	NOT NECESSARY	187.50	-
1	REAR WIPER BLADE	NOT NECESSARY	98.40	-
1	REAR END PANEL OUTER	BENT	498.20	498.20
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	498.20	-
1	REAR END PANEL GARNISH	DEFORMED	195.20	195.20
1	SPARE TYRE WELL PANEL	TO REPAIR SEE LABOUR	822.60	-
1	SPARE TYRE BOARD	NOT NECESSARY	256.00	-
1	SPARE TYRE BRACKET	NOT NECESSARY	60.00	-
1	SPARE TYRE INSULATOR	NOT NECESSARY	280.00	-
1	SPARE TYRE TOOL TRAY	NOT NECESSARY	758.10	-
1	EXHAUST MUFFLER	NOT NECESSARY	700.00	-
1	EXHAUST MUFFLER MOUNTING	NOT NECESSARY	70.10	-
1	EXHAUST HEAT SHIELD	NOT NECESSARY	90.00	-
2	REAR FENDER LH/RH	NOT NECESSARY	2,682.00	-

Report Ref No. CS/FCI18009657/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER LOWER TRIM LH/RH	CRACKED	1,214.50	1,214.50
2	REAR FENDER GARNISH LOWER LH/RH	NOT NECESSARY	157.60	-
1	AIR FILTER HOUSING ASSY (ADDITIONAL)	CRACKED	897.10	897.10
2	REAR FENDER AIR DUCT LH/RH	NOT NECESSARY	149.55	-
2	REAR FENDER GARNISH UPPER LH/RH	NOT NECESSARY	360.00	-
	LESS 25% DISCOUNT		-10,349.94	-6,256.43
			31,049.81	18,769.27
	<u>SPECIAL NETT ITEMS</u>			
1	RADIATOR COOLANT (SN)	NECESSARY	80.00	80.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	40.00
1	SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	SPARE TYRE SOUND DAMPER (SN)	NOT NECESSARY	250.00	-
1	SUNDRIES (SN)	NECESSARY	60.00	30.00
1	TAIL GATE SEAL (SN)	NECESSARY	60.00	30.00
1	REAR FENDER SEALANT (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN)	NOT WORKING	300.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	550.00	-
1	REAR NUMBER PLATE WITH FRAME (SN)	NOT NECESSARY	45.00	-
1	FRONT NUMBER PLATE WITH FRAME (SN)	CRACKED	45.00	45.00
1	AIRCON GAS (SN)	NECESSARY	100.00	100.00
			1,730.00	525.00
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA. BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT SUPPORT PANEL, FRT FENDER LH/RH, INCLUSIVE OF THE REPAIR OF FRONT CHASSIS MEMBER LH/RH, REAR END PANEL INNER AND SPARE TYRE WELL PANEL.		1,800.00	700.00
	TO REMOVE AND REFIT RADIATOR, CONDENSER AND TOP UP A/C GAS.		250.00	150.00
	TO MOUNT CHASSIS MEMBER TO RESET ALIGNMENT.		350.00	200.00
	TO RUSTPROOF ACCIDENT REPAIR AREA. FRONT PORTION.		100.00	50.00

Report Ref No. CS/FCI18009657/T1sd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA. BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT SUPPORT PANEL, FRT FENDER LH/RH.		1,800.00	1,000.00
	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA. TAILGATE, TAILGATE GARNISH, RR BUMPER, RR END PANEL, SPARE TYRE PANEL, RR FENDER LH/RH, RR FENDER GARNISH UPPER LH/RH.		1,800.00	700.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.		150.00	30.00
	TO REMOVE AND REPLACE REVERSE SENSOR.		150.00	30.00
	TO REMOVE AND REFIT INNER TRIM, INNER SEAT, TRIM BOARD, TO ASSIST REPAIR.		200.00	60.00
	TO RUSTPROOF ACCIDENT REPAIR AREA. REAR PORTION.		150.00	50.00
	TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE.		150.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA. TALGATE, TAILGATE GARNISH, RR BUMPER, RR END PANEL, SPARE TYRE PANEL, RR FENDER LH/RH, RR FENDER GARNISH UPPER LH/RH.		2,000.00	800.00
			9,050.00	3,950.00
GRAND TOTAL			41,829.81	23,244.27
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				18,600.00

Report Ref No. CS/FCI18009657/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.