

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288
 ATTN: Motor Claim Department
 WS Ref: TP/AXA/AMK
 Claim Type: Third Party
 Accident Date: 24/05/2018
 TP Veh Reg No: SHD9985H

FAX: 68804739

Not Authorized
11 May 2018
Resurvey After Pain

Estimate No: ES1890582/AMK
Date: 25 May 2018
Policy No: 5045798735-07
Veh Reg No: SBR6330P
Make/Model: MERCEDES BENZ 200E
Chassis No: WDB1240212B182517
Engine No: 10296322015162
Reg. Date: 14/03/1990

Fdani

Estimate Repair Cost to Vehicle No :SBR6330P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR BUMPER	3,086.00	1 PC	3,086.00	✓
2 REAR BUMPER PROTECTOR	627.00	1 PC	627.00	✓
3 REAR BUMPER SIDE CHROME	724.00	2 PC	1,448.00	✓
4 REAR BOOT	1,475.00	1 PC	1,475.00	✓
5 REAR BOOT INNER LOCK	398.00	1 PC	398.00	✓
6 REAR BOOT INNER RUBBER	295.00	1 PC	295.00	?
7 REAR BOOT LOGO	48.00	1 PC	48.00	✓
8 REAR BOOT EMBLEM 'E200'	78.00	1 PC	78.00	✓
9 REAR BOOT OUTER CHROME	41.00	1 PC	41.00	X
10 TAILLAMP	470.00	2 PC	940.00	✓
11 TAILLAMP PANEL	98.00	2 PC	196.00	2+
12 REAR END PANEL	657.00	1 PC	657.00	✓
13 REAR END PANEL INNER TOP GARNISH	79.00	1 PC	79.00	✓
14 REAR SPARE TYRE COMPARTMENT	2,980.00	1 PC	2,980.00	X
15 REAR SPARE TYRE TOP BOARD	209.00	1 PC	209.00	✓
			12,557.00	
		Less 10%	1,255.70	11,301.30
Special Net				
16 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
17 SPARE TYRE COMPARTMENT INSULATOR	100.00	1 PC	100.00	60%
			135.00	135.00
Labour				
18 REMOVE & REFIX REAR BUMPER,REAR BOOT & ATTACHMENTS,TAILLAMPS; TO CUT,WELD & RENEW REAR END PANEL,SPARE TYRE COMPARTMENT:KNOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	2,000.00	1 LA	2,000.00	1200
19 PUTTY & RESPRAY REAR BUMPER,REAR BOOT,BOTH FENDERS,REAR END PANEL,REAR SPARE TYRE COMPARTMENT & ALL AFFECTED AREAS	1,100.00	1 LA	1,100.00	1000
20 REMOVE & REFIX REAR EXHAUST ASSY & REALIGN THE SAME	80.00	1 LA	80.00	60
21 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✓
22 RUSTPROOFING	120.00	1 LA	120.00	60
			3,550.00	3,550.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK

Claim Type: Third Party

Accident Date: 24/05/2018

TP Veh Reg No: SHD9985H

Estimate No: ES1890582/AMK

Date: 25 May 2018

Policy No: 5045798735-07

Veh Reg No: SBR6330P

Make/Model: MERCEDES BENZ 200E

Chassis No: WDB1240212B182517

Engine No: 10296322015162

Reg. Date: 14/03/1990

Estimate Repair Cost to Vehicle No :SBR6330P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 14,986.30
			Add GST @ 7%	1,049.04
			Total Amount Payable	SS 16,035.34

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

DORLYN LI

AUTHORISED SIGNATURE