



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20180521/0763		LOCATION OF FIRE: Bukit Timah Saddle Club 51, Fairways Drive Singapore 286965	
FIRE REPORTED ON : 21 May 2018			
TIME OF CALL : 17:33:29 hrs			
STATION COVERAGE : Bukit Batok Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine of a Mercedes car (SB4D) at an open space car park.			
METHOD OF EXTINGUISHMENT: By a member of public using a dry powder fire extinguisher before the arrival of SCDF crew.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine was damaged. Other parts of the engine compartment sustained smoke damage. The bonnet sustained heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
 CINDY HAN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.