

22/03/2002

ASS. REC. BY:

REF:

CS/MSH18009665/Avb22

Special Instruction:

Surveyor

Adrian.

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSH

Date/Time:

28/05/2018 4:18pm

Estimated Cost:

Bill to:

OD / TI / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGY 5869M

Insured:

FBH 3286G

at Workshop m/s

Twincar Automotive

Tel:

of

2 Kaki Bukit Ave 2 # 01-17

Policy No:

MSD / VMT / 18-382030-CA

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

28/05/2018

Person Contacted:

Hui Xin

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

31/5/18

Informed Catherine Thia pending workshop est by merimen

11/10/18

Adrian confirmed LS \$ 2650 (Red 4540.90, 63/15

12/10/18

Sand preti revised via merimen

ASS. REC. BY: Adrian King**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGY5869M Yr Regn: _____ /Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lanes C.C. _____Colour: Red A/C: Insured / Std / NI / NASp. Reading: 112539 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/50R17R: 215/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 28/05/18Survey held at TwincacDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS/G

RECEIVED 12 OCT 2018

12/10/2018

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) 12/10 - typistDays Of Repair: 4Resurvey No. of Trip: 2Survey Fee: 150

Transportation: _____

____ S + RS ____ SI

Photos

Others 10

TOTAL

160Report Format: merimenLump Sum / I.B.I: (\$) 2650 1/2Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 May 2018		28 May 2018 16:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	MUHAMMAD SYUKRI BIN REDZWAN, ID: S9626106C	
Main Claimant:	TAN KHIAM TECK, ID: S0137698E	
Vehicle Reg. No.:	SGY5869M	Date of Loss: 25/05/2018 11:00 - :59 [127 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.: MSD/VMT/18-382030-CA Coverage: 24/04/2018 - 13/05/2019
Vehicle Reg. No. (Insured):	FBH3286G	Policy No. (Claimant):
		Excess:
Repairer:	Twincar Automotive Pte Ltd (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17, 417921 Kaki Bukit - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/05/2018]	
Adj Asg. Remarks:	oi non reporting. Liability cannot be established. TP agree with SJE - assign Adrian Ling of LKK Auto Consultants Pte Ltd.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS							View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	
No results.										

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 12 Oct 2018

Preliminary Advice

Insured Vehicle No	: FBH3286G	Accident Date	: 25/05/2018
TP Vehicle No	: SGY5869M	Assignment Date	: 28/05/2018
Make	: MITSUBISHI LANCER	Est. Duration of Repair	: 4.00
Date of Inspection	: 28/05/2018		
Inspection At	: TWINCAR AUTOMOTIVE PTE LTD (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17 SINGAPORE 417921		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,190.90
Revised Amount	:S\$	2,650.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,650.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***SGY5869M (MSC/V/18-000734)**
[FBH3286G]

TP
TAN KHIAM TECK
May 25 2018 11:00AM
[MUHAMMAD SYUKRI BIN REDZWAN]
Twincar Automotive Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **31/05/2018 10:58 AM**.
To MSI_TSY
Subject TP SURVEY SGY 5869M

Dear Catherine,

Please be informed that we have inspected the vehicle SGY 5869M on 28/5/2018.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/05/2018 12:31
Date Of Accident	25/05/2018 11:05
Exact Location Of Accident	PIE TWDS CHANGI AT ERP 37 AFT ADAM RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY5869M
Insured/Policyholder	
Name Of Registered Owner	TAN,KHIAM TECK
NRIC No	S0137698E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94773918
Alternative Phone No	OTHERS-94773918

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00204318/03
Cover Note Number	

Driver

Name of Driver	TAN,KHIAM TECK
NRIC No	S0137698E
Date Of Birth	09/06/1946
Occupation	INDOOR
Date Of Driving Pass	17/03/1965
Driving Experience	53 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94773918
Fax Number	
Contact Number	OTHERS-94773918
EEmail Address	NOEMAIL

Address	11 CASHEW ROAD #11-03
Postcode	679672
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBH3286G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	SYUKRI
NRIC/Passport Number	
Contact Number	96372347
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Individual Statement

SKETCH PLAN Pte Tommas CHANGE After Lorne road Exit A1 ERP 37 After Adam Road.

A - SGY 5869 M

B - FBH 3286 G.




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Pte towards Change in my veh(A) SGY 5869 M on the center lane of 5-lanes, expressway. Just after ERP 37 After Adam road, veh(B) FBH 3286 G from my left was between lane 3 and lane 4 suddenly filtered to the right without checking blindspot and signal encroaching my path causing veh(B) right portion whided onto my veh(A) left front portion and fall on the left. Therefore, we alighted and take pictures of the accident scene.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

 25/04/18
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TAN KHIAM TECK

101 CASHEW ROAD #11-03

SINGAPORE 679672

Contact : 94773918

TPMSLG

Veron

ESTIMATE

Repair Code : CLM14088

Date in : 25/05/2018

Vehicle Num. : SGY5869M

Model : MITSUBISHI LANCER 2.0L MIVEC GLS 6-CVT

Chassis/Eng# : JMYSTCY4A8U000848/4B11AN2852

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>replaced</i>	1	810.00	810.00 ✓
FRONT BUMPER LH FOGLAMP <i>replaced</i>	1	430.00	430.00 +
FRONT BUMPER LH FOGLAMP GARNISH <i>replaced</i>	1	45.00	45.00 +
FRONT BUMPER LH SIDE BRACKET <i>new</i>	1	20.00	20.00 ✓
FRONT BUMPER LOWER SPOILER <i>new</i>	1	221.00	221.00 +
FRONT BUMPER SIDE RETAINER L/R <i>LH new</i>	2	20.00	40.00 <i>20</i>
FRONT LH FENDER <i>new</i>	1	496.00	496.00 +
FRONT LH FENDER INNER SHIELD <i>replaced</i>	1	105.00	105.00 ✓
FRONT LH HEADLAMP <i>replaced</i>	1	1891.00	1891.00 <i>1036</i>
FRONT LH KNUCKLE ARM <i>new</i>	1	308.00	308.00 +
FRONT LH KNUCKLE ARM BEARING	1	137.00	137.00 ✓
FRONT LH SPORT RIM <i>new</i>	1	1098.00	1,098.00 <i>45</i>
Subtotal before discount			5,601.00 <i>(50)</i>
Percentage discount 10%			560.10
Sub-total 1			5,040.90
FRONT 215/50/R17 TYRE <i>new</i>	1	450.00	450.00 ✓
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00 <i>30</i>
FRONT BUMPER LOWER SPOILER CLIPS - SET <i>new</i>	1	50.00	50.00 <i>20</i>

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TAN KHIAM TECK

101 CASHEW ROAD #11-03

SINGAPORE 679672

Contact : 94773918

ESTIMATE

Repair Code : CLM14088

Date in : 25/05/2018

Vehicle Num. : SGY5869M

Model : MITSUBISHI LANCER 2.0L MIVEC GLS 6-CVT

Chassis/Eng# : JMYSTCY4A8U000848/4B11AN2852

FRONT LH FENDER INNER SHIELD CLIPS - SET <i>AL</i>	1	50.00	50.00 30
Subtotal before discount			600.00
Percentage discount 0%			0.00
Sub-total 2			600.00
Parts-total			5,640.90

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

~~80.00~~ 30

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

~~200.00~~ 100

To road test driving, check and resetting wheel alignments system.

~~100.00~~ 80

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1010

~~600.00~~ 50

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~450.00~~ 30

To apply anti-rust chemical on repaired and replaced panel.

~~120.00~~ 10

Labour Total

1,550.00

Parts & Labour Total

7,190.90

Consultants hence notify

of the following:

• After spray painting

• Part(s) during res

• Used to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer-generated document which requires no signature.

page 2

Adrian Lij
H/S

04 May

total: 3331.9

H/S: 2650.

total: 2886.90

H/S: 23K




































...CLAIM SUBFOLDER...(Pending for Survey Report)




























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 May 2018		28 May 2018 16:18 Edit Adj Rpt	S\$3,331.90 Edit Estimates	S\$3,331.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MUHAMMAD SYUKRI BIN REDZWAN , ID: S9626106C								
Main Claimant:	TAN KHIAM TECK , ID: S0137698E								
Vehicle Reg. No.:	SGY5869M	Date of Loss:	25/05/2018 11:00 - :59 [127 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000734	Policy/Cover Note No.:	MSD/VMT/18-382030-CA Coverage: 24/04/2018 - 13/05/2019						
Vehicle Reg. No. (Insured):	FBH3286G	Policy No. (Claimant):							
		Excess:							
Repairer:	Twincar Automotive Pte Ltd (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17, 417921 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/06/2018]								
Adj Asg. Remarks:	oi non reporting. Liability cannot be established. TP agree with SJE - assign Adrian Ling of LKK Auto Consultants Pte Ltd.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGY5869M (MSC/V/18-000734)
[FBH3286G]
TP
TAN KHIAM TECK
May 25 2018 11:00AM
[MUHAMMAD SYUKRI BIN REDZWAN]
Twincar Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	12/10/18 08:51	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
2	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
3	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
4	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
5	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
6	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
7	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
8	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
9	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
10	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
11	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
12	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
13	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
14	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
15	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
16	11/10/18 17:53	General View						Load JPG	<input checked="" type="checkbox"/>	
17	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
18	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
19	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
20	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
21	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
22	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
23	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
24	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
25	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
26	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
27	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
28	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
29	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
30	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
31	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
32	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
33	11/10/18 17:53	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
34	11/10/18 17:53	Reinspection Photo						Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/10/18 17:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/10/18 17:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/05/18 09:24	TP PRI Request	 Load PDF	
2	28/05/18 09:25	TP PRI Request email	 Load PDF	
3	28/05/18 11:16	tp agree with SJE	 Load PDF	
4	28/05/18 11:16	TP agree with SJE - assign LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009665/AVBE2

Date: 15/10/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-382030-CA
Claimant Vehicle No :	SGY5869M	Insured Vehicle No :	FBH3286G
Date of Loss:	25/05/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000734

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY5869M		
Make & Model:	MITSUBISHI LANCER, 2.0 L MIVEC GLS6-CVT (A)		
Reg. Date:	01/10/2007 (Man. Year: 2007)	Engine No:	4B11AN2852
Colour:	Red	Chassis No:	JMYSTCY4A8U000848
Engine Capacity:	1998 cc	Odometer:	112539 km
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,640.90	2,321.90	3,319.00	58.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,010.00	540.00	34.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,190.90	3,331.90	3,859.00	53.67
+ GST 7.00/7.00% (S\$)	503.36	233.23	270.13	53.67
Nett Amount (S\$)	7,694.26	3,565.13	4,129.13	53.67

INSPECTION

Date of Assignment:	28/05/2018	
Date Inspected:	28/05/2018	Inspected At: Twincar Automotive Pte Ltd (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17 Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2018)
Parts:	143	mitsubishi LANCER 2.0 L MIVEC GLS6-CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGY5869M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	810.00 FL	*810.00 FL
2	1		*FRONT BUMPER LH FOGLAMP	Not Necessary	430.00 FL	*- FL
3	1		*FRONT BUMPER LH FOGLAMP GARNISH	Not Necessary	45.00 FL	*- FL
4	1		*FRONT BUMPER LH SIDE BRACKET	Necessary	20.00 FL	*20.00 FL
5	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	221.00 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER L/R	N/S Necessary	40.00 FL	*20.00 FL
7	1		*FRONT LH FENDER	Repair	496.00 FL	*- FL
8	1		*FRONT LH FENDER INNER SHIELD	Deformed	105.00 FL	*105.00 FL
9	1		*FRONT LH HEADLAMP	Cracked	1,891.00 FL	*1,036.00 FL
10	1		*FRONT LH KNUCKLE ARM	Not Necessary	308.00 FL	*- FL
11	1		*FRONT LH KNUCKLE ARM BEARING	Not Necessary	137.00 FL	*- FL
12	1		*FRONT LH SPORT RIM	Cut	988.20 FS	*450.00 FS
13	1		*FRONT 215/50/R17 TYRE	Not Necessary	450.00 FS	*- FS
14	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
15	1		*SET FRONT BUMPER LOWER SPOILER CLIPS	Necessary	50.00 FS	*20.00 FS
16	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,091.20	2,521.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	450.30	199.10
Total Parts (\$\$)	5,640.90	2,321.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)	New	80.00	30.00
2	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	New	200.00	100.00
3	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM	New	100.00	80.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	600.00	500.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	450.00	300.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	0.00
Gross Labour Cost (S\$)			1,550.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >