

INS. CASE OWNER:

CC 4 / Ass 1800

9689 / UH0322

LKK:

IDAC:

47969

Surveyor:

M. Adams

DOI:

ASSIGNMENT

28/5/18

Date / Time:

28/05/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLW 4795L

Name of Insured:

Bun Hang Lee Motor Services

Insured Tel No.:

HP:

Claim No.:

58 M001KG

Excess Sec II :SS

1,250.00

D.O.A.:

28/05/2018

Policy No.:

P1624268

Make / Model:

7. Vios

Place of Accident:

Lempur Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

ong kuan barn

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

96576615

(VL: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLJ 7231 X



INSRS:

WSP:

Tel:

Liability:

RMKS:

V.F.S.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

6/6
vucSLJ 7231 X
- Pandu, RECEIVED 1 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

12/06/18 - vic

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

31/5

Sent By:

Hm

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L6

SS

3,500.00

(5 days)

Reduction:

31

%

Email

Call

FINAL SETTLEMENT

Date/Time:

10/09/18

Confirm with:

Hm

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/ass)

SS

3,745.00

Loss of Rental (LOR) (w/ass)

SS

749.00

(7 days)

x \$ 100.00

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

4,496.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4,496.00

Name 1:

KAN TOOK SING MOTOR WORKSHOP

Payee 2: (Strike if N.A.)

SS

-

Name 2:

Payee 3: (Strike if N.A.)

SS

-

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

COPY SENT 11/9/18

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 72314at Workshop m/s LFS

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 14k.

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLH 72314 Yr Regn: 12 ofType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: mit lance c.c. 1499Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 127696 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSRCY2A94000351Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mmR/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A. 24/5/18 D.O.I. 28/5/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27A 950k 6mth plus nett 4495L/S \$3,500.00CR00: \$1,545.40/31%

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Phone: _____

Others: _____

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18009689/Uha3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 30-05-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 4795L	Veh. Inspected	SJL 7231Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00IKG	Excess (\$)	0.00	
Assign From		Assign Date	30/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/05/2018	Inspection Date	28/05/2018	
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



簡福星摩哆工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 26-05-2018

VEHICLE NO. : SJL7231Y
ACCIDENT DATE : 24-05-2018 19:30
THIRD PARTY REF. : SKW4795L

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SJL7231Y MITSUBISHI LANCER EX 1.5A

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
NETT ITEMS			
1	1	REAR BOOT COVER <i>Sod's do</i>	569.00
2	1	REAR BOOT CENTRE EMBLEM <i>neu</i>	38.00
3	1	REAR BOOT LANCER EMBLEM <i>neu</i>	43.00
4	1	REAR BOOT EX EMBLEM <i>neu</i>	32.00
5	1	REAR BOOT LOCK <i>tw</i>	60.00
6	1	REAR BOOT RUBBER <i>tw</i>	155.00
7	1	REAR END PANEL <i>Sod's do</i>	423.00
8	1	REAR END PANEL TOP GARNISH <i>tw</i>	144.00
9	1	REAR BUMPER <i>DD</i>	669.00
10	1	REAR BUMPER TOP BEAM <i>Ref</i>	173.00
11	1	REAR BUMPER REINFORCEMENT <i>BW</i>	670.00
12	2	REAR BUMPER SIDE RETAINER@S13.00 <i>bw</i>	26.00
13	2	REAR BUMPER REFLECTOR@S18.00 <i>17</i>	36.00
14	1	REAR BUMPER TOW COVER <i>17</i>	18.00
15	10	REAR BUMPER CLIP@S2.00 <i>neu</i>	20.00
16	1	REAR NUMBER PLATE LAMP <i>17</i>	30.00
			3,106.00
LESS 10 %			310.60
TOTAL (B)			2,795.40

SPECIAL NETT ITEMS

1	1	REAR NUMBER PLATE <i>Bent</i>	30.00
2	1	REAR REVERSE SENSOR <i>Shed</i>	200.00

Not Allocated
mk
L/C = 3500
Take up the Allocation
28/5/18
Sdy.



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SJL7231Y
ACCIDENT DATE : 24-05-2018 19:30
THIRD PARTY REF. : SKW4795L

#	QTY	PARTS DESCRIPTION
3	1	BABY STROLLER

AMOUNT (SGS)

11 300.00 X

TOTAL (C)

530.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM
---	---	------------------------

30.00

20

2	1	TO REMOVE/REFIT REAR FENDER INNER GARNISH AND ETC
---	---	---

120.00

60

3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS
---	---	--

820.00

700

4	1	SPRAYPAINTING CHARGES
---	---	-----------------------

750.00

700

TOTAL (D)

1,720.00

T46

ESTIMATE TOTAL

5,045.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

Not Allocated
make
h/c
Take up Allocation
28/5/18
S.T.

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 26-05-2018

VEHICLE NO. : SJL7231Y
ACCIDENT DATE : 24-05-2018 19:30
THIRD PARTY REF. : SKW4795L

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SJL7231Y MITSUBISHI LANCER EX 1.5A

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
NETT ITEMS			
1	1	REAR BOOT COVER <i>Sod 300</i>	569.00
2	1	REAR BOOT CENTRE EMBLEM <i>neu</i>	38.00
3	1	REAR BOOT LANCER EMBLEM <i>neu</i>	43.00
4	1	REAR BOOT EX EMBLEM <i>neu</i>	32.00
5	1	REAR BOOT LOCK <i>twi</i>	60.00
6	1	REAR BOOT RUBBER <i>twi</i>	155.00
7	1	REAR END PANEL <i>Sod 300</i>	423.00
8	1	REAR END PANEL TOP GARNISH <i>twi</i>	144.00
9	1	REAR BUMPER <i>DD</i>	669.00
10	1	REAR BUMPER TOP BEAM <i>Ref</i>	173.00
11	1	REAR BUMPER REINFORCEMENT <i>Bu</i>	670.00
12	2	REAR BUMPER SIDE RETAINER@\$13.00 <i>bu</i>	26.00
13	2	REAR BUMPER REFLECTOR@\$18.00 <i>17</i>	36.00
14	1	REAR BUMPER TOW COVER <i>u7</i>	18.00
15	10	REAR BUMPER CLIP@\$2.00 <i>neu</i>	20.00
16	1	REAR NUMBER PLATE LAMP	30.00
			3,106.00
LESS 10 %			310.60
TOTAL (B)			2,795.40

SPECIAL NETT ITEMS

1	1	REAR NUMBER PLATE <i>Bent</i>	30.00
2	1 set	REAR REVERSE SENSOR <i>Shut</i>	200.00



簡福星摩哆工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SJL7231Y
ACCIDENT DATE : 24-05-2018 19:30
THIRD PARTY REF. : SKW4795L

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)	
3	1	BABY STROLLER	300.00	?
TOTAL (C)			530.00	
LABOUR CHARGES				
1	1	TO CHECK WIRING SYSTEM	30.00	20
2	1	TO REMOVE/REFIT REAR FENDER INNER GARNISH AND ETC	120.00	60
3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	820.00	700
4	1	SPRAYPAINTING CHARGES	750.00	700
TOTAL (D)			1,720.00	1480
ESTIMATE TOTAL			5,045.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 30/5/2018

Survey Details:

Date of loss	24-May-18
Date of appointment	28-May-18
Date of survey	28-May-18
Location of survey	Kan Fook Sing Motor Workshop

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJL 7231Y
Make and Model	Mitsubishi Lancer 1.5 GLS - 1499cc
Date of registration	10-Dec-08
Excess	
Market Value	\$ 14,000.00
Part Rebate	\$ 9,505.00
Nett Loss	\$ 4,495.00

Repair details:

Initial Estimate	\$ 10,814.20
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 2,949.80
Check items (estimate)	\$ 327.00
Labour	\$ 1,480.00
Total	\$ 4,756.80
Lump Sum(if applicable)	TBA

Number of days for repair	<u>5 days</u>
---------------------------	---------------



Service Request Details

Claim

S8M00IKG

Reference

None

Loss Date

May 24, 2018

Request Date

May 28, 2018

Due Date

June 5, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

28/5/2018 @ 1:14pm

Yen veh in

Ken Fouk Sin

marus.

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJL7231Y

Make

TPVD MITSUBISHI

Service Address

...

Primary Contact/Insured

BAN HONG LEE MOTOR SERVICES
BLK 5033 ANG MO KIO IND PARK 2, #01-279, 569536, Singapore
63234456
SAEENT@SINGNET.COM.SG

Claim Handler

TAY Ernest
6568804835
ernest.tay@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Friday, 7 September, 2018 11:08 AM
To: patricia
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: RE: SJL 7231Y & SKW 4795L on 24.05.2018 at SLE *LKK REF: CC4/ASM18009689/Uha3
Attachments: DV.pdf

WITHOUT PREJUDICE

Dear Patricia,

We refer further to your below email.

On a without prejudice basis and purely for an amicable settlement on a without admission of liability to our Insured's part, we have our principal's mandate and we offer settlement as below:

Cost of Repair (w/gst)	\$ 3,745.00
Loss of Rental w/gst (\$100 x 7 days)	\$ 749.00
GIA Search Fee	\$ 2.00
TOTAL	\$ 4,496.00

If agreeable, kindly let the owner sign the attached DV and forward back to us payment processing.

The above amount is to be made payable to **KAN FOOK SING MOTOR WORKSHOP**.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: patricia [mailto:patricia@kanfs.net]
Sent: Monday, 13 August, 2018 11:43 AM
To: Vic (LKKAuto)
Subject: Fw: RE: SJL 7231Y & SKW 4795L on 24.05.2018 at SLE *LKK REF: CC4/ASM18009689/Uha3

Dear Sir,

Please update on offer

Thank you
patricia

----- Forwarded Message -----

From: "patricia" <patricia@kanfs.net>
To: "Vic (LKKAuto)" <vicalpeh@lkkauto.com>, Admin A <admin-a@lkkauto.com>
Sent: Tue, 24 Jul 2018 13:31:23 +0800
Subject: Fw: RE: SJL 7231Y & SKW 4795L on 24.05.2018 at SLE *LKK REF: CC4/ASM18009689/Uha3

Dear Vic,

Please kindly revert on offer

Thank you
patricia

----- Forwarded Message -----

From: "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>
To: patricia <patricia@kanfs.net>
Cc: "Vic (LKKAuto)" <vicalpeh@lkkauto.com>, Admin A <admin-a@lkkauto.com>
Sent: Fri, 6 Jul 2018 23:55:17 +0000
Subject: RE: SJL 7231Y & SKW 4795L on 24.05.2018 at SLE *LKK REF: CC4/ASM18009689/Uha3

Without Prejudice

Hi Patricia,

Thank you for your email.

The case is handled by Mr Vic.

Hi Vic,

Kindly assist. CC4/ASM18009689/Uha3

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: patricia [<mailto:patricia@kanfs.net>]
Sent: Friday, 6 July 2018 11:01 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: SJL 7231Y & SKW 4795L on 24.05.2018 at SLE

Dear Mdm,

With reference to the above mentioned case, we have submitted all documents to your office.

Please kindly revert on offer

COR	\$	3745.00
LTA	\$	2.00
LOR	\$	1391.00
Total	\$	5138.00

Thank you
Patricia
Kan Fook Sing Motor Workshop

----- End of Forwarded Message -----

--

----- End of Forwarded Message -----

--



Re:SEEK QUANTUM MANDATE APPROVAL S8M00IKG OI: SKW 4795L

Type

🔗 Question

Message

PLS PROCEED FOR QUANTUM AS PROPOSED

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKW 4795L (Insd veh)	Model:	MITSUBISHI
	SJL 7231Y (TP veh)		LANCER 1.5 MIVEC GLS
Date of Accident:	24/05/2018		4A/T

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	5,398.58
Final Repair Cost	:	\$	3,745.00
Loss of Use	:	\$	days at \$00.00 per day
Rental (if any)	:	\$	749.00 7 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	4,496.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	KAN FOOK SING MOTOR WORKSHOP	:	\$ 4,496.00

NUR SHAQILAH BTE ABDOL
WAHAB

13/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

<< Service Request Details

Claim: S8M00#KG

Reference: CC4/ASM18009689/Uha3s2  Loss Date: May 24, 2018 Request Date: August 21, 2018 Due Date: May 28, 2019 Vendor Name: LKK AUTO CONSULTANTS PTE LTD (TP) Type of Loss: Third Party Vehicle Damage Services: Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step: Finish the work

Complete Work

More

Document Type: Document SubType:

Upload Documents

Vehicle Information

Incident Vehicle Registration #: SUL7231Y Make: TPVD MITSUBISHI Model: LANCER Primary Contact/Insured: BAN HONG LEE MOTOR SERVICES BLK 5033 ANG MO KIO IND PARK 2, #01-279, 569536, Singapore 63234456 SAEENT@singnet.com.sg

Claim Handler

CHAN Kian Chuan 6568804269 kianchuan.chan@axa.com.sg

NAME

TYPE SUB-TYPE AUTHOR DATE UPLOADED

SKW4795L INS GIA Reports & Statement GIA Report Merimen

Service Request Details

Claim

S8M00JKG

Reference

CC4/ASM18005689Uha3s2 

Loss Date

May 24, 2018

Request Date

August 21, 2018

Due Date

May 28, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete Work

More

Auto

Vehicle Information

Incident Vehicle Registration #

SJL7231Y

Make

Service Address

TPVD MITSUBISHI

Model

...

LANCER

Primary Contact/Insured

BAN HONG LEE MOTOR SERVICES
BLK 5033 ANG MO KIO IND PARK 2, #01-279, 569536, Singapore
63234456
SAEENT@SINGNET.COM.SG

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

STATUS

SHARE

CLONE

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SIL7231Y	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	12/10/2008
Mileage	129696	Age of Vehicle	9
Driver Details			
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2008		
Make	TPVD MITSUBISHI	Driver Name	KHOO GUAN JIE (QIU GUANJIE)
Model	LANCER	Date of Birth	mm/dd/yyyy
Type		Age	0
Type of Paint		Occupation	Unknown
Chassis No	JMYSRCY2A9U000351	Education Qualification	Other
Engine No	4A910107573	Driving Experience	0
Engine Capacity	1499 cc	Driver License #	

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	05/28/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unarmed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	205/60R16	Rear Tyre Size	205/60R16
Front left side	YOKOHAMA 6mm	Rear left side	YOKOHAMA 6mm
Front right side	YOKOHAMA 6mm	Rear right side	YOKOHAMA 6mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details				Vehicle & Driver Details			Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTIR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE			
	1	1			REAR BOOT COVER			Dented	569		10		512.1	Reviewing				
	2	1			REAR BOOT CENTRE EMBLEM			Necessary	38		10		34.2	Reviewing				
	3	1			REAR BOOT LANCER EMBLEM			Necessary	43		10		38.7	Reviewing				
	4	1			REAR BOOT EX EMBLEM			Necessary	32		10		28.8	Reviewing				
	5	1			REAR BOOT LOCK			Twisted	60		10		54	Reviewing				
	6	1			REAR BOOT RUBBER			Twisted	155		10		139.5	Reviewing				
	7	1			REAR END PANEL			Dented	423		10		380.7	Reviewing				
	8	1			REAR END PANEL TOP GARNISH			Twisted	144		10		129.6	Reviewing				
	9	1			REAR BUMPER			Dented	669		10		602.1	Reviewing				
	10	1			REAR BUMPER TOP BEAM			Bent	173		10		155.7	Reviewing				
	11	1			REAR BUMPER REINFORCEMENT			Bent	670		10		603	Reviewing				
	12	2			REAR BUMPER SIDE RETAINER			Bent	13		10		23.4	Reviewing				
	13	2			REAR BUMPER REFLECTOR			Serviceable	0		10		0	Reviewing				

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR	Reviewing		5	
		2	REAR NUMBER PLATE	Reviewing	30	BENT	
		3	SET REAR REVERSE SENSOR	Reviewing	200	SHORTED	
		4	BABY STROLLER	Reviewing	0	NOT NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS

<< **Assessment Details**

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$4,429.80

Claim Amount

\$4,429.80

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$2,719.80	\$2,719.80
Labour	\$1,480.00	\$1,480.00
Miscellaneous	\$230.00	\$230.00

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	FINAL LUMP SUM	Reviewing	35000		