



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

Not Allocated
make
L/C
Take up Allocation
28/5/18
Sdy.

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 26-05-2018

VEHICLE NO. : SJL7231Y
ACCIDENT DATE : 24-05-2018 19:30
THIRD PARTY REF. : SKW4795L

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SJL7231Y MITSUBISHI LANCER EX 1.5A

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
NETT ITEMS			
1	1	REAR BOOT COVER <i>Soddy</i>	569.00 <i>—</i>
2	1	REAR BOOT CENTRE EMBLEM <i>neu</i>	38.00 <i>—</i>
3	1	REAR BOOT LANCER EMBLEM <i>neu</i>	43.00 <i>—</i>
4	1	REAR BOOT EX EMBLEM <i>neu</i>	32.00 <i>—</i>
5	1	REAR BOOT LOCK <i>twi</i>	60.00 <i>—</i>
6	1	REAR BOOT RUBBER <i>twi</i>	155.00 <i>—</i>
7	1	REAR END PANEL <i>Soddy</i>	423.00 <i>—</i>
8	1	REAR END PANEL TOP GARNISH <i>twi</i>	144.00 <i>—</i>
9	1	REAR BUMPER <i>DD</i>	669.00 <i>—</i>
10	1	REAR BUMPER TOP BEAM <i>Ref</i>	173.00 <i>—</i>
11	1	REAR BUMPER REINFORCEMENT <i>Ref</i>	670.00 <i>—</i>
12	2	REAR BUMPER SIDE RETAINER@\$13.00 <i>Ref</i>	26.00 <i>—</i>
13	2	REAR BUMPER REFLECTOR@\$18.00 <i>17</i>	36.00 <i>X</i>
14	1	REAR BUMPER TOW COVER <i>17</i>	18.00 <i>X</i>
15	10	REAR BUMPER CLIP@\$2.00 <i>neu</i>	20.00 <i>—</i>
16	1	REAR NUMBER PLATE LAMP	30.00 <i>?</i>
			3,106.00
LESS 10 %			310.60
TOTAL (B)			2,795.40

SPECIAL NETT ITEMS

1	1	REAR NUMBER PLATE <i>Ref</i>	30.00 <i>—</i>
2	1 set	REAR REVERSE SENSOR <i>Shut</i>	200.00 <i>—</i>



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SJL7231Y

ACCIDENT DATE : 24-05-2018 19:30

THIRD PARTY REF. : SKW4795L

QTY PARTS DESCRIPTION

3 1 BABY STROLLER

AMOUNT (SG\$)

300.00

TOTAL (C)

530.00

LABOUR CHARGES

1 1 TO CHECK WIRING SYSTEM

30.00

2 1 TO REMOVE/REFIT REAR FENDER INNER GARNISH AND ETC

120.00

3 1 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS

820.00

4 1 SPRAYPAINTING CHARGES

750.00

TOTAL (D)

1,720.00

ESTIMATE TOTAL

5,045.40

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: