# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building

51 Ubi Ave 1 #01-25 78 Shenton Way #07-16 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Tr, Tinesh Date: 21 Jun 2018

## **Preliminary Advice**

Vehicle No : SLT1093C **Accident Date** : 25/05/2018 Make : AUDI A5 Policy No. : 1700065210 **Assignment Date** : 30/05/2018 **Excess** : S\$1,600.00 Date of Inspection : 25/05/2018 Est. Duration of Repair : 13 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	98,336.00
Revised Amount	:S\$	46,702.00
Check Items (Estimated)	:S\$	35,783.00
Total	:S\$	82,485.00

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 175,000.00 COE / PARF Rebate 77,441.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 97,559.00

#### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Kindly approved of supplementary amount \$36,378.00, included check item. ( X )