

ASS. REC. BY: Adrian Ling

REF: C03/16/18009702/Asd302

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: \$1,600/-
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 175K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 28 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLT1093C Yr Regn: 2017, act
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A5 SB cc 1984Colour: Black A/C: Insured / Std / NI / NASp. Reading: 17357 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40R18R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD AIG.

RECEIVED 15 JUL 2019

31/05/18 @ 10:47 a.m. revised IA to AIG Insurance via merimer.
 31/05/18 @ 10:49 a.m. mandate request authorise repair to AIG Insurance via merimer.
 01/06/18 @ 14:30 p.m. mandate approve by Andy Fong via merimer. (Authorized rep)
 01/06/18 @ 14:41 p.m. revised authorized repair to Tony Cooper via email.
 21/06/18 @ 11:09 a.m. revised IA (including supplementary) to Fresh via merimer.
 21/06/18 @ 11:15 a.m. mandate requested supplementary to Fresh via merimer.
 03/07/18 @ Confirmed P/P \$ 42,256.20 @ 28 days with Adrian
 (\$ 56,030.32 Red - 57%)

Date/Time, File Pass to?

15/07/19

1)

Type

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final ReportDays Of Repair: 28Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format

Lump Sum / I.E: (\$ 42,256.20 P/P)

200

10

210

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8295I
Vehicle Details	
Vehicle No.:	SLT1093C
Vehicle to be Exported:	No
Intended De-registration Date:	31 May 2018
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	CVK047034
Chassis No.:	WAUZZZF58JA034474
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$39,115.00
Original Registration Date:	17 Oct 2017
First Registration Date:	17 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$41,761.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Oct 2027
PARF Rebate Amount:	\$31,320.00
Intended COE Rebate Details	
COE Expiry Date:	16 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,189.00
COE Rebate Amount:	\$46,121.00
Total Rebate Amount:	\$77,441.00

The information contained herein is correct as at 31 May 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 3 July 2019 1:45 PM
To: 'Carrine Leong'; Adrian Ling (LKKAuto); SUR
Cc: jayee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLT1093C - OD AIG - SURVEYED 15 MAY 18

Hi Carrine,

As spoken, confirmed final fig \$ 42,256.20 @ 28 days of repairs before excess \$ 1,600/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong [mailto:carrine.leong@premiumauto.com.sg]
Sent: Thursday, 18 April 2019 2:51 PM
To: 'Adrian Ling' <adrianling@lkkauto.com>; shirleyhiew@lkkauto.com; sur@lkkauto.com
Cc: jayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SLT1093C - OD AIG - SURVEYED 15 MAY 18

Dear Adrian and all,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.
Revised estimate was mailed to you on 29 Aug 2018, 22 Jan & 21 Feb 2019.
We sincerely appreciate your early closure.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 1 June 2018 2:41 PM
To: 'Claims'
Cc: 'SUR'
Subject: RE: OD CLAIM FOR SLT 1093 C
Attachments: ESTIMATE.pdf

Dear Tony,

Please refer to the attachment.

Part item no. 21 has been correction to check item by Arian.

As instructed by our client, please proceed to repair the insured vehicle **SLT 1093C (Excess \$ 1,600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Thursday, 31 May 2018 8:26 AM
To: 'SUR' <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: OD CLAIM FOR SLT 1093 C

Dear all,

Any update on repair approval?

Thank you.

Best Regards,

Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 1996022719W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 **d.** +65 6768 9828 **f.** +65 6841 1183

e. claims@premiumauto.com.sg **w.** www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 **p.** +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

View Received Message

This mail is associated with :

***SLT1093C (2742446143SG)**

OD

May 25 2018 9:45AM

[ONG SWEE SENG, RAYMOND]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 11/06/2019 16:31 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$42256.20) - SLT1093C - Claim Handler: Dally Amri, Mimi Zarina

Approved:42256.20.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLT1093C (2742446143SG)**

OD

May 25 2018 9:45AM

[ONG SWEE SENG, RAYMOND]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 18/01/2019 15:00 PM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SLT1093C - Claim Handler: Dally Amri, Mimi Zarina

Maintained:Kindly advise how was the sun visor damage consistent with the damage.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLT1093C (2742446143SG)**

OD

May 25 2018 9:45AM

[ONG SWEE SENG, RAYMOND]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 03/07/2018 10:19 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$82485.00) - SLT1093C - Claim Handler: Tr, Tinesh

Approved:82485.00:To furnish clear damage photographs of items paid out during finalization

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

*SLT1093C (2742446143SG)

OD

May 25 2018 9:45AM

[ONG SWEE SENG, RAYMOND]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 01/06/2018 14:30 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$46107.00) - SLT1093C - Claim Handler: Tr, Tinesh

Approved:46107.00:to commence repairs, all check and supplementary items to be supplemented by clear damage photographs.

DOCUMENTS SUMMARY

There are no documents.



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 19 Nov 2018

Preliminary Advice

Vehicle No	: SLT1093C	Accident Date	: 25/05/2018
Make	: AUDI A5	Policy No.	: 1700065210
Assignment Date	: 30/05/2018	Excess	: S\$1,600.00
Date of Inspection	: 28/05/2018	Est. Duration of Repair	: 28 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	99,225.00 (inclusive supplementary)
Revised Amount	:S\$	42,650.20 (inclusive supplementary)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	42,650.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	77,441.00
Salvage Value	:S\$	
Margin for Repair	:S\$	97,559.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : supplementary amount \$ 790.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 12 Nov 2018

Preliminary Advice

Vehicle No	: SLT1093C	Accident Date	: 25/05/2018
Make	: AUDI A5	Policy No.	: 1700065210
Assignment Date	: 30/05/2018	Excess	: S\$1,600.00
Date of Inspection	: 28/05/2018	Est. Duration of Repair	: 28 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	99,225.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	42,650.20 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	42,605.20
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	77,441.00
Salvage Value	:S\$	
Margin for Repair	:S\$	97,559.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : supplementary amount \$ 790.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr. Tinesh

Date: 21 Jun 2018

Preliminary Advice

Vehicle No	: SLT1093C	Accident Date	: 25/05/2018
Make	: AUDI A5	Policy No.	: 1700065210
Assignment Date	: 30/05/2018	Excess	: S\$1,600.00
Date of Inspection	: 25/05/2018	Est. Duration of Repair	: 13 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	98,336.00
Revised Amount	:S\$	46,702.00
Check Items (Estimated)	:S\$	35,783.00
Total	:S\$	82,485.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	77,441.00
Salvage Value	:S\$	
Margin for Repair	:S\$	97,559.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approved of supplementary amount \$ 36,378.00, included check item.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 31 May 2018

Preliminary Advice

Vehicle No	: SLT1093C	Accident Date	: 25/05/2018
Make	: AUDI A5	Policy No.	: 1700065210
Assignment Date	: 30/05/2018	Excess	: S\$0.00
Date of Inspection	: 28/05/2018	Est. Duration of Repair	: 13 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	61,358.00
Revised Amount	:S\$	41,993.00
Check Items (Estimated)	:S\$	4,114.00
Total	:S\$	46,107.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	77,441.00
Salvage Value	:S\$	
Margin for Repair	:S\$	97,559.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/05/2018 20:39
Date Of Accident	25/05/2018 09:45
Exact Location Of Accident	PIE ENTERING KALLANG WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT1093C
Insured/Policyholder	
Name Of Registered Owner	ONG SWEE SENG, RAYMOND
NRIC No	S8718295I
Email Address	RRAYMONDI87@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91530053
Alternative Phone No	OTHERS-91530053

Vehicle Particulars

Manufacturer	AUDI
Model	A5 SB 2.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700065210
Cover Note Number	-

Driver

Name of Driver	ONG SWEE SENG, RAYMOND
NRIC No	S8718295I
Date Of Birth	25/06/1987
Occupation	INDOOR
Date Of Driving Pass	26/07/2008
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91530053
Fax Number	
Contact Number	OTHERS-91530053
Email Address	RRAYMONDI87@GMAIL.COM

Address	30 YIO CHU KANG GARDENS
Postcode	568077
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGH9658T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ONG SWEE SENG, RAYMOND
Approximate Age	

Injuries Sustain

HEAD AND NECK

Injured person in which vehicle?

SLT1093C

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature
Date & Time: 24/11/11

Driver's Signature
(If Driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: LIM SEE SEN
NIC/FIN No: 6555281A

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, Raymond Ong Seng Sang, was driving up the ramp at the exit on PIE, entering Kallang Way at around 0945.

The vehicle (car), in front of me, slowed down, and I then collided into its rear.

There were no other cars involved.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 3/1/2016

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Ng Joo Sang
NIC/FIN No: B25526897

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S87182951**

ONG SWEE SENG, RAYMOND
(WANG RUISHENG)

Birth Date: 25 Jun 1987

Issue Date: 30 Jan 2018



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S87182951**



Name:

ONG SWEE SENG, RAYMOND
(WANG RUISHENG)

王瑞生

Race:

CHINESE

Date of birth:

25-06-1987

Sex:

M

Country/Place of birth:

SINGAPORE

S87182951

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$ 26 Jul 2008



Licence No: S87182951

NP 428A

S873468



NRIC No. **S87182951**



Date of issue:

30-01-2018

Address:

30 YIO CHU KANG GARDENS
SINGAPORE 568077

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0624/2018/GW
Date	:	26-May-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Ong Swee Seng, Raymond
Address	:	30 Yio Chu Kang Gardens Singapore 568077
Telephone	:	HP +65 91530053
Type of Claim	:	Own Damage Claim
Policy No.	:	1700065210
Vehicle No	:	SLT 1093 C
Model Code	:	Audi A5 SB 2.0 TFSI
Model / Year	:	Oct-17
Engine No	:	CVK 047034
Chassis No	:	WAUZZZF58JA034474
Mileage	:	
Date In	:	25-May-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	25-May-18
Place of Accident	:	PIE Entering Kallang Way

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 1093 C.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
5	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	\$ 5,400.00	4000
6	To remove both front door panel trims, dismantle wing mirror assy and renew both door's chrome moldings.	S/N \$ 600.00	✓
7	To respray front bumper, both front fenders, bonnet, hinges, lhs A-pillar. And both front doors.	\$ 5,300.00	3300
8	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 14,872.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 1093 C.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N TBC	✓
2	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid. Inspect for damages and renew if necessary.	S/N \$ 480.00	✓
3	To remove and renew, aircon condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,100.00	✓
4	To remove and reinstall center console. Renew both front seat belts, air bag control unit and battery central protection.	S/N \$ 1,800.00	✗
TOTAL LABOUR CHARGES		: \$ 3,380.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 1093 C.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,970.00	✓ 1,576.00
2	FRONT BUMPER FIXING PARTS	\$ 349.00	✓ 279.20
3	FRONT BUMPER GRILLE	\$ 171.00	✓ 136.80
4	RADIATOR GRILLE	\$ 2,022.00	✓ 1,617.60
5	FRONT PARKING AID SENSOR SUPPORT-LH/RH	2 \$ 100.00	✓ 79.68
6	RADIATOR GRILLE COVER	\$ 165.00	✓ 132.00
7	FRONT BUMPER CLOSING ELEMENT	\$ 195.00	✓ 156.00
8	FRONT BUMPER SPOILER	\$ 465.00	✓ 372.00
9	FRONT BUMPER AIR GUIDE-LH/RH	2 \$ 146.00	✓ 115.68
10	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$ 828.00	✓ 662.40
11	FRONT PARKING AID SENSOR	2 \$ 421.00	✓ 336.80
12	FRONT PARKING AID SENSOR SEAL	4 \$ 14.00	✓ 10.88
13	FRONT BUMPER WIRING	\$ 456.00	✓ 364.80
14	FOAM FILLER PIECE	\$ 107.00	✓ 85.20
15	FRONT BUMPER CARRIER	\$ 702.00	✓ 561.60
16	FRONT BUMPER SUPPORT-LH/RH	2 \$ 48.00	✓ 38.24
17	FRONT BUMPER BRACKET-LH/RH	2 \$ 368.00	✓ 294.40
18	FRONT BUMPER LOCK CARRIER BRACKET	\$ 118.00	✓ 94.00
19	FRONT BUMPER COVER	\$ 109.00	✓ 87.20
20	RELEASE LEVER	\$ 12.00	✓ X
SUB-TOTAL SPARE PARTS		\$ 8,766.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLT 1093 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BOWDEN CABLE -CENTER <i>Not New</i>	\$ 50.00	<i>wood ? X</i>
22	"SIGN CAUTION" <i>new</i>	\$ 12.00	<i>9.28</i>
23	AIR CONDITIONER STICKER <i>new</i>	\$ 7.00	<i>4.88</i>
24	FRONT FENDER-LH/RH <i>new Buckled</i>	2 \$ 1,840.00	<i>1471.20</i>
25	FENDER ATTACHMENT PARTS	2 \$ 90.00	<i>x</i>
26	FRONT FENDER CLOSING ELEMENT-LH/RH	2 \$ 130.00	<i>x</i>
27	FRONT FENDER BRACKET-LH/RH	2 \$ 62.00	<i>x</i>
28	FRONT FENDER BRACE-LH/RH	2 \$ 206.00	<i>x</i>
29	FRONT FENDER COVER-LH/RH <i>new</i>	2 \$ 28.00	<i>20.96</i>
30	COVE R-LH/RH	2 \$ 60.00	<i>48.00</i>
31	STONE CHIP GUARD-LH/RH <i>new</i>	2 \$ 88.00	<i>69.12</i>
32	FRONT WHEEL SPOILER-LH/RH <i>new Buckled</i>	2 \$ 126.00	<i>x</i> <i>100.32</i>
33	LED HEADLIGHT-LH/RH <i>new</i>	2 \$ 14,038.00	<i>11230.40</i>
34	LED HEADLIGHT POWER MODULE	\$ 665.00	<i>x</i>
35	LED HEADLIGHT CONTROL UNIT	\$ 657.00	<i>x</i>
36	LED WITH HEAT SINK-LH/RH	2 \$ 1,980.00	<i>x</i>
37	HOSE <i>Not New</i>	2 \$ 60.00	<i>x</i>
38	COMPENSATING PIECE <i>Not New</i>	4 \$ 145.00	<i>? X</i>
39	RETAINER PLATE SPACER <i>Not New</i>	2 \$ 70.00	<i>? X</i>
40	LED HEADLIGHT LIFT CYLINDER-LH/RH <i>2H Dmgd</i>	2 \$ 348.00	<i>? 147.20</i>
SUB-TOTAL SPARE PARTS		\$ 20,662.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLT 1093 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
40	LED HEADLIGHT LIFT CYLINDER BRACKET-LH/RH <i>Not new</i>	\$ 26.00	? X
41	CORRUGATED PIPE <i>And one Bent.</i>	\$ 73.00	✓ 52
42	BONNET <i>Disturbed</i>	\$ 2,499.00	✓ 1999.20
43	BONNET ATTACHMENT PARTS <i>Not new</i>	\$ 105.00	✓ X
44	BONNET LID HINGE-LH/RH <i>Not new</i>	2 \$ 734.00	✓ ? X
45	IMPACT PROTECTION-CENTER <i>from</i>	\$ 24.00	✓ 18.88
46	IMPACT PROTECTION-RH/LH	2 \$ 48.00	✓ 33.76
47	BONNET SOUND ABS <i>sampled</i>	\$ 296.00	? ✓ 236.80
48	BONNET GAS FILLED STRUT <i>new</i>	2 \$ 209.00	✓
49	BONNET STRIKER-LH/RH <i>Not new</i>	2 \$ 88.00	? X
50	BONNET BOWDEN CABLE <i>Not new</i>	\$ 50.00	? X
51	BONNET LID LOCK <i>Not new</i>	2 \$ 376.00	? X
52	LOCK CARRIER WITH MOUNTING <i>checked</i>	\$ 891.00	✓ 712.80
53	AIR GUIDE-LH/RH <i>Disturbed</i>	2 \$ 52.00	✓ 40.88
54	INNER AIR DUCT-LH/RH <i>Disturbed</i>	2 \$ 28.00	✓ 21.12
55	UPPER AIR GUIDE <i>checked</i>	\$ 14.00	? ✓ 10.56
56	AIR COOLER CHARGE <i>Disturbed</i>	\$ 514.00	✓ 411.20
57	AIR COOLER SEAL RING <i>Not new</i>	\$ 79.00	✓ X
58	HOSE CLAMP <i>Not new</i>	2 \$ 37.00	? X
59	A/C CONDENSER <i>Disturbed</i>	\$ 550.00	✓ 440.00
60	PRESSURE SENSOR <i>Not new</i>	\$ 170.00	? X
SUB-TOTAL SPARE PARTS		\$ 6,863.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLT 1093 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	PRESSURE VALVE <i>Not Nec</i>	\$ 46.00	?X
62	RADIATOR <i>Distorted</i>	\$ 630.00	✓ 503.60
63	SLEEVE <i>Not Nec</i>	2 \$ 15.00	?X
64	RUBBER BUSH <i>in</i>	4 \$ 38.00	✓ 30.40
65	COOLANT CONCENTRATE <i>in</i>	4 \$ 133.00	✓ 65.28
66	BREATHING LINE <i>Not Nec</i>	\$ 29.00	?X
67	FAN RING <i>Cracked</i>	\$ 230.00	✓ 184.00
68	RADIATOR FAN WITH CONTROL UNIT <i>Distorted</i>	\$ 2,055.00	✓ 1644.00
69	FRONT WINDOW SLOT SEAL-LH/RH <i>Not Nec</i>	2 \$ 690.00	X
70	FRONT FENDER TRIM-LH/RH <i>Not</i>	2 \$ 276.00	? ✓ 220.80
71	FRONT DOOR TRIM-LH/RH <i>Not Nec</i>	2 \$ 276.00	?X
72	THREE POINT AUTOMATIC SEAT BELT-LH/RH	2 \$ 1,912.00	X
73	SEAT BELT HEIGHT ADJUSTER	2 \$ 306.00	↓
74	AIR BAG CONTROL UNIT	\$ 1,870.00	↓
75	AIRBAG CRASH SENSOR	4 \$ 545.00	+
76	CENTRAL PROTECTION <i>in</i>	\$ 470.00	X
77	INTAKE AIR DUCT-RH <i>Distorted</i>	\$ 18.00	✓ 14.16
78	AIR INTAKE HOSE <i>Distorted</i>	\$ 31.00	✓ 24.30
79	FRONT NO. PLATE <i>missing</i>	S/N \$ 25.00	✓
80	SUNDRIES <i>Not</i>	\$ 600.00	? ✓ 257.60
TOTAL SPARE PARTS		:	\$ 46,486.00
TOTAL LABOUR CHARGES		:	\$ 14,872.00
GRAND TOTAL		:	\$ 61,358.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

99225

98286 SL

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Achian King
Surveyed Date : 28/05/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0624/2018/GW
14-Jun-18
CHANG
1 of 1
SLT 1093 C
Audi A5 SB 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	To cut out and weld rhs front chassis frame striker plate. Align to position.	\$ 900.00	500
2	To respray rhs front chassis frame.	\$ 500.00	300
3	To remove and renew engine assy and damaged attachment. S/N	\$ 3,200.00	2900
4	To carry out LTA inspection for engine stamping. S/N	\$ 300.00	2X
TOTAL LABOURS :		\$ 4,900.00	

Parts

1	WIRE CONNECTOR	\$ 15.00	CR / 11.36
2	A/C PIPE	\$ 145.00	RA / 115.60
3	WIRE CONNECTOR	\$ 7.00	CM / 5.12
4	FLAT CONNECTOR HOUSING	\$ 16.00	CR / 12.32
5	HEADLIGHT WASHER JET BRACKET - LH/RH	\$ 26.00	CR / 19.24
6	WASHER JAT SPRING CLIP	\$ 43.00	AN / 34.03
7	BASE ENGINE <i>NOT REC</i>	\$ 27,809.00	X
8	OIL SUMP-LOWER PART	\$ 283.00	CR / 236.80
9	OIL SUMP BOLT SET	\$ 17.00	AN / 13.60
10	OIL LEVEL SENSOR <i>changed</i>	\$ 232.00	AN / 194.50
11	ENGINE OIL	\$ 264.00	AN / 210.20
12	A/C COMPRESSOR	\$ 2,327.00	CR / 1861.60
13	VIBRATION DAMPER	\$ 379.00	BA / 302.80
14	TIMING CASE	\$ 253.00	SEA / 202.00
15	SILICON SEALANT	\$ 35.00	AN / 27.52
16	POLY-V-BELT	\$ 45.00	AN / 35.68
17	BELT TENSIONER DAMPER <i>changed</i>	\$ 128.00	AN / 102.40
18	CHASSIS SHOCK ABSORBER MOUNTING - RH	\$ 54.00	RA / 43.20

TOTAL PARTS : \$ 32,078.00

GRAND TOTAL : \$ 36,978.00

For Premium Automobiles Pte Ltd

Authorised Signature

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

14/6 by Rasal.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0624/2018/GW 14-Jun-18 CHANG 1 of 1 SLT 1093 C Audi A5 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To cut out and weld rhs front chassis frame striker plate. Align to position.	\$ 900.00	\$ 500.00
2	To respray rhs front chassis frame.	\$ 500.00	\$ 300.00
3	To remove and renew engine assy and damaged attachment. <i>(Remove and renew below damaged parts)</i> S/N	\$ 3,200.00	\$ 900.00
4	To carry out LTA inspection for engine stamping. S/N	\$ 300.00	
TOTAL LABOURS :		\$ 4,900.00	\$ 1,700.00
Parts			
1	WIRE CONNECTOR	\$ 15.00	\$ 11.36
2	A/C PIPE	\$ 145.00	\$ 115.60
3	WIRE CONNECTOR	\$ 7.00	\$ 5.12
4	FLAT CONNECTOR HOUSING	\$ 16.00	\$ 12.32
5	HEADLIGHT WASHER JET BRACKET - LH/RH 2	\$ 26.00	\$ 19.84
6	WASHER JAT SPRING CLIP 2	\$ 43.00	\$ 34.08
7	BASE ENGINE	\$ 27,809.00	
8	OIL SUMP-LOWER PART	\$ 283.00	\$ 236.80
9	OIL SUMP BOLT SET	\$ 17.00	\$ 13.60
10	OIL LEVEL SENSOR	\$ 232.00	\$ 194.80
11	ENGINE OIL	\$ 264.00	\$ 210.80
12	A/C COMPRESSOR	\$ 2,327.00	\$ 1,861.60
13	VIBRATION DAMPER	\$ 379.00	\$ 302.80
14	TIMING CASE	\$ 253.00	\$ 202.00
15	SILICON SEALANT	\$ 35.00	\$ 27.52
16	POLY-V-BELT	\$ 45.00	\$ 35.68
17	BELT TENSIONER DAMPER	\$ 128.00	\$ 102.40
18	CHASSIC SHOCK ABSORBER MOUNTING - RH	\$ 54.00	\$ 43.20
19	ENGINE SUMP GUARD	\$ 495.00	\$ 396.00
TOTAL PARTS :		\$ 32,573.00	\$ 3,825.52
GRAND TOTAL :		\$ 37,473.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0624/2018/GW 14-Jun-18 CHANG 1 of 1 SLT 1093 C Audi A5 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	SUN VISOR - DRIVER SIDE <i>original see new</i>	\$ 394.00	A ✓
	TOTAL PARTS	\$ 394.00	
	GRAND TOTAL	\$ 394.00	

For Premium Automobiles Pte Ltd

Adrian Ling

Authorised Signature

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0624/2018/GW
Date : 26-May-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Adrian
You recommended 13 days
We took 38 days with parts order
jb 29 Aug 18*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ong Swee Seng, Raymond
Address : 30 Yio Chu Kang Gardens
Singapore 568077
Telephone : HP +65 91530053
Type of Claim : Own Damage Claim
Policy No. : 1700065210
Vehicle No : **SLT 1093 C**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : Oct-17
Engine No : CVK 047034
Chassis No : WAUZZZF58JA034474
Mileage :
Date In : 25-May-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-May-18
Place of Accident : PIE Entering Kallang Way

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 1093 C.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N	TBC	
2	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid. Inspect for damages and renew if necessary.	S/N \$	480.00	\$ 480.00
3	To remove and renew, aircon condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,100.00	\$ 1,100.00
4	To remove and reinstall center console. Renew both front seat belts, air bag control unit and battery central protection.	S/N \$	1,800.00	
TOTAL LABOUR CHARGES		:	<u>\$ 3,380.00</u>	<u>\$ 1,580.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 1093 C.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 1,580.00
5	To dismantle front bumper, both front fenders, headlights and bonnet. Renew front lock carrier and align to position. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.		\$ 5,400.00	\$ 4,000.00
6	To remove both front door panel trims, dismantle wing mirror assy and renew both door's chrome moldings.	S/N	\$ 600.00	\$ 600.00
7	To respray front bumper, both front fenders, bonnet, hinges, lhs A-pillar. And both front doors.		\$ 5,300.00	\$ 3,300.00
8	Added labour charges - see attached		\$ 4,900.00	\$ 1,700.00
9	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES			\$ 19,772.00	\$ 11,372.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 1093 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,970.00	\$ 1,576.00
2	FRONT BUMPER FIXING PARTS	\$ 349.00	\$ 279.20
3	FRONT BUMPER GRILLE	\$ 171.00	\$ 136.80
4	RADIATOR GRILLE	\$ 2,022.00	\$ 1,617.60
5	FRONT PARKING AID SENSOR SUPPORT-LH/RH	2 \$ 100.00	\$ 79.68
6	RADIATOR GRILLE COVER	\$ 165.00	\$ 132.00
7	FRONT BUMPER CLOSING ELEMENT	\$ 195.00	\$ 156.00
8	FRONT BUMPER SPOILER	\$ 465.00	\$ 372.00
9	FRONT BUMPER AIR GUIDE-LH/RH	2 \$ 146.00	\$ 115.68
10	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$ 828.00	\$ 662.40
11	FRONT PARKING AID SENSOR	2 \$ 421.00	\$ 336.80
12	FRONT PARKING AID SENSOR SEAL	4 \$ 14.00	\$ 10.88
13	FRONT BUMPER WIRING	\$ 456.00	\$ 364.80
14	FOAM FILLER PIECE	\$ 107.00	\$ 85.20
15	FRONT BUMPER CARRIER	\$ 702.00	\$ 561.60
16	FRONT BUMPER SUPPORT-LH/RH	2 \$ 48.00	\$ 38.24
17	FRONT BUMPER BRACKET-LH/RH	2 \$ 368.00	\$ 294.40
18	FRONT BUMPER LOCK CARRIER BRACKET	\$ 118.00	\$ 94.00
19	FRONT BUMPER COVER	\$ 109.00	\$ 87.20
20	RELEASE LEVER	\$ 12.00	
SUB-TOTAL SPARE PARTS		\$ 8,766.00	\$ 7,000.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLT 1093 C

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	7,000.48
21	BOWDEN CABLE -CENTER		\$ 50.00	
22	"SIGN CAUTION"		\$ 12.00	\$ 9.28
23	AIR CONDITIONER STICKER		\$ 7.00	\$ 4.88
24	FRONT FENDER-LH/RH	2	\$ 1,840.00	\$ 1,471.20
25	FENDER ATTACHMENT PARTS	2	\$ 90.00	
26	FRONT FENDER CLOSING ELEMENT-LH/RH	2	\$ 130.00	
27	FRONT FENDER BRACKET-LH/RH	2	\$ 62.00	
28	FRONT FENDER BRACE-LH/RH	2	\$ 206.00	
29	FRONT FENDER COVER-LH/RH	2	\$ 28.00	\$ 20.96
30	COVE R-LH/RH	2	\$ 60.00	\$ 48.00
31	STONE CHIP GUARD-LH/RH	2	\$ 88.00	\$ 69.12
32	FRONT WHEEL SPOILER-LH/RH	2	\$ 126.00	\$ 100.32
33	LED HEADLIGHT-LH/RH	2	\$ 14,038.00	\$ 11,230.40
34	LED HEADLIGHT POWER MODULE		\$ 665.00	
35	LED HEADLIGHT CONTROL UNIT		\$ 657.00	
36	LED WITH HEAT SINK-LH/RH	2	\$ 1,980.00	
37	HOSE	2	\$ 60.00	
38	COMPENSATING PIECE	4	\$ 145.00	
39	RETAINER PLATE SPACER	2	\$ 70.00	
40	LED HEADLIGHT LIFT CYLINDER-LH/RH	2	\$ 348.00	\$ 147.20
SUB-TOTAL SPARE PARTS			\$ 20,662.00	\$ 20,101.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLT 1093 C

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	20,101.84
40	LED HEADLIGHT LIFT CYLINDER BRAKET-LH/RH	2	\$ 26.00	
41	CORRUGATED PIPE		\$ 73.00	\$ 58.00
42	BONNET		\$ 2,499.00	\$ 1,999.20
43	BONNET ATTACHMENT PARTS		\$ 105.00	
44	BONNET LID HINGE-LH/RH	2	\$ 734.00	
45	IMPACT PROTECTION-CENTER		\$ 24.00	\$ 18.88
46	IMPACT PROTECTION-RH/LH	2	\$ 48.00	\$ 37.76
47	BONNET SOUND ABS		\$ 296.00	\$ 236.80
48	BONNET GAS FILLED STRUT	2	\$ 209.00	
49	BONNET STRIKER-LH/RH	2	\$ 88.00	
50	BONNET BOWDEN CABLE		\$ 50.00	
51	BONNET LID LOCK	2	\$ 376.00	
52	LOCK CARRIER WITH MOUNTING		\$ 891.00	\$ 712.80
53	AIR GUIDE-LH/RH	2	\$ 52.00	\$ 40.88
54	INNER AIR DUCT-LH/RH	2	\$ 28.00	\$ 21.12
55	UPPER AIR GUIDE		\$ 14.00	\$ 10.56
56	AIR COOLER CHARGE		\$ 514.00	\$ 411.20
57	AIR COOLER SEAL RING		\$ 79.00	
58	HOSE CLAMP	2	\$ 37.00	
59	A/C CONDENSER		\$ 550.00	\$ 440.00
60	PRESSURE SENSOR		\$ 170.00	
SUB-TOTAL SPARE PARTS			\$ 6,863.00	\$ 24,089.04

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLT 1093 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
		c/f	\$ 24,089.04
61	PRESSURE VALVE	\$ 46.00	
62	RADIATOR	\$ 630.00	\$ 503.60
63	SLEEVE	2 \$ 15.00	
64	RUBBER BUSH	4 \$ 38.00	\$ 30.40
65	COOLANT CONCENTRATE	4 \$ 133.00	\$ 65.28
66	BREATHER LINE	\$ 29.00	
67	FAN RING	\$ 230.00	\$ 184.00
68	RADATOR FAN WITH CONTROL UNIT	\$ 2,055.00	\$ 1,644.00
69	FRONT WINDOW SLOT SEAL-LH/RH	2 \$ 690.00	
70	FRONT FENDER TRIM-LH/RH	2 \$ 276.00	\$ 220.80
71	FRONT DOOR TRIM-LH/RH	2 \$ 276.00	
72	THREE POINT AUTOMATIC SEAT BELT-LH/RH	2 \$ 1,912.00	
73	SEAT BELT HEIGHT ADHUSTER	2 \$ 306.00	
74	AIR BAG CONTROL UNIT	\$ 1,870.00	
75	AIRBAG CRASH SENSOR	4 \$ 545.00	
76	CENTRAL PROTECTION	\$ 470.00	
77	INTAKE AIR DUCT-RH	\$ 18.00	\$ 14.16
78	AIR INTAKE HOSE	\$ 31.00	\$ 24.80
79	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
81	<i>Added parts - see attached</i>	\$ 32,573.00	\$ 3,825.52
82	SUNDRIES	\$ 600.00	\$ 257.60
	TOTAL SPARE PARTS	\$ 79,059.00	\$ 30,884.20
	TOTAL LABOUR CHARGES	\$ 19,772.00	\$ 11,372.00
	GRAND TOTAL	\$ 98,831.00	\$ 42,256.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLT 1093 C

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0624/2019/KK

6 July 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLT 1093 C, Audi A5 SB 2.0 TFSI.

With reference to the above-mentioned vehicle, no. **SLT 1093 C** claimant, **Mr. Ong Swee Seng, Raymond**, please find the related document per attached.

1. A copy of the Original invoice no. 85013996 – S\$43,502.13.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLT 1093 C

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2223
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2223
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 11:20

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013996 Date : 05/07/2019 Order : SLT1093C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLT1093C (V 35603) Regn Date: 17/10/2017 Mileage: 29175 WIP No.: 11531

Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF58JA034474 Engine: CVK 047034 Dept: 0

You have been assisted by :- UB-Tony Poong (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-1600.00	1.00	-1,600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER, TURBO COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	1100.00	1.00	1,100.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDER, HEADLIGHT AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	4000.00	1.00	4,000.00
S	BODYWORK	M: TO REMOVE BOTH FRONT DOOR PANEL TRIMS. DISMANTLE WING MIRROR ASSY AND BOTH DOOR'S CHROME MOLDINGS.	600.00	1.00	600.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH FRONT DOORS.	3300.00	1.00	3,300.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO CUT OUT AND WELD RHS FRONT CHASSIS FRAME STRIPER PLATE. ALIGN TO POSITION.	500.00	1.00	500.00
S	BODYWORK	M: TO CUT OUT AND WELD RHS FRONT CHASSIS FRAME STRIPER PLATE. ALIGN TO POSITION.	300.00	1.00	300.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 2 11:20

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013996 Date : 05/07/2019 Order : SLT1093C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLT1093C (V 35603) Regn Date: 17/10/2017 Mileage: 29175 WIP No.: 11531

Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF58JA034474 Engine: CVE 047034 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO RESPRAY RHS FRONT CHASSIS FRAME M: TO REMOVE AND RENEW ENGINE ASSY AND DAMAGED ATTACHMENT	900.00	1.00	900.00
X	A8W6919267D RN4	MOUNTING (V) (G)	Less 020%	1.00	49.80
X	A8W6919268D RN4	MOUNTING (V) (G)	Less 020%	1.00	49.80
X	A8W6853887	SPOILER (A)	Less 020%	1.00	62.70
X	A8W6823746	COVER (A)	Less 020%	1.00	13.10
X	A8W6820582B	COVER (A)	Less 020%	1.00	30.00
X	A8W0955339	CLIP (TECH) (V) (G)	Less 020%	2.00	21.30
X	A06L103598R	OIL SUMP (V)	Less 020%	1.00	296.00
X	A8W6971095A	HARNES (V)	Less 020%	1.00	456.00
X	A8W6863825B	SILENCER	Less 020%	1.00	296.00
X	A8W0816741AK	COOLANT PIP (V) (G)	Less 020%	1.00	144.50
X	A8W6955970	TUBING (A)	Less 020%	1.00	72.50
X	A8W6853651R RN4	GRILLE	Less 020%	1.00	2022.00
X	AG 052167M4	ENGINE OIL 5W40 5L (	Less 020%	1.00	263.50
X	A8W0145805	COOLER (A)	Less 020%	1.00	514.00
X	A8W6941773E	HEADLIGHT	Less 020%	1.00	7019.00
X	A8W6821105B	FENDER	Less 020%	1.00	919.50
X	A8W6941774E	HEADLIGHT	Less 020%	1.00	7019.00
X	A8W6853888	SPOILER	Less 020%	1.00	62.70
X	A8W0863821B	BAFFLE	Less 020%	1.00	495.00
X	A8W6821106B	FENDER (A)	Less 020%	1.00	919.50
X	A8W6807081B	COVER (A)	Less 020%	1.00	109.00
X	A8W0121251AK	RADIATOR	Less 020%	1.00	629.50
X	A8W0816421C	CONDENSER	Less 020%	1.00	550.00
X	A8W6807611	PLATE	Less 020%	1.00	195.00
X	A8W0805594	CARRIER	Less 020%	1.00	891.00
X	A8W0959455F	ELECTRIC F	Less 020%	1.00	2055.00
X	A8W6807550J	FOAM INSER (A)	Less 020%	1.00	106.50
X	A8W0807113	BRACKET	Less 020%	1.00	702.00
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	20.40
X	A8W6823029	HOOD	Less 020%	1.00	2499.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6886 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6886 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408599
Main Telephone 6386 2323
Main Telefax 6841 1163

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 3 11:20

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013996 Date : 05/07/2019 Order : SLT1093C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLT1093C (V 35603) Regn Date: 17/10/2017 Mileage: 29175 WIP No.: 11531

Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF58JA034474 Engine: CVK 047034 Dept: 0

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
X	A8W6807065D GRU	COVER (V) (G)	Less 020%	1.00	1970.00
X	A8K0973703	HOUSING (TECH)	Less 020%	1.00	14.20
X	A1J0973081	HOUSING	Less 020%	1.00	6.40
X	A06L903137A	RIBBEDBELT (TECH)	Less 020%	1.00	44.60
X	A7H0820896	SEAL	Less 020%	2.00	2.30
X	A4M0121275A	MOUNTING	Less 020%	2.00	7.80
X	A4M0121268A	MOUNTING	Less 020%	2.00	10.90
X	A8W0129617A	AIR DUCT (A)	Less 020%	1.00	17.70
X	A06H105243K	DAMPER (TECH)	Less 020%	1.00	378.50
X	A8W0121292B	AIR DUCT	Less 020%	1.00	13.20
X	A8W0121293A	AIR DUCT (A)	Less 020%	1.00	17.70
X	A8W0807334	SUPPORT	Less 020%	1.00	23.90
X	A8W0807333	SUPPORT	Less 020%	1.00	23.90
X	A8W6853603A PUZ	TRIM	Less 020%	1.00	138.00
X	A8W6853604A PUZ	TRIM	Less 020%	1.00	138.00
X	A8W0805678A	MOUNTING(V)	Less 020%	1.00	54.00
X	A8W6807133	BRACKET	Less 020%	1.00	184.00
X	A8W6807134	BRACKET	Less 020%	1.00	184.00
X	A8W6121763	AIR DUCT (A)	Less 020%	1.00	72.30
X	A8W6121764	AIR DUCT (V) (G)	Less 020%	1.00	72.30
X	A8W6121673B	AIR DUCT (A)	Less 020%	1.00	13.20
X	A8W6121674B	AIR DUCT (A)	Less 020%	1.00	13.20
X	A8W0820536	BRACKET	Less 020%	1.00	15.60
X	A8W6820581E	COVER (A)	Less 020%	1.00	30.00
X	A8W0853834	SPOILER	Less 020%	1.00	30.40
X	A8W6823125	PROTECTION (A)	Less 020%	1.00	23.60
X	A8W6823745	COVER (A)	Less 020%	1.00	13.10
X	A8W6853823B 9B9	STONEGUARD (A)	Less 020%	1.00	43.20
X	A8W6823126	PROTECTION (A)	Less 020%	1.00	23.60
X	A4E0260749A	WASHER	Less 020%	1.00	3.20
X	A8E0260749C	WASHER (TECH)	Less 020%	1.00	3.10
X	A4E0260749A	WASHER (TECH)	Less 020%	1.00	3.20
X	A3D0260749C	WASHER	Less 020%	1.00	3.80
X	A8W6853824B 9B9	STONEGUARD (A)	Less 020%	1.00	43.20

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 4 11:20

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013996 Date : 05/07/2019 Order : SLT1093C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLT1093C (V 35603)	Regn Date: 17/10/2017	Mileage: 29175	WIP No.: 11531
Model: A5 SPORTBACK 2.0 TFSI 8 tronic	Chassis: WAUZZZF58JA034474	Engine: CVR 047034	Dept: U
You have been assisted by :- UB-Tony Foong [33]			

		Details	Qty	Unit Price	Amount
X	ABW6853601A PUZ	TRIM (A)	Less 020%	1.00	138.00
X	ABW6823529	BOWD CABLE	Less 020%	1.00	50.00
X	A4M0820803	COMPRESSOR (TECH)	Less 020%	1.00	2327.00
X	ABW6807683 9B9	GRILLE (A)	Less 020%	1.00	171.00
X	ABW6807682M RN4	GRILL (V) (G)	Less 020%	1.00	414.00
X	ABW6807681M RN4	GRILL	Less 020%	1.00	414.00
X	ABW0853833	SPOILER	Less 020%	1.00	29.90
X	ABW6853602A PUZ	TRIM (A)	Less 020%	1.00	138.00
X	ABW6955775A	BRACKET (TECH) (V) (G)	Less 020%	1.00	12.40
X	ABW6955776A	BRACKET (TECH) (V)	Less 020%	1.00	12.40
X	A06L903133D	BELTDAMPER (TECH)	Less 020%	1.00	128.00
X	ABW0955102A	CYLINDER	Less 020%	1.00	184.00
X	A06L907660	OIL SENSOR (V)	Less 020%	1.00	243.50
X	A5Q0919275C GRU	Sensor	Less 020%	2.00	210.50
X	A5Q0919133 704	WASHER	Less 020%	4.00	3.40
X	A000979940	CONNECTOR (WHITE)	Less 020%	1.00	9.00
X	A000979141E	WIRE SET	Less 020%	1.00	20.20
X	A1J0973081	HOUSING (TECH)	Less 020%	1.00	6.40
X	A4D0971992	HOUSING (TECH)	Less 020%	1.00	15.40
X	ABW0010515A	STICKER	Less 020%	1.00	6.10
X	ABW0010520A	PLATE	Less 020%	1.00	11.60
X	AD 176501A1	SEALANT (TECH)	Less 020%	1.00	34.40
X	AD 176501A1	SEALANT	Less 020%	1.00	34.40
X	AD 174003M2	SEALANT	Less 020%	1.00	55.50
X	AD 007000A2	SILICSPRAY (DG)	Less 020%	1.00	29.30
X	A06K109210AF	TIMINGCASE (TECH)	Less 020%	1.00	252.50
X	ABW6121284AF	AIR DUCT (A)	Less 020%	1.00	25.40
X	ABW6121283AF	AIR DUCT (A)	Less 020%	1.00	25.70
X	ABW6807771	BRACKET (A)	Less 020%	1.00	117.50
X	ABW0121207E	COWL (A)	Less 020%	1.00	230.00
X	AN 0161857	POP-RIVET	Less 020%	10.00	2.90
X	AN 91093901	RIVET	Less 020%	4.00	0.70
X	AN 91093901	RIVET	Less 020%	4.00	0.70
X	AN 90536901	RIVET	Less 020%	2.00	0.70

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6896 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6888 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 5 11:20

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013996 Date : 05/07/2019 Order : SLT1093C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLT1093C (V 35603) Regn Date: 17/10/2017 Mileage: 29175 WIP No.: 11531

Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF58JA034474 Engine: CVK 047034 Dept: 0

You have been assisted by :- UB-Tony Foong (33)

		Details		Qty	Unit Price	Amount
X	AN 0385053	RIVET	Less 020%	6.00	0.40	1.92
X	AN 10036203	BOLT	Less 020%	4.00	11.70	37.44
X	AN 10347204	BOLT (TECH)	Less 020%	17.00	1.00	13.60
X	AN 91096702	BOLT (TECH)	Less 020%	15.00	0.70	8.40
X	AWHT001760	SCREW (TECH)	Less 020%	1.00	14.60	11.68
X	A8W6807110	SPOILER	Less 020%	1.00	465.00	372.00
X	A8W6823124	PROTECTION (A)	Less 020%	1.00	23.60	18.88
X	A8W6853037	COVER (V) (G)	Less 020%	1.00	165.00	132.00

Parts 30,859.20
Labour 0.00
Sublet 11,397.00
Menus 0.00
Lubricant 0.00



Sub-Total 40,656.20

7% GST 2,845.93

Grand Total 43,502.13

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLT1093C

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0624/2018/TF
17 July 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A5 SPORTBACK 2.0 TFSI S tronic
Vehicle Chassis No. : WAUZZZF58JA034474
Vehicle Regn No. : SLT1093C
Vehicle Mileage : 17405KM
Vehicle Owner : Mr. Ong Swee Seng
Certificate No : 1700065210
Policy Excess : \$1712.00 (Inclusive GST)
Accident Date : 25 May 2018
Place : PIE Entering Kallang Way
Repair Cost : \$ 42,502.13
WIP No. : 11531
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 18/7/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 May 2018		30 May 2018 14:18 Edit Adj Rpt	S\$42,256.20 Edit Estimates	S\$42,256.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ONG SWEE SENG, RAYMOND , ID: S8718295I, Tel: +6591530053, Email: rraymond87@gmail.com								
Vehicle Reg. No.:	SLT1093C	Date of Loss:	25/05/2018 09:00 - :59 [7 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 2742446143SG	Policy/Cover Note No.:	1700065210 (Comprehensive)						
		Excess:	S\$1,600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/06/2018]								
Driver/Custodian:	ONG SWEE SENG, RAYMOND (30 / Male), NRIC: S8718295I, Tel: +6591530053 Email: rraymond87@gmail.com								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (11/06/2019): Alert - Adj Mandate Approved (S\$42256.20) - SLT1093C - Claim Handler: Dally Amri... - AIG_SG (18/01/2019): Alert - Adj Mandate Maintained - SLT1093C - Claim Handler: Dally Amri, Mimi Zari... - AIG_SG (03/07/2018): Alert - Adj Mandate Approved (S\$82485.00) - SLT1093C - Claim Handler: Tr, Tinesh - AIG_SG (26/06/2018): Alert - Adj Mandate Maintained - SLT1093C - Claim Handler: Tr, Tinesh - AIG_SG (01/06/2018): Alert - Adj Mandate Approved (S\$46107.00) - SLT1093C - Claim Handler: Tr, Tinesh - AIG_SG (31/05/2018): SLT1093C / OD / 25/05/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT1093C (2742446143SG)
OD
May 25 2018 9:45AM
[ONG SWEE SENG, RAYMOND]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Assessment Reports											1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	31/05/18 10:47	Adjuster Immediate Advice										Load HTM		
2	21/06/18 11:09	Adjuster Immediate Advice										Load HTM		
3	12/11/18 16:19	Adjuster Immediate Advice										Load HTM		
4	19/11/18 16:07	Adjuster Immediate Advice										Load HTM		
5	27/06/19 15:47	Adjuster Immediate Advice										Load HTM		
Photos/Images											3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	31/05/18 10:20	General View										Load JPG	☒	
2	31/05/18 10:20	General View										Load JPG	☒	
3	31/05/18 10:20	Chassis Number										Load JPG	☒	
4	31/05/18 10:20	General View										Load JPG	☒	
5	31/05/18 10:20	General View										Load JPG	☒	
6	31/05/18 10:20	General View										Load JPG	☒	
7	31/05/18 10:20	General View										Load JPG	☒	
8	31/05/18 10:20	General View										Load JPG	☒	
9	31/05/18 10:20	General View										Load JPG	☒	
10	31/05/18 10:20	General View										Load JPG	☒	
11	31/05/18 10:20	General View										Load JPG	☒	
12	31/05/18 10:20	General View										Load JPG	☒	
13	31/05/18 10:20	General View										Load JPG	☒	
14	31/05/18 10:20	General View										Load JPG	☒	
15	31/05/18 10:20	General View										Load JPG	☒	
16	31/05/18 10:20	General View										Load JPG	☒	
17	31/05/18 10:20	General View										Load JPG	☒	
18	31/05/18 10:20	General View										Load JPG	☒	
19	31/05/18 10:20	General View										Load JPG	☒	
20	31/05/18 10:20	General View										Load JPG	☒	
21	31/05/18 10:20	General View										Load JPG	☒	
22	31/05/18 10:20	General View										Load JPG	☒	
23	31/05/18 10:20	General View										Load JPG	☒	
24	31/05/18 10:20	General View										Load JPG	☒	
25	31/05/18 10:20	General View										Load JPG	☒	
26	31/05/18 10:20	General View										Load JPG	☒	
27	31/05/18 10:20	General View										Load JPG	☒	
28	31/05/18 10:20	General View										Load JPG	☒	
29	31/05/18 10:20	General View										Load JPG	☒	
30	31/05/18 10:20	General View										Load JPG	☒	
31	31/05/18 10:20	General View										Load JPG	☒	
32	31/05/18 10:20	General View										Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	31/05/18 10:20	General View	 Load JPG	☒
34	31/05/18 10:20	General View	 Load JPG	☒
35	31/05/18 10:20	General View	 Load JPG	☒
36	31/05/18 10:20	General View	 Load JPG	☒
37	31/05/18 10:20	General View	 Load JPG	☒
38	31/05/18 10:20	General View	 Load JPG	☒
39	31/05/18 10:20	General View	 Load JPG	☒
40	31/05/18 10:20	General View	 Load JPG	☒
41	31/05/18 10:20	General View	 Load JPG	☒
42	31/05/18 10:20	General View	 Load JPG	☒
43	31/05/18 10:20	General View	 Load JPG	☒
44	31/05/18 10:20	General View	 Load JPG	☒
45	31/05/18 10:20	General View	 Load JPG	☒
46	31/05/18 10:20	General View	 Load JPG	☒
47	31/05/18 10:20	General View	 Load JPG	☒
48	31/05/18 10:20	General View	 Load JPG	☒
49	31/05/18 10:20	General View	 Load JPG	☒
50	31/05/18 10:20	General View	 Load JPG	☒
51	31/05/18 10:20	General View	 Load JPG	☒
52	31/05/18 10:20	General View	 Load JPG	☒
53	31/05/18 10:20	General View	 Load JPG	☒
54	31/05/18 10:20	General View	 Load JPG	☒
55	31/05/18 10:20	General View	 Load JPG	☒
56	31/05/18 10:20	General View	 Load JPG	☒
57	31/05/18 10:20	General View	 Load JPG	☒
58	31/05/18 10:20	General View	 Load JPG	☒
59	31/05/18 10:20	General View	 Load JPG	☒
60	31/05/18 10:20	General View	 Load JPG	☒
61	31/05/18 10:20	General View	 Load JPG	☒
62	31/05/18 10:20	General View	 Load JPG	☒
63	31/05/18 10:20	General View	 Load JPG	☒
64	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
65	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
66	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
67	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
68	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
69	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
70	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
71	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
72	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
73	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
74	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
75	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
76	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
77	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
78	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
79	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
80	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
81	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
82	26/06/18 16:34	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
83	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
84	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
85	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
86	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
87	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
88	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
89	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
90	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
91	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
92	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
93	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
94	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
95	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
96	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
97	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
98	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
99	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
100	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
101	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
102	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
103	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
104	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
105	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
106	26/06/18 16:34	Reinspection Photo	 Load JPG	☒
107	08/11/18 10:44	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/05/18 10:18	IC & DRIVING	 Load PDF	
2	31/05/18 10:18	ESTIMATE	 Load PDF	
3	21/06/18 11:10	SUPPLEMENTARY	 Load PDF	
4	12/11/18 16:08	ESTIMATE MARKED.pdf	 Load PDF	
5	12/11/18 16:08	SUPPLEMENTARY 1.pdf	 Load PDF	
6	07/06/19 17:14	ESTIMATE & SUPP MARKED.pdf	 Load PDF	
7	15/07/19 17:18	Discharge Voucher	 Load PDF	
8	15/07/19 17:18	Workshop Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	25/05/18 21:10	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	25/05/18 20:47	Accident Photo	 Load JPG	☒
2	25/05/18 20:47	Accident Photo	 Load JPG	☒
3	25/05/18 20:47	Accident Photo	 Load JPG	☒
4	25/05/18 20:47	Accident Photo	 Load JPG	☒
5	25/05/18 20:47	Accident Photo	 Load JPG	☒
6	25/05/18 20:47	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
7	25/05/18 20:47	Accident Photo		☒
8	25/05/18 20:47	Accident Photo		☒
9	25/05/18 20:47	Accident Photo		☒
10	25/05/18 20:47	Accident Photo		☒
11	25/05/18 20:47	Accident Photo		☒
12	25/05/18 20:47	Accident Photo		☒
13	25/05/18 20:47	Accident Photo		☒
14	25/05/18 20:47	Accident Photo		☒
15	25/05/18 20:47	Accident Photo		☒
16	25/05/18 20:47	Accident Photo		☒
17	25/05/18 20:47	Accident Photo		☒
18	25/05/18 20:47	Accident Photo		☒
19	25/05/18 20:47	Accident Photo		☒
20	25/05/18 20:47	Accident Photo		☒
21	25/05/18 20:47	Accident Photo		☒
22	25/05/18 20:47	Accident Photo		☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	25/05/18 21:09	Sketch Plan		☒
2	25/05/18 21:09	Sketch Plan #2		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18009702/ASD3E2

Date: 15/07/2019

REFERENCE

Insured/Claimant: ONG SWEE SENG, RAYMOND Policy No: 1700065210
Date of Loss: 25/05/2018 Nature of Claim: OD Claim No: 2742446143SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT1093C**
Make & Model: AUDI A5, 2.0 SPORTBACK (A) Engine No: CVK047034
Reg. Date: 17/10/2017 (Man. Year: 2017) Chassis No: WAUZZZF58JA034474
Colour: Black Odometer: 17357 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$175,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	78,514.52	30,884.20	47,630.32	60.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,772.00	11,372.00	8,400.00	42.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	98,286.52	42,256.20	56,030.32	57.01
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	96,686.52	40,656.20	56,030.32	57.95
+ GST 7.00/7.00% (S\$)	6,768.06	2,845.93	3,922.13	57.95
Nett Amount (S\$)	103,454.58	43,502.13	59,952.45	57.95

INSPECTION

Date of Assignment: 30/05/2018
Date Inspected: 28/05/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 30.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,970.00 FS	*1,576.00 FS
2	1	*FRONT BUMPER FIXING PARTS	Distorted	349.00 FS	*279.20 FS
3	1	*FRONT BUMPER GRILLE	Distorted	171.00 FS	*136.80 FS
4	1	*RADIATOR GRILLE	Distorted	2,022.00 FS	*1,617.60 FS
5	2	*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Missing	100.00 FS	*79.68 FS
6	1	*RADIATOR GRILLE COVER	Distorted	165.00 FS	*132.00 FS
7	1	*FRONT BUMPER CLOSING ELEMENT	Distorted	195.00 FS	*156.00 FS
8	1	*FRONT BUMPER SPOILER	Deformed	465.00 FS	*372.00 FS
9	2	*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Distorted	828.00 FS	*662.40 FS
10	2	*FRONT PARKING AID SENSOR	Missing	421.00 FS	*336.80 FS
11	4	*FRONT PARKING AID SENSOR SEAL	Missing	14.00 FS	*10.88 FS
12	1	*FRONT BUMPER WIRING	Damaged	456.00 FS	*364.80 FS
13	1	*FOAM FILLER PIECE	Cracked	107.00 FS	*85.20 FS
14	1	*FRONT BUMPER CARRIER	Bent	702.00 FS	*561.60 FS
15	2	*FRONT BUMPER SUPPORT - LH / RH	Damaged	48.00 FS	*38.24 FS
16	2	*FRONT BUMPER BRACKET - LH / RH	Damaged	368.00 FS	*294.40 FS
17	1	*FRONT BUMPER LOCK CARRIER BRACKET	Cracked	118.00 FS	*94.00 FS
18	1	*FRONT BUMPER COVER	Deformed	109.00 FS	*87.20 FS
19	1	*RELEASE LEVER	Not Necessary	12.00 FS	*- FS
20	1	*BOWDEN CABLE - CENTER	Not Necessary	50.00 FS	*- FS
21	1	*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
22	1	*AIR CONDITIONER STICKER	Necessary	7.00 FS	*4.88 FS
23	2	*FRONT FENDER - LH / RH	Buckled	1,840.00 FS	*1,471.20 FS
24	2	*FENDER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
25	2	*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	130.00 FS	*- FS
26	2	*FRONT FENDER BRACKET - LH / RH	Not Necessary	62.00 FS	*- FS
27	2	*FRONT FENDER BRACE - LH / RH	Not Necessary	206.00 FS	*- FS
28	2	*FRONT FENDER COVER - LH / RH	Necessary	28.00 FS	*20.96 FS
29	2	*COVER - LH / RH	Necessary	60.00 FS	*48.00 FS
30	2	*STONE CHIP GUARD - LH / RH	Necessary	88.00 FS	*69.12 FS
31	2	*FRONT WHEEL SPOILER - LH / RH	Deformed	126.00 FS	*100.32 FS
32	2	*LED HEADLIGHT - LH / RH	Cracked	14,038.00 FS	*11,230.40 FS
33	1	*LED HEADLIGHT POWER MODULE	Not Necessary	665.00 FS	*- FS
34	1	*LED HEADLIGHT CONTROL UNIT	Not Necessary	657.00 FS	*- FS
35	2	*LED WITH HEAT SINK - LH / RH	Not Necessary	1,980.00 FS	*- FS
36	2	*HOSE	Not Necessary	60.00 FS	*- FS
37	4	*COMPENSATING PIECE	Not Necessary	145.00 FS	*- FS
38	2	*RETAINER PLATE SPACER	Not Necessary	70.00 FS	*- FS
39	1	*LED HEADLIGHT LIFT CYLINDER - LH / RH	N/S Damaged	348.00 FS	*147.20 FS
40	2	*LED HEADLIGHT LIFT CYLINDER BRACKET - LH / RH	Not Necessary	26.00 FS	*- FS
41	1	*CORRUGATED PIPE	Bent	73.00 FS	*58.00 FS
42	1	*BONNET	Distorted	2,499.00 FS	*1,999.20 FS
43	1	*BONNET ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
44	2	*BONNET LID HINGE - LH / RH	Not Necessary	734.00 FS	*- FS
45	1	*IMPACT PROTECTION - CENTER	Necessary	24.00 FS	*18.88 FS
46	2	*IMPACT PROTECTION - RH / LH	Necessary	48.00 FS	*37.76 FS
47	1	*BONNET SOUND ABS	Crumpled	296.00 FS	*236.80 FS
48	2	*BONNET GAS FILLED STRUT	Not Necessary	209.00 FS	*- FS
49	2	*BONNET STRIKER - LH / RH	Not Necessary	88.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*BONNET BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
51	2		*BONNET LID LOCK	Not Necessary	376.00 FS	*- FS
52	1		*LOCK CARRIER WITH MOUNTING	Cracked	891.00 FS	*712.80 FS
53	2		*AIR GUIDE - LH / RH	Distorted	52.00 FS	*40.88 FS
54	2		*INNER AIR DUCT - LH / RH	Distorted	28.00 FS	*21.12 FS
55	1		*UPPER AIR GUIDE	Deformed	14.00 FS	*10.56 FS
56	1		*AIR COOLER CHARGE	Distorted	514.00 FS	*411.20 FS
57	1		*AIR COOLER SEAL RING	Not Necessary	79.00 FS	*- FS
58	2		*HOSE CLAMP	Not Necessary	37.00 FS	*- FS
59	1		*A/C CONDENSER	Distorted	550.00 FS	*440.00 FS
60	1		*PRESSURE SENSOR	Not Necessary	170.00 FS	*- FS
61	1		*PRESSURE VALVE	Not Necessary	46.00 FS	*- FS
62	1		*RADIATOR	Distorted	630.00 FS	*503.60 FS
63	2		*SLEEVE	Not Necessary	15.00 FS	*- FS
64	4		*RUBBER BUSH	Necessary	38.00 FS	*30.40 FS
65	4		*COOLANT CONCENTRATE	Necessary	133.00 FS	*65.28 FS
66	1		*BREATHING LINE	Not Necessary	29.00 FS	*- FS
67	1		*FAN RING	Cracked	230.00 FS	*184.00 FS
68	1		*RADIATOR FAN WITH CONTROL UNIT	Distorted	2,055.00 FS	*1,644.00 FS
69	2		*FRONT WINDOW SLOT SEAL - LH / RH	Not Necessary	690.00 FS	*- FS
70	2		*FRONT FENDER TRIM - LH / RH	Necessary	276.00 FS	*220.80 FS
71	2		*FRONT DOOR TRIM - LH / RH	Not Necessary	276.00 FS	*- FS
72	2		*THREE POINT AUTOMATIC SEAT BELT - LH / RH	Not Necessary	1,912.00 FS	*- FS
73	2		*SEAT BELT HEIGHT ADJUSTER	Not Necessary	306.00 FS	*- FS
74	1		*AIR BAG CONTROL UNIT	Not Necessary	1,870.00 FS	*- FS
75	4		*AIRBAG CRASH SENSOR	Not Necessary	545.00 FS	*- FS
76	1		*CENTRAL PROTECTION	Not Necessary	470.00 FS	*- FS
77	1		*INTAKE AIR DUCT - RH	Distorted	18.00 FS	*14.16 FS
78	1		*AIR INTAKE HOSE	Distorted	31.00 FS	*24.80 FS
79	1		*FRONT NO. PLATE	Missing	25.00 FS	*25.00 FS
80	1		*SUNDRIES	Necessary	600.00 FS	*257.60 FS
81	1		*WIRE CONNECTOR	Cracked	11.36 FS	*11.36 FS
82	1		*A/C PIPE	Bent	115.60 FS	*115.60 FS
83	1		*WIRE CONNECTOR	Cracked	5.12 FS	*5.12 FS
84	1		*FLAT CONNECTOR HOUSING	Cracked	12.32 FS	*12.32 FS
85	2		*HEADLIGHT WASHER JET BRACKET - LH / RH	Cracked	19.84 FS	*19.84 FS
86	2		*WASHER JAT SPRING CLIP	Necessary	34.08 FS	*34.08 FS
87	1		*BASE ENGINE	Not Necessary	27,809.00 FS	*- FS
88	1		*OIL SUMP-LOWER PART	Cracked	236.80 FS	*236.80 FS
89	1		*SET OIL SUMP BOLT	Necessary	13.60 FS	*13.60 FS
90	1		*OIL LEVEL SENSOR	Damaged	194.80 FS	*194.80 FS
91	1		*ENGINE OIL	Necessary	210.80 FS	*210.80 FS
92	1		*A/C COMPRESSOR	Cracked	1,861.60 FS	*1,861.60 FS
93	1		*VIBRATION DAMPER	Bent	302.80 FS	*302.80 FS
94	1		*TIMING CASE	Scratched	202.00 FS	*202.00 FS
95	1		*SILICON SEALANT	Necessary	27.52 FS	*27.52 FS
96	1		*POLY-V-BELT	Cut	35.68 FS	*35.68 FS
97	1		*BELT TENSIONER DAMPER	Damaged	102.40 FS	*102.40 FS
98	1		*CHASSIS SHOCK ABSORBER MOUNTING - RH	Bent	43.20 FS	*43.20 FS
99	1		*ENGINE SUMP GUARD	Damaged	396.00 FS	*396.00 FS
100	1		*SUN VISOR - DRIVER SIDE	Not Necessary	394.00 FS	*- FS
101	2		*FRONT BUMPER AIR GUIDE - LH / RH	Distorted	146.00 F	*115.68 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	78,514.52	30,884.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	480.00	480.00
2	TO REMOVE AND RENEW, AIRCON CONDENSER, TURBO COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,100.00	1,100.00
3	TO REMOVE AND REINSTALL CENTER CONSOLE. RENEW BOTH FRONT SEAT BELTS, AIR BAG CONTROL UNIT AND BATTERY CENTRAL PROTECTION	New	1,800.00	0.00
4	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, HEADLIGHTS AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,400.00	4,000.00
5	TO REMOVE BOTH FRONT DOOR PANEL TRIMS, DISMANTLE WING MIRROR ASSY AND RENEW BOTH DOORS CHROME MOLDINGS	New	600.00	600.00
6	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, LHS A-PILLAR. AND BOTH FRONT DOORS	New	5,300.00	3,300.00
7	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
8	TO CUT OUT AND WELD RHS FRONT CHASSIS FRAME STRIKER PLATE. ALIGN TO POSITION	New	900.00	500.00
9	TO RESPRAY RHS FRONT CHASSIS FRAME	New	500.00	300.00
10	TO REMOVE AND RENEW ENGINE ASSY AND DAMAGED ATTACHMENT	New	3,200.00	900.00
11	TO CARRY OUT LTA INSPECTION FOR ENGINE STAMPING	New	300.00	0.00
Gross Labour Cost (S\$)			19,772.00	11,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >