


ESTIMATE

DATE OF ACCIDENT : 24/05/2018
VEHICLE : SLJ1885L
MAKE & MODEL : HONDA VEZEL
INSURANCE : AXA INSURANCE
SURVEYOR : LKK AUTO

PARTS		CONDITION	COST
1.	FRONT RIGHT DOOR / <i>Done</i>		\$ 1580
2.	REAR RIGHT DOOR / <i>Done</i>		\$ 1430
3.	REAR RIGHT DOOR WEATHERSTRIP / <i>Twis</i>		\$ 280
4.	CENTRE WEATHERSTRIP / <i>TN</i>		\$ 420
5.	RIGHT SIDE SKIRT / <i>cut</i>		\$ 420
6.	RIGHT ROCKER PANEL x <i>repair</i>		\$ 780
7.	REAR RIGHT WHEELARCH / <i>scr</i>		\$ 280
8.	REAR RIGHT POWER WINDOW MOTOR ?		\$ 680
9.	REAR RIGHT DOOR POWER WINDOW FRAME ?		\$ 530
SPECIAL NETT			
1.	REAR RIGHT TYRE / <i>cut</i>		\$ 350
2.	FRONT RIGHT RIM x <i>NN</i>		\$ 620
3.	SILICON SEALANT / <i>Done</i>		\$ 200
4.	CLIPS / <i>Done</i>		\$ 100
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	<i>400.</i>	\$ 2000
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	<i>400.</i>	\$ 3200
3.	TO CHECK WIRING & REWIRE	<i>NN X</i>	\$ 180

150



4.	TO REMOVE AND REINSTALL DOORS	120	\$ 500
5.	TO REMOVE & INSTALL POWER WINDOW MECHANICAL & ELECTRICAL PARTS	NNP X	\$ 250
6.	TO REMOVE AND REINSTALL WINDOWS	X	\$ 250
	PARTS - 20% :	\$ 5,120	
	SPECIAL NETT :	\$ 1,270	
	LABOUR :	\$ 6,380	
	TOTAL :	\$ 12,770	
	7% GST :	\$ 893.90	
	GRAND TOTAL :	\$ 13,663.90	

4 Days .

part by part .

before paint photos .

Eric Giau - 82880282

31/5/18

LKK Auto Components hence notify
the keeper of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: