



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SCV870D
Date of Accident : 27 May 2018

Messrs Leong Wah Kee Mini Market

Date : 28 May 2018

Estimate To Repair GBA4237D - Mitsubishi FB70BB1SRDEA
Chassis No : FB70BBA10007

S/No	Quantity	Description	Amount
SPECIAL NETT ITEMS			
01	1 pc	rear bumper under rim with stay D.S	\$ 800.00
02	1 pc	o/s rear lamp SRO	\$ 200.00
03	1 pc	o/s rear lamp panel SRO	\$ 120.00
04	1 pc	rear license plate SRO	\$ 50.00
05	1 pc	rear license plate lamp 11	\$ 60.00
06	1 ps	rear over rider rubber block 11	\$ 120.00
			\$ 1,350.00
LABOUR & MISC. CHARGES			
01		To check electrical lighting concerned.	\$ 80.00
02		repair, realign rear exhaust pipe 11	\$ 180.00
03		Putty and spray painting of the affected portion.	\$ 250.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00
			\$ 910.00
Total			\$ 2,260.00

600
11
14
X
X

20
X
150
300

not Authorised
d/s
2 dy.

30/5/18

Take photo After rep.

KK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: