

INS. CASE OWNER

NY YONG

CC

b UP
ATG1800

A710

A710, A710

LKK

IDAC

Surveyor:

Admin

DOI:

ASSIGNMENT

28/5/18

Date / Time:

Registered in Merimen:

26/5/18
710/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.

SLE 3282L

Name of Insured

URP

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

18/5/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

u sn ymo

Driver Tel No.:

(V/L: ☒ YES / NO)

Claim No.:

:

46656812456

Policy No.:

:

99999999

Make / Model:

:

Honda

Place of Accident:

:

Kong Kong ME 3

OI GIA REPORT (YES / NO):

:

YES / NO

Insured Liability:

:

Final? Yes / No

SET 8700C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

26/6/18 email.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA/ GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

- to close.

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

7,800.00

(6 days)

Reduction:

45

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27.

If NO or B 28, Ass. Lia:

Repair Cost:

SS

8,326.00

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

250.00

(\$ 50 x 7 days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

10.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost:

SS

-

Total:

SS

8,706.00

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

8,706.00

Name 1:

KANG CAR REPAIRERS PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 320.00

COPY SENT

REF:

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKT8260C Yr Regn: 2017, Oct.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan cc 999Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 11687 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZSV1J1013737Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 28/05/18Survey held at KaryDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG26/11/18 Confirm L/S \$7900.00 with 6 working day(Ref = \$663.6
43%)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp. (\$ _____) S + RS _____ SI☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/LCR18009710/Awb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 30-05-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 3283L	Veh. Inspected	SKT 8260C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/05/2018	Inspection Date	28/05/2018
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 18/05/2018
TP Veh Reg No: SLE3283L

Estimate No: EST1800154
Date: 28 May 2018
Veh Reg No: SKT8260C
Make/Model: AUDI A3 SEDAN 1.0TFSI
Chassis No: WAUZZZ8V1J1013737
Reg. Date: 28/10/2017
Your Ref No: SLE3283L

Vivian

Estimate Repair Cost to Vehicle No :SKT8260C

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Buckled.</i>	2,310.00 ✓	
2	1 PC BOOT LID INNER LOCK <i>Damaged</i>	285.00 ✓	
3	1 PC BOOT LID LAMP LH <i>not nec</i>	730.00 x	
4	1 PC BOOT LID LAMP RH <i>crushed</i>	730.00 ✓	
5	1 PC BOOT LID LOGO <i>nec</i>	126.00 ✓	
6	1 PC BOOTLID INNER TRIM <i>2 art</i>	290.00 x	
7	2 PCS BOOT LID HINGE <i>1 nec</i>	340.00 x	
8	1 PC BOOT LID RUBBER <i>nec</i>	220.00 ✓	
9	1 PC TAIL LAMP LH <i>not nec</i>	750.00 x	
10	1 PC TAIL LAMP - RH <i>crushed</i>	750.00 ✓	
11	1 PC REAR PANEL <i>dented</i>	406.00 ✓	
12	1 PC REAR PANEL TRIM <i>deformed</i>	155.00 ✓	
13	1 PC REAR BUMPER <i>deformed</i>	1,697.00 ✓	
14	2 PCS REAR BUMPER SIDE RETAINER <i>nec</i>	8477 150.00 ✓	
15	1 PC REAR BUMPER REINFORCEMENT <i>But</i>	8053.15 554.00 ✓	
16	1 PC REAR BUMPER CENTRE RETAINER <i>not nec</i>	98.00 x	
17	4 PCS REVERSE SENSORS <i>2 pieces damaged</i>	980.00 490 ✓	
18	2 PCS REAR BUMPER REFLECTOR <i>not nec</i>	176.00 x	
19	1 PC REAR BUMPER LOWER LIP <i>deformed</i>	286.00 ✓	
20	1 PC REAR TOWING COVER <i>not nec</i>	40.00 x	
21	1 PC EXHAUST PIPE	642.20 x	
22	2 PCS EXHAUST PIPE MOUNTING <i>not nec</i>	82.00 x	
23	1 PC BOOT LID SENSOR <i>Damaged</i>	210.00 ✓	
24	2 PCS REAR BUMPER BOTTOM RETAINER <i>Damaged.</i>	108.00 ✓	
		12,115.20	
		Less 10%	1,211.52 10,903.68
	Special Net		
25	1 PC REAR NUMBER PLATE <i>ent</i>	50.00 ✓	
26	1 SET REAR BOOTLID INNER TRIM CLIPS <i>not nec</i>	40.00 x	
27	1 SET REAR PANEL TRIM CLIPS <i>nec</i>	40.00 10.1 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 18/05/2018
TP Veh Reg No: SLE3283L

Estimate No: EST1800154
Date: 28 May 2018
Veh Reg No: SKT8260C
Make/Model: AUDI A3 SEDAN 1.0TFSI
Chasis No: WAUZZZ8V1J1013737
Reg. Date: 28/10/2017
Your Ref No: SLE3283L

Estimate Repair Cost to Vehicle No :SKT8260C

Quantity	Description	List Price	Amount
		SS	SS
		130.00	130.00
	Labour		
28	1 TO CHECK WIRING	50.00	30
29	1 TO SPRAY UNDERSEAL	180.00	50
30	1 TO REMOVE AND REFIT REVERSE SENSOR	100.00	60
31	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	200.00	*
32	1 (REAR) TO SPRAY PAINTING	1,200.00	800
33	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00	800
		2,930.00	2,930.00
	Total	SS 13,963.68	
	Add GST @ 7%		977.46
	Total Amount Payable	SS 14,941.14	

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND NINE HUNDRED FORTY ONE AND CENTS FOURTEEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

tel 985315
t/s 7.9K
(7.9K)

Akhan King
t/s 28/05/18
06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Print Received Message

This mail is associated with :

***SKT8260C (4665681274SG)**
[SLE3283L]

TP
ONG TECK WEE
May 18 2018 6:00PM
[LCRF PTE LTD]
Kang Car Repairers Pte Ltd

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on **05/03/2019 09:15 AM**.
To **LKK_HQ**
Subject **Alert - Adj Mandate Approved (S\$8706.00) - SKT8260C - Claim Handler: Yong, Ivy-AV**

Approved:8706.00.

Vic (LKKAUTO)

From: Yong, Ivy-AV <Ivy-AV.Yong@aig.com>
Sent: Tuesday, 26 February, 2019 2:50 PM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: RE: <SEEK MANDATE> Your Ref: 4665681274SG_ACCIDENT INVOLVING VEHICLES SLE 3283L (OI) AND SKT 8260C (TP) ON 18/05/2018 LKK REF CC6/LCR18009710/Ahb3

Hi Vic,

Kindly offer COR at \$8,132.00 and start from low.

The rest of the items agreed as per your recommendation.

Thank you

Ivy Yong
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +64191637
Ivy-AV.Yong@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Tuesday, February 26, 2019 11:25 AM
To: Yong, Ivy-AV <Ivy-AV.Yong@aig.com>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: <SEEK MANDATE> Your Ref: 4665681274SG_ACCIDENT INVOLVING VEHICLES SLE 3283L (OI) AND SKT 8260C (TP) ON 18/05/2018 LKK REF CC6/LCR18009710/Ahb3

Dear Ivy,

Marked estimate uploaded in merimen.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Yong, Ivy-AV [<mailto:ivy-AV.Yong@aig.com>]

Sent: Tuesday, 26 February, 2019 11:15 AM

To: Vic (LKKAuto)

Cc: Admin A

Subject: RE: <SEEK MANDATE> Your Ref: 4665681274SG_ACCIDENT INVOLVING VEHICLES SLE 3283L (OI) AND SKT 8260C (TP) ON 18/05/2018 LKK REF CC6/LCR18009710/Ahb3

Hi Vic,

Please let us have your marked estimated COR.

Thank you

Ivy Yong

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +64191637

Ivy-AV.Yong@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use

From: Vic (LKKAuto) [<mailto:vicalpeh@lkkauto.com>]

Sent: Tuesday, February 26, 2019 11:04 AM

To: Yong, Ivy-AV <Ivy-AV.Yong@aig.com>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: <SEEK MANDATE> Your Ref: 46656812745G_ACCIDENT INVOLVING VEHICLES SLE 3283L (OI) AND SKT 8260C (TP) ON 18/05/2018 LKK REF CC6/LCR18009710/Ahb3

Your Ref: 46656812745G

Our Ref: CC6/LCR18009710/Ahb3

Dear Ivy,

ACCIDENT INVOLVING VEHICLES SLE 3283L (OI) AND SKT 8260C (TP) ON 18/05/2018

We refer to the subject matter.

It was reported that Insured vehicle had rear-ended to the TP vehicle.

An email was sent out to the Insured to notify TP claim and no further feedback till to date.

Summary to offer to repairer **KANG CAR REPAIRERS PTE LTD** is as follows:

TP CLAIMED		REVISED - TO OFFER
Cost of Repair (w/gst)	\$ 15,589.30	\$ 8,453.00
Loss of Use (\$100 x 7 days)	\$ 700.00	\$ 350.00 (\$50 x 7 days)
LTA Search Fee	\$ 10.00	\$ 10.00
TOTAL	\$ 16,299.30	\$ 8,813.00

Breakdown of days is as follows:

Recommended days	6 Days
Weekends / Downtime	1 Days
TOTAL	7 Days

Relevant supporting claim documents are uploaded in merimen for your perusal.

For your approval and/or further instruction please.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient,

you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

Our Ref : KCR0520188260AIG
Your Ref : SLE3283L

Date : 26 SEP 2018

WITHOUT PREJUDICE

AIG Asia Pacific Insurance Pte Ltd
C/O LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933
Attention : Motor Claim Department

Dear Sirs,

Accident involving SKT8260C and SLE3283L on 18.05.2018 along Hougang Ave 5.

We refer to the above accident. On our record showed that you are the insurer of motor vehicle SSLE3283L.

We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense.

On behalf of and as authorized by Mr Ong Teck Wee, the owner of motor-vehicle no: SKT8260C, we submit his claim to you:

Cost of repairs (Inclusive of 7% GST)	\$ 8,453.00
Loss of use (7 days (6 +1Sunday)x \$100.00)	\$ 700.00
LTA search by law firm	\$ 10.00
	\$ 9,163.00
	=====

Enclosed herewith are copies of the following documents in support of our client's claim:

- 1) Tax invoice no: KCR-INV1800571
- 2) GIA report and certificate insurance of SKT8260C
- 3) Police Report No : T/20180519/7002
- 4) LTA search fee & invoice from A C Syed & Partners

We hope to receive your early reply soon.

Thank you.

Yours faithfully,
KANG CAR REPAIRERS PTE LTD

.....

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Thursday, 14 June, 2018 11:12 AM
To: 'eyap@lioncityrentals.com.sg'; 'insurance@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: ACCIDENT INVOLVING SLE 3283L AND SKT 8260C ON 18/05/2018

Our Ref: CC6/LCR18009710/Awb3

14 June 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLE 3283L AND SKT 8260C ON 18/05/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Ong Teck Wee ("the third party claimant")
of Blk 269B Punggol Field #10-197 S822269 (address),
owner of SKT8260C (vehicle no.) hereby authorize
Kang Car Repairers Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKT8260C that was
damaged pursuant to the accident which occurred on 18.05.2018 (date) along
Hougang Ave 5 (location)
involving vehicle no/s SLE3283L ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment fortherto settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this _____ day of -5 MAR 2019 (month) 20____ (year)



Signed by "the third party claimant"

KANG CAR REPAIRERS PTE. LTD.



Signed by "the workshop"

This Discharge Voucher applies strictly for Claimant's claim for personal-injury/property damages only and does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident. This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **KANG CAR REPAIRERS PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$8,346.00** (Repair Cost), **S\$350.00** (Loss of Rental/Use), **S\$10.00** (Disbursement), for vehicle no. **SKT 8260C** that was damaged pursuant to the accident which occurred on **18/05/2018** (date) along **HOUGANG AVENUE 5** (location) involving vehicle no/s **SLE 3283L**. This is pursuant to the inspection conducted on **28/05/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **ONG TECK WEE** ("the third party claimant") of vehicle no. **SKT 8260C** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SKT 8260C** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.


- 5 MAR

Dated this _____ (day) of _____ (month) **2019** (year)

 LKK
LWP

Signed by appointed surveyor

KANG CAR REPAIRERS PTE. LTD.


Signed by "the workshop" (with chop)



江氏修理汽車私人有限公司
KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120

TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Your Ref No: SLE3283L
Claim Type: Third Party
Accident Date: 18/05/2018
TP Veh Reg No: SLE3283L

Final No: KCR-INV1800571
Claim No: EST1800154
Date: 25 Sep 2018
Policy No: 1700079711
Veh Reg No: SKT8260C
Make/Model: AUDI A3 SEDAN
1.0TFSI
Chassis No: WAUZZZ8V1J1013737
Engine No: CHZ531218
Reg. Date: 28/10/2017

Tax Invoice to Vehicle No :SKT8260C

Description	Quantity	List Price	PAGE:1
			Amount
		SS	SS

As recommended by surveyor to proceed repair at total cost/lumpsum cost	S\$ 7,900.00
Add GST @ 7%	553.00
Total Amount payable	S\$ 8,453.00

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FOUR HUNDRED FIFTY THREE ONLY

For Kang Car Repairers Pte Ltd

E. & O. E.


AUTHORISED SIGNATURE

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS
COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : KANG CAR REPAIRERS PTE LTD	BILL NO: B048 /2018
YOUR REF:	
OUR REF : ACS.KC.LTA.MAY.2018	DATE : 7/6/18
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.	
<u>LTA SEARCHES FOR THE MONTH MAY 2018</u>	
1. GBD 5711D as at 2.5.18	\$ 10.00
2. SLE 3283L as at 18.5.18 SKT 8260C	\$ 10.00
3. SLP 6590Y as at 2.5.18	\$ 10.00
4. SLQ 5744Y as at 29.5.18	\$ 10.00
5. EW 8833E as at 19.5.18	\$ 10.00
6. YN 2829T as at 31.5.18	\$ 10.00
Total:	<u>\$ 60.00</u>
[SINGAPORE DOLLARS: SIXTY ONLY.]	
	
M/s A C SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE	
We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. & O.E.	

Enquire Vehicle & Owner Information (Vehicle No. SLE3283L As At 18 May 2018 / 18:00:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: ACS.KC.LTA.05.18

Current Owner Details

Owner ID Type: Company
Owner ID: 2D1624597K
Owner Name: LCRF PTE LTD
Registered Address Type: Private Residential (non-Condo Apt / non-House)
Registered Block/House No.: 60
Registered Street Name: ANSON ROAD
Registered Unit No.: # 11 - 01
Registered Building Name: MAPLETREE ANSON
Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SLE3283L
Make Description/Model: HONDA / VEZEL 1.5X CVT
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2018 Edit Reg		28 May 2018 00:00 Edit Adj Rpt	S\$7,800.00 Edit Estimates	S\$7,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	ONG TECK WEE, ID: S8109829H								
Vehicle Reg. No.:	SKT8260C	Date of Loss:	18/05/2018 18:00 - :59 [6 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4665681274SG	Policy/Cover Note No.:	0999994814 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLE3283L	Policy No. (Claimant):	1700079711						
		Excess:							
Reparer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Ivy-AV] Ivy-VA.Yong@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (05/03/2019): Alert - Adj Mandate Approved (S\$8706.00) - SKT8260C - Claim Handler: Yong, Ivy-A...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKT8260C (4665681274SG)
[SLE3283L]
TP
ONG TECK WEE
May 18 2018 6:00PM
[LCRF PTE LTD]
Kang Car Repairers Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <div>View in Browser</div>		
Letters/Correspondences												1 per page		<div></div>	<div></div>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)									Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown									1	Edit				
Photos/Images												3 per page		<div></div>	<div></div>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)									Thumbnail		Print			
1	26/02/19 10:52		Chassis Number									1	Load JPG	<div></div>			
2	26/02/19 10:52		General View									1	Load JPG	<div></div>			
3	26/02/19 10:52		General View									1	Load JPG	<div></div>			
4	26/02/19 10:52		General View									1	Load JPG	<div></div>			
5	26/02/19 10:52		General View									1	Load JPG	<div></div>			
6	26/02/19 10:52		General View									1	Load JPG	<div></div>			
7	26/02/19 10:52		General View									1	Load JPG	<div></div>			
8	26/02/19 10:52		General View									1	Load JPG	<div></div>			
9	26/02/19 10:52		General View									1	Load JPG	<div></div>			
10	26/02/19 10:52		General View									1	Load JPG	<div></div>			
11	26/02/19 10:52		General View									1	Load JPG	<div></div>			
12	26/02/19 10:52		General View									1	Load JPG	<div></div>			
13	26/02/19 10:52		General View									1	Load JPG	<div></div>			
14	26/02/19 10:52		General View									1	Load JPG	<div></div>			
15	26/02/19 10:52		General View									1	Load JPG	<div></div>			
16	26/02/19 10:52		General View									1	Load JPG	<div></div>			
17	26/02/19 10:52		General View									1	Load JPG	<div></div>			
18	26/02/19 10:52		General View									1	Load JPG	<div></div>			
19	26/02/19 10:52		General View									1	Load JPG	<div></div>			
20	26/02/19 10:52		General View									1	Load JPG	<div></div>			
21	26/02/19 10:52		General View									1	Load JPG	<div></div>			
22	26/02/19 10:52		General View									1	Load JPG	<div></div>			
23	26/02/19 10:52		General View									1	Load JPG	<div></div>			
24	26/02/19 10:52		General View									1	Load JPG	<div></div>			
25	26/02/19 10:52		General View									1	Load JPG	<div></div>			
26	26/02/19 10:52		General View									1	Load JPG	<div></div>			
27	26/02/19 10:52		General View									1	Load JPG	<div></div>			
28	26/02/19 10:52		Reinspection Photo									1	Load JPG	<div></div>			
29	26/02/19 10:52		Reinspection Photo									1	Load JPG	<div></div>			
30	26/02/19 10:52		Reinspection Photo									1	Load JPG	<div></div>			
31	26/02/19 10:52		Reinspection Photo									1	Load JPG	<div></div>			
32	26/02/19 10:52		Reinspection Photo									1	Load JPG	<div></div>			
33	26/02/19 10:52		Reinspection Photo									1	Load JPG	<div></div>			
34	26/02/19 10:52		Reinspection Photo									1	Load JPG	<div></div>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/02/19 10:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	26/02/19 10:53	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/05/18 09:32	TP GIA REPORT	Load PDF	
2	14/06/18 11:11	Email letter to OIACCIDENT INVOLVING SLE 3283L AND SKT 8260C ON 18.05.2018	Load PDF	
3	12/12/18 14:52	LTA SEARCH	Load PDF	
4	26/02/19 11:24	TP ESTIMATE - MARKED	Load PDF	
5	27/02/19 16:52	EMAIL FROM AIG	Load PDF	
6	08/03/19 15:34	WORKSHOP INVOICE	Load PDF	
7	08/03/19 15:34	AUTHORISATION TO ACT FORM	Load PDF	
8	08/03/19 15:34	Release Voucher	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/06/18 13:26	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLE3283L (Insd veh)	Model:	AUDI A3 2.0 TFSI (A)
	SKT8260C (TP veh)		
Date of Accident:	18/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		15,589.30
Final Repair Cost	:	\$		8,346.00
Loss of Use	:	\$		350.00
				7.00 days at \$50.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		10.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		8,706.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kang Car Repairers Pte Ltd	:	\$ 8,706.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

08 Mar
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18009710/AHB3Q2

Date: 08/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994814
Claimant Vehicle No : SKT8260C **Insured Vehicle No :** SLE3283L
 Date of Loss: 18/05/2018 Nature of Claim: TP Claim No: 4665681274SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT8260C**
 Make & Model: AUDI A3, 2.0 TFSI (A) Engine No: CHZ531218
 Reg. Date: 28/10/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V1J1013737
 Colour: Grey Odometer: 11689 km
 Engine Capacity: 999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,639.44	8,113.15	3,526.29	30.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,740.00	1,190.00	40.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,569.44	9,853.15	4,716.29	32.37
Approved Total (Overridden) (S\$)		7,800.00		
(S\$)	14,569.44	7,800.00	6,769.44	46.46
+ GST 7.00/7.00% (S\$)	1,019.86	546.00	473.86	46.46
Nett Amount (S\$)	15,589.30	8,346.00	7,243.30	46.46
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		10.00		
Nett Liability (S\$)		8,706.00		

INSPECTION

Date of Assignment: 28/05/2018
 Date Inspected: 28/05/2018 Inspected At: Kang Car Repairers Pte Ltd (HQ)
 No 1 Kaki Bukit Ave 6, #02-06

AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	2,310.00 FL	*2,310.00 FL
2	1		*BOOT LID INNER LOCK	Damaged	285.00 FL	*285.00 FL
3	1		*BOOT LID LAMP LH	Not Necessary	730.00 FL	*- FL
4	1		*BOOT LID LAMP RH	Cracked	730.00 FL	*730.00 FL
5	1		*BOOT LID LOGO	Necessary	126.00 FL	*126.00 FL
6	1		*BOOTLID INNER TRIM	Not Necessary	290.00 FL	*- FL
7	2		*BOOT LID HINGE	Not Necessary	340.00 FL	*- FL
8	1		*BOOT LID RUBBER	Necessary	220.00 FL	*220.00 FL
9	1		*TAIL LAMP LH	Not Necessary	750.00 FL	*- FL
10	1		*REAR PANEL	Dented	406.00 FL	*406.00 FL
11	1		*TAIL LAMP RH	Cracked	750.00 FL	*750.00 FL
12	1		*REAR PANEL TRIM	Deformed	155.00 FL	*155.00 FL
13	1		*REAR BUMPER	Deformed	1,697.00 FL	*1,697.00 FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	150.00 FL	*150.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Bent	554.00 FL	*554.00 FL
16	1		*REAR BUMPER CENTRE RETAINER	Not Necessary	98.00 FL	*- FL
17	4		*REVERSE SENSORS	Damaged (2 PCS ONLY)	980.00 FL	*490.00 FL
18	2		*REAR BUMPER REFLECTOR	Not Necessary	176.00 FL	*- FL
19	1		*REAR BUMPER LOWER LIP	Deformed	286.00 FL	*286.00 FL
20	1		*REAR TOWING COVER	Not Necessary	40.00 FL	*- FL
21	1		*EXHAUST PIPE	Not Necessary	642.20 FL	*- FL
22	2		*EXHAUST PIPE MOUNTING	Not Necessary	82.00 FL	*- FL
23	1		*REAR NUMBER PLATE	Cut	50.00 FS	*50.00 FS
24	1		*SET REAR BOOTLID INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
25	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*10.00 FS
26	1		*BOOT LID SENSOR	Damaged	210.00 FL	*210.00 FL
27	2		*REAR BUMPER BOTTOM RETAINER	Damaged	108.00 FL	*108.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,245.20	8,537.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	605.76	423.85
Total Parts (\$\$)	11,639.44	8,113.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY UNDERSEAL	New	180.00	50.00
3	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	60.00
4	TO REMOVE AND REFIX REAR EXHAUST PIPE	New	200.00	0.00
5	(REAR) TO SPRAY PAINTING	New	1,200.00	800.00
6	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,200.00	800.00
Gross Labour Cost (S\$)			2,930.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >