

United

53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934

Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg

UEN No. 201729521C | GST Registered No: 2017259521C

AIG ASIA PACIFIC INSURANCE PTE LTD *Benm*
78 Shenton Way
#08-16
Singapore 079120
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : *GBG* ~~GBG~~2107C
MAKE MODEL : NISSAN NV 350
REFERENCE : USG-201805-15
DOA : 25-May-18
CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

REAR BUMPER <i>Defect</i>	1	\$	632.70	✓
FLOOR PANEL <i>Rep</i>	1	\$	1,883.20	+
END PANEL OUTER <i>Defect</i>	1	\$	347.60	✓
END PANEL INNER <i>Rep</i>	1	\$	561.60	+
TAILGATE <i>Defect</i>	1	\$	2,181.40	✓

3161.7
2213.19

\$ 5,606.50
LESS 30% \$ 1,681.95
SUBTOTAL \$ 3,924.55
BALANCE C/F \$ 3,924.55

BALANCE B/F \$ 3,924.55

REAR BUMPER SIDE HOLDER <i>new</i>	2	\$	30.00	✓
REAR BUMPER CHECKER PLATE <i>Best</i>	1	\$	162.80	✓
REAR EXHAUST SILENCER <i>3 new</i>	1	\$	718.00	+
REAR EXHAUST MOUNTING	2	\$	46.00	+
FLOOR PANEL TOP BEAM <i>new</i>	1	\$	304.50	+
TAILLAMP <i>2H carload</i>	2	\$	481.50	240.75
TAILGATE EMBLEM LOGO <i>3 new</i>	1	\$	45.60	✓
TAILGATE EMBLEM NV350	1	\$	77.40	✓
TAILGATE CHROME GARNISH <i>new</i>	1	\$	443.50	+
TAILGATE ABSORBER <i>new</i>	2	\$	375.00	+
TAILGATE WEATHERSTRIP <i>at</i>	1	\$	95.00	✓
TAILGATE LOCK <i>2 new</i>	1	\$	281.50	✓
TAILGATE LOCK STRIKER <i>3 new</i>	1	\$	30.00	+
TAILGATE HINGE	2	\$	120.00	+
TAILGATE INNER TRIM	1	\$	131.00	+

933.05
839.74

\$ 3,341.80
LESS 10% \$ 334.18
SUBTOTAL \$ 3,007.62
BALANCE C/F \$ 6,932.17

ESTIMATION QUOTE

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 Shenton Way
 #08-16
 Singapore 079120
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : GZ5652R
MAKE MODEL : NISSAN CABSTAR
REFERENCE : USG-201805-18
DOA : 26-May-18
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

BALANCE B/F \$ 6,932.17			
REAR NUMBER PLATE <i>men</i>	1	\$ 60.00	<i>X</i>
REAR BUMPER CLIP <i>m</i>	1 SET	\$ 50.00	<i>30</i>
REAR REVERSE SENSOR <i>P-2</i>	1 SET	\$ 400.00	<i>200</i>
JOINT SEALANT <i>Reu</i>	1	\$ 150.00	<i>60</i>
WINDSCREEN SEALANT <i>Reu</i>	1	\$ 150.00	<i>60</i>
<i>350</i> SUBTOTAL		\$ 810.00	
BALANCE C/F \$ 7,742.17			

BALANCE B/F \$ 7,742.17			
CHECK REAR WIRING AND LIGHTNING SYSTEM	1	\$ 60.00	<i>50</i>
REMOVE AND RENEW REAR REVERSE SENSOR	2	\$ 120.00	<i>50</i>
REMOVE AND REFIT REAR LINING TRIM AND GARNISH	3	\$ 200.00	<i>60</i>
REMOVE AND RENEW REAR EXHAUSY ASSY	4	\$ 150.00	<i>A.</i>
REMOVE AND REFIT REAR WINDSCREEN	5	\$ 150.00	<i>120</i>
TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	6	\$ 200.00	<i>80</i>
PANEL BEATING ON AFFECTED AREAS	7	\$ 1,000.00	<i>80</i>
SPRAY PAINTING ON AFFECTED AREAS	8	\$ 1,000.00	<i>800</i>
APPLY ANTI RUST ON AFFECTED AREAS	9	\$ 150.00	<i>40</i>
<i>1580</i> SUBTOTAL		\$ 20,134.34	

GRAND TOTAL \$ 27,066.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5382.93

L/S: 4.3K

Adrian Lim

w/s 06 Days