

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLN2196P

TP/MG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1890612/YISHUN

Date: 04 Jun 2018

Policy No: 1700005499-01

Veh Reg No: SLN2196P

Make/Model: MAZDA MAZDA5 5-
DOOR WAGON 2.0L
SP.6EAT

Chassis No: JM6CW1071G0125183

Engine No: PE10439953

Reg. Date: 26/04/2017

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 25/05/2018

TP Veh Reg No: SKN3286T

Not Withheld

*1-B1
Primary B&P*

Estimate Repair Cost to Vehicle No :SLN2196P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	915.70	1 PC	915.70	✓
2 REAR BUMPER REINFORCEMENT	148.00	1 PC	148.00	✓
3 REAR BUMPER CLIPS	6.90	6 PCS	41.40	✓
			1,105.10	
		Less 20%	221.02	884.08
Special Net				
4 REVERSE SENSOR	200.00	1 SET	200.00	✓
			200.00	200.00
Labour				
5 PANEL BEATING	400.00	1 LA	400.00	300
6 PUTTY & RESPRAY	500.00	1 LA	500.00	400
			900.00	900.00
Total				S\$ 1,984.08
Add GST @ 7%				138.89
Total Amount Payable				S\$ 2,122.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE