

ASS. REC. BY:

REF:

C8/FCI18009716/Uqd3⁷²

Special Instructions:

Survivor:

From (Person):

Marcos
Lurene jaw

ASSIGNMENT (Office)

FCI

Date/Time: 3/15/18 @ 11:41am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 5146X

Insured:

8HC 0729X

at Workshop n/s

NPH Auto

Tel:

678 40663

of

Blk 900S Tampines Street 93 # 01-246/254

Claim No:

D18004225 MFSTH

Policy No:

Sum Insured:

Excess:

D.O.A. 2475/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

11:51am @ 3/15/18

Person Contacted:

Peggy

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

01/6/18 @ 4:53pm Varied to Lurene by email.

03/11/13 Wof

ASS. REC. BY: Marcus

REF: fu/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: G335146X
at Workshop m/s: NPM
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: sk.
IDAC Accident Report: Consistent? : Yes or No
GLA / PR Seen: Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Turn Sum: 20 % \$ Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: G335146X Yr Regn: 5109
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: FIAT FIORINO c.c. 1248
Colour: Sher A/C: Insured / Std / NI / NA
Sp. Reading: 153609 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ZFA2250000059556
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Good / Jammed / Leaked / Burnt or
Brake: Good / Jammed / Leaked / Burnt or
Modi: Good / STD A/Rim or
Tyre Size: F: 185/65-R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: 6 mm Rear: 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 24/5/18 D.O.I. 31/5/18
Survey held at _____
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>214 627</u>	<u>11 months plus</u>
<u>4/6/18</u>	<u>2/542530 continued with Reg 1 Red 51400, 3627</u>
RECEIVED 08 JUN 2018	

Date/Time, File Pass to? ☐ : Prelim. Report
1/05/16 fu/ ☐ : Final Report
Date/Time, File Return to? _____

Days Of Repair: 4
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	130
Transportation:	50
\$ - RG - SI	50
Photos	58
Others	
TOTAL	288

Report Format: 7P
Lump Sum / I.B.I: (\$ 2550)

MOTOR SURVEY ASSIGNMENT

Date	28-05-2018	Our Ref No. D18004225MFSH
Accident Date	24-05-2018	Claim Type. Third Party
Insured Vehicle	SHC0729X	Third Party Vehicle. GBB5146X
Survey Location	BLK 9005 TAMPINES STREET 93 #01-246/254	
Contact Person.	PEGGY FOO	Fax No. 67840692
Contact No.	67840663/ 0	
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	NPH AUTO SERVICE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 1 June 2018 4:53 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004225MFSH/1
Attachments: CSFCI18009716Uqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of GBB 5146X.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 31 May 2018 11:52 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004225MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 31 May 2018 11:40 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004225MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004225MFSH

Date: 01 June 2018

Our Ref: CS/FC118009716/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBB 5146X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/05/2018 at the premises of M/s NPH AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ 3,934.00 .
Revised Estimate Amount	: S\$ 3,215.50 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Article](#)

Up to 64% off Car Insurance
with SG's No. 1 Motor Insurer

Receive \$150
shopping vouchers*

FIND OUT MORE

Fiat Fiorino

Price Range ▼

Depreciation ▼

2009 ▼

Vehicle Type ▼

Home » Used Cars » GB Auto Pte Ltd » Fiat Fiorino 1.3JTD

Resources

[Car Buying](#)[Car Selling](#)[Car Ownership](#)[Car Aftermarket](#)[On The Move](#)[Lifestyle](#)

Car Tyres



Fiat Fiorino 1.3JTD

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)[Add to Shortlist](#)[Add to Compare](#)[Add a Note](#)[Report Error](#)[More Actions](#)

Car Details

Price	\$10,800	
Depreciation	\$7,370 /yr View models with similar depreciation	?
Reg Date	17-Nov-2009 (1yr 5mths 17days COE left)	
Manufactured	2009	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,248 cc	
Curb Weight	1,220 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	Priced To Sell, Cheapest On The Market, Van In Excellent Condition, No Further Repairs Needed, New Tyres, View It To Believe, Call Or SMS Now To Arrange For A Viewing.	
COE	\$18,110	?
OMV	\$19,024	?
ARF	\$952	?
Dereg Value	\$2,654 as of today (change)	?
No. of Owners	1	?
Type of Veh	Van	
Category	-	
Availability	Available	



Location Ma

Seller Infor

Company

Address

Location

Office No

[Compare](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1391R
Vehicle Details	
Vehicle No.:	GBB5146X
Vehicle to be Exported:	No
Intended De-registration Date:	30 May 2018
Vehicle Make:	FIAT
Vehicle Model:	FIORINO 1.3MJTD (225.2L20)
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	199A20003053452
Chassis No.:	ZFA22500000059556
Maximum Power Output:	-
Open Market Value:	\$18,780.00
Original Registration Date:	13 May 2009
First Registration Date:	13 May 2009
Transfer Count:	2
Actual ARF Paid:	\$939.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 May 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$6,610.00
COE Rebate Amount:	\$627.00
Total Rebate Amount:	\$627.00

The information contained herein is correct as at 30 May 2018

OK



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0048/05/18

Page : 1/2
Date : 28/05/2018

THIRD PARTY CLAIM

M/S : KO HONG CONSTRUCTION PTE LTD
3016 BEDOK NORTH AVE 4
#01-27 EASTECH
SINGAPORE 489947

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : GBB5146X - FIAT FIORINO
INSURED : KO HONG CONSTRUCTION PTE LTD
DATE OF ACCIDENT : 24/05/2018
POLICY NO : DMCG18001713

ENGINE# :
CHASSIS# :

*not adjust
mark
2500
H/S
48 dry
30/5/18
To be paid Agency*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost \$	U/Price \$	Total \$
Replacement of Parts				
1 rear bumper <i>20/22</i>	10	680.00	680.00	680.00
2 rear bumper clip <i>re</i>	10	5.00	5.00	5.00
3 rear bumper reinforcement <i>cr</i>	10	415.00	415.00	415.00
4 rear boot MULTJET emblem <i>re</i>	10	85.00	85.00	85.00
5 rear boot FIORINO emblem <i>re</i>	10	98.00	98.00	98.00
6 rear bumper sponge <i>nz</i>	10	315.00	315.00	315.00
7 rear center panel <i>DD</i>	10	412.00	412.00	412.00
				2,010.00
				-201.00
				\$1,809.00

Less 10%

Total Material

Special Nett Items

8 rear bumper parking sensor <i>shld</i>	10	200.00	200.00	200.00
9 rear boot 70km sticker <i>re</i>	10	10.00	10.00	10.00
				210.00

Total S/Nett

Labour & Misc

1 Remove & install r/lamp, r/bumper, knock r/boot L&R, r/floorboard pabel, cut out & renew r/lamp center panel and restraighten body & chassis.	850.00	<i>600</i>
2 Spray painting.	700.00	<i>600</i>
3 Check wiring system.	25.00	<i>20</i>
4 Remove & install rear boot garnish and carpet.	80.00	<i>60</i>
5 Body lettering.	<i>re</i> 280.00	<i>200</i>
	1,935.00	



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0048/05/18

Page : 2/2
Date : 28/05/2018

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Total Labour				\$1,935.00
Nett Total Before Gst				\$3,954.00

Your faithfully



NPH AUTO SERVICE
(Manager)

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before other spray painting
 - To display damaged parts during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :

Page

: 1/2

Our Ref :

TP0048/05/18

Date

: 28/05/2018

THIRD PARTY CLAIM

M/S :

KO HONG CONSTRUCTION PTE LTD
3016 BEDOK NORTH AVE 4
#01-27 EASTECH
SINGAPORE 489947

*not adjust
Mark*

45 2550/-

43 dy

30/5/18

Take photo. Agency

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : GBB5146X - FIAT FIORONO
INSURED : KO HONG CONSTRUCTION PTE LTD
DATE OF ACCIDENT : 24/05/2018
POLICY NO : DMCG18001713

ENGINE# :

CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost \$	U/Price \$	Total \$
<u>Replacement of Parts</u>				
1 rear bumper <i>20/22</i>	10	680.00	680.00	680.00
2 rear bumper clip <i>re</i>	10	5.00	5.00	5.00
3 rear bumper reinforcement <i>one</i>	10	415.00	415.00	415.00
4 rear boot MULTJET emblem <i>re</i>	10	85.00	85.00	85.00
5 rear boot FIORONO emblem <i>re</i>	10	98.00	98.00	98.00
6 rear bumper sponge <i>re</i>	10	315.00	315.00	315.00
7 rear center panel <i>207</i>	10	412.00	412.00	412.00
				2,010.00
				-201.00
				\$1,809.00
Less 10%				
Total Material				
<u>Special Nett Items</u>				
8 rear bumper parking sensor <i>sheld</i>	10	200.00	200.00	200.00
9 rear boot 70km sticker <i>re</i>	10	10.00	10.00	10.00
				210.00

Total S/Nett

Labour & Misc

1 Remove & install r/lamp, r/bumper, knock r/boot L&R, r/floorboard pabel, cut out & renew r/lamp center panel and restraighthen body & chassis.	850.00
2 Spray painting.	700.00
3 Check wiring system.	25.00
4 Remove & install rear boot garnish and carpet.	80.00
5 Body lettering.	280.00
	1,935.00

Parts: \$1695.00
- 10% = \$169.50

\$1525.50
SN: \$210.00
LB: \$1480.00
\$3215.50

4 sum: \$2550



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref.: CS/FCI18009716/Uqd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date: 08-06-2018



Code: FCI2

Policy Particulars :- THIRD PARTY CLAIM

1.

Insured Veh.	SHC 729X	Veh. Inspected	GBB 5146X
Policy No.		Coverage (\$)	0.00
Claim No.	D18004225MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	31/05/2018

Vehicle Particulars & Condition

2.

Make & Model	FIAT FIORINO (A)	c.c	1248
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	ZFA22500000059556	Colour	SILVER
Odometer	153609	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

Conditions of Tyres

3.

	Size	Make	Balance
R/H Front Tyre	185/65 R15	GOODYEAR	6 mm
L/H Front Tyre	185/65 R15	GOODYEAR	6 mm
R/H Rear Tyre	185/65 R15	GOODYEAR	6 mm
L/H Rear Tyre	185/65 R15	GOODYEAR	6 mm

Description of Damages

4.

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

General Information

5.

Accident Date	24/05/2018	Inspection Date	31/05/2018
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839		

Remarks

5a.

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Estimate Days of Repair

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 5146X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	680.00	680.00
1	REAR BUMPER CLIP	NECESSARY	5.00	5.00
1	REAR BUMPER REINFORCEMENT	CRACKED	415.00	415.00
1	REAR BOOT MULTJET EMBLEM	NECESSARY	85.00	85.00
1	REAR BOOT FIORINO EMBLEM	NECESSARY	98.00	98.00
1	REAR BUMPER SPONGE	NOT FITTED	315.00	-
1	REAR CENTER PANEL	DENTED	412.00	412.00
	LESS 10% DISCOUNT		-201.00	-169.50
			1,809.00	1,525.50
SPECIAL NETT ITEMS				
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	200.00	200.00
1	REAR BOOT 70KM STICKER (SN)	NECESSARY	10.00	10.00
1	BODY LETTERING (SN)	NECESSARY	280.00	200.00
			490.00	410.00
LABOUR				
	REMOVE & INSTALL R/LAMP, R/BUMPER, KNOCK R/BOOT L&R, R/FLOORBOARD PABEL, CUT OUT & RENEW R/LAMP CENTER PANEL AND RESTRAIGHTEN BODY & CHASSIS.		850.00	600.00
	SPRAY PAINTING.		700.00	600.00
	CHECK WIRING SYSTEM.		25.00	20.00
	REMOVE & INSTALL REAR BOOT GARNISH AND CARPET.		80.00	60.00
			1,655.00	1,280.00
GRAND TOTAL			3,954.00	3,215.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CS/FCI18009716/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.