



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLW 9352 L

Parts	(a) Cost / List Price Items	\$	1,108.25
	Plus/Less 25%	\$	277.06
	Total of Cost / List	\$	831.19
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
Total Parts Cost		\$	1,181.19
Labour		\$	1,990.00
Total		\$	3,171.19

Not authorized
Resurvey Required

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : CLIC
Survey conducted on : 28/5/18 at 10 a.m.

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : Le Date: 28/5/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLW 9352 L
Make & Model : TOYOTA PRIUS
Chassis No : ZVW508031139

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper <i>Br / N</i>	1	\$497.50		✓
2	Rear bumper clip <i>M</i>	10	\$40.00		✓
3	Rear bumper side retainer LH <i>Sn</i>	1	\$112.70		X
4	Rear bumper side retainer RH <i>Sn</i>	1	\$112.70		X
5	Rear bumper lower garnish LH	1	\$149.70		?
6	LH rear hub cab <i>Red / G</i>	1	\$195.65		✓
7	LH rear tyre <i>Sn</i>	1	\$350.00	S.N	X
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

JKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLW 9352 L** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,LHR FENDER)	\$800.00	4001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,LHR FENDER)	\$800.00	4001
3	To check wiring	\$50.00	156
4	To remove & refit reverse sensor to assit work load	\$120.00	501
5	To tuff coat <i>nn</i>	\$100.00	x
6	To do wheel alignment	\$120.00	601

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.