

TS

DATE 28/5/2018 15:48

LKF-Kalvin

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover X repair			\$ 562.30
	Front Bumper Bracket Top (RH) X sue			\$ 22.40
	Front Bumper Side Bracket X sue			\$ 14.30
	Front Fender (RH) X repair			\$ 619.00
	Front Fender Shield (RH) X sue			\$ 169.80
	Front Fender Retainer X sue			\$ 9.20
	Front Wheel Hub Cap (RH) - hinged			\$ 150.70
	Front RH Door X repair			
	SUB TOTAL			\$ 1,547.70
	LESS 20%			\$ 309.54
	DISCOUNTED TOTAL			\$ 1,238.16
	Front Door Comfort Logo (RH) ✓ sue			\$ 75.00
	Kalvin Loke 28/5/18 1600L 3 Pys 4/5 After Repair ph			
	Labour Charge			
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 750.00
	Tuff Kote			\$ 50.00
	FRT Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 1,480.00
	ESTIMATE TOTAL			\$ 2,793.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.