



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR FLEXSPEED TECHNOLOGY PTE LTD
71 WOODLANDS AVE 10
#05-07/08 WOODLANDS INDUSTRIAL XCHANGE
SINGAPORE 737743

POLICY NO : THIRD PARTY CLAIM
YOUR REF : SBG 77 T (LONPAC)
OUR REF : TP 6048
VEHICLE NO : GBG 7257 U
MAKE/MODEL : NISSAN NV200
DATE OF ACCIDENT : 28.05.18

SURVEY BY

DATE : 11.07.19

1 PC FRONT BUMPER	DR	S\$	589.70	NETT
1 PC FRONT BUMPER TOWING COVER	x		24.00	"
1 PC FRONT BUMPER SIDE RETAINER LH	DR		24.00	"
1 PC FRONT BUMPER REINFORCEMENT	?		1,004.80	"
		S\$	1,642.50	
		LESS 10%	164.25	
		S\$	1,478.25	

TO CHECK WIRING FUNCTION

S\$ 30.00

LABOUR CHARGES

300.00

TO PUTTY AND SPRAY PAINTING CHARGES

300.00

S\$ 2,108.25

SIN DOLLARS: TWO THOUSAND ONE HUNDRED EIGHT AND CENTS TWENTY-FIVE ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

Steve (LKK) with Minda
2 days 12/7/19, 11.00 am
P/P
Ry Bel Spy

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700
Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg