

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 01 Jun 2018

Preliminary Advice

Vehicle No	: SJQ1925S	Accident Date	: 25/05/2018
Make	: KIA RIO	Policy No.	: MPC18A00091102
Assignment Date	: 30/05/2018	Excess	: S\$500.00
Date of Inspection	: 31/05/2018	Est. Duration of Repair	: 7 days
Inspection At	: Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,235.00
Revised Amount	:S\$	3,376.40
Check Items (Estimated)	:S\$	1,221.00
Total	:S\$	4,597.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	11,000.00
COE / PARF Rebate	:S\$	6,130.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,870.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :