

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3085U

DATE 28/5/2018 9:29

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover X			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 280.00 200	
	Spray Painting Charge			\$ 250.00 250	
	Wiring Charge			\$ 50.00 X	
	R/Refix Reverse Sensor			\$ 120.00 20	
	TOTAL LABOUR			\$ 700.00	
	ESTIMATE TOTAL			\$ 2,411.58	

Veh at 2nd Floor

Kalin 10/11/18

28/5/18 11:15 hrs.

2 Days

PIP

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: