

15/03/2019

INS. CASE OWNER:

CC 3/III1800 9749, T. Wb3sr

LKK:  
IDAC:

Surveyor:

T. Wb3sr

DOI:

ASSIGNMENT

15/6/18


Date / Time:

20/6/18

Registered in Merimen:

20/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 2022

Name of Insured:

LPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

25/6/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

TAN SENG SOON

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MT 18150805

Policy No.:

MOMOO 15

Make / Model:

Hyundai

Place of Accident:

15th Ave, Lrg


OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLV 87002



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
21/6/18	SLV 87002 -x	Non-Reporting ltr (1st):	
21/6/18	SLV 87002 -x	Non-Reporting ltr (2nd):	
21/6/18	SLV 87002 -x	Non-Reporting ltr (Final):	
21/6/18	SLV 87002 -x	Notification ltr (if non-pickup):	
21/6/18	SLV 87002 -x	Call OI:	vinan
21/6/18	SLV 87002 -x	After call ltr to OI:	
21/6/18	SLV 87002 -x	Documentation Check List:	Handler Typist
21/6/18	SLV 87002 -x	Notification ltr (if non-pickup)	<input type="checkbox"/>
21/6/18	SLV 87002 -x	After call ltr to OI:	<input type="checkbox"/>
21/6/18	SLV 87002 -x	Authorisation To Act:	<input checked="" type="checkbox"/>
21/6/18	SLV 87002 -x	Release Voucher:	<input checked="" type="checkbox"/>
21/6/18	SLV 87002 -x	Final Repair Bill:	<input checked="" type="checkbox"/>
21/6/18	SLV 87002 -x	Car Rental Invoice:	<input type="checkbox"/>
21/6/18	SLV 87002 -x	Towing Invoice:	<input type="checkbox"/>
21/6/18	SLV 87002 -x	LTA / GIA:	<input type="checkbox"/>
21/6/18	SLV 87002 -x	Medical Bill:	<input type="checkbox"/>
21/6/18	SLV 87002 -x	PIR:	<input type="checkbox"/>
21/6/18	SLV 87002 -x	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
21/6/18	SLV 87002 -x	LOD	<input checked="" type="checkbox"/>
21/6/18	SLV 87002 -x	Payment Breakdown Form:	<input type="checkbox"/>
21/6/18	SLV 87002 -x	Post-Repair Photos:	<input type="checkbox"/>
21/6/18	SLV 87002 -x	Others:	<input type="checkbox"/>

<b>PRELIMINARY ADVICE</b>		Date/Time:	Sent By:
<b>FINALIZATION</b>		Date/Time:	Confirm with:
Repair Cost:	RP	SS 20,921.80	( 7 days) Reduction: 28 %
<b>FINAL SETTLEMENT</b>		Date/Time: 14.03.19	Confirm with: CAROLINE
Final Liability:	%	100	(Agreed / Assessed) BOLA S/N No.: 27.
Repair Cost:	SS	23,586.33	
Loss of Rental (LOR):	SS	-	( days)
Loss of Use (LOU):	SS	1200.00	(S 100 x 12 days)
Loss of Income (LOI):	SS	-	(S x days)
LOR only <input type="checkbox"/>	LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/>	LOR + LOI <input type="checkbox"/> [Tick only one]
GIA/LTA Search	SS	-	
Medical:	SS	-	
Disbursement:	SS	-	(e.g. Tow/ Independent)
Legal Cost	SS	-	
Total:	SS	23,586.33	Global Sum SS:
<b>FINAL PAYMENT</b>		Date/Time: 14.03.19	Confirm with: CAROLINE
Payee 1:	SS	23,586.33	Name 1: PRE PERFORMANCE MOTORS LIMITED
Payee 2: (Strike if N.A.)	SS	-	Name 2:
Payee 3: (Strike if N.A.)	SS	-	Name 3:

COPY SENT  
18/7/18

- 1) Claim status: Normal/Reject/Private Settle  
 2) Report Format: TP  
 3) Survey fee: P 600



Signature

Tamper

REF:

III

W

# ASSIGNMENT

From:

Date:

12/06/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLV 83002

at Workshop m/s

Performance

of

303 Alexandra

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Han

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.:

Yes or No

Lum Sum:

I.B.2

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Han

Date / Time

Action / Instruction

12/10/18 Confirm 2.B.2 \$20921.80 with 7 working days

Veh No:

SLV 83002

Yr Regn:

2018 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X3

C.C.

1998

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

6994

T/Radio:

Insured / Std / NI / NA

Eng/No:

WKA TR 92070 LA 49022

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/50R19

R:

n n

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

5/12/4/8 @ 12/15

Survey held at

pm L.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

Report Format :

Lump Sum / I.B.1: (\$

Add Fee:

☐

: Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

(Ref. # 808.76 28.1)





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18009749/wb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 30-05-2018		
		Code : III2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 2022Z	Veh. Inspected	SLV 8300Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	30/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	25/05/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Mon 11/06 @ 10am SLV8300Z  
SBR

BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

30 MAY 2018

Estimate No. : b1 47102  
Date Estimated : 28/05/2018  
Prepared By : Han Kwan Yong

Page No. : 1 of 5

### - ESTIMATE REPAIR FOR -

Tan Lay Ling  
83 Parbury Avenue

Singapore 467321

### - ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV8300Z	LA49022	26/01/2018	X3 xDrive30i	0

#### DESCRIPTION

#### VALUE

To replace rear bumper & attachments, boot lid including to knock out tail panel and dent area caused by the accident

2550 3,400.00

To respray rear bumper, boot lid and tail panel

2336 2,749.00

To carry out body cavity preservation.  
(Per panel).

100 118.00

To conduct water leak tests.

63 75.00

To replace front exhaust silencer including align exhaust system and conduct checks for leak.

451? photo 531.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

451? photo 531.00

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

561? 661.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

7 150.00

Total Labour 1: 8,392.00

#### DESCRIPTION

#### QTY PRIC

#### VALUE

C CLIP FOR PLASTIC NUT

10 1.00

not all 10.00

EXPANDING RIVET

10 2.50

25.00

Mounting

3 33.65

100.95

SILENCER CLAMPING BUSH

1 60.60

60.60

MUFFLER CLAMP D=80.0MM

1 41.80

41.80

TAILPIPE TRIM CHROME D=90MM

2 119.20

238.40

REAR SILENCER WITH EXHAUST FLAP

1 1,509.05

1,509.05

22995.56





303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 47102  
Date Estimated : 28/05/2018  
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV8300Z	LA49022	26/01/2018	X3 xDrive30i	0

DESCRIPTION	QTY	PRIC	VALUE
# FRONT SILENCER	1	1,333.55	1,333.55
TRUNK LID	1	1,915.65	1,915.65
REAR BUMPER BOTTOM REINFORCEMENT	1	67.15	67.15
REAR UNDERRIDE GUARD (X LINE)	1	237.20	237.20
REAR BUMPER PANEL PRIMED (X LINE PM)	1	1,437.65	1,437.65
REAR BUMPER CLADDING (PDC)	1	538.65	538.65
EMBLEM GROMMET	2	0.80	1.60
LETTERING X3	1	62.55	62.55
PLAQUE 82MM	1	69.50	69.50
REAR WINDOW GREEN	1	932.05	932.05
REAR SILENCER CENTRE HEAT INSULATION	1	68.70	68.70
REAR SILENCER LH INSULATION	1	68.70	68.70
REAR SILENCER RH INSULATION	1	68.70	68.70
REAR SILENCER HEAT INSULATION	1	68.70	68.70
Undershield	1	76.45	76.45
EXPANDING RIVET	30	1.35	40.50
SENSOR WIRE FOR SMART OPENER TOP	1	42.10	42.10
SENSOR WIRE FOR SMART OPENER BOTTOM	1	40.50	40.50
LH REFLECTOR	1	36.25	36.25
ULTRASONIC TRANSDUCER DARK SHADOW	1	368.80	368.80
DECOUPLING RING PDC TORQUE CONVERTER	5	5.05	25.25
ULTRASONIC SENSOR MINERALWEISS(WA96)	4	368.80	1,475.20
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85

Total Parts : 11,276.00

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 12/118@1215 Claim No. 12/118@1215

Date & Time 12/118@1215 Excess \$ 12/118@1215

Surveyor's Name 12/118@1215 Sign 12/118@1215

Surveyor's Tel 12/118@1215 E-mail 12/118@1215

Authorized Date 12/118@1215 Time 12/118@1215

RESURVEY PARTS PHOTO BY SURVEYOR Yes/No 12/118@1215 PMS Yes/No 12/118@1215

Surveyor's E-mail 12/118@1215

No. of Working Days Recommend 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Labour 1 : 8,392.00

Parts : 1,968 11,276.00

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 1,376.76

Grand Total : 21,044.76

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

27618.80



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 47102  
Date Estimated : 28/05/2018  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Tan Lay Ling  
83 Parbury Avenue

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

Singapore 467321

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV8300Z	LA49022	26/01/2018	X3 xDrive30i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid and attachments, rear underbody panelling include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	
* To respray rear bumper, boot lid and tail end panel	2336.00		2,336.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
To conduct water leak tests.	75.00		75.00	
To replace rear exhaust silencer and attachments include alignment and conducting checks for leak	451.00		451.00	
To replace boot lid smart opener bottom sensor lines include programming and conducting checks on the top sensor lines and control units for proper function	561.00		561.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
* To tow accident vehicle to PML workshop	195.00	✓	195.00	
* To remove and install rear suspension, rear axle and control system for inspection and replacement of damaged parts	2557.00	✓	2,557.00	
* To check steering geometry and conduct wheel alignment in accordance with BMW specifications (2x)	902.00	✓	902.00	
* To replace battery with registering battery replacement, perform high current test and check for function	150.00	✓	150.00	
Sundries	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

# CLIP WITH WASHER GREY *	1.25	10.00	12.50
EXPANDING RIVET	2.50	10.00	25.00
# BLIND RIVET NUT M6 *	2.90	6.00	17.40
SILENCER CLAMPING BUSH	60.60	1.00	60.60
# VIBRATION ABSORBER (42HZ) *	95.95	1.00	95.95
# REAR SILENCER LH BRACKET *	36.25	1.00	36.25
# EXHAUST SYSTEM HOLDER *	23.60	1.00	23.60
# RR SILENCER BRACKET *	23.60	1.00	23.60
TAILPIPE TRIM CHROME D=90MM	119.20	1.00	119.20
REAR SILENCER WITH EXHAUST FLAP	1,509.05	1.00	1,509.05
# COLLAR SCREW *	13.10	1.00	13.10
# REPAIR KIT INSERT NUT *	39.80	1.00	39.80
# LH TOE ARM WITH RUBBER MOUNTING *	131.70	1.00	131.70
# REAR AXLE CARRIER *	2,180.90	1.00	2,180.90
TRUNK LID	1,915.65	1.00	1,915.65
# REAR BUMPER CARRIER *	684.40	1.00	684.40
# LH SIDE GUIDE FOR BUMPER *	60.00	1.00	60.00
REAR BUMPER BOTTOM REINFORCEMENT	67.15	1.00	67.15
REAR UNDERRIDE GUARD (X LINE)	237.20	1.00	237.20
REAR BUMPER PANEL PRIMED (X LINE PM	1,437.65	1.00	1,437.65
REAR BUMPER CLADDING (PDC)	538.65	1.00	538.65
EMBLEM GROMMET	0.80	2.00	1.60
LETTERING X3	62.55	1.00	62.55
PLAQUE 82MM	69.50	1.00	69.50
# BUMP STOP *	3.25	10.00	32.50
REAR SILENCER LH INSULATION	68.70	1.00	68.70
REAR SILENCER HEAT INSULATION	68.70	1.00	68.70
# REAR END UNDERBODY PANELLING *	76.45	1.00	76.45
# (DG/SL) BMW AGM BATTERY (92 AH) *	718.65	1.00	718.65
SENSOR WIRE FOR SMART OPENER BOTTOM	40.50	1.00	40.50
LH REFLECTOR	36.25	1.00	36.25
DECOUPING RING PDC TORQUE CONVERTER	5.05	5.00	25.25
(DG) CLEANER R1 (100ML)	23.85	1.00	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00	27.85

### # SUPPLEMENTARY ITEMS

Total Labour :	10,177.00
Total Parts :	10,744.80
Total Labour & Parts :	20,921.80
Deduction for Excess :	0.00
Total Repair Costs less Excess:	20,921.80
GST @7%:	1,464.53
Grand Total :	22,386.33



# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 47102  
Date Estimated : 28/05/2018  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Tan Lay Ling  
83 Parbury Avenue

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

Singapore 467321

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV8300Z	LA49022	26/01/2018	X3 xDrive30i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLIP WITH WASHER GREY *	1.25	10.00		12.50 net ✓
# BLIND RIVET NUT M6 *	2.90	6.00		17.40 net ✓
# VIBRATION ABSORBER (42HZ) *	95.95	1.00		95.95 dis ✓
# REAR SILENCER LH BRACKET *	36.25	1.00		36.25 bt ✓
# EXHAUST SYSTEM HOLDER *	23.60	1.00		23.60 bt ✓
# RR SILENCER BRACKET *	23.60	1.00		23.60 bt ✓
# COLLAR SCREW *	13.10	1.00		13.10 net ✓
# REPAIR KIT INSERT NUT *	39.80	1.00		39.80 net ✓
# LH TOE ARM WITH RUBBER MOUNTING *	131.70	1.00		131.70 bt ✓
# REAR AXLE CARRIER *	2,180.90	1.00		2,180.90 bt ✓
# REAR BUMPER CARRIER *	684.40	1.00		684.40 bt ✓
# LH SIDE GUIDE FOR BUMPER *	60.00	1.00		60.00 net ✓
# BUMP STOP *	3.25	10.00		32.50 net ✓
# REAR END UNDERBODY PANELLING *	76.45	1.00		76.45 dis ✓
# (DG/SL) BMW AGM BATTERY (92 AH) *	718.65	1.00		718.65 net ✓

Total Labour :	
Total Parts :	4,146.80
Total Labour & Parts :	4,146.80



**Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796501 (AfterSales)  
64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X**

**E S T I M A T E**

Estimate No. : **b1 47102**  
Date Estimated : **28/05/2018**  
Prepared By : **Han Kwan Yong**

Page No. : **3 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLV8300Z</b>	<b>LA49022</b>	<b>26/01/2018</b>	<b>X3 xDrive30i</b>	<b>0</b>

**Terms & Conditions of Service**

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.



# Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : **b1 47102**  
Date Estimated : **28/05/2018**  
Prepared By : **Han Kwan Yong**

Page No. : **4 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLV8300Z</b>	<b>LA49022</b>	<b>26/01/2018</b>	<b>X3 xDrive30i</b>	<b>0</b>

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
  - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
  - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
  - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
  - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
  - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
  - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
  - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
  - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
  - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
  - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
  - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
  - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
  - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.





303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No. : **b1 47102**  
Date Estimated : **28/05/2018**  
Prepared By : **Han Kwan Yong**

Page No. : **5 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLV8300Z</b>	<b>LA49022</b>	<b>26/01/2018</b>	<b>X3 xDrive30i</b>	<b>0</b>

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- (a) put his request in writing;
  - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
  - (c) specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing by way of an email sent to the Vendor;
  - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
  - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer  
Performance Motors Limited

Address:  
Sime Darby Performance Centre  
303 Alexandra Road  
Singapore 159941

Email address:  
dataprotection@pmi.com.sg



## View Received Message

This mail is associated with :

**\*SLV8300Z**  
**[SHA2022Z]**  
TP  
TAN LAY LING  
May 25 2018 6:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on **04/06/2018 11:10 AM**.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$0.00) - SLV8300Z - Claim Handler: Sherini Pillai

Approved:0.00.

### DOCUMENTS SUMMARY

There are no documents.



## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	30 May 2018 17:00	Clim Veh Model Changed	(203868) BMW X3 2.0 (A).	[A] Lau Shu Pei
2	30 May 2018 17:00	Clim Created	Reg No: SLV8300Z. Acct Date: 2018/05/25. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Performance Motors Limited (Alexandra)	[A] Lau Shu Pei
3	30 May 2018 17:00	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	30 May 2018 17:00	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/08	[A] Lau Shu Pei
5	30 May 2018 17:00	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	30 May 2018 17:00	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	30 May 2018 17:00	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Lau Shu Pei
8	31 May 2018 10:11	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	31 May 2018 10:11	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	04 Jun 2018 10:04	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remark: BOLA 27	[A] VIVIAN LAU PEI FENG
11	04 Jun 2018 11:10	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/08	[I] Sherini Pillai
12	04 Jun 2018 11:10	Adj Mandate Set	Approved:0.00.	[I] Sherini Pillai
13	18 Dec 2018 17:14	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
14	18 Dec 2018 17:14	Clim Dtl Modified	Claimant's ID: -> -.	[A] NUR SHAQILAH BTE ABDOL WAHAB
15	18 Dec 2018 17:14	Clim Dtl Modified	JPJ Reg. Date: -> 2018/01/26.	[A] NUR SHAQILAH BTE ABDOL WAHAB
16	18 Dec 2018 17:14	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
17	22 Feb 2019 12:21	Adj Mandate Request	Cur.Req:23586.33:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST: \$22,386.33 + (b) LOU : \$1,200.00 (12days x \$100) Total: a+b = \$23,586.33 VEH MODEL: BMW X3 1998cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.	[A] Asher Sng Rong Yi

Date From  Date To  Audit Type

### ACTIVITY

[04/06/2018 10:04] VIVIAN LAU PEI FENG:  
seek liability via merimen

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2006606	18/12/2018 17:14	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLV8300Z	SHA2022Z	10.70



## Print Received Message

This mail is associated with :

**\*SLV8300Z (MCT18050805)**

**[SHA2022Z]**

TP

TAN LAY LING

May 25 2018 6:00PM

[COMFORT TRANSPORTATION PTE LTD]

Performance Motors Limited

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 04/03/2019 12:22 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$23586.33) - SLV8300Z - Claim Handler: Sherini Pillai

Approved:23586.33.



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 May 2018 <a href="#">Edit Reg</a>		12 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$20,921.80</b> <a href="#">Edit Estimates</a>	<b>S\$20,921.80</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	TAN LAY LING, ID: S7005753J		
Vehicle Reg. No.:	SLV8300Z	Date of Loss:	25/05/2018 18:00 - :59 [3 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18050805	Policy/Cover Note No.:	MCOM0016
Vehicle Reg. No. (Insured):	SHA2022Z	Policy No. (Claimant):	CN871277
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/06/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III\_SG (04/03/2019): Alert - Adj Mandate Approved (S\$23586.33) - SLV8300Z - Claim Handler: Sherini Pi...
- III\_SG (04/06/2018): Alert - Adj Mandate Approved (S\$0.00) - SLV8300Z - Claim Handler: Sherini Pillai

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									










































## Claim Documents

**\*SLV8300Z (MCT18050805)**  
**[SHA2022Z]**  
**TP**  
**TAN LAY LING**  
**May 25 2018 6:00PM**  
**[COMFORT TRANSPORTATION PTE LTD]**  
**Performance Motors Limited**
















































Upload Documents Upload Photos Compose New Letter

View View in Browser ▼









### Photos/Images

3 per page ▼			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	22/02/19 12:19	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	22/02/19 12:19	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
4	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
5	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
6	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
7	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
8	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
9	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
10	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
11	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
12	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
13	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
14	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
15	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
16	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
17	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
18	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
19	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
20	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
21	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
22	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
23	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
24	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
25	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
26	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
27	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
28	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
29	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
30	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
31	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
32	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
33	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
34	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
35	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
37	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
38	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
39	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
40	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
41	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
42	22/02/19 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
43	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	22/02/19 12:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	22/02/19 12:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/05/18 17:00	TP GIA REPORT	 Load PDF	
2	14/06/18 08:55	TP ESTIMATE- MARKED	 Load PDF	
3	19/12/18 09:27	AUTHORISATION TO ACT	 Load PDF	
4	19/12/18 09:27	LOD	 Load PDF	
5	19/12/18 09:27	WORKSHOP INVOICE	 Load PDF	
6	19/03/19 10:43	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	31/05/18 09:05	Singapore Accident Statement	 Load PDF	
2	19/06/18 15:18	TAX INVOICE	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III18009749/T1EB3S2  
**Date:** 19/03/2019

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0016  
**Claimant Vehicle No :** SLV8300Z **Insured Vehicle No :** SHA2022Z  
 Date of Loss: 25/05/2018 Nature of Claim: TP Claim No: MCT18050805

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV8300Z**  
 Make & Model: BMW X3, 2.0 (A) Engine No: 14955099B48B20B  
 Reg. Date: 26/01/2018 (Man. Year: 2017) Chassis No: WBATR92070LA49022  
 Colour: White Odometer: 6994 km  
 Engine Capacity: 1998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/50R19 Rear Tyre Size: 245/50R19  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,572.80	10,894.80	4,678.00	30.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,046.00	10,027.00	2,019.00	16.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>27,618.80</b>	<b>20,921.80</b>	<b>6,697.00</b>	<b>24.25</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,933.32</b>	<b>1,464.53</b>	<b>468.79</b>	<b>24.25</b>
<b>Nett Amount (S\$)</b>	<b>29,552.12</b>	<b>22,386.33</b>	<b>7,165.79</b>	<b>24.25</b>
<b>+ Loss of Use (12.0 x S\$100.00/day) (S\$)</b>		<b>1,200.00</b>		
<b>Nett Liability (S\$)</b>		<b>23,586.33</b>		

### INSPECTION

Date of Assignment: 12/06/2018  
 Date Inspected: 12/06/2018 Inspected At: Performance Motors Limited (Alexandra)  
 303 Alexandra Road, Sime Darby Performance Centre  
 Singapore 159941  
 Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but  
[https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\\_printprt&caseid=712697&extid=273614&CFID=49999713&C...](https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=712697&extid=273614&CFID=49999713&C...) 1/5



*any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2019)
<b>Parts:</b>	M1-SUV	BMW X3 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV8300Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*C CLIP FOR PLASTIC NUT	Not Necessary	10.00 FS	*- FS
2	10		*EXPANDING RIVET	Necessary	25.00 FS	*25.00 FS
3	3		*MOUNTING	Not Necessary	100.95 FS	*- FS
4	1		*SILENCER CLAMPING BUSH	Bent	60.60 FS	*60.60 FS
5	1		*MUFFLER CLAMP D=80.0MM	Not Necessary	41.80 FS	*- FS
6	1		*TAILPIPE TRIM CHROME D=90MM	N/s Dented / O/s Not Necessary	238.40 FS	*119.20 FS
7	1		*REAR SILENCER WITH EXHAUST FLAP	Bent	1,509.05 FS	*1,509.05 FS
8	1		*FRONT SILENCER	Not Necessary	1,333.55 FS	*- FS
9	1		*TRUNK LID	Bent	1,915.65 FS	*1,915.65 FS
10	1		*REAR BUMPER BOTTOM REINFORCEMENT	Bent	67.15 FS	*67.15 FS
11	1		*REAR UNDERRIDE GUARD (X LINE)	Deformed	237.20 FS	*237.20 FS
12	1		*REAR BUMPER PANEL PRIMED (X LINE PM	Deformed	1,437.65 FS	*1,437.65 FS
13	1		*REAR BUMPER CLADDING (PDC)	Deformed	538.65 FS	*538.65 FS
14	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
15	1		*LETTERING X3	Necessary	62.55 FS	*62.55 FS
16	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
17	1		*REAR WINDOW GREEN	Not Necessary	932.05 FS	*- FS
18	1		*REAR SILENCER CENTRE HEAT INSULATIO	Not Necessary	68.70 FS	*- FS
19	1		*REAR SILNECER LH INSULATION	Bent	68.70 FS	*68.70 FS
20	1		*REAR SILENCER RH INSULATION	Not Necessary	68.70 FS	*- FS
21	1		*REAR SILENCER HEAT INSULATION	Bent	68.70 FS	*68.70 FS
22	1		*UNDERSHIELD	Not Necessary	76.45 FS	*- FS
23	1		*EXPANDING RIVET	Not Necessary	40.50 FS	*- FS
24	1		*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	42.10 FS	*- FS
25	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Distorted	40.50 FS	*40.50 FS
26	1		*LH REFLECTOR	Cut	36.25 FS	*36.25 FS
27	1		*ULTRASONIC TRANSDUCER DARK SHADOW	Not Necessary	368.80 FS	*- FS
28	5		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	25.25 FS	*25.25 FS
29	4		*ULTRASONIC SENSOR MINERAL WEISS(WA96	Not Necessary	1,475.20 FS	*- FS
30	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
31	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
32	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
33	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
34	10		*CLIP WITH WASHER GREY	Necessary	12.50 FS	*12.50 FS
35	6		*BLIND RIVET NUT M6	Necessary	17.40 FS	*17.40 FS
36	1		*VIBRATION ABSORBER (42HZ)	Distorted	95.95 FS	*95.95 FS
37	1		*REAR SILENCER LH BRACKET	Bent	36.25 FS	*36.25 FS
38	1		*EXHAUST SYSTEM HOLDER	Bent	23.60 FS	*23.60 FS
39	1		*RR SILENCER BRACKET	Bent	23.60 FS	*23.60 FS
40	1		*COLLAR SCREW	Necessary	13.10 FS	*13.10 FS
41	1		*REPAIR KIT INSERT NUT	Necessary	39.80 FS	*39.80 FS

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*LH TOE ARM WITH RUBBER MOUNTING	Bent	131.70 FS	*131.70 FS
43	1		*REAR AXLE CARRIER	Bent	2,180.90 FS	*2,180.90 FS
44	1		*REAR BUMPER CARRIER	Bent	684.40 FS	*684.40 FS
45	1		*LH SIDE GUIDE FOR BUMPER	Necessary	60.00 FS	*60.00 FS
46	10		*BUMP STOP	Necessary	32.50 FS	*32.50 FS
47	1		*REAR END UNDERBODY PANELLING	Deformed	76.45 FS	*76.45 FS
48	1		*(DG/SL) BMW AGM BATTERY (92 AH)	Not Working	718.65 FS	*718.65 FS

F=Franchise part, S=SpcNett.

**Total Parts (S\$) 15,572.80 10,894.80**

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS, BOOT LID INCLUDING TO KNOCK OUT TAIL PANEL AND DENTED CAUSED BY THE ACCIDENT.	New	3,400.00	2,550.00
2	TO RESPRAY REAR BUMPER, BOOT LID AND TAIL PANEL.	New	2,749.00	2,336.00
3	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL).	New	118.00	100.00
4	TO CONDUCT WATER LEAK TESTS.	New	75.00	75.00
5	TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGN EXHAUST SYSTEM AND CONDUCT CHECKS FOR LEAK.	New	531.00	0.00
6	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.	New	531.00	451.00
7	TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.	New	661.00	561.00
8	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
9	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP.	New	195.00	195.00
10	TO REMOVE AND INSTALL REAR SUSPENSION, REAR AXLE AND CONTROL SYSTEM FOR INSPECTION AND REPLACEMENT OF DAMAGED PARTS,	New	2,557.00	2,557.00
11	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE BMW SPECIFICATIONS.	New	902.00	902.00
12	TO REPLACE BATTERY WITH REGISTERING BATTERY REPLACEMENT, PERFORM HIGH CURRENT TEST AND CHECK FOR FUNCTION.	New	150.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>12,046.00</b>	<b>10,027.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >