

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0783/2018
DATE : 28-MAY-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : DR. YEOH CHENG EE
ADDRESS : 2 ESSEX ROAD #10-04

S(309330)
TELEPHONE NO : 9769 3225

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 2100448398-02
VEHICLE NO : SCF3278D
MODEL CODE : SJ5CK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y152918
CHASSIS NO : JF1SJ5KC5FG062414
MILEAGE : 1 KM
DATE IN : 28/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 25/05/2018

Print Date : 28/05/2018
Print Time : 18:36:39

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SCF3278D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ODCLAIM	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AIG LOCATION:CLAYMORE RD,OUTSIDE AMERICAN CLUB DATE:25/05/2018 TIME:1220HRS		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER,HOOD AND PANEL 250	1000.00	500 - 750
4	ZZ/003	RESPRAY FRONT BUMPER,HOOD AND PANEL 200	800.00	400
5	ZZ/004	TO CONDUCT FRONT PROTECTANT COATING	250.00	X
6	ZZ/005	REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	125.00	80.
7	ZZ/006	SUNDRIES	100.00	X
TOTAL LABOUR CHARGES			2275.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCF3278D

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1 HOOD F CPL /	57229SG0009P			882.00	
2 HINGE COMPL F HD RH X	57260SG0009P			43.20	
3 HINGE COMPL F HD LH X	57260SG0109P			43.20	
4 LOCK ASSY F HOOD RHD ?	57310SG000			54.00	
5 STRIKER X	57311AG010			36.00	
6 BUMPER FACE F NA (FOR H/L WSH) - Re	57709SG001			594.00	
7 BACK BEAM CPL F ?	57711SG0009P			288.00	
8 ENERGY ABSOR F / BT.	57722SG020			126.00	
9 COVER HOOK F ST X	57731SG000			7.20	
10 INSULATOR HOOD NA X	90815SG051			79.20	
11 GRILLE ASSY F UPRSTD NA ?	91121SG001			108.00	
12 GRILLE ASSY F CTRSTD NA ?	91121SG020			108.00	
13 GRILLE ASSY F LWRSTD NA ?	91121SG030			216.00	
14 FRONT NUMBER PLATE / BT	WM001			45.00	
SUB TOTAL		0.00	0.00	45.00	2584.80
LESS DISCOUNT (S/LIST-30 %)		0.00	0.00	0.00	775.44
GRAND TOTAL		0.00	0.00	45.00	1809.36
OVERALL TOTAL		1854.36			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

Lamp Assy Head LH 84002SG011 2160.00 / BR.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SCF3278D

TOTAL LABOUR CHARGES	2275.00	
TOTAL SPARE PARTS CHARGES	1854.36	

GRAND TOTAL	4129.36 *	5641.36

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Guo Qiang - 82880282
SURVEYED DATE	:	31/5/18
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	Guo Qiang @ lkk auto. com
		Excess : TBA .
		Not Authorised .
		4 Days . before paint photos .

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

<u>LKK Auto Consultants</u> hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: