

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

30 MAY 2018

Estimate No. : **b1 47113** Page No. : **1 of 5**
Date Estimated : **28/05/2018**
Prepared By : **Kevin Leong Wai Kit**

- ESTIMATE REPAIR FOR -
Dilys Charmaine Boey Mengyi
28 Jalan Bahasa

Singapore 299309

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN2007B	G636028	06/02/2018	540iA xDRIVE TOURING	0

DESCRIPTION	VALUE
To replace rear bumper assembly & all attachments cause by accident.	850 2,550.00
Painting on rear bumper assembly	934 1,038.00
To replace tyre and wheel rim including balancing. (1x).	80 94.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 80.00
Total Labour 1:	3,939.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM ORBITGREY 9JX20 V SPK 759	1	2,167.45	art ✓ 2,167.45
REAR BUMPER CARRIER	1	793.55	✓ 793.55
EXHAUST SUPPORT	1	47.45	✗ 47.45
Guide, rear	1	54.40	✗ 54.40
Guide, cente	1	60.05	✗ 60.05
Bumper trim	1	1,587.75	Rx 1,587.75
Kit, mount f	1	62.95	? 62.95
DECOUPLING RING PDC TORQUE CONVERTER	6	5.05	? 30.30
Total Parts :			4,803.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47113	Page No. : 2 of 5
Date Estimated : 28/05/2018	
Prepared By : Kevin Leong Wai Kit	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN2007B	G636028	06/02/2018	540iA xDRIVE TOURING	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 6/7/18 Excess S\$ _____

Surveyor's Name Tan Jiah Sign [Signature]

Surveyor's Tel 97495709 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR / No PML Yes / No _____

Surveyor's E-mail tanjiah@lkkauto.com

No. of Working Days Recommend 3-4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	3,939.00
Parts	:	4,803.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	612.00
Grand Total	:	9,354.90

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **