

ASS. REC. BY

REF

es/SM018009755/Dtd3

n2

Special Instruction:

Surveyor

Bryan

ASSIGNMENT (Office)

From (Person):

Cruee Leo

890

Date/Time:

30/5/18 @ 2:41pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 6580L

Insured:

CB 7671X

at Workshop m/s

Teamwork Garage

Tel:

6844 2475

of

53 Ybi Ave 1 # 01-23/24

Policy No:

Claim No:

CMTD1802242 / AGC

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/5/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup)

H.O.D. Endorsement:

Date/Time:

3:02pm @ 20/5/18

Person Contacted:

Sue

Vehicle:

IN / OUT

Date/Time

Action/Instruction ( ) Estimate

SKU 6580L - NA / EQ 18009516 / 24

DOA: 25/5/18

CB 7671X - NA / EQ 18009516 / 24

DOA: 25/5/18

R/S

Finalised at \$20000/- (Red: 16068.75; 44%)

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh. \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 21 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No. **8KU6580L** Yr Regn. **2015 August**  
 Type **Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make **Toyota Corolla Altis** C.C. **1598**  
 Colour **Grey** A/C Insured / Std / NI / NA  
 Sp. Reading **196076** T/Radio: Insured / Std / NI / NA  
 Eng/No: **12RX521023**  
 C/No: **MR053REH104535755**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / **SR** / STD A/Rim or  
 Tyre Size: F: **205/55 R16**  
 R: **— " —**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Dunlop**  
 Front Rear  
 R/Bal. **S** mm R/Bal. **S** mm  
 L/Bal. **S** mm L/Bal. **S** mm  
 D.O.A. **25/05/2018** D.O.I. **30/05/2018**  
 Survey held at **Teamwork Page Ubi**  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
**Rear**  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

**Sompo CB7671X**  
**MV 73K**  
**LTA 53.2K**  
**NL 20K**

RECEIVED 09 NOV 2018

Date/Time, File Pass to?

9/11 Typist



: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I. (\$) **20000**Days Of Repair: **21**Resurvey No. of Trip: **2**

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

) \$ + P5 \$

) Photos

) Other

) =

TOTAL

450

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Wednesday, 30 May 2018 2:41 PM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** TEAMWORK GARAGE CLAIMS; Chan, Shu Hui Agnes; Ye, Yong Kang Melvin  
**Subject:** CMTD1802242/AGC - SUV(LKK)/ CB7671X & SKU6580L ACC ON 25.05.18  
**Attachments:** 20180528162249867.pdf

Our Reference: CMTD1802242/AGC  
Your Reference: SKU6580L

Dear LKK AUTO,

Please make arrangement to conduct the survey for SKU6580L.

Please be informed that Agnes Chan the handler of this case.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** TEAMWORK GARAGE CLAIMS [mailto:claims@teamworkgarage.com]  
**Sent:** Wednesday, May 30, 2018 2:31 PM  
**To:** Teo, Grace  
**Cc:** Chan, Shu Hui Agnes; Ye, Yong Kang Melvin; claims@teamworkgarage.com  
**Subject:** RE: CMTD1802242/AGC - PRI/ CB7671X & SKU6580L ACC ON 25.05.18  
**Importance:** High

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK AUTO CONSULTANTS

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

\*Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop

Darren Ng  
Teamwork Garage Pte Ltd  
53 Ubi Avenue 1  
#01-24 Paya Ubi Industrial Park  
Singapore 408934  
Tel: 68442475  
Fax: 68442474

---

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]  
Sent: Wednesday, May 30, 2018 10:28 AM  
To: CLAIMS TEAMWORK <claims@teamworkgarage.com>  
Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>  
Subject: CMTD1802242/AGC - PRI/ CB7671X & SKU6580L ACC ON 25.05.18

Our Reference: CMTD1802242/AGC  
Your Reference: 1805-35

**Without Prejudice**

Date: 30<sup>th</sup> May 2018

**Attention:**  
**M/S TEAMWORK GARAGE PTE LTD**

Dear Sue,

**ACCIDENT INVOLVING CB7671X & SKU6580L ON 25.05.2018**

We refer to your Notice of Accident dated 28/05/2018.

Please be informed that Agnes Chan the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** CLAIMS TEAMWORK [<mailto:claims@teamworkgarage.com>]

**Sent:** Monday, May 28, 2018 4:31 PM

**To:** Claims - Motor Survey

**Cc:** TEAMWORK - CLAIMS

**Subject:** PRE-REPAIR INSPECTION FOR SKU6580L

**Importance:** High

**WITHOUT PREJUDICE**

**OUR REF:** 1805-35

**YOUR REF:** CB7671X

Dear Sir/Madam,

**PRE-REPAIR INSPECTION FOR SKU6580L  
ACCIDENT INVOLVING SKU6580L AND CB7671X ON 25.05.18**

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

Please let us have your list of surveyors for us to select as stated in the Practice Direction – Amendment No. 1 of 2016; Pre-action Protocol within 2 working days as of the date of our notice to you.

**Please take note: We will not entertain any of your surveyor calling us for the above inspection, without you giving us your list of surveyors for us to select by the Practice Direction of Pre-repair Inspection.**

Thank you.

Sue  
Teamwork Garage Pte Ltd  
53 Ubi Ave 1 #01-23/24  
Paya Ubi Industrial Park  
Singapore 408934  
Tel : 6844 2475  
Fax : 6844 2474

XX  
Please do not change the subject heading for easier reference. Thank you.  
XX

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/05/2018 11:31
Date Of Accident	25/05/2018 06:05
Exact Location Of Accident	CALSHOT RD TWDS UPP CHANGI RD NORTH
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU6580L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ROSET LIMOUSINE SERVICES PTE LTD
Co Reg No	200406722Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMCFHQ17-000185
Cover Note Number	

### Driver

Name of Driver	LOHESWARAN S/O KULAGANATHAN
NRIC No	S9110095I
Date Of Birth	20/03/1991
Occupation	OUTDOOR
Date Of Driving Pass	16/08/2010
Driving Experience	7 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91116826
Fax Number	
Contact Number	OFFICE-91116826
Email Address	NOEMAIL

Address	BLK 244 YISHUN RING ROAD #10-1123
Postcode	760244
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB7671X
Vehicle Make/Model/Colour	TOYOTA HIACE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMED ZULHIMI BIN MUSA
NRIC/Passport Number	S9325054J
Contact Number	83281034
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that report of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time

Driver's Signature  
(if driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name  
NRIC/FIN No.

# Accident Sketch Plan

SKETCH PLAN



A - SKU65801

B - CB7671X

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Calshot Road , while driving , I heard an unusual noise from the rear left portion . I stopped my car safely on the side of the road and got down to check if there is anything wrong with my vehicle. Suddenly vehicle B hit onto my vehicle causing a huge impact and causing my vehicle to dash in front for about 10-15 metres. There was nobody in the vehicle .

## DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature  
Date & Time



Driver's Signature  
(if driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NRIC/TIN No.:

**Sompo Insurance Pte Ltd**  
 50 Raffles Place , #05-01/06  
 Singapore Land Tower

Vehicle number	SKU6580L
Make / Model	TOYOTA/ALTIS
Chassis number	MR053REH104535755
Accident date	25 May 2018
Reference	1805-35

Qty    Particulars    Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS			
1	BOOTLID Bnc	906.52	✓
1	BOOTLID LOGO Nec	72.09	✓
1	BOOTLID EMBLEM COROLLA broken	58.37	✓
1	BOOTLID EMBLEM ALTIS broken	58.92	✓
1	BOOTLID CHROME GARNISH broken	280.80	✓
1	BOOTLID LICENCE PLATE LAMP Hnl	69.60	x
2	BOOTLID LAMP broken / missing / crack	804.00	✓
2	BOOTLID INNER SEAL HS	222.81	x
1	BOOTLID LOCK Dam	462.43	✓
1	BOOTLID LOCK COVER HS	43.30	x
1	BOOTLID LOCK CATCH Bt	54.03	✓
2	BOOTLID HINGE Bt	163.20	✓
1	BOOTLID INNER TRIM Bt	515.40	✓
2	BOOTLID STOPPER Nec	40.00	✓
1	REAR BUMPER Bnc	685.32	✓
2	BUMPER REFLECTOR o/s broken N/S SVC	139.20	✓
2	REAR BUMPER BRACKET o/s broken N/S SVC	163.20	✓
2	REAR BUMPER RETAINER o/s broken N/S SVC	288.30	✓
4	REAR BUMPER PDC SENSOR Dam	220.00	✓
1	REAR BUMPER PDC SENSOR WIRE HARNESS Hnl	342.40	x
1	REAR BUMPER REINFORCEMENT Dented	474.42	✓
1	REAR WINDSCREEN broken	1460.40	✓
2	REAR FENDER Bnc	2366.40	✓
2	REAR FENDER INNER PANEL Dented	1164.32	✓
2	REAR FENDR INNER SHIELD o/s deformed N/S SVC	132.14	✓
2	REAR FENDER INNER TRIM Crumpled	759.02	✓
1	REAR END PANEL Bnc	719.80	✓
1	REAR END PANEL GARNISH deformed	282.80	✓
2	REAR TAILLAMP broken	963.80	✓
2	REAR TAILALAMP PANEL Bnc	261.08	✓
2	REAR TAILLAMP INNER SEAL Nec	70.34	✓
1	REAR FLOOR PANEL Bnc	973.34	✓
1	REAR SPARE TYRE TOP BOARD Bt	309.88	✓
1	REAR RH CHASSIS Dented	742.98	✓
1	REAR AXLE BEAM Dented	314.76	✓
2	REAR KNUCKLE BEARING o/s Dam N/S Hnl	1634.80	✓
2	REAR SHOCK ABSORBER o/s distorted N/S Hnl	688.44	✓
1	REAR EXHAUST SILENCER Bt	1145.58	✓
1	REAR EXHAUST MID PIPE Bt	3409.90	✓
1	REAR EXHAUST HEAT SHIELD Bt	189.10	✓

69.60

81.60

144.15

SN 220.00 280.00 ✓

66.07

817.40

344.22

21232.04

2	REAR EXHAUST MOUNTING <i>svc</i>	60.00 X
1	FUEL TANK <i>Revised</i>	972.34 ✓
1	FUEL TANK BRACKET <i>rev</i>	245.22 X
1	ROOF LINING <i>crumpled</i>	1306.62 ✓
1	SPEAKER PANEL <i>Bnc</i>	1094.34 ✓
1	SPEAKER PANEL LINING <i>damaged</i>	951.60 ✓
2	REAR FENDER EXTENSION PANEL <i>Bnc</i>	749.08 ✓
2	REAR FENDER INNER TOP GARNISH <i>damaged</i>	671.00 ✓
2	REAR FENDER QUARTER GLASS RUBBER <i>damaged 1 h/c</i>	368.44 ✓
2	REAR FENDER AIR VENT <i>o/s dislodged N/S svc</i>	251.32 ✓
2	SPARE TYRE EXTENSION PANEL <i>Bnc</i>	451.40 ✓
2	ROOF MOULDING <i>o/s 6t N/S svc</i>	490.44 ✓

6935.70

28167.74

21125.80

Less 25 %

Subtotal

Balance C/F

### PARTS REPLACEMENT - SPECIAL NETT ITEMS

1 SET	REAR BUMPER CLIP <i>h/c</i>	60.00 30/-
1 SET	REAR FENDER INNER TRIM CLIP <i>h/c</i>	40.00 20/-
1 SET	REAR FENDER INNER SHIELD CLIP <i>h/c</i>	40.00 20/-
1 SET	REAR BOOTLID INNER TRIM CLIP <i>h/c</i>	40.00 20/-
1	REAR WINDSCREEN SEALANT <i>h/c</i>	150.00 40/-
1	REAR JOINT SEALANT <i>h/c</i>	150.00 40/-
1	REAR FLOOR INSULATOR <i>h/c</i>	150.00 50/-
1	REAR REVERSE CAMERA <i>HH</i>	500.00 X
1	BRAKE FULID <i>HH</i>	60.00 X

220.00  
+ 220.00  
440.00

Subtotal

Balance C/F

S/No

### LABOUR AND MISCELLANEOUS CHARGES

1	CHECK REAR WIRING AND LIGHTNING SYSYEM	60.00 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	400.00 200/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND REFIT FUEL TANK	150.00 60/-
5	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 60/-
6	REMOVE AND RENEW FLOOR INSULATOR	150.00 50/-
7	REMOVE AND REFIT REAR WINDSCREEN	150.00 120/-
8	TRANSFER PARTS, ATTACHEMENT FROM OLD BOOTLID TO NEW	200.00 60/-
9	MOUNT VEHICLE ON BENCH FOR REPLACEMENT ON REAR CHASSIS	600.00 180/-
10	PANEL BEATING ON AFFECTED AREAS	6000.00 2800/-
11	SPRAY PAINTING ON AFFECTED AREAS	2800.00 1600/-
12	APPLY ANTI RUST ON AFFECTED AREAS	200.00 120/-

5320.00

Subtotal

30/05/2018 @ 1430hrs

Grand total

LKK Auto Consultants hence no

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

21 days

21 days

21 days

21 days

21 days

21 days

Check MV

regm limit.

26885.80

R/S 20,000/-

regm limit.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18009755/Dtd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 15-11-2018



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 7671X	Veh. Inspected	SKU 6580L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802242/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	30/05/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MR053REH104535755	Colour	GREY
Odometer	196076	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	5 mm
L/H Front Tyre	205/55 R16	DUNLOP	5 mm
R/H Rear Tyre	205/55 R16	DUNLOP	5 mm
L/H Rear Tyre	205/55 R16	DUNLOP	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	25/05/2018	Inspection Date	30/05/2018
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	21 Working Days
-------------------------------------	-----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 6580L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BOOTLID	BUCKLED	906.52	906.52
1	BOOTLID LOGO	NECESSARY	72.09	72.09
1	BOOTLID EMBLEM COROLLA	BROKEN	58.37	58.37
1	BOOTLID EMBLEM ALTIS	BROKEN	58.92	58.92
1	BOOTLID CHROME GARNISH	BROKEN	280.80	280.80
1	BOOTLID LICENCE PLATE LAMP	NOT NECESSARY	69.60	-
2	BOOTLID LAMP	BROKEN / MTG CRACKED	804.00	804.00
2	BOOTLID INNER SEAL	NO SUCH PARTS	222.81	-
1	BOOTLID LOCK	DAMAGED	462.43	462.43
1	BOOTLID LOCK COVER	NO SUCH PARTS	43.30	-
1	BOOTLID LOCK CATCH	BENT	54.03	54.03
2	BOOTLID HINGE	BENT	163.20	163.20
1	BOOTLID INNER TRIM	BENT	515.40	515.40
2	BOOTLID STOPPER	NECESSARY	40.00	40.00
1	REAR BUMPER	BUCKLED	685.32	685.32
2	BUMPER REFLECTOR	O/S BROKEN / N/S SERVICEABLE	139.20	69.60
2	REAR BUMPER BRACKET	O/S BROKEN / N/S SERVICEABLE	163.20	81.60
2	REAR BUMPER RETAINER	O/S BROKEN / N/S SERVICEABLE	288.30	144.15
1	REAR BUMPER PDC SENSOR WIRE HARNESS	NOT NECESSARY	342.40	-
1	REAR BUMPER REINFORCEMENT	DENTED	474.42	474.42
1	REAR WINDSCREEN	BROKEN	1,460.40	1,460.40
2	REAR FENDER	BUCKLED	2,366.40	2,366.40
2	REAR FENDER INNER PANEL	DENTED	1,164.32	1,164.32
2	REAR FENDER INNER SHIELD	O/S DEFORMED / N/S SERVICEABLE	132.14	66.07
2	REAR FENDER INNER TRIM	CRUMPLED	759.02	759.02
1	REAR END PANEL	BUCKLED	719.80	719.80
1	REAR END PANEL GARNISH	DEFORMED	282.80	282.80
2	REAR TAILLAMP	BROKEN	963.80	963.80
2	REAR TAILLAMP PANEL	BUCKLED	261.08	261.08
2	REAR TAILLAMP INNER SEAL	NECESSARY	70.34	70.34

Report Ref No. CS/SMO18009755/Dtd3n2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL	BUCKLED	973.34	973.34
1	REAR SPARE TYRE TOP BOARD	BENT	309.88	309.88
1	REAR RH CHASSIS	DENTED	742.98	742.98
1	REAR AXLE BEAM	DENTED	314.76	314.76
2	REAR KNUCKLE BEARING	O/S DAMAGED / N/S NOT NECESSARY	1,634.80	817.40
2	REAR SHOCK ABSORBER	O/S DISTORTED / N/S NOT NECESSARY	688.44	344.22
1	REAR EXHAUST SILENCER	BENT	1,145.58	1,145.58
1	REAR EXHAUST MID PIPE	BENT	3,409.90	3,409.90
1	REAR EXHAUST HEAT SHIELD	BENT	189.10	189.10
2	REAR EXHAUST MOUNTING	SERVICEABLE	60.00	-
1	FUEL TANK	DENTED	972.34	972.34
1	FUEL TANK BRACKET	TO REPAIR SEE LABOUR	245.22	-
1	ROOF LINING	CRUMPLED	1,306.62	1,306.62
1	SPEAKER PANEL	BUCKLED	1,094.34	1,094.34
1	SPEAKER PANEL LINING	DEFORMED	951.60	951.60
2	REAR FENDER EXTENSION PANEL	BUCKLED	749.08	749.08
2	REAR FENDER INNER TOP GARNISH	DEFORMED	671.00	671.00
2	REAR FENDER QUARTER GLASS RUBBER	DEFORMED / NECESSARY	368.44	368.44
2	REAR FENDER AIR VENT	O/S DISLODGE / N/S SERVICEABLE	251.32	125.66
2	SPARE TYRE EXTENSION PANEL	BUCKLED	451.40	451.40
2	ROOF MOULDING	O/S BENT / N/S SERVICEABLE	490.44	245.22
	LESS 25% DISCOUNT		-7,761.24	-7,041.94
			23,283.75	21,125.80
4	REAR BUMPER PDC SENSOR (SN)	DAMAGED	780.00	220.00
	LESS 25% DISCOUNT		-195.00	-
			585.00	220.00
	<b>SPECIAL NETT ITEMS</b>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR FENDER INNER TRIM CLIP (SN)	NECESSARY	40.00	20.00

Report Ref No. CS/SMO18009755/Dtd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER INNER SHIELD CLIP (SN)	NECESSARY	40.00	20.00
1	SET REAR BOOTLID INNER TRIM CLIP (SN)	NECESSARY	40.00	20.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00
1	REAR JOINT SEALANT (SN)	NECESSARY	150.00	40.00
1	REAR FLOOR INSULATOR (SN)	NECESSARY	150.00	50.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	500.00	-
1	BRAKE FULID (SN)	NOT NECESSARY	60.00	-
			1,190.00	220.00
	<b>LABOUR</b>			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND REFIT REAR LINING,TRIM AND GARNISH.		400.00	200.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND REFIT FUEL TANK.		150.00	60.00
	REMOVE AND RENEW REAR EXHAUST ASSY.		150.00	60.00
	REMOVE AND RENEW FLOOR INSULATOR.		150.00	50.00
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	TRANSFER PARTS,ATTACHMENT FROM OLD BOOTLID TO NEW.		200.00	60.00
	MOUNT VEHICLE ON BENCH FOR REPLACEMENT ON REAR CHASSIS.		600.00	180.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FUEL TANK BRACKET.		6,000.00	2,800.00
	SPRAY PAINTING ON AFFECTED AREAS.		2,800.00	1,600.00
	APPLY ANTI RUST ON AFFECTED AREAS.		200.00	120.00
			11,010.00	5,320.00
	<b>GRAND TOTAL</b>		<b>36,068.75</b>	<b>26,885.80</b>
	<b>RECOMMENDED COST OF REPAIR SUM</b>			<b>20,000.00</b>

Report Ref No. CS/SMO18009755/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.