

ASS. REC. BY:

REF: CS/SM018009757/Dtd3/72

Special Instruction:

Surveyor: Bryen

ASSIGNMENT (Office)

From (Person): Crane Leo

of

8MODate/Time: 30/5/18 @ 2:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SID 6171L

Insured:

PA 8496E

at Workshop m/s:

Teamwork Garage

Tel:

6844 2475

of

53 ubi Ave 1 # 01-23/24

Policy No:

Claim No:

CMTD1802286/ GPL

Sum Insured:

Excess:

Make of Vch:
(Client's Record)

D.O.A.

23/05/2018CA / REV / REP. / REV 24 HRS ^{1up}

H.O.D. Endorsement:

Date/Time:

3:02pm @ 30/5/18

Person Contacted:

sueVehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SID 6171L - xPA 8496E - CS31A x A140US820 / Mlgby2-1DOA: 26/3/19

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt. _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No. SLD 6171 L Yt Regn: 2016 JuneType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Valleyfire c.c. 2493Color: White A/C: Insured / Std / NI / NASp. Reading: 40422 T/Radio: Insured / Std / NI / NAEng/No: 2ARH591540C/No: AGH300027145Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/65 R 16R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Michelin

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 23/05/2018 D.O.I. 30/05/2018Survey held at Tamworth Page Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sompo PA 8496E

11/03/19 found 1/5 5700/- with 5 days 2 yr
(Red: 5626/- 49%)

RECEIVED 12 MAR 2019

Date/Time, File Pass to?

1) 12/3 Typist

Date/Time, File Return to?

2)

Report Format: TPLump Sum / I.B.I. (\$) 5700/-

Preli. Report



Final Report

Days Of Repair: 5Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

1) S + RS \$

2) Photos

3) Others

TOTAL

350

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 30 May 2018 2:45 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: TEAMWORK GARAGE CLAIMS; Gnoh, Pau Loong; Ye, Yong Kang Melvin
Subject: CMTD1802286/GPL -SUV(LKK)/ PA8496E & SLD6171L ACC ON 23.05.18
Attachments: 20180530102301182.pdf

Our Reference: CMTD1802286/GPL
Your Reference: SLD6171L

Dear LKK AUTO,

Please make arrangement to conduct the survey for SLD6171L.

Please be informed that Gnoh Pau Loong the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: TEAMWORK GARAGE CLAIMS [mailto:claims@teamworkgarage.com]
Sent: Wednesday, May 30, 2018 2:32 PM
To: Teo, Grace
Cc: Gnoh, Pau Loong; Ye, Yong Kang Melvin; claims@teamworkgarage.com
Subject: RE: CMTD1802286/GPL -PRIL/ PA8496E & SLD6171L ACC ON 23.05.18
Importance: High

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK AUTO CONSULTANTS

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

*Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop

Darren Ng
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Wednesday, May 30, 2018 11:47 AM
To: CLAIMS TEAMWORK <claims@teamworkgarage.com>
Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1802286/GPL -PRIL/ PA8496E & SLD6171L ACC ON 23.05.18

Our Reference: CMTD1802286/GPL
Your Reference: 1805-34

Without Prejudice

Date: 30th May 2018

Attention:
M/S TEAMWORK GARAGE PTE LTD

Dear Sue,

ACCIDENT INVOLVING PA8496E & SLD6171L ON 23.05.2018

We refer to your Notice of Accident dated 30/05/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: CLAIMS TEAMWORK [<mailto:claims@teamworkgarage.com>]

Sent: Wednesday, May 30, 2018 10:35 AM

To: Claims - Motor Survey

Cc: TEAMWORK - CLAIMS

Subject: PRE-REPAIR INSPECTION FOR SLD6171L

Importance: High

WITHOUT PREJUDICE

OUR REF: 1805-34

YOUR REF: PA8496E

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SLD6171L

ACCIDENT INVOLVING SLD6171L AND PA8496E ON 23.05.18

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

Please let us have your list of surveyors for us to select as stated in the Practice Direction – Amendment No. 1 of 2016; Pre-action Protocol within 2 working days as of the date of our notice to you.

Please take note: We will not entertain any of your surveyor calling us for the above inspection, without you giving us your list of surveyors for us to select by the Practice Direction of Pre-repair Inspection.

Thank you.

Sue
Teamwork Garage Pte Ltd
53 Ubi Ave 1 #01-23/24
Paya Ubi Industrial Park
Singapore 408934
Tel : 6844 2475
Fax : 6844 2474

XX
Please do not change the subject heading for easier reference. Thank you.
XX

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2018 16:44
Date Of Accident	23/05/2018 16:00
Exact Location Of Accident	ALONG JLN SEAVIEW JUNCT OF CRESCENT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD6171L
Insured/Policyholder	
Name Of Registered Owner	RAJMAN B M SANI
NRIC No	S1741628F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97821553
Alternative Phone No	OTHERS-97821553
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VELLFIRE 2.5X CVT ABS D/AIRBAG 2WD 5DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092057929
Cover Note Number	
Driver	
Name of Driver	RAJMAN B M SANI
NRIC No	S1741628F
Date Of Birth	26/01/1966
Occupation	INDOOR
Date Of Driving Pass	25/10/1986
Driving Experience	31 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97821553
Fax Number	
Contact Number	OTHERS-97821553
Email Address	NOEMAIL

Address 123 MEYER ROAD #07-03
 Postcode 437934
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY
Other Information
 Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : SPOUSE
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY VEHICLE WAS STATIONARY ON A SINGLE LANE ROAD DUE TO CONGESTION AHEAD, ALONG JLN SEAVIEW. VEHICLE B BEARING REGN NO, PA8496E WHICH WAS TRAVELLING ON THE OPPOSITE LANE WAS TURNING LEFT INTO CRESCENT ROAD. UNFORTUNATELY, THE DRIVER MISJUDGED AND AS A RESULT, THE REAR RIGHT PORTION OF VEHICLE B IMPACTED ONTO THE REAR RIGHT PORTION OF MY STATIONARY VEHICLE. THAT'S ALL.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PA8496E
 Vehicle Make/Model/Colour
Details Of Properties
 Vehicle Category BUS
 Name of Driver KASMANI
 NRIC/Passport Number
 Contact Number 87500796
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may affect insurance cover and will repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurers (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

CRASH SITE ROAD

Stationary



TUN 30000000

A = SLDB71L
B = PA8471E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to document

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(if driver is not the policyholder)

Date & Time:



Reporting Centre/Personnel's Signature

Name:

NRIC/FIN No.



Teamwork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

Sompo Insurance Pte Ltd
50 Raffles Place , #05-01/06
Singapore Land Tower
Singapore 048623

Vehicle number	SLD6171L
Make / Model	TOYOTA/VELLFIRE
Chassis number	2ARH300027145
Accident date	23 May 2018
Reference	1805-34

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR RH FENDER Dented	1500.00
1	REAR RH FENDER INNER TRIM mostly broken	1700.00 ✓
1	REAR RH QUARTER GLASS MOULDING H/W	855.00 ✓
1	REAR RH CORNER UPPER BUMPER broken	1025.00 X
1	REAR BUMPER LOWER Dented	535.00 ✓
1	REAR BUMPER RETAINER broken	890.00 ✓
1	REAR RH TAILLAMP Scratched	262.00 310.00 ✓
1	END PANEL rep	651.00 ✓
1	END PANEL INNER TRIM H/W	998.00 X
1	AIRCON BLOWER broken	267.00 X
1	REAR BUMPER REFLECTOR H/W SVC	2107.00 ✓
1	TOW COVER destroyed	80.00 X
1	REAR REVERSE SENSOR Down	65.00 ✓
		525.00 501- SH
		10008.00
	Less 25%	2502.00
	Subtotal	7506.00
	Balance C/F	7506.00
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
	Balance B/F	7506.00
1 SET	REAR BUMPER CLIP H/W	60.00 30/-
1 SET	REAR RH FENDER INNER TRIM CLIP H/W	50.00 20/-
1	JOINT SEALANT H/W	150.00 40/-
1	WINDSCREEN SEALANT H/W	150.00 40/-
	Subtotal	410.00
	Balance C/F	7916.00
LABOUR AND MISCELLANEOUS CHARGES		
	Balance B/F	7916.00
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND REFIT REAR RH QATER GLASS	150.00 80/-
5	PANEL BEATING ON AFFECTED AREAS	1500.00 800/-
6	SPRAY PAINTING ON AFFECTED AREAS	1200.00 800/-
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	3410.00
	Grand total	11326.00
		7198.90

30/05/2018 @ 1700hrs

Not Antenna 5 days.

L/S M/L

M/L

L/KK Antu

L/S 5700/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18009757/Dtd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 12-03-2019



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 8496E	Veh. Inspected	SLD 6171L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802286/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	30/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	AGH300027145	Colour	WHITE
Odometer	40422	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/65 R16	MICHELIN	5 mm
L/H Front Tyre	215/65 R16	MICHELIN	5 mm
R/H Rear Tyre	215/65 R16	MICHELIN	5 mm
L/H Rear Tyre	215/65 R16	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/05/2018	Inspection Date	30/05/2018
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 6171L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR RH FENDER	DENTED	1,700.00	1,500.10
1	REAR RH FENDER INNER TRIM	MOUNTING BROKEN	855.00	855.00
1	REAR RH QUARTER GLASS MOULDING	NOT NECESSARY	1,025.00	-
1	REAR RH CORNER UPPER BUMPER	BROKEN	535.00	535.00
1	REAR BUMPER LOWER	DENTED	890.00	890.00
1	REAR BUMPER RETAINER	BROKEN	310.00	262.10
1	REAR RH TAILLAMP	SCRATCHED	651.00	651.00
1	END PANEL	TO REPAIR SEE LABOUR	998.00	-
1	END PANEL INNER TRIM	NOT NECESSARY	267.00	-
1	AIRCON BLOWER	BROKEN	2,107.00	2,107.00
1	REAR BUMPER REFLECTOR	SERVICEABLE	80.00	-
1	TOW COVER	DISLODGE	65.00	65.00
	LESS 25% DISCOUNT		-2,370.75	-1,716.30
			7,112.25	5,148.90
1	REAR REVERSE SENSOR (SN)	DAMAGED	525.00	50.00
	LESS 25% DISCOUNT		-131.25	-
			393.75	50.00
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR RH FENDER INNER TRIM CLIP (SN)	NECESSARY	50.00	20.00
1	JOINT SEALANT (SN)	NECESSARY	150.00	40.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00
			410.00	130.00
<u>LABOUR</u>				
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.		200.00	80.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND REFIT REAR RH QATER GLASS.		150.00	80.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF END PANEL.		1,500.00	800.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	800.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
			3,410.00	1,870.00
GRAND TOTAL			11,326.00	7,198.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,700.00

Report Ref No. CS/SMO18009757/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.