

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0185/2018
DATE : 22-MAY-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : ES ASIA TECHNOLOGIES LLP
ADDRESS : 21 WOODLANDS CLOSE
#07-06
PRIMZ BIZHUB S(737854)
TELEPHONE NO : 97324973

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-SLU9421G
VEHICLE NO : GBE9698C
MODEL CODE : NV200 DX 1.6 A
MODEL/YEAR : NV200
ENGINE NO : HR16056051D
CHASSIS NO : VM20088300
MILEAGE : 1 KM
DATE IN : 22/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 12/05/2018

DS
Lawrence
Chick
Revised
\$100 x 06
= \$600 part
= \$642/-

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBE9698C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	120.00
3	RRSCM	REMOVE/REFIX SUSPENSION CROSS MEMBER	120.00	.00
4	RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE LH FRONT	480.00	.00
5	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	100.00
6	WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	103.00
7	ZZ/001	REPAIR LH SUPPORT, LH FRONT FENDER AND RENEW FRONT BUMPER	1800.00	1170.00
8	ZZ/002	S/PAINT LH HEADLAMP FINISHER, LH SUPPORT, LH FRONT FENDER, RADIATOR GRILLE	1600.00	725.00
9	ZZ/003	CODNUCT WHEEL BALANCING LH FRONT STEEL RIM	15.00	.00
TOTAL LABOUR CHARGES			4626.00	2266.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBE9698C

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	SUNDRIES	NPN			20.00	OK
2	ORNAMENT-FRONT	62889-WB60A	59.70			X
3	PROTECTOR-FR,LH FENDER	63843-JX31A	70.00			X
4	GRILLE-RADIATOR	62310-JX00B	338.00			X
5	BRKT-BPR SIDE,L	62225-JX00A	20.90			OK
6	CLIP APRON \$1.20 EA X 20	01553-05933	24.00			OK
7	BRKT-APRON LWR	62663-5LG0A	210.00			X
8	ARMATURE ASSY-F	62030-JX01A	559.00			OK
9	ENERGY ABSORBER	62090-JX52B	265.10			OK
10	FACE-FR BUMPER	62022-JX00A	487.30			OK
11	GEAR&LINKAGE	48001-JX00C			1428.00	X
12	MEMBER	54400-3LR1A			302.50	X
13	ROD-STABILIZER	54618-JX00A	32.30			X
14	LINK COMPL,LH	54501-1FU0B	200.50			X
15	LINK COMPL,LH UPPER	54525-ED001	106.00			X
16	CAP-STRUT MTG	54330-ED000	8.00			X
17	INSULATOR-STRUT MTG	54321-JX00A	87.30			X
18	BRG STRUT MTG	54325-ED02A			126.10	X
19	BUMPER ASSY-BOU	54050-AZ100			38.20	X
20	STRUT KIT-FRONT	E4303-JX05A			252.80	X
21	SPDL-KNU LH	40015-ED000			357.20	X
22	HUB ASSY-ROAD W	40202-JX00A			329.70	X
23	SFT ASSY-DRIVE	39101-JX01B			861.70	X
24	LAMP ASSY-LH	26060-JX31A	405.80			OK
25	BUMPER-FRONT LH FINISHER HEADLAMP	62025-JX06A	329.30			OK

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBE9698C

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
SUB TOTAL		2091.40	0.00	20.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		418.28	0.00	0.00
GRAND TOTAL		1673.12	0.00	20.00
OVERALL TOTAL		1693.12		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO GBE9698C

NETT ITEM	2091.40
LESS 20.00%)	-418.28
NETT AMOUNT	1673.12
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	20.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	20.00
TOTAL LABOUR CHARGES	2266.00
TOTAL SPARE PARTS CHARGES	1693.12
TOTAL CHARGES	3959.12
ADD 7 % GST	277.14
GRAND TOTAL	4236.26
