

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU748Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	120.00
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	120.00
3	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	110.00
4	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	100.00
5	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	150.00
6	UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	240.00
7	ZZ/001	REPAIR BOTH REAR FENDER AND RENEW END PANEL, TAILGATE, REAR BUMPER	1200.00	750.00
8	ZZ/002	S/PAINT REAR PORTION AND BUMPER (2 TONES)	1400.00	700.00
9	ZZ/003	TRANSFER TAILGATE MECHANICAL PARTS	80.00	80.00
10	ZZ/004	R/I DVR TO ASSST REPAIR	120.00	120.00
11	ZZ/005	SUPPLY AND RENEW REAR NO. PLATE (SMART PLATE WITH CASING) BLACK CASING (LONG)		
TOTAL LABOUR CHARGES			4080.00	2490.00
ADDITIONAL DISCOUNT(5.00%)				124.50
FINAL LABOUR CHARGES				2365.50

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU748X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	BRACKET-BUMPER RH	85220-4EA0A	35.90		X
2	A FIN BACK DOOR NO PLATE	90810-4ES0H	336.00		X
3	GROMMET C/LAMP \$4.40 EA X 02	26557-2U000	8.80		X
4	GROMMET C/LAMP	76848-35F00	1.90		X
5	CLIP C/LAMP \$4.80 EA X 02	26398-ED000	9.60		X
6	LAMP COMB RR,LH TAILGATE	26555-HV55A	215.90		OK
7	LAMP COMB RR,LH	26555-HV00A	323.70		X
8	EMBLEM	90892-4EA0A	87.00		OK
9	EMBLEM-REAR	90890-4EA0A	59.70		OK
10	STRIKER-TAIL GA	90570-4EA0A	31.70		X
11	A LOCK LIFT	90502-4EA1B	116.70		X
12	DOOR BACK	X0100-HV0MB	2936.80		OK
13	RUBBER-DUM	G2716-89901	60.20		OK
14	GLASS-TAIL GATE	90300-HV00A	930.00		OK
15	STAY ASSY-REAR RH	H5210-4EAMA	126.00		X
16	STAY ASSY-REAR LH	H5211-4EAMA	126.00		X
17	REINF-BUMPER RR	H5030-4EAMA	619.20		X
18	ENERGY ABSORBER	85090-HV00A	126.40		OK
19	CANOE BUMPER \$6.50 EA X 02	76882-0M000	13.00		OK
20	CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20		OK
21	RETAINER-BUMPER RH	79184-4EA0A	23.80		X
22	BRACKET-BUMPER LH	85221-4EA0A	35.90		OK
23	RETAINER-BUMPER LH	79185-4EA0A	23.80		OK
24	FINISHER-REAR BUMPER TOW	85071-HV00A	16.80		X
25	FASCIA-RR BUMP	85022-HV00H	717.00		OK

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU7498

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
26 CLIP FENDER \$1.20 EA X 02	01553-05323	2.40			OK
27 CLIP FENDER \$1.20 EA X 04	01554-00181	4.80			OK
28 PLATE-LUGGAGE 	84992-4EA0A	63.50			OK
29 CLIP FENDER \$1.20 EA X 05	01553-05131	6.00			OK
30 GROMMET FENDER	01281-00831	1.50			X
31 PROTECTOR-REAR LH FENDER	76749-4EA0A	196.40			X
32 FENDER LH REAR ARC	93829-4EA0A	483.00			X
33 REAR W/SCREEN SEALANT	SEALANT - 4			80.00	OK
34 SUNDRIES	NPN			20.00	OK
35 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00	OK
36 REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG RLP				60.00	X
SUB TOTAL		5304.60	0.00	310.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1060.92	0.00	0.00	
GRAND TOTAL		4243.68	0.00	310.00	
ADDITIONAL DISCOUNT (NETT-5.00%, LIST-5.00%, S/NETT-.00%)		212.18	0.00	0.00	
OVERALL TOTAL		4341.50			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLU748X

NETT ITEM	5304.60
LESS 20.00%)	-1060.92
NETT AMOUNT	4243.68
ADDITIONAL DISCOUNT(5.00%)	-212.18
FINAL AMOUNT	4031.50
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	310.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	310.00
TOTAL LABOUR CHARGES	2365.50
TOTAL SPARE PARTS CHARGES	4341.50
TOTAL CHARGES	6707.00
ADD 7 % GST	469.49
GRAND TOTAL	7176.49

Service Request Details

Claim

S8M00H71

Reference

None 

Loss Date

May 14, 2018

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Request Date

May 28, 2018

Due Date

June 5, 2018

28052018 @ 128pm
Lawrence Veh.

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SLU748Z

Make

TPVD NISSAN

Service Address

...

Primary Contact/Insured

KDY HOLDINGS PTE LTD
44 SUNGEI KADUT STREET 1, 729349, Singapore
65674755

Claim Handler

TAY Ernest
6568804835
ernest.tay@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Hsiao Tong (LKKAUTO)

From: Norsipah <norsipah@tanchong.com>
Sent: Wednesday, 5 December 2018 10:57 AM
To: Asher Sng (LKKAUTO); Shu Pei (LKKAUTO)
Cc: SUR; Admin A; Taufikh (LKKAUTO)
Subject: RE: Finalization SLU748Z DOA 14.05.2018
Attachments: SLU748Z_LOD.pdf

Hi

Our letter of demand attached for your perusal.

Kindly revert with your offer soon. Thank you.

Best Regards,
Sipah
Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
E: norsipah@tanchong.com D: +6567038915
Website: www.tanchong.com :: www.nissan.com.sg

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: 10 November 2018 15:46
To: Norsipah <norsipah@tanchong.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: Finalization SLU748Z DOA 14.05.2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sipah,

We refer to the above matter.

Our surveyor have finalise COR at \$6,707.00 (exclude gst) 6 days, finalize amount subject to our principal approval.

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

- Please do not send the LOD to our principal for direct settlement.

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants Pte Ltd
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norsipah <norsipah@tanchong.com>
Sent: Wednesday, 24 October 2018 12:21 PM

To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Finalization SLU748Z DOA 14.05.2018

Best Regards,
Sipah

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: 18 October 2018 17:15
To: Norsipah <norsipah@tanchong.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Finalization SLU748Z DOA 14.05.2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Norsipah,

Please let us have the resurvey photo for the check item.

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants Pte Ltd
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Norsipah <norsipah@tanchong.com>
Sent: Thursday, 18 October 2018 2:46 PM
To: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Finalization SLU748Z DOA 14.05.2018

Hi,

Please finalize.

Best Regards,
Sipah

From: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>
Sent: 20 August 2018 10:03
To: Norsipah <norsipah@tanchong.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: Finalization SLU748Z DOA 14.05.2018