

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0198/2018
DATE : 26-MAY-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MISS NG CHIU LI (HUANG QIULI)
ADDRESS : BLK 704 CHOA CHU KANG STREET 53
#13-76
S(680704)
TELEPHONE NO : 96952923

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : TP-YN3306D
VEHICLE NO : SLU748Z
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2511680A
CHASSIS NO : SJNFEAJ11U2064575
MILEAGE : 1 KM
DATE IN : 26/05/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 14/05/2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR AT WORKSHOP / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H/P : 94568832

FAX : 64697472

1216-

26/05/2018

Lawrence 2222

LKK

05/06/18

Tanlin 92493749
5/6/18 @1630

WP' Gdys

Resurvey before print

Sur @ lkkauto.com.

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU748Z

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	✓
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	120.
3 RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	✓
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	100.
5 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	✓
6 UG10	RENEW FRONT ^{REAR} WINDSHIELD GLASS ASSY.	240.00	✓
7 ZZ/001	REPAIR BOTH REAR FENDER AND RENEW END PANEL, TAILGATE, REAR BUMPER	1200.00	250. 750.
8 ZZ/002	S/PAINT REAR PORTION AND BUMPER (2 TONES)	1400.00	700.
9 ZZ/003	TRANSFER TAILGATE MECHANICAL PARTS	80.00	✓
10 ZZ/004	R/I DVR TO ASSST REPAIR	120.00	✓
11 ZZ/005	SUPPLY AND RENEW REAR NO. PLATE (SMART PLATE WITH CASING) BLACK CASING (LONG)		
TOTAL LABOUR CHARGES		4080.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU748Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 GROMET C/LAMP \$4.40 EA X 02	26557-2U000	8.80	?		
2 GROMMET C/LAMP	76848-35F00	1.90	?		
3 CLIP C/LAMP \$4.80 EA X 02	26398-ED000	9.60	?		
4 LAMP COMB RR,LH TAILGATE	26555-HV55A	215.90			cut
5 LAMP COMB RR,LH	26555-HV00A	323.70	?		
6 EMBLEM	90892-4EA0A	87.00			new
7 EMBLEM-REAR	90890-4EA0A	59.70			new
8 STRIKER-TAIL GA	90570-4EA0A	31.70	?		
9 A LOCK LIFT	90502-4EA1B	116.70	?		
10 A FIN BACK DOOR NO PLATE	90810-4ES0H	336.00	?		
11 DOOR BACK	K0100-HV0MB	2936.80			bt
12 RUBBER-DUM	G2716-89901	60.20			new
13 GLASS-TAIL GATE	90300-HV00A	930.00			new
14 STAY ASSY-REAR RH	H5210-4EAMA	126.00	X		
15 STAY ASSY-REAR LH	H5211-4EAMA	126.00	?		
16 REINF-BUMPER RR	H5030-4EAMA	619.20	?		
17 ENERGY ABSORBER	85090-HV00A	126.40	?		
18 CANOE BUMPER \$6.50 EA X 02	76882-0M000	13.00			new
19 CLIP BUMPER \$7.40 EA X 03	85284-JD00A	22.20			new
20 BRACKET-BUMPER RH	85220-4EA0A	35.90	X		
21 RETAINER-BUMPER RH	79184-4EA0A	23.80	X		
22 BRACKET-BUMPER LH	85221-4EA0A	35.90			new
23 RETAINER-BUMPER LH	79185-4EA0A	23.80			new
24 FINISHER-REAR BUMPER TOW	85071-HV00A	16.80	X		
25 FASCIA-RR BUMP	85022-HV00H	717.00			de

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU748Z

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26 CLIP FENDER \$1.20 EA X 02	01553-05323	2.40	net	
27 CLIP FENDER \$1.20 EA X 04	01554-00181	4.80	net	
28 PLATE-LUGGAGE	84992-4EA0A	63.50	?	
29 CLIP FENDER \$1.20 EA X 05	01553-05131	6.00	net	
30 GROMMET FENDER	01281-00831	1.50	?	
31 PROTECTOR-REAR LH FENDER	76749-4EA0A	186.40	X	
32 FENDER LH REAR ARC	93829-4EA0A	483.00	?	
33 REAR W/SCREEN SEALANT	SEALANT - 4			80.00 net
34 SUNDRIES	NPN			100.00 20.
35 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			210.00 ant
36 REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG RLP				60.00 X
SUB TOTAL		7751.60	0.00	450.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1550.32	0.00	0.00
GRAND TOTAL		6201.28	0.00	450.00
OVERALL TOTAL		6651.28		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLU748Z

TOTAL LABOUR CHARGES	4080.00
TOTAL SPARE PARTS CHARGES	6651.28

GRAND TOTAL	10731.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.