

PASS. REC. BY:

REF: CS/CTI18009791/4td3d4 Social Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Cheng Boon Senof CTIDate/Time: 28/5/18 @ 5:02pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKN7151Y

Insured:

at Workshop m/s

Jin Auto ServiceTel: 6289 8126of Blk 14 Defu Lane 10 # 01-410Policy No: DMPCS N1753391700 Claim No: SNM18D02629C01Sum Insured: Excess: \$250.00Make of Veh:
(Client's Record)D.O.A. 25/5/2018CA / REV REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 5:01pm @ 30/5/18 Person Contacted: JavisVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
3/15-	<u>SKN 7151Y-X</u>
3/15@	<u>Report via menmen</u>
3/15@	<u>11:57am - authorise repair by Alfred Tan excess \$250</u>
3/15@	<u>1:15pm - email to Javis authorise repair excess \$250 P/R</u>

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKN 71514at Workshop n/s J. n. Ave.

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 250

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 2864.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLump Sum: 1.3d % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Rep 9800

Vehicle: IN / OUT

Veh No: SKN 71514 Yr Regn: 31/12 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Toyota Camry o.c. 1998Colour: Grey W/O: Insured / Std / NI / NASp. Reading: 125743 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053BK4107047701

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Green - Max

Front

Rear

R/Bal. 2 mm R/Bal. 2 mmL/Bal. 2 mm L/Bal. 2 mmD.O.A. 25/5/18 D.O.I. 30/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rep.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L7A 17989Repair ashy p/p because no second hand parts
Part by part \$4858.04 (Red: 2642.68 : 35%)

RECEIVED 14 JUN 2013

Date/Time, File Pass to?



: Prell. Report

1) 14/6 TYPST.

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S > RS, \$

Photos

Others

TOTAL

Report Format: OPLump Sum / I.B.I. (\$) 4858.04220220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018 Sendback Est	28 May 2018 15:48 S\$7,410.72	28 May 2018 17:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	TAN MENG HARK MELVIN, ID: S7125006G, Tel: +6581882428		
Vehicle Reg. No.:	SKN7151Y	Date of Loss:	25/05/2018 00:00 - :59 [100 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D02629C01	Policy/Cover Note No.:	DMPCSN1753391700 (Comprehensive)
		Excess:	S\$250.00
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/06/2018]		
Driver/Custodian:	TAN MENG HARK MELVIN (/ Male), NRIC: S7125006G, Tel: +6581882428		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Mawcus will
survey.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18009791/Utd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 31-05-2018		
		Code : CTI		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SKN 7151Y	
Policy No.	DMPCSN1753391700	Coverage (\$)	0.00	
Claim No.	SNM18D02629C01	Excess (\$)	250.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	31/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/05/2018	Inspection Date	30/05/2018	
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

View Received Message

This mail is associated with :

SKN7151Y (SNM18D02629C01)

OD

May 25 2018 12:00AM

[TAN MENG HARK MELVIN]

Jin Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **31/05/2018 11:57 AM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5569.84) - SKN7151Y - Claim Handler: Chong Boon Sen

Approved:5569.84:PROCEED TO AUTHORIZE REPAIRS AT \$5,569.84 BEFORE EXCESS OF \$250.00

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAUTO)

From: jouis <jouis@jinauto.com.sg>
Sent: Thursday, 14 June 2018 12:25 PM
To: Denise Tay (LKKAUTO)
Subject: RE: SKN 7151Y OD CHINA TAI PING

Dear Denise ,

Ok Confirm

Thank you & Best Regards,
Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590
Email : jouis@jinauto.com.sg

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 14 June 2018 11:54 AM
To: jouis@jinauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: SKN 7151Y OD CHINA TAI PING

Dear Jouis,

Finalized amount at \$4858.04 on part by part. 5days.

Please check and confirm.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 31 May 2018 12:10 PM
To: jouis@jinauto.com.sg
Cc: SUR
Subject: SKN7151Y / OD / CHINA TAIPING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKN7151Y (Excess \$250/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 5006G

Vehicle Details

Vehicle No.: SKN7151Y
Vehicle to be Exported: No
Intended De-registration Date: 30 May 2018
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: 1AZE144480
Chassis No.: MR053BK4107047701
Maximum Power Output: 108.0 kW (144 bhp)
Open Market Value: \$27,271.00
Original Registration Date: 31 Dec 2009
First Registration Date: 31 Dec 2009
Transfer Count: 1
Actual ARF Paid: \$27,271.00 13135

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Dec 2019
PARF Rebate Amount: \$14,999.00

Intended COE Rebate Details

COE Expiry Date: 30 Dec 2019
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$18,890.00
COE Rebate Amount: \$2,990.00
Total Rebate Amount: \$17,989.00

The information contained herein is correct as at 30 May 2018

OK

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 5006G

Vehicle Details

Vehicle No.: SKN7151Y

Vehicle to be Exported: No

Intended De-registration Date: 30 May 2018

Vehicle Make: TOYOTA

Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: 1AZE144480

Chassis No.: MR053BK4107047701

Maximum Power Output: 108.0 kW (144 bhp)

Open Market Value: \$27,271.00

Original Registration Date: 31 Dec 2009

First Registration Date: 31 Dec 2009

Transfer Count: 1

Actual ARF Paid: \$27,271.00 13135

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Dec 2019

PARF Rebate Amount: \$14,999.00

Intended COE Rebate Details

COE Expiry Date: 30 Dec 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$18,890.00

COE Rebate Amount: \$2,990.00

Total Rebate Amount: \$17,989.00

The information contained herein is correct as at 30 May 2018

OK

- North Korea Situation 2017 and beyond
- VES 2018
- The continuing GLOBAL stressful thread! Part II

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



\$2500 Downpayment Monthly
From \$580 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd



Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

31 vehicles

Toyota Camry

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Camry		Any	Any	2009	Any	Any	Any	Available



Toyota Camry 2.4A

\$30,500

\$11,560 /yr

14-Oct-2009

2,362 cc

-

Luxury

Available

1 Owner Car With High OMV Of \$29264. Very Well Maintained. Efficient And Powerful. In House And Trade In Available. Contact Our Friendly Sales Team For Free Quotes On Loans And Insurance!

Posted: 30-May-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$29,800

\$10,330 /yr

23-Dec-2009

1,998 cc

118,000 km

Luxury

Available

3 Months Warranty From Our In-house Workshop, Excellent Condition, Accident Free, Bank Loan In-house Loan Available, Trade In Welcome.

Posted: 29-May-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$26,500

\$10,430 /yr

24-Aug-2009

1,998 cc

164,783 km

Luxury

Available

Well Maintained, Well Taken Care Of. One Owner Only. Sincere Seller, Call/Text For Viewing! No Dealers/Agent.

Posted: 29-May-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

DIRECT OWNER



Toyota Camry 2.0A

\$26,500

\$12,110 /yr

01-Jul-2009

1,998 cc

-

Luxury

Available

Elegant Silver, Spacious Sedan, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 28-May-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Buy Tyres Online!

Latest Special Offers from Tyrepac!



Toyota Camry 2.4A

\$21,999

\$8,990 /yr

24-Apr-2009

2,362 cc

171,048 km

Luxury

Available

Depreciation \$8400 Plus 6 Month Road Tax(\$819) Paid Till Oct 2018.(100% Accident Free, Very Low Mileage Done! Very Well Maintained By Owner. View To Appreciate! Drive This Pristine Silver Exterior Wi...

Posted: 25-May-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.4A

\$26,800

\$10,560 /yr

19-Aug-2009

2,362 cc

94,000 km

Luxury

Available

Best Buy! Low Mileage! Servicing Just Done, Excellent Condition View To Believe, Well Kept Interior, Very Smooth & Quiet While Driving!, Superb Conditions, Grab It Before It Gone, Loan And Trade In Av...

Lay Auto Pte Ltd

Posted: 25-May-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

PREMIUM AD

Toyota Camry 2.0A

\$18,800

\$9,380 /yr

21-Jan-2009

1,998 cc

-

Luxury

Available

Well Maintained By Meticulous Owner. Excellent Condition. Spacious Interior And Large Boot Space. Ideal For Short Term Driving Or Renewal Of COE! Please Feel Free To Call Our Friendly Sales Consultant...

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/05/2018 14:09
Date Of Accident	25/05/2018 20:30
Exact Location Of Accident	TPE NEAR TAMPINES EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN7151Y
Insured/Policyholder	
Name Of Registered Owner	TAN MENG HARK MELVIN
NRIC No	S7125006G
Email Address	MELVIN.TAN@OCTOPUSGROUP.COM.SG
Mobile Phone No	(LOCAL) +65-81882428
Alternative Phone No	OTHERS-81882428

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.0 AUTO ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	PTE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1753391700
Cover Note Number	

Driver

Name of Driver	TAN MENG HARK MELVIN
NRIC No	S7125006G
Date Of Birth	16/07/1971
Occupation	INDOOR
Date Of Driving Pass	18/08/2007
Driving Experience	10 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81882428
Fax Number	
Contact Number	OTHERS-81882428
EMail Address	MELVIN.TAN@OCTOPUSGROUP.COM.SG

Vehicle Make/Model/Colour	TOYOTA WISH
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ADELINE
NRIC/Passport Number	
Contact Number	96799720
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: :
	GENDER: :

DETAILS OF OTHER VEHICLE PROPERTY 3


Vehicle Registration Number	GBA1094T
Vehicle Make/Model/Colour	TOYOTA DYNA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PANNEER SELVAM RAVI KUMAR
NRIC/Passport Number	G5273203X
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CASSANDRA WONG CHUAY MIN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJH8296A
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN



Date: 25-5-2018
 A: SKN7151Y
 B: SSH8296A
 C: SKK9666G
 D: GBA1094T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I travelled along TPE towards Tampines on the third lane. Front Vehicle B,
 SSH8296A suddenly stopped, I could not stopped in time, hit onto its rear portion.
 Upon checking, I realised that Vehicle C, SKK9666G and Vehicle D, GBA1094T
 were also involved in the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: Cassandra
 NRIC/FIN No.: 63229391W



REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 May 2018)**Parts:** 143 TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Jin Auto Services Pte Ltd/SKN7151Y/28/05/2018 15:48**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BONNET	0.00	0.00	Buc ✓ *520.00 F
2	1	NA	*BONNET FRONT SEAL	0.00	0.00	nn X *25.00 F
3	1	NA	*BONNET INSULATION	0.00	0.00	SVC X *200.00 F
4	1	NA	*BUMPER SUPPORT	0.00	0.00	DD ✓ *165.00 F
5	1	NA	*CONDENSER	0.00	0.00	Bent Rm *450.00 F
6	1	NA	*CTR BUMPER GRILLE	0.00	0.00	GO Tm *70.00 F
7	1	NA	*FRONT BUMPER	0.00	0.00	DIS ✓ *550.00 F
8	1	NA	*FRONT NUMBER PLATE	0.00	0.00	Brt 20 *30.00 F
9	1	NA	*FRONT PANEL	0.00	0.00	Bent Rm *450.00 F
10	1	NA	*FRT BUMPER ABSORBER	0.00	0.00	ORA ✓ *70.00 F
11	1	NA	*FRT NO PLATE REINF	0.00	0.00	Bent 20 *30.00 F
12	1	NA	*GRILLE	0.00	0.00	ORA ✓ *250.00 F
13	1	NA	*L/BLOWER FAN	0.00	0.00	nn X *90.00 F
14	1	NA	*L/F WING	0.00	0.00	R X *210.00 F
15	1	NA	*L/FAN MOTOR	0.00	0.00	nn *300.00 F
16	1	NA	*L/HORN	0.00	0.00	nn *80.00 F
17	1	NA	*L/WHEELHOUSE SHELL	0.00	0.00	nn X *90.00 F
18	1	NA	*LEFT HEADLAMP ASSY	0.00	0.00	ORA ✓ *500.00 F
19	1	NA	*LOCK CARRIER STRUT	0.00	0.00	Twl ✓ *60.00 F
20	1	NA	*LOWER BONNET LOCK	0.00	0.00	Twl ✓ *75.00 F
21	1	NA	*R/BLOWER FAN	0.00	0.00	nn *90.00 F
22	1	NA	*R/F WING	0.00	0.00	R X *210.00 F
23	1	NA	*R/FAN MOTOR	0.00	0.00	nn X *300.00 F
24	1	NA	*R/WHEELHOUSE SHELL	0.00	0.00	nn X *90.00 F
25	1	NA	*RADIATOR	0.00	0.00	SVC X *550.00 F
26	1	NA	*RADIATOR SHROUD	0.00	0.00	nn X *160.00 F
27	1	NA	*RIGHT HEADLAMP ASSY	0.00	0.00	ORA ✓ *500.00 F
28	1	NA	*SUNDRY PARTS	0.00	0.00	✓ *100.00 F

F=Franchise part.

Total Parts (S\$)**6,215.00**

Jin Auto Services Pte Ltd/SKN7151Y/28/05/2018 15:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New 428.40	512.40
2	Total Paint Materials	New 209.44	250.72
3	Total Panel/Mechanical Labour	New 340.70	432.60
Gross Labour Cost (S\$)			1,195.72

Jin Auto Services Pte Ltd/SKN7151Y/28/05/2018 15:48. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: SNM18D02629C01
Assessment Number: JA000103
Version: LKKAUTOC/3
Date Calculated: 14/06/2018 04:27

Full Report - V1
Registration: SKN7151Y
Printed: 14/06/2018 11:28

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	25/05/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D02629C01	Estimated Repair Time:	
Policy Number:	DMPCSN1753391700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Camry
Sub Model:	BASE MODEL
Model Sheet Number:	YCA 01
Registration:	SKN7151Y
Registration Month:	December
Registration Year:	2009
VIN Number:	MR053BK4107047701
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 12/2009	AUTO AIR CON
XENON HEADLAMPS	FOG LAMPS
2.0 LTR 108 KW	HYDRAULIC SERVO
WHEELS 6.5J X 16	VERSION THAILAND
PRODUCT THAILAND	PREMIUM PACK
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on	Mobile
	Inspection:	
Brakes Pedal Travel:	Date of Inspection:	28/05/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Good	
Tread Depth LHF:		Tread Depth RHF:
Tread Depth LHR:		Tread Depth RHR:
Damage Areas:		Direction of Impact:



Addresses

Cost Summary

Total Labour	\$768.60
Total Paint/Material	\$209.44
Total Parts	\$3,880.00
Repair Cost Exc GST:	\$4,858.04
Overall Discount (0.0%):	- \$0.00
Excess:	-\$250.00
After Deduction -	
Grand Total Exc GST:	\$4,608.04
7 % GST:	\$322.56
Grand Total Inc GST:	\$4,930.60

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
B100	R + R LEFT FRONT WING (FRT BUMPER AND L/HEADLAMP ASSY REMOVED)	4.0	16.80
B100	R + R RIGHT FRONT WING (FRT BUMPER AND R/HEADLAMP ASSY REMOVED)	4.0	16.80
B140	RENEW FRONT PANEL	22.0	92.40
B100	R + R LEFT SILL RAIL	3.0	12.60
B100	R + R RIGHT SILL RAIL	3.0	12.60
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS	15.0	63.00
B040	RENEW BOTH HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS	7.0	29.40
B070	RENEW BONNET	6.0	25.20
M010)	RENEW CONDENSER (REMOVED)	1.0	4.20
M010	R + R RADIATOR AND CONDENSER (FRONT BUMPER REMOVED) INCLUDES: BLEED COOLING SYSTEM	16.0	67.20

LABOUR COST

Total Work Units	81.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	8.1HRS	\$340.20
Paint Labour	10.2HRS	\$428.40
Total Labour	18.3HRS	\$768.60

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	BUMPER SUPPORT SURFACE PAINT	4.0	
471	BONNET NEW PART PAINTING	26.0	
988	LOCK CARRIER STRUT SURFACE PAINT	4.0	
1009	FRONT PANEL SURFACE PAINT	7.0	
344	FRT BUMPER ABSORBER SURFACE PAINT PLAST.	3.0	
283	FRONT BUMPER REPAIR PAINT PLASTIC	16.0	
410	GRILLE REPAIR PAINT PLASTIC	9.0	
LABOUR COST - PAINT			
	TIME(PAINT)	69.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	102.0	
	Total Paintwork Labour	10.2HRS	\$428.40
MATERIAL COST - PAINT			
	New Part Painting		\$87.72
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$22.66
	Surface Paint Plastic		\$1.46
	Repair Painting Plastic		\$56.30
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$209.44
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$209.44

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0%	20.00*
258	1	FRT NO PLATE REINF	KNPL0		0%	20.00*
283	1	FRONT BUMPER	52119 06961		0%	550.00*
340	1	BUMPER SUPPORT	52021 06060		0%	165.00*
344	1	FRT BUMPER ABSORBER	52611 06160		0%	70.00*
410	1	GRILLE	53111 06280		0%	250.00*
412	1	CTR BUMPER GRILLE	53112 06120		0%	60.00*
471	1	BONNET	53301 06110		0%	520.00*
493	1	LOWER BONNET LOCK	53510 06101		0%	75.00*
561	1	LEFT HEADLAMP ASSY	81150 06550		0%	500.00*
562	1	RIGHT HEADLAMP ASSY	81110 06550		0%	500.00*
988	1	LOCK CARRIER STRUT	53208 06040		0%	60.00*
1009	1	FRONT PANEL	53201 06171		0%	450.00*
4465	1	CONDENSER	88460 06170		0%	450.00*
1000	1	RADIATOR GRILLE LOGO	Renew		0%	40.00*
1000	1	NUMBER PLATE GARNISH	Renew		0%	50.00*
f: OEM Parts		Sub Total				\$3,780.00
g: Original		Sundry Parts				\$100.00
h: Secondhand		Total Parts				\$3,880.00

(Fixed)

p: Parallel
x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras		\$0.00
<hr/>		
Final Calculation		
Total Parts		\$3,880.00
Labour		
Total Panel/Mechanical	\$340.20	
Total Paintwork	\$428.40	
Total Labour		\$768.60
Total Paint/Material Costs		\$209.44
Repair Costs Excludes GST		\$4,858.04
Deductions		
Deduction for Excess (Fixed)	-\$250.00	
Total Deductions		-\$250.00
Grand Total Excludes GST (After Deduction)		\$4,608.04
GST @ 7 %		\$322.56
Grand Total Includes GST (After Deduction)		\$4,930.60

Assessment Notes

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jun 2018)

Parts: 143 TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Jin Auto Services Pte Ltd/SKN7151Y/13/06/2018 16:25

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RADIATOR GRILLE LOGO	0.00	0.00	*40.00 F ✓
2	1	ADD {	*NUMBER PLATE GARNISH	0.00	0.00	*50.00 F ✓
Total Parts (S\$)						90.00

F=Franchise part.

Jin Auto Services Pte Ltd/SKN7151Y/13/06/2018 16:25. Not valid without Reference section.

Generated using Merimen e-Claims IEAS