

ASS. REC. BY:

REF: es/FCI18009823/T1sd3 ⁿ²

Special Instruction:

Surveyor:

CWS

Taufik

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time: 30/5/18 @ 9.59am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGT 9723A

Insured:

SHA 7208Y

at Workshop m/s

Prime Auto Claim

Tel:

68610908

of

G Benoi Place

Policy No:

Claim No:

D18004231MP8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/05/2018

CA / REV / REP. / REV 24 HRS

lup)

H.O.D. Endorsement:

Date/Time:

10:10am @ 31/5/18

Person Contacted:

pei yee

Vehicle:

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SGT 9723A - CS/INC14008838/Gqbd1

Dof: 3/4/18

SHA 7208Y - CS/TMI13005590/M/vd1

Dof: 22/03/2013

04/06/18 @ 10:53am. revised PA to Eileen via email.

Signature

Taufik

REF:

FCI

ASSIGNMENT

col 2022 mod

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 425K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Alice

Veh No: SGT 9723A Yr Regn: 2007 mod
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Altis C.C. 1598
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: M R0537EC 107143354
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/B / STD A/Rim or
 Tyre Size: F: 185/70R14
 R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Good ride

Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 50/5/18

Survey held at Prime Auto
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt o/s, u/c
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction No Key
1/5/2018, 6 days conf e-mail to Alice
(P2,659.27 Red - 47%)

RECEIVED 22 JUN 2018

Date/Time: File Pass to?

22/06/18

1) Typist

Date/Time: File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$) HS \$2,950/-

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

140

50

29

219



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004231MFSH

Date: 04 June 2018

Our Ref: CS/FCI18009823/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGT 9723A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/05/2018 at the premises of M/s Prime Auto Claims Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,609.27</u> .
Revised Estimate Amount	: S\$ <u>3,284.72</u> .
"Check" Items Amount	: S\$ <u>1,343.22</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the front o/s portion and u/c affected due to collision.



Comments/ Present Status:

Damages Consistent.
Repair days: 6 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-05-2018	Our Ref No. D18004231MFSH
Accident Date	25-05-2018	Claim Type. Third Party
Insured Vehicle	SHA7208Y	Third Party Vehicle. SGT9723A
Survey Location	6 Benoi Place	
Contact Person.	PEI YEE	
Contact No.	68610908/ 0	Fax No. 65152948
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIME AUTO CLAIMS SERVICE PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SGT9723A
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Chassis No.:	MR053ZEC107143354
Propellant:	Petrol
Engine No.:	3ZZ4636662
Engine Capacity:	1598 cc
Maximum Power Output:	81.0 kW (108 bhp)
Maximum Laden Weight:	1600 kg
Unladen Weight:	1115 kg
Year Of Manufacture:	2007
Original Registration Date:	19 Mar 2007
Lifespan Expiry Date:	-
COE Category:	A - Car (1600cc & below)
PQP Paid:	\$24,715.00
COE Expiry Date:	18 Mar 2022
Road Tax Expiry Date:	18 Mar 2018
Inspection Due Date:	18 Mar 2018
Intended Transfer Date:	02 Jan 2018
CO2 Emission:	-

Shirley Hiew (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Thursday, 21 June 2018 6:43 PM
To: Admin-D (LKKAuto)
Subject: FW: FINALIZE TO SGT9723A

CS/FCI18009823/T1sd3

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Taufikh (LKKAuto)
Sent: Thursday, 21 June, 2018 1:07 PM
To: 'Alice Leong' <aliceleong@primeautoclaims.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: FINALIZE TO SGT9723A

Hi Alice,

COR I/s \$2950 , 6 days.

Regards

Taufikh

Lkk Auto

From: Alice Leong [<mailto:aliceleong@primeautoclaims.com>]
Sent: Tuesday, 5 June 2018 9:42 AM
To: 'Taufikh (LKKAuto)'
Cc: admin-a@lkkauto. com
Subject: FINALIZE TO SGT9723A
Importance: High

Hi Taufikh,

We enclosed our after repair photos & our calculation sheet for your retention. Shall we finalize at LS \$2,950/- and 6 days

Please let us have your confirmation within three days from our e-mail.

Thank you

Alice Leong

Motor Claims Manager

Prime Auto Claims Service Pte Ltd
5 Benoi Place Singapore 629926
T (65): 6861 0908 | F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

Disclaimer

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 4 June 2018 10:53 AM
To: 'cwsmotorclaims@msfirstcapital.com.sg'; 'EILEENLEE@MSFIRSTCAPITAL.COM.SG'
Cc: 'assignments@lkkauto.com'; 'Nivitha (LKK Auto)'
Subject: RE: SURVEY ASSESSMENT - D18004231MFSH/1
Attachments: SGT 9723A - Preli Advise.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SGT 9723A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Wednesday, 30 May, 2018 10:10 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D18004231MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 28 May, 2018 4:39 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004231MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 28.05.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SGT9723A TOYOTA ALTIS (2007)

To Supply

1)	1pc	Right front door	\$	bt	1,135.50
2)	1pc	Right front door protector	\$	de	72.10
3)	1pc	Right front door protector chrome	\$	mt	32.10
4)	1set	Right front door frame black sticker	\$	rec	59.30
5)	1pc	Right front door top hinge	\$	o ?	82.40 Xnn
6)	1pc	Right front door lower hinge	\$	mt ?	83.50 bt
7)	1pc	Right front door checker	\$	?	157.60 Xnn
8)	1pc	Right front fender	\$	bt	436.80
9)	1pc	Right front fender cowling	\$	de	188.60
10)	1set	Right front fender cowling clip	\$	mt	30.00
11)	1pc	Front right wheel nuckle	\$	?	516.50 Xnn
12)	1pc	Front right lower arm	\$	?	245.07 Xnn
13)	1pc	Front right shock absorber	\$	?	311.47 bt
14)	1pc	Front right tie rod end	\$	?	127.75 Xnn
15)	1pc	Right front fender lamp	\$	dy	25.23
16)	1pc	Right front wheel house panel	\$	Ry	255.10

Sub total parts	\$	3,759.02	2574.60
Less: 25% discount	\$	939.75	
	\$	2,819.27	1780.95

To Supply S.Nett Parts

1) 1pc	Right front sport rim	\$	200.00	cut ✓
Sub total S.Nett Parts		\$	200.00	

L/charges

1)	Towing charges	\$	40.00	✓
2)	To tuff kote	\$	50.00	30
3)	To transfer right front door trim, handle, window glass, mechanism parts	\$	60.00	40
4)	To remove front right wheel, replace sport rim & balance tyre	\$	60.00	30 ✓
5)	To computer wheel alignment	\$	80.00	60 ✓
6)	To remove front right wheel nuckle, shock absorber, lower arm & tie rod end. Replace the above parts.	\$	200.00	120 ✓
7)	To remove right front door, right front fender & front bumper. To knock & repair right front door pillar & right front wheel house panel. Replace right front door & right front fender. Align & adjust right front fender and right front door.	\$	900.00	700
8)	To putty, respray painting right front door inner & outer, right front door pillar, right front fender, front bumper & right front wheel house panel. To polish	\$	1,200.00	700

Sub total L/charges \$ 2,590.00
 Estimate Grand Total \$ 5,609.27

3700.95
 4150 2950 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 97425749
 - WP

30/5/18 @ 5pm

Curry

Repair after repair

6 days

sure@lkk.com

6 days
 26/18

26-05-18 11:57 From

To 62659941

1 / 7



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 28.05.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SGT9723A TOYOTA ALTIS (2007)

To Supply

- 1) 1pc Right front door
- 2) 1pc Right front door protector
- 3) 1pc Right front door protector chrome
- 4) 1set Right front door frame black sticker
- 5) 1pc Right front door top hinge
- 6) 1pc Right front door lower hinge
- 7) 1pc Right front door checker
- 8) 1pc Right front fender
- 9) 1pc Right front fender cowl
- 10) 1set Right front fender cowl clip
- 11) 1pc Front right wheel nuckle
- 12) 1pc Front right lower arm
- 13) 1pc Front right shock absorber
- 14) 1pc Front right tie rod end
- 15) 1pc Right front fender lamp
- 16) 1pc Right front wheel house panel

\$	bt	1,135.50
\$	de	72.10
\$	mt	32.10
\$	pac	59.30
\$	a	82.40 X
\$	pac	83.50
\$	?	157.60 X
\$	bt	436.80
\$	de	188.60
\$	mt	30.00
\$	a	516.50 X
\$	?	245.07 X
\$	?	311.47 ✓
\$	?	127.75 X
\$	mt	25.23
\$	Rv	255.10 X

Sub total parts	\$	3,759.02	2374.60
Less: 25% discount	\$	939.75	- 594.00
	\$	2,819.27	1781.00

28-05-18 11:57 From

To: 62659941

21 7

To Supply S. Nett Parts

- 1) 1pc Right front sport rim

\$ 200.00 *cal ✓*

Sub total S Nett Parts \$ 200.00 *✓*

L/charges

- 1) Towing charges

\$ 40.00 *✓*

- 2) To tuff kote

\$ 50.00 *30*

- 3) To transfer right front door trim, handle, window glass, mechanism parts

\$ 60.00 *40*

- 4) To remove front right wheel, replace sport rim & balance tyre

\$ 60.00 *30 ✓*

- 5) To compute wheel alignment

\$ 80.00 *60 ✓*

- 6) To remove front right wheel nuckle, shock absorber, lower arm & tie rod end. Replace the above parts.

\$ 200.00 *120 ✓*

- 7) To remove right front door, right front fender & front bumper. To knock & repair right front door pillar & right front wheel house panel. Replace right front door & right front fender. Align & adjust right front fender and right front door.

\$ 900.00 *200*

- 8) To putty, respray painting right front door inner & outer, right front door pillar, right front fender, front bumper & right front wheel house panel. To polish

\$ 1,200.00 *200*

Sub total L/charges \$ 2,590.00 *1780.00*
Estimate Grand Total \$ 5,609.27

*- 65 - 20% 3701.00
- 740.00*

*Tanjan 9744549
WP
20/5/18 @ Spm
Cumpson
Rony after repair
Gdgs
sue@kumkum.com*

2961.00

✓

15 2950/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009823/T1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7208Y	Veh. Inspected	SGT 9723A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004231MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	30/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053ZEC107143354	Colour	SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	GOODRIDE	6 mm	
L/H Front Tyre	185/70 R14	GOODRIDE	6 mm	
R/H Rear Tyre	185/70 R14	GOODRIDE	6 mm	
L/H Rear Tyre	185/70 R14	GOODRIDE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/05/2018	Inspection Date	30/05/2018	
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 9723A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RIGHT FRONT DOOR	BENT	1,135.50	1,135.50
1	RIGHT FRONT DOOR PROTECTOR	DEFORMED	72.10	72.10
1	RIGHT FRONT DOOR PROTECTOR CHROME	CUT	32.10	32.10
1	SET RIGHT FRONT DOOR FRAME BLACK STICKER	NECESSARY	59.30	59.30
1	RIGHT FRONT DOOR TOP HINGE	NOT NECESSARY	82.40	-
1	RIGHT FRONT DOOR LOWER HINGE	BENT	83.50	83.50
1	RIGHT FRONT DOOR CHECKER	NOT NECESSARY	157.60	-
1	RIGHT FRONT FENDER	BENT	436.80	436.80
1	RIGHT FRONT FENDER COWLING	DEFORMED	188.60	188.60
1	SET RIGHT FRONT FENDER COWLING CLIP	NECESSARY	30.00	30.00
1	FRONT RIGHT WHEEL NUCKLE	NOT NECESSARY	516.50	-
1	FRONT RIGHT LOWER ARM	NOT NECESSARY	245.07	-
1	FRONT RIGHT SHOCK ABSORBER	BENT	311.47	311.47
1	FRONT RIGHT TIE ROD END	NOT NECESSARY	127.75	-
1	RIGHT FRONT FENDER LAMP	DISTORTED	25.23	25.23
1	RIGHT FRONT WHEEL HOUSE PANEL	TO REPAIR SEE LABOUR	255.10	-
	LESS 25% DISCOUNT		-939.75	-593.65
			2,819.27	1,780.95
SPECIAL NETT ITEMS				
1	RIGHT FRONT SPORT RIM (SN)	CUT	200.00	200.00
			200.00	200.00
LABOUR				
	TOWING CHARGES.		40.00	40.00
	TO TUFF KOTE.		50.00	30.00
	TO TRANSFER RIGHT FRONT DOOR TRIM,HANDLE,WINDOW GLASS,MECHANISM PARTS.		60.00	40.00
	TO REMOVE FRONT RIGHT WHEEL,REPLACE SPORT RIM & BALANCE TYRE.		60.00	30.00
	TO COMPUTER WHEEL ALIGNMENT.		80.00	60.00

Report Ref No. CS/FCI18009823/T1sd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE FRONT RIGHT WHEEL NUCKLE,SHOCK ABSORBER,LOWER ARM & TIE ROD END.REPLACE THE ABOVE PARTS.		200.00	120.00
	TO REMOVE RIGHT FRONT DOOR,RIGHT FRONT FENDER & FRONT BUMPER.TO KNOCK & REPAIR RIGHT FRONT DOOR PILLAR & RIGHT FRONT WHEEL HOUSE PANEL.REPLACE RIGHT FRONT DOOR & RIGHT FRONT FENDER,ALIGN & ADJUST RIGHT FRONT FENDER AND RIGHT FRONT DOOR.		900.00	700.00
	TO PUTTY,RESPRAY PAINTING RIGHT FRONT DOOR INNER & OUTER,RIGHT FRONT DOOR PILLAR,RIGHT FRONT FENDER,FRONT BUMPER & RIGHT FRONT WHEEL HOUSE PANEL.TO POLISH.		1,200.00	700.00
			2,590.00	1,720.00
GRAND TOTAL			5,609.27	3,700.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,950.00

Report Ref No. CS/FCI18009823/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.