

YUWING

ASS. REC. BY:

REF: C3/FCI18069825/R1/d30

Special Instruction:

Surveyor: Ralsu

ASSIGNMENT (Office)

From (Person): Karen Tan

of FCI

Date/Time: 28/5/18 @ 542pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 1750H

Insured:

SHC 1036 E

Workshop m/s

Ding Auto

Tel:

6458 9523

of

Blk 10, 8n ming Ind. Est. Sec-C #01-20

Policy No:

Claim No:

D18004165 MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/05/2018

Insp: 219 jalan bron lay

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS 'up'

Date/Time:

12:48pm 31/5/18

Person Contacted:

Ah hong

Vehicle

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 1750H - C03/1CR17C0568E/H/og3s2 D.O.A: 17/03/2017
	SHC1036E - NS/INC130160A9/Yqk3 D.O.A: 28/5/13
	Time n \$25,000/- cRed. 30106511.54%)

SUNDAY

REF:

4597K

ASSIGNMENT

From: Date:

Estimated Cost:

OO / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLN 1750H

at Workshop m/s DUNH AUTO

of 249, Glen Rowley

Insured

FLI/TP

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

79K

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 1750H

Yr Regn:

2016 86P

Type: M.Co / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA COROLLA ALTIS

CC:

1500

Colour:

GREY

A/C:

Insured / Std / NI / NA

Sp Reading:

122312

Ti/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053 REH 6455796

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Harder / Jammed / Leaked / Burnt or

Brake: Harder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/65R15

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

23/05/18

D.O.I:

30/05/18

Survey held at

DUNH AUTO

Des. of Damages:

Rear

UIC

Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/05/18 spoken to jeng for nett repair limit is :25K He noted

RECEIVED 8 AUG 2018

Date/Time: File Pass to?



Prefl. Report



Final Report

11/8 Typist

Date/Time: File Return to?

Days Of Repair: 30

Resurvey No. of Trip: 2

Add Fee:



Site Insp: \$



Interview: \$



Tech. Insp: \$



Weekend: \$

Report Format:

Lump Sum / L.B.I: \$

25 000/-

Survey Fee:

Transport:

Other:

Other:

Other:

Other:

56Y15 = 690

170 + 690

50

50+50

200

1250

8/8/18

MOTOR SURVEY ASSIGNMENT

Date	24-05-2018	Our Ref No. D18004165MFSH
Accident Date	23-05-2018	Claim Type. Third Party
Insured Vehicle	SHC1036E	Third Party Vehicle. SLG1750H
Survey Location	BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-20	
Contact Person.	YOU JING FENG	
Contact No.	64589523/ 97335832	Fax No. 64534227
Survey Type		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	DING AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

MDAP18068353 / Ding Auto Pte Ltd - HQ

ENTRY DATE & TIME: 25/05/2018 17:49

SUBMITTED BY: You Jing Feng

Your NCD will be affected due to late reporting

Actual e-Filing Submission Date & Time: 25/05/2018 18:30

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/05/2018 17:49
Date Of Accident	23/05/2018 03:10
Exact Location Of Accident	JUNCTION BUKIT BATOK WEST AVENUE 3 AND AVE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG1750H
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995145
Cover Note Number	

Driver

Name of Driver	GOH JUN HAO
NRIC No	S8613266D
Date Of Birth	09/05/1986
Occupation	OUTDOOR
Date Of Driving Pass	09/11/2015
Driving Experience	2 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92394128
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	249 JALAN BOON LAY
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 92 BOON LAY WAY , POSTCODE: 609962 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8999999 - FAX NO: 66655791
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE NO SUBTABLE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC1036E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LIM SEE ANN
NRIC/Passport Number	S6941999B
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name GOH JUN HAO

Approximate Age

Injuries Sustain SERIOUS

Injured person in which vehicle? SLG1750H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

SKETCH PLAN



A: SLG1750H

B: SHC1036E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report (T/20180524/2128)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PM No.:



SINGAPORE POLICE FORCE



T/20180524/2128

1 of 4

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

Report No. T/20180524/2128

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/05/2018 16:01	Vide Report No.:	Station Diary No.: 86
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: GOH JUN HAO		Address: APT BLK 620 JURONG WEST STREET 65 #03-448 SINGAPORE 640620	
ID Type / ID No.: NRIC NO / S8613266D		Contact No.: Home/Office: Mobile: 88097554	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 32	Date of Birth: 09/05/1986	Type of Informant: Driver
Race: Chinese		Language: Chinese	Institution / School Name:
Occupation: Grab Driver		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/05/2018 03:30	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 BUKIT BATOK WEST AVENUE 3 BUKIT BATOK WEST AVENUE 8 near to Princess Elizabeth Primary School				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC1036E	Taxi				Slightly Damaged	0
SLG1750H	Car	TOYOTA	Altis	Grey	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

CONTINUATION OF REPORT

Driver				
Name	Lim See Ann @ Koh See Ann		ID No.	S6941999B
Related Vehicle	SHC1036E (Taxi)		Contact No.	85007197
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	Slight
Driver				
Name	GOH JUN HAO		ID No.	S8613266D
Related Vehicle	SLG1750H (Car)		Contact No.	88097554
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	23/05/2018		Date Discharge	23/05/2018
No. of Days granted Medical Leave	10		Degree of Injury	Serious

Brief Details.

On 23/05/2018 at about 0330hrs, I was driving my car bearing registration plate number of SLG1750H along Bukit Batok West Ave 3 on the left lane. Upon approaching cross junction of Bukit Batok West Ave 3 and Bukit Batok West Ave 8 near to Princess Elizabeth, I saw traffic light ahead was green light. I just proceed to drive to the traffic junction.

I then saw a Taxi bearing registration plate number of SHC1036E was on my left side. Suddenly I felt a huge impact from the left side of my car and then from my vision my car flip upside down and roll to the grass batch opposite Princess Elizabeth Primary School. I realized my car was upright position and I felt pain on my head, neck and elbow. I was conscious at the point of time but I felt very giddy. I then exited my car through passenger side as the driver door was stuck with the assistant of a motorcyclist. He also assisted to call for the police and ambulance. Then I called my parents and also my elder brother.

Subsequently, ambulance arrived and also SCDF. The paramedics checked on me and informed me that I need to be conveyed but I refused to. Then subsequently, traffic police came down and also informed me to make a police report if my medical leave is more than 3 days. Then my parents and elder brother came down and exchanged particulars with the other parties.

Then my family brought me to Ng Teng Fong General Hospital and I was given 10 days Hospitalization Leave. My injury is Avulsion Fracture and required to go physiotherapy on 07/06/2018 at 0930hrs. There is front camera installed in my vehicle.



**SINGAPORE
POLICE FORCE**



T/20180524/2128

3 of 4

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

Report No. T/20180524/2128

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180524/2128

4 of 4

Report No. T/20180524/2128

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 MERVYN PEA JIA WEI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

SI THABAGESH JEYATHESH

Contact No.: 65476232

Signature Of Informant:

Date/Time:

24/05/2018 16:01

Classification Of Case:

Authentication Stamp
NP168



SINGAPORE
POLICE FORCE

SN 34

SIGNATURE

Address 249 JALAN BOON LAY

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name JURONG EAST NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: NO. 92 BOON LAY WAY, POSTCODE: 609962, COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-8999999 - FAX NO: 66655791

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: FILE NO SUBTABLE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC1036E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver LIM SEE ANN

NRIC/Passport Number S6941999B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name GOH JUN HAO

Approximate Age

Injuries Sustain SERIOUS

Injured person in which vehicle? SLG1750H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRUC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLG1750H
Vehicle to be Exported:	Yes
Intended De-registration Date:	30 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRY332293
Chassis No.:	MR053REH104557796
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,800.00
Original Registration Date:	22 Sep 2016
First Registration Date:	22 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$16,800.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Sep 2026
PARF Rebate Amount:	\$12,600.00
Intended COE Rebate Details	
COE Expiry Date:	21 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,334.00
COE Rebate Amount:	\$42,667.00
Total Rebate Amount:	\$55,267.00

The information contained herein is correct as at 30 May 2018

OK

$$\begin{array}{r} 81,000 \\ 55,267 \\ \hline 25,733 \end{array}$$

25K

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SLG1750H
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Chassis No.:	MR053REH104557796
Propellant:	Petrol
Engine No.:	1ZRY332293
Engine Capacity:	1598 cc
Maximum Power Output:	90.0 kW (120 bhp)
Maximum Laden Weight:	1640 kg
Unladen Weight:	1205 kg
Year Of Manufacture:	2016
Original Registration Date:	22 Sep 2016
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$53,334.00
COE Expiry Date:	21 Sep 2026
Road Tax Expiry Date:	21 Mar 2019
PARF Eligibility Expiry Date:	21 Sep 2026
Inspection Due Date:	21 Sep 2019
Intended Transfer Date:	30 May 2018
CO2 Emission:	151.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

- 2015 Forester 2.0
- Do you have a "neighbor" car everyday you park...
- Maids scolded for sitting down with dogs and not walking

toyota altis

Price Range

Depreciation

Year Reg

Vehicle Type

Search

Advanced Search

Home > Used Cars > Viking Motor Pte Ltd > Toyota Corolla Altis 1.6A

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



Toyota Corolla Altis 1.6A

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$79,800	
Depreciation	\$8,570 /yr View models with similar depreciation	?
Reg Date	26-Sep-2016 (Byrs 3mths 26days COE left)	
Manufactured	2016	?
Mileage	20,158 km (12k /yr)	
Transmission	Auto	
Engine Cap	1,598 cc	
Road Tax	\$742 /yr	?
Power	90.0 kW (123 bhp) View specs of the Toyota Corolla Altis (2014)	
Curb Weight	1,205 kg	?
Features	Powerful 1.6L 4 Cylinders Inline 16 Valves Dual VVT-i Engine, CVT Auto Transmission, ABS, Airbags, Auto Headlights, Remote Key, Traction Control.	
Accessories	16" Sports Rims, New Leather Seats, Reverse Sensors, Electrical Retractable Side Mirrors, Auto Climate Control Aircon, Audio Aux/Ipod/USB.	
Description	\$0 Drive Away, 100% Loan Inclusive Of Insurance. Excellent Fuel Economy And Easy Handling. Flexible Loan Available, Non Smoker Car. Trade In Welcome. Price Negotiable, Call Or Visit Our Showroom Now For Viewing Now! 1 Year Free Warranty.	
COE	\$53,334	?
OMV	\$16,800	?
ARF	\$16,800	?
Dereg Value	\$57,021 as of today (change)	?
No. of Owners	2	?
Type of Veh	Mid-Sized Sedan	
Category	PARF Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 27-May-2018 | Last Updated on: 29-May-2018
Tag: Toyota Corolla, 2016 Toyota Corolla, Toyota, Corolla, Used Toyota



Seller Information

Company	Viking Motor Pte Ltd = dealer's pricelist = 9 vehs sold 14 vehs available
Address	210 Turf Club Road Lot 833 Search cars nearby this location
Location	Car Mall @ The Grandstand
Office No	64631339
Contact Person(s)	David 98417307 Alex 90016932 Jeffrey 86601482 Richard 90081978

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare

Upfront Payment

= more Financial Info

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

30/05/2018 14:39

JOB-NO: 85008337

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 6

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLG1750H

TRANS: AUTO

CHASSIS: MR053REH104557796

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY332293

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO R&R ENGINE WITH TRANSFER(TO FACILITATE BODYWORK REPAIRS AND TRANSFER AUTOMOTIVE TRANSMISSION ASSY)	1.00	350.00	0.00	350.00	Y	X	
2 TO R&R FRONT AND REAR SUSPENSION AND UNDERCARRIAGE PARTS DUE TO ACCIDENT DAMAGED	1.00	350.00	0.00	350.00	Y	250	
3 TO R&R AND ADJUST HEAD LAMP&TAIL LAMP AND RESET HEADLAMP FOCUSING AND CHECK LIGHTING AND CHECK WHOLE WIRING AND SORT CIRUIT	1.00	300.00	0.00	300.00	Y	30	
4 TO FULL WHEEL ALIGNMENT,BALANCING,BRAKE BLEEDING AND ROAD TEST	1.00	150.00	0.00	150.00	Y	60	
5 MOUNT ON WORKBENCH	1.00	350.00	0.00	350.00	Y	X	
6 TO REFILL A/C GAS	1.00	120.00	0.00	120.00	Y	100	
7 TO R&R SEAT BEALT,SEAT AND CARPET	1.00	150.00	0.00	150.00	Y	X	
8 TO R&R FRT WINDSCREEN	1.00	120.00	0.00	120.00	Y	120	
9 TO R&R REAR WINDSCREEN	1.00	120.00	0.00	120.00	Y	120	
10 TO SPRAY AND PATTY FRONT ACCIDENT DAMAGED AREA (FRONT BUMPER,SUPPORT PANEL,BRACE PANEL,BONNET),FRT FENDER RH&LH,REAR FENDER RH&LH,BOOTLID,REAR BUMPER,A PILLAR,B PILLAR,ROOFTOP PANEL,REVERSE SENSOR	1.00	3,000.00	0.00	3,000.00	Y	2800	
11 TO R&R AND WHOLE PANEL BEAT AND RE-ALIGN BODY WORKS AND ADJUST PART ON ACCIDENT DAMAGED AREA	1.00	6,000.00	0.00	6,000.00	Y	3800	
12 RUST PROOFING	1.00	100.00	0.00	100.00	Y	100	
13 TO R&R FRT RH&LH AND REAR RH&LH DOOR AND DOOR COMPARTMENT	1.00	400.00	0.00	400.00	Y	120/80	
14 TO R&R AND JACK ROOFTOP AND ROOF LINING	1.00	300.00	0.00	300.00	Y	100/200	
15 TO R&R DASHBOARDAND AND RE-ALIGNMENT DASHBOARD AND R&R SPEAKER PANEL AND SPEAKER PANEL TRIM	1.00	400.00	0.00	400.00	Y	150?	
16 TO RE-ALIGN EXHAUST PIPE AND FUEL TANK	1.00	200.00	0.00	200.00	Y	X	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
17 TO REPAIR AND RE-ALIGN ALL CHASSIS	1.00	200.00	0.00	200.00		Y	X <i>QVC</i>
TOTAL:		12,610.00	0.00	12,610.00			
MATERIALS							
1 FRONT BUMPER	1.00	511.22	127.81	383.41	L	Y	<i>DE</i>
2 FRONT BUMPER SIDE COVER(NO FOGLAMP)	<i>1pc</i> 1.00	116.34	<i>53.17</i> 29.09	87.25 <i>X</i>	L	Y	<i>cut</i> <i>43.62</i>
3 FRONT BUMPER LOWER GRILLE	1.00	58.17	14.54	43.63	L	Y	<i>DE</i>
4 FRONT BUMPER SIDE RETAINER RH	1.00	138.17	34.54	103.63	L	Y	<i>na</i>
5 FRONT BUMPER SIDE RETAINER LH	1.00	58.17	14.54	43.63	L	Y	<i>na</i>
6 FRONT REINFORCEMENT	1.00	386.60	96.65	289.95	L	Y	<i>X</i> <i>SVC</i>
7 FRONT BUMPER SPONGE	1.00	102.38	25.60	76.78	L	Y	<i>cut</i>
8 FRONT BUMPER LOWER CENTER COVER(ENGINE CENTER COVER)	1.00	211.67	52.92	158.75	L	Y	<i>cut</i>
9 BONNET	1.00	1,140.40	285.10	855.30	L	Y	<i>SVC</i>
10 BONNET RUBBER SEAL	1.00	65.70	16.43	49.27	L	Y	<i>na</i>
11 BONNET INSULATOR	1.00	301.36	75.34	226.02	L	Y	<i>na</i> <i>? compacted</i>
12 BONNET LOCK	1.00	162.80	40.70	122.10	L	Y	<i>X</i>
13 BONNET LOCK CABLE	1.00	77.80	19.45	58.35	L	Y	<i>X</i> <i>SVC</i>
14 BONNET LOCK CABLE HOLDER SET	1.00	81.60	20.40	61.20	L	Y	<i>X</i>
15 BONNET HINGE RH	1.00	76.60	19.15	57.45	L	Y	<i>BT</i>
16 BONNET HINGE LH	1.00	76.60	19.15	57.45	L	Y	<i>BT</i>
17 HEAD LAMP RH	1.00	794.10	198.53	595.57	L	Y	<i>SVC</i>
18 HEAD LAMP LH	1.00	794.10	198.53	595.57	L	Y	<i>SVC</i>
19 HEAD LAMP TOP CHROME MOULDING RH	1.00	150.67	37.72	113.15	L	Y	<i>SVC</i>
20 HEAD LAMP TOP CHROME MOULDING LH	1.00	150.67	37.72	113.15	L	Y	<i>SVC</i>
21 FRONT SUPPORT PANEL	1.00	1,074.60	268.65	805.95	L	Y	<i>na</i>
22 FRONT BRACE PANEL	1.00	115.70	28.93	86.77	L	Y	<i>na</i>
23 FRONT RADIATOR GRILLE	1.00	564.97	141.24	423.73	L	Y	<i>cha</i>
24 FRONT RADIATOR GRILLE "TOYOTA" EMBLEM	1.00	47.44	11.86	35.58	L	Y	<i>na</i>
25 FRONT RADIATOR GRILLE TOP GARNISH	1.00	124.70	31.18	93.52	L	Y	<i>X</i> <i>SVC</i>
26 FRONT FENDER RH	1.00	858.05	214.51	643.54	L	Y	<i>na</i>
27 FRONT FENDER LH	1.00	858.05	214.51	643.54	L	Y	<i>na</i>
28 FRONT FENDER "VVTI" EMBLEM RH	1.00	45.17	11.29	33.88	L	Y	<i>na</i>
29 FRONT FENDER "VVTI" EMBLEM LH	1.00	45.17	11.29	33.88	L	Y	<i>na</i>
30 FRONT FENDER INNER SHIELD RH	1.00	181.20	45.30	135.90	L	Y	<i>cut</i>
31 FRONT FENDER INNER SHIELD LH	1.00	181.20	45.30	135.90	L	Y	<i>cut</i>
32 FUSE BOX COVER	1.00	0.00	0.00	0.00	L	Y	<i>X</i>
33 FUSE BOX BASE	1.00	0.00	0.00	0.00	L	Y	<i>X</i>
34 RADIATOR ASSY	1.00	1,510.50	377.63	1,132.87	L	Y	<i>X</i> <i>SVC</i>
35 RADIATOR UPPER HOSE	1.00	55.69	13.92	41.77	L	Y	<i>X</i>
36 RADIATOR LOWER HOSE	1.00	61.25	15.31	45.94	L	Y	<i>X</i>
37 FRONT ENGINE MOUNTING RH	1.00	215.60	53.90	161.70	L	Y	<i>X</i>
38 FRONT ENGINE MOUNTING LH	1.00	215.60	53.90	161.70	L	Y	<i>X</i>
39 REAR ENGINE MOUNTING(GEARBOX)	1.00	0.00	0.00	0.00	L	Y	<i>X</i>
40 FRONT CROSSMEMBER CENTER	1.00	0.00	0.00	0.00	L	Y	<i>X</i>
41 FRONT CROSSMEMBER ENGINE MOUNTING	2.00	1,002.74	250.69	752.05	L	Y	<i>X</i>
42 FRONT W/S	1.00	1,458.30	364.58	1,093.72	L	Y	<i>na</i>
43 FRONT W/S MOULDING	1.00	102.40	25.60	76.80	L	Y	<i>na</i>
44 FRONT W/S WIPER BLADE	1.00	148.45	37.11	111.34	L	Y	<i>cut</i>
45 FRONT W/S COWL TOP VENTILATOR	1.00	0.00	0.00	0.00	L	Y	<i>X</i> <i>SVC</i>
46 FRONT W/S GARNISH SIDE SEAL	1.00	71.07	17.77	53.30	L	Y	<i>na</i>
47 REAR W/S	1.00	0.00	0.00	0.00	L	Y	<i>X</i> <i>SVC</i>
48 REAR W/S MOULDING	1.00	0.00	0.00	0.00	L	Y	<i>X</i> <i>SVC</i>
49 FRT DRIVE SHAFT RH	1.00	1,441.60	360.40	1,081.20	L	Y	<i>na</i> <i>BT</i>
50 FRT DRIVE SHAFT LH	1.00	1,441.60	360.40	1,081.20	L	Y	<i>na</i> <i>BT</i>
51 FRT LOWER ARM RH	1.00	265.07	66.27	198.80	L	Y	<i>na</i>
52 FRT LOWER ARM LH	1.00	0.00	0.00	0.00	L	Y	<i>na</i>
53 FRT SHOCK ABSORBER RH	1.00	316.97	79.24	237.73	L	Y	<i>na</i> <i>BT</i>

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
54 FRT SHOCK ABSORBER LH	1.00	316.97	79.24	237.73	L	Y	BT
55 FRT SHOCK ABSORBER TOP MOUNTING RH	1.00	0.00	0.00	29.66 0.00	L	Y	X SVC
56 FRT SHOCK ABSORBER TOP MOUNTING LH	1.00	0.00	0.00	219.60 0.00	L	Y	X BT
57 FRT SHOCK ABSORBER TOP MOUNTING DUST COVER RH	1.00	0.00	0.00	45.97 0.00	L	Y	X nec
58 FRT SHOCK ABSORBER TOP MOUNTING DUST COVER LH	1.00	0.00	0.00	45.97 0.00	L	Y	X nec
59 FRONT STABILIZER LINK RH	1.00	0.00	0.00	171.03 0.00	L	Y	PA
60 FRONT STABILIZER LINK LH	1.00	0.00	0.00	171.03 0.00	L	Y	X SVC
61 FRONT STABILIZER BAR	1.00	0.00	0.00	349.33 0.00	L	Y	X BT
62 FRONT STABILIZER BAR BRACKET LH	1.00	0.00	0.00	0.00	L	Y	X SVC
63 FRONT STABILIZER BAR BUSH RH	1.00	0.00	0.00	29.96 0.00	L	Y	X nec
64 FRONT STABILIZER BAR BUSH LH	1.00	0.00	0.00	29.95 0.00	L	Y	X nec
65 FRT STEERING RAIL&PINION ASSY	1.00	0.00	0.00	120.70 0.00	L	Y	X BT
66 FRT WHEEL BEARING RH	1.00	147.80	36.95	110.85	L	Y	X nec
67 FRT WHEEL BEARING LH	1.00	147.80	36.95	110.85	L	Y	X nec
68 FRT WHEEL BEARING HUB RH	1.00	238.70	59.68	179.02	L	Y	X SVC
69 FRT WHEEL BEARING HUB LH	1.00	238.70	59.68	179.02	L	Y	X BT
70 FRT GLASS RUBBER BEADING RH	1.00	0.00	0.00	0.00	L	Y	na
71 FRT GLASS RUBBER BEADING LH	1.00	0.00	0.00	0.00	L	Y	na
72 FRT DOOR GLASS RUN CHANNEL RH	1.00	142.50	35.83	106.67	L	Y	X SVC
73 FRT DOOR GLASS RUN CHANNEL LH	1.00	142.50	35.83	106.67	L	Y	X SVC
74 REAR BUMPER	1.00	486.55	121.64	364.91	L	Y	MS
75 REAR BUMPER SIDE RETAINER RH LONG	1.00	104.40	26.10	78.30	L	Y	X SVC
76 REAR BUMPER SIDE RETAINER LH LONG	1.00	104.40	26.10	78.30	L	Y	na
77 REAR BUMPER SIDE RETAINER RH SHORT	1.00	79.20	19.80	59.40	L	Y	X
78 REAR BUMPER SIDE RETAINER LH SHORT	1.00	79.20	19.80	59.40	L	Y	X
79 REAR BUMPER BEAM ARM RH	1.00	101.97	25.49	76.48	L	Y	X SVC
80 REAR BUMPER BEAM ARM LH	1.00	101.97	25.49	76.48	L	Y	X
81 REAR BUMPER REINFORCEMENT	1.00	378.42	94.81	283.61	L	Y	X
82 REAR BUMPER REFLECTOR RH	1.00	61.70	15.43	46.27	L	Y	MS
83 REAR BUMPER REFLECTOR LH	1.00	61.70	15.43	46.27	L	Y	MS
84 BOOTLID	1.00	679.61	219.90	659.71	L	Y	Repair
85 BOOTLID TOYOTA EMBLEM	1.00	66.17	16.54	49.63	L	Y	na
86 BOOTLID COROLLA EMBLEM	1.00	0.00	0.00	0.00	L	Y	na
87 BOOTLID ALTIS EMBLEM	1.00	0.00	0.00	0.00	L	Y	nec
88 BOOTLID OUTER CHROME GARNISH	1.00	211.20	52.80	158.40	L	Y	X SVC
89 TAIL LAMP RH (OUTER)	1.00	377.50	94.38	283.12	L	Y	X CR4
90 TAIL LAMP LH (OUTER)	1.00	377.50	94.38	283.12	L	Y	X SVC
91 TAIL LAMP RH (INNER)	1.00	293.57	73.39	220.18	L	Y	X SVC
92 TAIL LAMP LH (INNER)	1.00	293.57	73.39	220.18	L	Y	PA
93 REAR SPARE TYRE COMPARTMENT FLOOR BOARD	1.00	411.65	102.91	308.74	L	Y	CR4
94 REAR END PANEL WEATHERSTRIP	1.00	0.00	0.00	0.00	L	Y	X cut
95 REAR END PANEL INNER CENTER TRIM	1.00	242.70	60.68	182.02	L	Y	X SVC
96 REAR FENDER RH	1.00	1,084.90	271.23	813.67	L	Y	PA
97 REAR FENDER LH	1.00	1,084.90	271.23	813.67	L	Y	PA
98 REAR FENDER INNER SHIELD RH	1.00	67.75	16.94	50.81	L	Y	X SVC
99 REAR FENDER INNER SHIELD LH	1.00	67.75	16.94	50.81	L	Y	X SVC
100 SIDE MIRROR RH	1.00	1,128.35	282.09	846.26	L	Y	PA
100 SIDE MIRROR LH	1.00	1,128.35	282.09	846.26	L	Y	PA
100 SIDE MIRROR COVER RH	1.00	81.50	20.38	61.12	L	Y	PA
100 SIDE MIRROR COVER LH	1.00	81.50	20.38	61.12	L	Y	MS
100 SIDE MIRROR LAMP RH	1.00	0.00	0.00	0.00	L	Y	Sch
100 SIDE MIRROR LAMP LH	1.00	0.00	0.00	0.00	L	Y	MS
100 REAR SHOCK ABSORBER RH	1.00	0.00	0.00	0.00	L	Y	X SVC
100 REAR SHOCK ABSORBER LH	1.00	0.00	0.00	0.00	L	Y	X BT
100 REAR SHOCK ABSORBER TOP MOUNTING RH	1.00	0.00	0.00	0.00	L	Y	X nec

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
10 REAR SHOCK ABSORBER TOP MOUNTING LH	1.00	0.00	125.30	0.00	L	Y	? nce
11 REAR AXLE	1.00	592.60	148.15	444.45	L	Y	BT
11 ROOFTOP PANEL	1.00	0.00	122.91	0.00	L	Y	BT
11 ROOFTOP SIDE CHANNEL GARNISH RH	1.00	0.00	0.00	0.00	L	Y	X you
11 ROOFTOP SIDE CHANNEL GARNISH LH	1.00	0.00	0.00	0.00	L	Y	X
11 ROOFTOP TOP MOULDING RH	1.00	0.00	95.60	0.00	L	Y	DE
11 ROOFTOP TOP MOULDING LH	1.00	0.00	95.60	0.00	L	Y	DE
11 FRONT RADIATOR LOWER BUSH RH	1.00	0.00	0.00	0.00	L	Y	X 300
11 FRONT RADIATOR LOWER BUSH LH	1.00	0.00	0.00	0.00	L	Y	X
11 FRONT FENDER QUARTER GARNISH RH	1.00	64.02	16.01	48.01	L	Y	SCA
11 FRONT FENDER QUARTER GARNISH LH	1.00	64.02	16.01	48.01	L	Y	MIS
12 FRONT W/S WIPER ARM	1.00	153.70	38.43	115.27	L	Y	X SVC
12 FRT TIE ROD END RH	1.00	0.00	0.00	0.00	L	Y	? 2 300
12 FRT TIE ROD END LH	1.00	0.00	0.00	0.00	L	Y	? 300
12 FRT LOWER ARM BALL JOINT RH	1.00	0.00	113.55	0.00	L	Y	? BT
12 FRT LOWER ARM BALL JOINT LH	1.00	0.00	113.55	0.00	L	Y	? BT
12 FRT KNUCKLE ARM RH	1.00	521.50	130.38	391.12	L	Y	? X SVC
12 FRT KNUCKLE ARM LH	1.00	521.50	130.38	391.12	L	Y	? BT
12 FRT KNUCKLE ARM BEARING RH	1.00	0.00	0.00	0.00	L	Y	? SVC
12 FRT KNUCKLE ARM BEARING LH	1.00	0.00	170.57	0.00	L	Y	? BT
12 FRT DOOR RUBBER BEADING RH	1.00	0.00	115.70	0.00	L	Y	Am
13 FRT DOOR RUBBER BEADING LH	1.00	0.00	175.70	0.00	L	Y	Am
13 FRT DOOR CHECKER RH	1.00	151.20	37.80	113.40	L	Y	? SVC
13 FRT DOOR CHECKER LH	1.00	151.20	37.80	113.40	L	Y	? SVC
13 ROOFTOP REINFORCEMENT NO 1	1.00	0.00	235.70	0.00	L	Y	? BT
13 ROOFTOP REINFORCEMENT NO 2	1.00	0.00	0.00	0.00	L	Y	? REPAIR
13 ROOFTOP REINFORCEMENT NO 3	1.00	0.00	0.00	0.00	L	Y	? BT
13 ROOFTOP REINFORCEMENT NO 4	1.00	0.00	0.00	0.00	L	Y	? JR
13 ROOFTOP REINFORCEMENT NO 5	1.00	0.00	0.00	0.00	L	Y	? BT
13 ROOFTOP REINFORCEMENT NO 6	1.00	0.00	241.61	0.00	L	Y	? BT
13 BOOTLID HINGE RH	1.00	0.00	0.00	0.00	L	Y	X 300
14 BOOTLID HINGE LH	1.00	0.00	0.00	0.00	L	Y	X 300
14 BONNET STAND HOLDER	1.00	0.00	0.00	0.00	L	Y	X
14 RADIATOR GRILLE TOP GARNISH	1.00	0.00	0.00	0.00	L	Y	X repeated no 25
14 WIPER TANK	1.00	0.00	0.00	0.00	L	Y	X
14 WIPER TANK MOTOR	1.00	0.00	0.00	0.00	L	Y	X SVC
14 WIPER TANK NECK WITH CAP	1.00	0.00	0.00	0.00	L	Y	X SVC
14 RADIATOR UPPER BRACKET	1.00	0.00	47.30	0.00	L	Y	BT
14 AIR DUCT	1.00	211.60	52.90	158.70	L	Y	X SVC
14 A/C LIQUID PIPE	1.00	625.70	156.43	469.27	L	Y	X SVC
14 FAN COWLING	1.00	211.02	52.76	158.26	L	Y	X SVC
15 CONDENSOR	1.00	1,289.24	322.31	966.93	L	Y	X
15 AIR RESONATOR	1.00	186.40	46.60	139.80	L	Y	X CRA
15 FRT BRAKE PAD	1.00	0.00	0.00	0.00	L	Y	X 300
15 REAR BRAKE PAD	1.00	0.00	0.00	0.00	L	Y	X 300
15 A PILLAR RH	1.00	0.00	347	0.00	L	Y	BT
15 A PILLAR RH REINFORCEMENT NO 2	1.00	0.00	377.11	0.00	L	Y	? BT
15 SPEAKER PANEL	1.00	0.00	0.00	0.00	L	Y	X
15 SPEAKER PANEL TRIM	1.00	0.00	0.00	0.00	L	Y	X SVC
15 DASHBOARD	1.00	0.00	0.00	0.00	L	Y	? X
15 DASHBOARD LOWER	1.00	0.00	0.00	0.00	L	Y	? X
16 FRT DOOR OUTER HANDLE RH	1.00	0.00	277.45	0.00	L	Y	SCA
16 FRT DOOR OUTER HANDLE LH	1.00	0.00	277.45	0.00	L	Y	SCA
16 REAR DOOR OUTER HANDLE RH	1.00	0.00	277.45	0.00	L	Y	SCA
16 REAR DOOR OUTER HANDLE LH	1.00	0.00	0.00	0.00	L	Y	REPAIR
16 FRT DOOR INNER LOCK RH	1.00	0.00	349.7	0.00	L	Y	JAM
16 FRT DOOR INNER LOCK LH	1.00	0.00	349.70	0.00	L	Y	BT

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
16REAR DOOR INNER LOCK RH	1.00	0.00	0.00	0.00	L	Y	349.70 SVC
16REAR DOOR INNER LOCK LH	1.00	0.00	349.70	0.00	L	Y	JAN
16FRT DOOR LOCK CATCH RH	1.00	0.00	0.00	0.00	L	Y	X SVC
16FRT DOOR LOCK CATCH LH	1.00	0.00	42.10	0.00	L	Y	SOL
17REAR DOOR LOCK CATCH RH	1.00	0.00	0.00	0.00	L	Y	X 3 SVC
17REAR DOOR LOCK CATCH LH	1.00	0.00	0.00	0.00	L	Y	2X
17FRT DOOR RH	1.00	0.00	1221.70	0.00	L	Y	TH
17FRT DOOR LH	1.00	0.00	1221.70	0.00	L	Y	TH
17REAR DOOR RH	1.00	0.00	1127.20	0.00	L	Y	Repair BT
17REAR DOOR LH	1.00	0.00	1127.20	0.00	L	Y	TH
17FRT DOOR REGULATOR RH	1.00	0.00	0.00	0.00	L	Y	X
17FRT DOOR REGULATOR LH	1.00	0.00	0.00	0.00	L	Y	X SVC
17REAR DOOR REGULATOR RH	1.00	0.00	0.00	0.00	L	Y	X
17REAR DOOR REGULATOR LH	1.00	0.00	139.24	0.00	L	Y	? BT
18FRT DOOR MOTOR RH	1.00	0.00	0.00	0.00	L	Y	X
18FRT DOOR MOTOR LH	1.00	0.00	0.00	0.00	L	Y	X SVC
18REAR DOOR MOTOR RH	1.00	0.00	0.00	0.00	L	Y	X
18REAR DOOR MOTOR LH	1.00	0.00	476.60	0.00	L	Y	? nec
18FRT DOOR GLASS RH	1.00	0.00	0.00	0.00	L	Y	X SVC
18FRT DOOR OUTER CHROME RH	1.00	0.00	195.15	0.00	L	Y	mes
18FRT DOOR OUTER CHROME LH	1.00	0.00	195.15	0.00	L	Y	cut
18REAR DOOR OUTER CHROME RH	1.00	0.00	0.00	0.00	L	Y	X 3 SVC
18REAR DOOR OUTER CHROME LH	1.00	0.00	0.00	0.00	L	Y	X
18FRT WHEEL BRAKE ROTOR RH	1.00	0.00	311.10	0.00	L	Y	2X SVC
18FRT WHEEL BRAKE ROTOR LH	1.00	0.00	311.10	0.00	L	Y	X SCR
19REAR WHEEL BRAKE ROTOR RH	1.00	0.00	0.00	0.00	L	Y	X
19REAR WHEEL BRAKE ROTOR LH	1.00	0.00	0.00	0.00	L	Y	X
19FRT WHEEL CALIPER RH	1.00	0.00	0.00	0.00	L	Y	X
19FRT WHEEL CALIPER LH	1.00	0.00	0.00	0.00	L	Y	X
19REAR WHEEL CALIPER RH	1.00	0.00	0.00	0.00	L	Y	X
19REAR WHEEL CALIPER LH	1.00	0.00	0.00	0.00	L	Y	X
19FRT BRAKE DISC RH	1.00	0.00	0.00	0.00	L	Y	X
19FRT BRAKE DISC LH	1.00	0.00	0.00	0.00	L	Y	X
19REAR BRAKE DISC RH	1.00	0.00	0.00	0.00	L	Y	X
20REAR BRAKE DISC LH	1.00	0.00	0.00	0.00	L	Y	X
20RH ROCKER PANEL	1.00	0.00	0.00	0.00	L	Y	X
20LH ROCKER PANEL	1.00	0.00	578.60	0.00	L	Y	X BT
20FRT DOOR STICKER RH	1.00	0.00	66.71	0.00	L	Y	TH
20FRT DOOR STICKER LH	1.00	0.00	66.71	0.00	L	Y	TH
20REAR DOOR STICKER RH	1.00	67.84	16.96	50.88	L	Y	TH
20REAR DOOR STICKER LH	1.00	67.84	16.96	50.88	L	Y	TH
20FRT DOOR FRAME GARNISH RH	1.00	0.00	79.70	0.00	L	Y	SOL
20FRT DOOR FRAME GARNISH LH	1.00	0.00	79.70	0.00	L	Y	SOL
20REAR DOOR FRAME GARNISH RH	1.00	68.30	17.08	51.22	L	Y	SOL
21REAR DOOR FRAME GARNISH LH	1.00	68.30	17.08	51.22	L	Y	TH
21REAR SIDE END PANEL LH	1.00	0.00	0.00	0.00	L	Y	X SVC
21WHEEL TYRE	3 pcs	0.00	546.90	0.00	L	70%	TH
21WHEEL TRYE RIM	3 pcs	0.00	1650	0.00	L	Y	TH
21A PILLAR RH	1.00	0.00	347.50	0.00	L	Y	TH
21A PILLAR RH REINFORCEMENT NO 2	1.00	0.00	0.00	0.00	L	Y	? repeated
21B PILLAR LH	1.00	0.00	347.50	0.00	L	Y	TH
21FRONT BUMPER CLIPS	10.00	38.90	0.00	38.90	S	Y	TH
21FRONT NUMBER PLATE&CASING	1.00	60.00	0.00	60.00	S	Y	TH
21BONNET RUBBER SEAL CLIP	10.00	32.10	0.00	32.10	S	Y	TH
22BONNET INSULATOR CLIP	10.00	32.10	0.00	32.10	S	Y	TH
22FRONT RADIATOR GRILLE TOP GARNISH CLIP	10.00	38.90	0.00	38.90	S	Y	TH
22FRONT FENDER INNER SHIELD CLIPS RH	10.00	35.00	0.00	35.00	S	Y	TH

G-STAR-WI-ET-001-02-Rev00

12995.90

2030 71

S = 3211.60

51003.21

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
22:FRONT FENDER INNER SHIELD CLIPS LH	1.00	3.50	0.00	3.50	S	Y	Ne /
22:BATTERY	1.00	0.00	0.00	0.00	S	Y	X SVC
22:FRONT W/S SEALANT	1.00	50.00	0.00	50.00	S	Y	Ne /
22:FRONT STABILIZER BAR BRACKET RH	1.00	0.00	0.00	0.00	S	Y	X 38V
22:FRT DOOR OUTER GLASS MOULDING	1.00	0.00	0.00	0.00	S	Y	Ne /
22:REAR BUMPER CLIP	10.00	38.90	0.00	38.90	S	Y	Ne /
22:REAR REVERSE SENSOR	1.00	0.00	0.00	0.00	S	Y	Ne /
23:REAR NUMBER PLATE&CASING	1.00	60.00	0.00	60.00	S	Y	X SVC
23:BOOTLID LICENSE PLATE LAMP	1.00	0.00	0.00	0.00	S	Y	X
23:REAR END PANEL TOP GARNISH CLIP	10.00	32.10	0.00	32.10	S	Y	X
23:REAR FENDER INNER SHIELD CLIP RH	10.00	35.00	0.00	35.00	S	Y	Ne /
23:REAR FENDER INNER SHIELD CLIP LH	10.00	35.00	0.00	35.00	S	Y	Ne /
23:PRIMER	1.00	50.00	0.00	50.00	S	Y	Ne /
23:REAR W/S PRIMER	1.00	50.00	0.00	50.00	S	Y	X 38V
23:DECAL	1.00	20.00	0.00	20.00	S	Y	X
23:FRONT W/S SEALANT	1.00	50.00	0.00	50.00	S	Y	Ne /
23:REAR W/S SEALANT	1.00	50.00	0.00	50.00	S	Y	Ne /
24:FRONT DOOR TRIM BOARD RH	1.00	1,333.60	0.00	1,333.60	S	Y	X SVC
24:REAR DOOR TRIM BOARD LH	1.00	0.00	0.00	0.00	S	Y	X SVC
24:ERP BRACKET	1.00	0.00	0.00	0.00	S	Y	Ne /
TOTAL:		35,732.64	422.03	27,310.61			

TOTAL PARTS & LABOUR : 48,342.64 8,422.03 39,920.61

EXCESS/LOADING:SS

0.00

No. Of Day:

30 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM SS

DATE OF SURVEY:

30 / 05 / 18 @ 1500

SURVEYED BY:

Rafael

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DING AUTO PTE LTD
 Blk 10 Sin Ming Industrial Estate Sector C
 #01-20
 Singapore 575645
 Tel: 6452 1208 Fax: 6452 0814

TO :

ESTIMATE REPORT 1ST Quotation

FAX NO:

30/05/2018 14:39

JOB-NO: 85008337

Page 1 of 6

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD
 ADDRESS: 50 UBI AVENUE 3
 #01-12
 SINGAPORE 408866

CONTACT: 0
 0
 NIL

VEHICLE DETAILS

LICENSE NO: SLG1750H TRANS: AUTO
 MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)
 OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.
 JOB-CODE: TP SA: Ding Auto User 1

CHASSIS: MR053REH104557796
 ENGINE: 1ZRY332293

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO R&R ENGINE WITH TRANSFER TO FACILITATE BODYWORK REPAIRS AND TRANSFER AUTOMOTIVE TRANSMISSION ASSY)	1.00	350.00	0.00	350.00	Y	X	
2 TO R&R FRONT AND REAR SUSPENSION AND UNDERCARRIAGE PARTS DUE TO ACCIDENT DAMAGED	1.00	350.00	0.00	350.00	Y	250	
3 TO R&R AND ADJUST HEAD LAMP&TAIL LAMP AND RESET HEADLAMP FOCUSING AND CHECK LIGHTING AND CHECK WHOLE WIRING AND SORT CIRCUIT	1.00	300.00	0.00	300.00	Y	30	
4 TO FULL WHEEL ALIGNMENT,BALANCING,BRAKE BLEEDING AND ROAD TEST	1.00	150.00	0.00	150.00	Y	60	
5 MOUNT ON WORKBENCH	1.00	350.00	0.00	350.00	Y	X	
6 TO REFILL A/C GAS	1.00	120.00	0.00	120.00	Y	100	
7 TO R&R SEAT BELT SEAT AND CARPET	1.00	150.00	0.00	150.00	Y	X	
8 TO R&R FRT WINDSCREEN	1.00	120.00	0.00	120.00	Y	80	
9 TO R&R REAR WINDSCREEN	1.00	120.00	0.00	120.00	Y	80	
10 TO SPRAY AND PATTY FRONT ACCIDENT DAMAGED AREA (FRONT BUMPER,SUPPORT PANEL,BRACE PANEL,BONNET),FRT FENDER RH&LH,REAR FENDER RH&LH,BOOTLID,REAR BUMPER,A PILLAR,B PILLAR,ROOFTOP PANEL,REVERSE SENSOR	1.00	3,000.00	0.00	3,000.00	Y	2800	
11 TO R&R AND WHOLE PANEL BEAT AND RE-ALIGN BODY WORKS AND ADJUST PART ON ACCIDENT DAMAGED AREA	1.00	6,000.00	0.00	6,000.00	Y	3800	
12 RUST PROOFING	1.00	100.00	0.00	100.00	Y	100	
13 TO R&R FRT RH&LH AND REAR RH&LH DOOR AND DOOR COMPARTMENT	1.00	400.00	0.00	400.00	Y	120/80	
14 TO R&R AND JACK ROOFTOP AND ROOF LINING	1.00	300.00	0.00	300.00	Y	100/200	
15 TO R&R DASHBOARD AND RE-ALIGN DASHBOARD AND R&R SPEAKER PANEL AND SPEAKER PANEL TRIM	1.00	400.00	0.00	400.00	Y	150	
16 TO RE-ALIGN EXHAUST PIPE AND FUEL TANK	1.00	200.00	0.00	200.00	Y	X	

G-STAR-WI-ET-001-02-Rev001

7910

7900

DESCRIPTION	QTY	COSTS	IND	SURDISP	PRICE
17 TO REPAIR AND RE-ALIGN ALL CHASSIS	1.00	200.00	0.00	900.00	X
TOTAL:		12,610.00	0.00	12,610.00	
MATERIALS					
1 FRONT BUMPER	1.00	511.22	127.81	383.41	L Y <u>98</u> / <u>43.62</u>
2 FRONT BUMPER SIDE COVER(NO FOG LAMP)	1.00	118.84 58.17	29.09	87.25	L Y <u>cut</u> / <u>43.62</u>
3 FRONT BUMPER LOWER GRILLE	1.00	58.17	34.54	43.63	L Y <u>DE</u> /
4 FRONT BUMPER SIDE RETAINER RH	1.00	138.17	34.54	103.63	L Y <u>an</u> /
5 FRONT BUMPER SIDE RETAINER LH	1.00	58.17	34.54	43.63	L Y <u>an</u> /
7 FRONT BUMPER SPONGE	1.00	102.38	25.80	76.78	L Y <u>cut</u> /
8 FRONT BUMPER LOWER CENTER COVER(ENGINE CENTER COVER)	1.00	211.67	52.92	158.75	L Y <u>cut</u> /
9 BONNET	1.00	1,140.40	265.10	855.30	L Y <u>scu</u> /
10 BONNET RUBBER SEAL	1.00	85.70	15.43	44.27	L Y <u>an</u> /
11 BONNET INSULATOR	1.00	301.36	75.34	226.02	L Y <u>7. covered</u>
12 BONNET LOCK CABLE	1.00	33.80	10.45	50.35	L Y <u>X</u>
13 BONNET LOCK CABLE HOLDER SET	1.00	31.60	20.40	81.20	L Y <u>X</u>
15 BONNET HINGE RH	1.00	76.60	19.15	57.45	L Y <u>2. 1st</u>
16 BONNET HINGE LH	1.00	76.60	19.15	57.45	L Y <u>2. 1st</u>
17 HEAD LAMP RH	1.00	794.10	198.53	595.57	L Y <u>scu</u>
18 HEAD LAMP LH	1.00	794.10	198.53	595.57	L Y <u>scu</u>
19 HEAD LAMP TOP CHROME MOULDING RH	1.00	150.87	37.72	113.15	L Y <u>scu</u>
20 HEAD LAMP TOP CHROME MOULDING LH	1.00	150.87	37.72	113.15	L Y <u>scu</u>
21 FRONT SUPPORT PANEL	1.00	1,074.80	268.85	805.95	L Y <u>1st</u>
22 FRONT BRACE PANEL	1.00	115.70	28.93	86.77	L Y <u>1st</u>
23 FRONT RADIATOR GRILLE	1.00	564.97	141.24	423.73	L Y <u>cha</u>
24 FRONT RADIATOR GRILLE "TOYOTA" EMBLEM	1.00	47.44	11.86	35.58	L Y <u>an</u>
26 FRONT FENDER RH	1.00	858.05	211.51	646.54	L Y <u>1st</u>
27 FRONT FENDER LH	1.00	858.05	211.51	646.54	L Y <u>1st</u>
28 FRONT FENDER "VVT" EMBLEM RH	1.00	45.17	11.29	33.88	L Y <u>an</u>
29 FRONT FENDER "VVT" EMBLEM LH	1.00	45.17	11.29	33.88	L Y <u>an</u>
30 FRONT FENDER INNER SHIELD RH	1.00	181.20	43.30	137.90	L Y <u>cut</u>
31 FRONT FENDER INNER SHIELD LH	1.00	181.20	43.30	137.90	L Y <u>cut</u>
32 FUSE BOX COVER	1.00	0.00	0.00	0.00	L Y <u>X</u>
33 FUSE BOX BASE	1.00	0.00	0.00	0.00	L Y <u>X</u>
34 RADIATOR ASSY	1.00	1,510.60	377.83	1,132.77	L Y <u>X</u>
35 RADIATOR UPPER HOSE	1.00	61.25	15.31	45.94	L Y <u>X</u>
36 RADIATOR LOWER HOSE	1.00	215.80	53.90	161.90	L Y <u>X</u>
37 FRONT ENGINE MOUNTING RH	1.00	215.80	53.90	161.90	L Y <u>X</u>
38 FRONT ENGINE MOUNTING LH	1.00	215.80	53.90	161.90	L Y <u>X</u>
39 REAR ENGINE MOUNTING(GEARBOX)	1.00	0.00	0.00	0.00	L Y <u>X</u>
40 FRONT CROSSMEMBER CENTER	1.00	0.00	0.00	0.00	L Y <u>X</u>
41 FRONT CROSSMEMBER ENGINE MOUNTING	2.00	1,002.74	250.65	752.08	L Y <u>X</u>
42 FRONT W/S	1.00	1,458.30	364.58	1,093.72	L Y <u>1st</u>
43 FRONT W/S MOULDING	1.00	102.40	25.80	76.60	L Y <u>an</u>
44 FRONT W/S WIPER BLADE	1.00	148.45	37.11	111.34	L Y <u>at</u>
45 FRONT W/S COWL TOP VENTILATOR	1.00	0.00	0.00	0.00	L Y <u>X</u>
46 FRONT W/S GARNISH SIDE SEAL	1.00	71.07	17.77	53.30	L Y <u>scu</u>
47 REAR W/S	1.00	0.00	0.00	0.00	L Y <u>X</u>
48 REAR W/S MOULDING	1.00	0.00	0.00	0.00	L Y <u>1st</u>
49 FRT DRIVE SHAFT RH	1.00	1,441.80	360.40	1,081.20	L Y <u>1st</u>
50 FRT DRIVE SHAFT LH	1.00	1,441.80	360.40	1,081.20	L Y <u>1st</u>
51 FRT LOWER ARM RH	1.00	265.07	65.27	199.80	L Y <u>1st</u>
52 FRT LOWER ARM LH	1.00	265.07	65.27	199.80	L Y <u>1st</u>
53 FRT SHOCK ABSORBER RH	1.00	315.97	78.24	237.73	L Y <u>1st</u>

12784.85 - 256
= 9588.64

G-STAR-WI-ET-001-07-Rev00

10.203.12

DESCRIPTION	QTY	COSTS		IND	SUR	DISP	PRICE
54 FRT SHOCK ABSORBER LH	1.00	318.97	79.24	237.73	L	Y	7.92
55 FRT SHOCK ABSORBER TOP MOUNTING RH	1.00	0.00	219.60	0.00	L	Y	2.19
56 FRT SHOCK ABSORBER TOP MOUNTING LH	1.00	0.00	219.60	0.00	L	Y	2.19
57 FRT SHOCK ABSORBER TOP MOUNTING DUST COVER RH	1.00	0.00	45.97	0.00	L	Y	4.59
58 FRT SHOCK ABSORBER TOP MOUNTING DUST COVER LH	1.00	0.00	45.97	0.00	L	Y	4.59
59 FRONT STABILIZER LINK RH	1.00	0.00	171.08	0.00	L	Y	17.10
60 FRONT STABILIZER LINK LH	1.00	0.00	171.08	0.00	L	Y	17.10
61 FRONT STABILIZER BAR	1.00	0.00	349.73	0.00	L	Y	34.97
62 FRONT STABILIZER BAR BRACKET LH	1.00	0.00	0.00	0.00	L	Y	0.00
63 FRONT STABILIZER BAR BUSH RH	1.00	-0.96	29.95	0.00	L	Y	2.99
64 FRONT STABILIZER BAR BUSH LH	1.00	-0.96	29.95	0.00	L	Y	2.99
65 FRT STEERING RAIL & PINION ASSY	1.00	-0.96	160.70	0.00	L	Y	16.07
66 FRT WHEEL BEARING RH	1.00	147.80	36.95	110.85	L	Y	14.78
67 FRT WHEEL BEARING LH	1.00	147.80	36.95	110.85	L	Y	14.78
68 FRT WHEEL BEARING HUB	1.00	238.70	59.68	179.02	L	Y	23.87
69 FRT WHEEL BEARING HUB LH	1.00	0.00	178.42	0.00	L	Y	17.84
70 FRT GLASS RUBBER BEADING RH	1.00	0.00	178.42	0.00	L	Y	17.84
71 FRT GLASS RUBBER BEADING LH	1.00	0.00	178.42	0.00	L	Y	17.84
72 FRT DOOR GLASS RUN CHANNEL RH	1.00	142.50	38.53	103.97	L	Y	14.25
73 FRT DOOR GLASS RUN CHANNEL LH	1.00	142.50	38.53	103.97	L	Y	14.25
74 REAR BUMPER	1.00	488.55	121.64	366.91	L	Y	48.85
75 REAR BUMPER SIDE RETAINER RY LONG	1.00	104.40	26.10	78.30	L	Y	10.44
76 REAR BUMPER SIDE RETAINER LH LONG	1.00	104.40	26.10	78.30	L	Y	10.44
77 REAR BUMPER SIDE RETAINER RY SHORT	1.00	73.25	18.36	54.89	L	Y	7.32
78 REAR BUMPER SIDE RETAINER LH SHORT	1.00	73.25	18.36	54.89	L	Y	7.32
79 REAR BUMPER BEAM ARM RH	1.00	101.57	25.40	76.17	L	Y	10.15
80 REAR BUMPER BEAM ARM LH	1.00	101.57	25.40	76.17	L	Y	10.15
81 REAR BUMPER REINFORCEMENT	1.00	376.02	64.67	311.35	L	Y	37.60
82 REAR BUMPER REFLECTOR RH	1.00	61.70	15.43	46.27	L	Y	6.17
83 REAR BUMPER REFLECTOR LH	1.00	61.70	15.43	46.27	L	Y	6.17
84 BOOTLID	1.00	878.91	212.90	666.01	L	Y	87.89
85 BOOTLID TOYOTA EMBLEM	1.00	66.17	16.54	49.63	L	Y	6.61
86 BOOTLID COROLLA EMBLEM	1.00	0.00	51.70	0.00	L	Y	5.17
87 BOOTLID ALTIS EMBLEM	1.00	0.00	49.17	0.00	L	Y	4.91
88 BOOTLID OUTER CHROME GARNISH	1.00	211.25	68.66	142.59	L	Y	21.12
89 TAIL LAMP RH (OUTER)	1.00	377.50	94.38	283.12	L	Y	37.75
90 TAIL LAMP LH (OUTER)	1.00	377.50	94.38	283.12	L	Y	37.75
91 TAIL LAMP RH (INNER)	1.00	293.57	73.39	220.18	L	Y	29.35
92 TAIL LAMP LH (INNER)	1.00	293.57	73.39	220.18	L	Y	29.35
93 REAR SPARE TYRE COMPARTMENT FLOOR BOARD	1.00	411.65	102.91	308.74	L	Y	41.16
94 REAR END PANEL WEATHERSTRIP	1.00	0.00	184.76	0.00	L	Y	18.47
95 REAR END PANEL INNER CENTER TRIM	1.00	842.75	68.66	774.09	L	Y	84.27
96 REAR FENDER RH	1.00	1,084.90	271.23	813.67	L	Y	108.49
97 REAR FENDER LH	1.00	1,084.90	271.23	813.67	L	Y	108.49
98 REAR FENDER INNER SHIELD RH	1.00	67.75	16.04	51.71	L	Y	6.77
99 REAR FENDER INNER SHIELD LH	1.00	67.75	16.04	51.71	L	Y	6.77
100 SIDE MIRROR RH	1.00	1,128.35	282.09	846.26	L	Y	112.83
101 SIDE MIRROR LH	1.00	1,128.35	282.09	846.26	L	Y	112.83
102 SIDE MIRROR COVER RH	1.00	81.50	20.38	61.12	L	Y	8.15
103 SIDE MIRROR COVER LH	1.00	81.50	20.38	61.12	L	Y	8.15
104 SIDE MIRROR LAMP RH	1.00	0.00	108.40	0.00	L	Y	10.84
105 SIDE MIRROR LAMP LH	1.00	0.00	108.40	0.00	L	Y	10.84
106 REAR SHOCK ABSORBER RH	1.00	0.00	0.00	0.00	L	Y	0.00
107 REAR SHOCK ABSORBER LH	1.00	-0.96	159.21	0.00	L	Y	15.92
108 REAR SHOCK ABSORBER TOP MOUNTING RH	1.00	-0.96	0.00	0.00	L	Y	0.00

Total \$ 11411.36 - 256
= \$ 8558.52

DESCRIPTION	QTY	COSTS		IND	SUR	DISP	PRICE
10 REAR SHOCK ABSORBER TOP MOUNTING LH	1.00	0.00	0.00	0.00	L	Y	2.00
11 REAR AXLE	1.00	592.80	148.15	444.65	L	Y	BA
11 ROOFTOP PANEL	1.00	0.00	128.87	0.00	L	Y	BA
12 ROOFTOP SIDE CHANNEL GARNISH RH	1.00	0.00	0.00	0.00	L	Y	X
12 ROOFTOP SIDE CHANNEL GARNISH LH	1.00	0.00	0.00	0.00	L	Y	X
11 ROOFTOP TOP MOULDING RH	1.00	0.00	95.60	0.00	L	Y	DE
11 ROOFTOP TOP MOULDING LH	1.00	0.00	95.60	0.00	L	Y	DE
14 FRONT FENDER LOWER BUSHING	1.00	0.00	0.00	0.00	L	Y	X
14 FRONT FENDER LOWER BUSHING	1.00	0.00	0.00	0.00	L	Y	X
11 FRONT FENDER QUARTER GARNISH RH	1.00	64.02	18.01	48.01	L	Y	SCA
11 FRONT FENDER QUARTER GARNISH LH	1.00	64.02	18.01	48.01	L	Y	MS
12 FRONT WIPER WASH	1.00	0.00	0.00	0.00	L	Y	X
12 FRT WIPER END RH	1.00	0.00	0.00	0.00	L	Y	X
12 FRT WIPER END LH	1.00	0.00	0.00	0.00	L	Y	X
12 FRT LOWER ARM BALL JOINT RH	1.00	0.00	173.55	0.00	L	Y	BA
12 FRT LOWER ARM BALL JOINT LH	1.00	0.00	173.55	0.00	L	Y	BA
12 FRT KNUCKLE ARM RH	1.00	521.50	130.38	391.12	L	Y	X
12 FRT KNUCKLE ARM LH	1.00	521.50	130.38	391.12	L	Y	X
12 FRT KNUCKLE ARM BEARING RH	1.00	0.00	0.00	0.00	L	Y	X
12 FRT KNUCKLE ARM BEARING LH	1.00	0.00	170.37	0.00	L	Y	BA
12 FRT DOOR RUBBER BEADING RH	1.00	0.00	185.70	0.00	L	Y	BA
13 FRT DOOR RUBBER BEADING LH	1.00	0.00	185.70	0.00	L	Y	BA
13 FRT DOOR CHECKER RH	1.00	151.20	37.80	113.40	L	Y	X
13 FRT DOOR CHECKER LH	1.00	151.20	37.80	113.40	L	Y	X
13 ROOFTOP REINFORCEMENT NO 1	1.00	0.00	286.70	0.00	L	Y	BA
13 ROOFTOP REINFORCEMENT NO 2	1.00	0.00	0.00	0.00	L	Y	X
13 ROOFTOP REINFORCEMENT NO 3	1.00	0.00	0.00	0.00	L	Y	X
13 ROOFTOP REINFORCEMENT NO 4	1.00	0.00	0.00	0.00	L	Y	X
13 ROOFTOP REINFORCEMENT NO 5	1.00	0.00	0.00	0.00	L	Y	X
13 ROOFTOP REINFORCEMENT NO 6	1.00	0.00	241.67	0.00	L	Y	BA
14 BOOTED HINGE RH	1.00	0.00	0.00	0.00	L	Y	X
14 BOOTED HINGE LH	1.00	0.00	0.00	0.00	L	Y	X
14 CONNET STAND HOLDER	1.00	0.00	0.00	0.00	L	Y	X
14 RADIATOR GRILLE TOP GARNISH	1.00	0.00	0.00	0.00	L	Y	X
14 WIPER TANK	1.00	0.00	0.00	0.00	L	Y	X
14 WIPER TANK MOTOR	1.00	0.00	0.00	0.00	L	Y	X
14 WIPER TANK NECK WITH CAP	1.00	0.00	0.00	0.00	L	Y	X
14 RADIATOR UPPER BRACKET	1.00	0.00	47.80	0.00	L	Y	BA
14 WIPER DUCT	1.00	211.80	32.95	178.85	L	Y	X
14 NO LIQUID PIPE	1.00	58.70	108.15	166.85	L	Y	X
14 EAV DOWLING	1.00	254.00	59.72	194.28	L	Y	X
15 CONDENSOR	1.00	1208.24	618.61	589.63	L	Y	X
15 AIR RESONATOR	1.00	186.40	48.80	137.60	L	Y	SCA
16 FRT BRAKE PAD	1.00	0.00	0.00	0.00	L	Y	X
15 REAR BRAKE PAD	1.00	0.00	0.00	0.00	L	Y	X
15A PILLAR RH	1.00	0.00	347.00	0.00	L	Y	BA
15A PILLAR RH REINFORCEMENT NO 2	1.00	0.00	379.11	0.00	L	Y	BA
15 DOOR PANEL	1.00	0.00	0.00	0.00	L	Y	X
15 DOOR PANEL TRIM	1.00	0.00	0.00	0.00	L	Y	X
15 DASHBOARD	1.00	0.00	0.00	0.00	L	Y	X
15 DASHBOARD LOWER	1.00	0.00	0.00	0.00	L	Y	X
16 FRT DOOR OUTER HANDLE RH	1.00	0.00	298.40	0.00	L	Y	SCA
16 FRT DOOR OUTER HANDLE LH	1.00	0.00	298.40	0.00	L	Y	SCA
16 REAR DOOR OUTER HANDLE RH	1.00	0.00	298.40	0.00	L	Y	SCA
16 REAR DOOR OUTER HANDLE LH	1.00	0.00	0.00	0.00	L	Y	SCA
16 FRT DOOR INNER LOCK RH	1.00	0.00	349.70	0.00	L	Y	BA
16 FRT DOOR INNER LOCK LH	1.00	0.00	349.70	0.00	L	Y	BA

Total \$ 6878.66 - 25%
= 5159.00

DESCRIPTION	QTY	COSTS		IND	SUR	DISP	PRICE
15REAR DOOR INNER LOCK RH	1.00	0.00	0.00	0.00	L	Y	341.78
16REAR DOOR INNER LOCK LH	1.00	0.00	341.78	0.00	L	Y	341.78
16FRT DOOR LOCK CATCH RH	1.00	0.00	0.00	0.00	L	Y	54.10
16FRT DOOR LOCK CATCH LH	1.00	0.00	42.10	0.00	L	Y	54.10
17REAR DOOR LOCK CATCH RH	1.00	0.00	0.00	0.00	L	Y	1127.28
17REAR DOOR LOCK CATCH LH	1.00	0.00	0.00	0.00	L	Y	1127.28
17FRT DOOR RH	1.00	0.00	1221.78	0.00	L	Y	1221.78
17FRT DOOR LH	1.00	0.00	1221.78	0.00	L	Y	1221.78
17REAR DOOR RH	1.00	0.00	1127.28	0.00	L	Y	1127.28
17REAR DOOR LH	1.00	0.00	1127.28	0.00	L	Y	1127.28
17FRT DOOR REGULATOR RH	1.00	0.00	0.00	0.00	L	Y	189.79
17REAR DOOR REGULATOR LH	1.00	0.00	0.00	0.00	L	Y	189.79
18FRT DOOR MOTOR RH	1.00	0.00	0.00	0.00	L	Y	498.60
18FRT DOOR MOTOR LH	1.00	0.00	0.00	0.00	L	Y	498.60
18REAR DOOR MOTOR RH	1.00	0.00	0.00	0.00	L	Y	155.15
18REAR DOOR MOTOR LH	1.00	0.00	498.60	0.00	L	Y	498.60
18FRT DOOR GLASS RH	1.00	0.00	0.00	0.00	L	Y	155.15
18FRT DOOR OUTER CHROME RH	1.00	0.00	155.15	0.00	L	Y	155.15
18FRT DOOR OUTER CHROME LH	1.00	0.00	155.15	0.00	L	Y	155.15
18REAR DOOR OUTER CHROME RH	1.00	0.00	0.00	0.00	L	Y	311.60
18REAR DOOR OUTER CHROME LH	1.00	0.00	0.00	0.00	L	Y	311.60
19FRT WHEEL BRAKE ROTOR LH	1.00	0.00	311.60	0.00	L	Y	311.60
19REAR WHEEL BRAKE ROTOR RH	1.00	0.00	0.00	0.00	L	Y	0.00
19REAR WHEEL BRAKE ROTOR LH	1.00	0.00	0.00	0.00	L	Y	0.00
19FRT WHEEL CALIPER RH	1.00	0.00	0.00	0.00	L	Y	0.00
19FRT WHEEL CALIPER LH	1.00	0.00	0.00	0.00	L	Y	0.00
19REAR WHEEL CALIPER RH	1.00	0.00	0.00	0.00	L	Y	0.00
19REAR WHEEL CALIPER LH	1.00	0.00	0.00	0.00	L	Y	0.00
19FRT BRAKE DISC RH	1.00	0.00	0.00	0.00	L	Y	0.00
19FRT BRAKE DISC LH	1.00	0.00	0.00	0.00	L	Y	0.00
19REAR BRAKE DISC RH	1.00	0.00	0.00	0.00	L	Y	0.00
19REAR BRAKE DISC LH	1.00	0.00	0.00	0.00	L	Y	0.00
20H ROCKER PANEL	1.00	0.00	0.00	0.00	L	Y	687.10
20FRT DOOR STICKER RH	1.00	0.00	687.10	0.00	L	Y	687.10
20FRT DOOR STICKER LH	1.00	0.00	687.10	0.00	L	Y	687.10
20REAR DOOR STICKER RH	1.00	67.84	16.96	50.88	L	Y	67.84
20REAR DOOR STICKER LH	1.00	67.84	16.96	50.88	L	Y	67.84
20FRT DOOR FRAME GARNISH RH	1.00	0.00	79.70	0.00	L	Y	79.70
20FRT DOOR FRAME GARNISH LH	1.00	0.00	79.70	0.00	L	Y	79.70
20REAR DOOR FRAME GARNISH RH	1.00	68.30	17.08	51.22	L	Y	68.30
20REAR DOOR FRAME GARNISH LH	1.00	68.30	17.08	51.22	L	Y	68.30
21REAR SIDE END PANEL LH	1.00	0.00	0.00	0.00	L	Y	0.00
21WHEEL TYRE	180 Per Pcs 3pc / S/N	0.00	540.00	0.00	L	Y	540.00
21WHEEL TRYE RIM	550 Per Pcs 3pc / S/N	0.00	1650.00	0.00	L	Y	1650.00
21A PILLAR RH	1.00	0.00	347.50	0.00	L	Y	347.50
21A PILLAR RH REINFORCEMENT NO 2	1.00	0.00	0.00	0.00	L	Y	0.00
21B PILLAR LH	1.00	0.00	347.50	0.00	L	Y	347.50
21FRONT BUMPER CLIPS	10.00	38.90	0.00	38.90	S	Y	38.90
21FRONT NUMBER PLATE&CASING	1.00	80.00	0.00	80.00	S	Y	80.00
21BONNET RUBBER SEAL CLIP	10.00	32.10	0.00	32.10	S	Y	32.10
22BONNET INSULATOR CLIP	10.00	32.10	0.00	32.10	S	Y	32.10
22FRONT RADIATOR GRILLE TOP GARNISH CLIP	10.00	38.90	0.00	38.90	S	Y	38.90
22FRONT FENDER INNER SHIELD CLIPS RH	10.00	35.00	0.00	35.00	S	Y	35.00

Total Parts \$ 8030.79 - 2576
= 6023.09
S/N = 2240

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SURDISP	REV PRICE
22FRONT FENDER INNER SHIELD CLIPS LH	1.00	3.50	0.00	3.50	S	Y	✓
22BATTERY	1.00	0.00	0.00	0.00	S	Y	✓
22FRONT W/S SEALANT	1.00	50.00	0.00	50.00	S	Y	✓
22FRONT STABILIZER BAR BRACKET RH	1.00	0.00	0.00	0.00	S	Y	✓
22FRONT DOOR OUTER GLASS MOULDING	1.00	0.00	0.00	0.00	S	Y	✓
22REAR BUMPER CLIP	10.00	38.90	0.00	38.90	S	Y	✓
22REAR REVERSE SENSOR	1.00	0.00	0.00	0.00	S	Y	✓
23REAR NUMBER PLATE CAGING	1.00	60.00	0.00	60.00	S	Y	✓
23BOOT LID LICENSE PLATE LAMP	1.00	0.00	0.00	0.00	S	Y	✓
23FRONT END PANEL TOP GARNISH CLIP	10.00	32.40	0.00	32.40	S	Y	✓
23REAR FENDER INNER SHIELD CLIP RH	10.00	35.00	0.00	35.00	S	Y	✓
23REAR FENDER INNER SHIELD CLIP LH	10.00	35.00	0.00	35.00	S	Y	✓
23PRIMER	1.00	50.00	0.00	50.00	S	Y	✓
23REAR W/S PRIMER	1.00	50.00	0.00	50.00	S	Y	✓
23SEAL	1.00	50.00	0.00	50.00	S	Y	✓
23FRONT W/S SEALANT	1.00	50.00	0.00	50.00	S	Y	✓
23REAR W/S SEALANT	1.00	50.00	0.00	50.00	S	Y	✓
24FRONT DOOR TRIM BOARD RH	1.00	1,333.80	0.00	1,333.80	S	Y	✓
24FRONT DOOR TRIM BOARD LH	1.00	0.00	0.00	0.00	S	Y	✓
24ZEP BRACKET	1.00	15.00	0.00	15.00	S	Y	✓
TOTAL:		35,732.54	422.03	27,310.61			

48,342.54 8,422.03 38,920.61

TOTAL PARTS & LABOUR :

EXCESS/LOADING:SS

No. Of Day:

RE-SURVEY: BEFORE/ AFTER PAINTING

PART-BY-PART OR LUMP SUM:SS

DATE OF SURVEY: 30/05/18 @ 1500

SURVEYED BY: Rame

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Fuel Tanks

Seat Belt

Labour # 7910.00

Parts # 39105.66-25%

= 29329.25

S/N # 2798.90

Total # 40038.15 - 20% L/S
= 32030.52



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009825/R1td3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 1036E	Veh. Inspected	SLG 1750H
Policy No.		Coverage (\$)	0.00
Claim No.	D18004165MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	28/05/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104557796	Colour	GREY
Odometer	122312	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	205/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	205/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	205/65 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/05/2018	Inspection Date	30/05/2018
Survey held at	249 JALAN BOON LAY		
Repairer	DING AUTO PTE LTD		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		30 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 9

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 1750H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT W/S WIPER ARM	SERVICEABLE	153.70	-
1	FRONT BUMPER	DEFORMED	511.22	511.22
2	FRONT BUMPER SIDE COVER (NO FOG LAMP)	CUT-1PC ONLY	116.34	58.17
1	FRONT BUMPER LOWER GRILLE	DEFORMED	58.17	58.17
1	FRONT BUMPER SIDE RETAINER RH	NECESSARY	138.17	138.17
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	58.17	58.17
1	FRONT REINFORCEMENT	SERVICEABLE	386.60	-
1	FRONT BUMPER SPONGE	CUT	102.38	102.38
1	FRONT BUMPER LOWER CENTER COVER (ENGINE CENTER COVER)	CUT	211.67	211.67
1	BONNET	SCRATCHED	1,140.40	1,140.40
1	BONNET RUBBER SEAL	NECESSARY	65.70	65.70
1	BONNET INSULATOR	CORRODED	301.36	301.36
1	BONNET LOCK	SERVICEABLE	162.80	-
1	BONNET LOCK CABLE	SERVICEABLE	77.80	-
1	SET BONNET LOCK CABLE HOLDER	SERVICEABLE	81.60	-
1	BONNET HINGE RH	BENT	76.60	76.60
1	BONNET HINGE LH	BENT	76.60	76.60
1	HEAD LAMP RH	SCRATCHED	794.10	794.10
1	HEAD LAMP LH	SCRATCHED	794.10	794.10
1	HEAD LAMP TOP CHROME MOULDING RH	SCRATCHED	150.87	150.87
1	HEAD LAMP TOP CHROME MOULDING LH	SCRATCHED	150.87	150.87
1	FRONT SUPPORT PANEL	BENT	1,074.60	1,074.60
1	FRONT BRACE PANEL	BENT	115.70	115.70
1	FRONT RADIATOR GRILLE	CRACKED	564.97	564.97
1	FRONT RADIATOR GRILLE "TOYOTA" EMBLEM	NECESSARY	47.44	47.44
1	FRONT RADIATOR GRILLE TOP GARNISH	SERVICEABLE	124.70	-
1	FRONT FENDER RH	BENT	858.05	858.05
1	FRONT FENDER LH	BENT	858.05	858.05
1	FRONT FENDER "VVTI" EMBLEM RH	NECESSARY	45.17	45.17
1	FRONT FENDER "VVTI" EMBLEM LH	NECESSARY	45.17	45.17

Report Ref No. CS/FCI18009825/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER INNER SHIELD RH	CUT	181.20	181.20
1	FRONT FENDER INNER SHIELD LH	CUT	181.20	181.20
1	FUSE BOX COVER (NPA)	SERVICEABLE	-	-
1	FUSE BOX BASE (NPA)	SERVICEABLE	-	-
1	RADIATOR ASSY	SERVICEABLE	1,510.50	-
1	RADIATOR UPPER HOSE	SERVICEABLE	55.69	-
1	RADIATOR LOWER HOSE	SERVICEABLE	61.25	-
1	FRONT ENGINE MOUNTING RH	SERVICEABLE	215.60	-
1	FRONT ENGINE MOUNTING LH	SERVICEABLE	215.60	-
1	REAR ENGINE MOUNTING (GEARBOX) (NPA)	SERVICEABLE	-	-
1	FRONT CROSSMEMBER CENTER (NPA)	SERVICEABLE	-	-
2	FRONT CROSSMEMBER ENGINE MOUNTING	SERVICEABLE	1,002.74	-
1	FRONT W/S	BROKEN	1,458.30	1,458.30
1	FRONT W/S MOULDING	NECESSARY	102.40	102.40
1	FRONT W/S WIPER BLADE	CUT	148.45	148.45
1	FRONT W/S COWL TOP VENTILATOR (NPA)	SERVICEABLE	-	-
1	FRONT W/S GARNISH SIDE SEAL	DEFORMED	71.07	71.07
1	REAR W/S (NPA)	SERVICEABLE	-	-
1	REAR W/S MOULDING (NPA)	SERVICEABLE	-	-
1	FRT DRIVE SHAFT RH	BENT	1,441.60	1,441.60
1	FRT DRIVE SHAFT L	BENT	1,441.60	1,441.60
1	FRT LOWER ARM RH	BENT	265.07	265.07
1	FRT LOWER ARM LH (NPA)	BENT	-	-
1	FRT SHOCK ABSORBER RH	BENT	316.97	316.97
1	FRT SHOCK ABSORBER LH	BENT	316.97	316.97
1	FRT SHOCK ABSORBER TOP MOULDING RH	NECESSARY	219.60	219.60
1	FRT SHOCK ABSORBER TOP MOULDING LH	NECESSARY	219.60	219.60
1	FRT SHOCK ABSORBER TOP MOULDING DUCT COVER RH	NECESSARY	45.97	45.97
1	FRT SHOCK ABSORBER TOP MOULDING DUCT COVER LH	NECESSARY	45.97	45.97
1	FRONT STABILIZER LINK RH	BENT	171.08	171.08
1	FRONT STABILIZER LINK LH	SERVICEABLE	171.08	-
1	FRONT STABILIZER BAR	BENT	349.73	349.73

Report Ref No. CS/FCI18009825/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT STABILIZER BAR BRACKET LH (NPA)	SERVICEABLE	-	-
1	FRONT STABILIZER BAR BUSH RH	NECESSARY	29.95	29.95
1	FRONT STABILIZER BAR BUSH LH	NECESSARY	29.95	29.95
1	FRT STEERING RAIL & PINION ASSY	BENT	1,620.70	1,620.70
1	FRT WHEEL BEARING RH	NECESSARY	147.80	147.80
1	FRT WHEEL BEARING LH	NECESSARY	147.80	147.80
1	FRT WHEEL BEARING HUB RH	SERVICEABLE	238.70	-
1	FRT WHEEL BEARING HUB LH	BENT	238.70	238.70
1	FRT GLASS RUBBER BEADING RH	NECESSARY	178.42	178.42
1	FRT GLASS RUBBER BEADING LH	NECESSARY	178.42	178.42
1	FRT DOOR GLASS RUN CHANNEL RH	SERVICEABLE	142.50	-
1	FRT DOOR GLASS RUN CHANNEL LH	SERVICEABLE	142.50	-
1	RAER BUMPER	MISSING	486.55	486.55
1	REAR BUMPER SIDE RETAINER RH LONG	SERVICEABLE	104.40	-
1	REAR BUMPER SIDE RETAINER LH LONG	DEFORMED	104.40	104.40
1	REAR BUMPER SIDE RETAINER RH SHORT	SERVICEABLE	79.20	-
1	REAR BUMPER SIDE RETAINER LH SHORT	SERVICEABLE	79.20	-
1	REAR BUMPER BEAM ARM RH	SERVICEABLE	101.97	-
1	REAR BUMPER BEAM ARM LH	SERVICEABLE	101.97	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	378.42	-
1	REAR BUMPER REFLECTOR RH	MISSING	61.70	61.70
1	REAR BUMPER REFLECTOR LH	MISSING	61.70	61.70
1	BOOTLID	TO REPAIR SEE LABOUR	879.61	-
1	BOOTLID TOYOTA EMBLEM	NECESSARY	66.17	66.17
1	BOOTLID COROLLA EMBLEM	NECESSARY	51.70	51.70
1	BOOTLID ALTIS EMBLEM	NECESSARY	49.17	49.17
1	BOOTLID OUTER CHROME MOULDING	SERVICEABLE	211.20	-
1	TAIL LAMP RH (OUTER)	CRACKED	377.50	377.50
1	TAIL LAMP LH (OUTER)	SERVICEABLE	377.50	-
1	TAIL LAMP RH (INNER)	SERVICEABLE	293.57	-
1	TAIL LAMP LH (INNER)	BROKEN	293.57	293.57
1	REAR SPARE TYRE COMPARTMENT FLOOR BOARD	CRACKED	411.65	411.65

Report Ref No. CS/FCI18009825/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL WEATHERSTRIP	CUT	184.70	184.70
1	REAR END PANEL INNER CENTER TRIM	SERVICEABLE	242.70	-
1	REAR FENDER RH	BUCKLED	1,084.90	1,084.90
1	REAR FENDER LH	BUCKLED	1,084.90	1,084.90
1	REAR FENDER INNER SHIELD RH	SERVICEABLE	67.75	-
1	REAR FENDER INNER SHIELD LH	SERVICEABLE	67.75	-
1	SIDE MIRROR RH	BROKEN	1,128.35	1,128.35
1	SIDE MIRROR LH	MISSING	1,128.35	1,128.35
1	SIDE MIRROR COVER RH	BROKEN	81.50	81.50
1	SIDE MIRROR COVER LH	MISSING	81.50	81.50
1	SIDE MIRROR LAMP RH	SCRATCHED	108.40	108.40
1	SIDE MIRROR LAMP LH	MISSING	108.40	108.40
1	REAR SHOCK ABSORBER RH (NPA)	SERVICEABLE	-	-
1	REAR SHOCK ABSORBER LH	BENT	159.40	159.40
1	REAR SHOCK ABSORBER TOP MOUNTING RH	NECESSARY	185.30	185.30
1	REAR SHOCK ABSORBER TOP MOUNTING LH	NECESSARY	185.30	185.30
1	REAR AXLE	BENT	592.60	592.60
1	ROOFTOP PANEL	BENT	1,288.87	1,288.87
1	ROOFTOP SIDE CHANNEL GARNISH RH (NPA)	SERVICEABLE	-	-
1	ROOFTOP SIDE CHANNEL GARNISH LH (NPA)	SERVICEABLE	-	-
1	ROOFTOP TOP MOULDING RH	DEFORMED	95.60	95.60
1	ROOFTOP TOP MOULDING LH	DEFORMED	95.60	95.60
1	FRONT RADIATOR LOWER BUSH RH (NPA)	SERVICEABLE	-	-
1	FRONT RADIATOR LOWER BUSH LH (NPA)	SERVICEABLE	-	-
1	FRONT FENDER QUARTER GARNISH RH	SCRATCHED	64.02	64.02
1	FRONT FENDER QUARTER GARNISH LH	MISSING	64.02	64.02
1	FRT TIE ROD END RH (NPA)	SERVICEABLE	-	-
1	FRT TIE ROD END LH (NPA)	SERVICEABLE	-	-
1	FRT LOWER ARM BALL JOINT RH	BENT	173.55	173.55
1	FRT LOWER ARM BALL JOINT LH	BENT	173.55	173.55
1	FRT KNUCKLE ARM RH	SERVICEABLE	521.50	-
1	FRT KNUCKLE ARM LH	BENT	521.50	521.50
1	FRT KNUCKLE ARM BEARING RH (NPA)	SERVICEABLE	-	-

Report Ref No. CS/FCI18009825/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT KNUCKLE ARM BEARING LH	BENT	170.37	170.37
1	FRT DOOR RUBBER BEADING RH	NECESSARY	185.70	185.70
1	FRT DOOR RUBBER BEADING LH	NECESSARY	185.70	185.70
1	FRT DOOR CHECKER RH	SERVICEABLE	151.20	-
1	FRT DOOR CHECKER LH	SERVICEABLE	151.20	-
1	ROOFTOP REINFORCEMENT NO.1	BENT	285.70	285.70
1	ROOFTOP REINFORCEMENT NO.2 (NPA)	TO REPAIR SEE LABOUR	-	-
1	ROOFTOP REINFORCEMENT NO.3 (NPA)	BENT	-	-
1	ROOFTOP REINFORCEMENT NO.4 (NPA)	TO REPAIR SEE LABOUR	-	-
1	ROOFTOP REINFORCEMENT NO.5 (NPA)	TO REPAIR SEE LABOUR	-	-
1	ROOFTOP REINFORCEMENT NO.6	BENT	241.67	241.67
1	BOOTLID HINGE RH (NPA)	SERVICEABLE	-	-
1	BOOTLID HINGE LH (NPA)	SERVICEABLE	-	-
1	BONNET STAND HOLDER (NPA)	SERVICEABLE	-	-
1	RADIATOR GRILLE TOP GARNISH (NPA)	REPEATED	-	-
1	WIPER TANK (NPA)	SERVICEABLE	-	-
1	WIPER TANK MOTOR (NPA)	SERVICEABLE	-	-
1	WIPER TANK NECK WITH CAP (NPA)	SERVICEABLE	-	-
1	RADIATOR UPPER BRACKET	BENT	47.80	47.80
1	AIR DUCT	SERVICEABLE	211.60	-
1	A/C LIQUID PIPE	SERVICEABLE	625.70	-
1	FAN COWLING	SERVICEABLE	211.02	-
1	CONDENSER	SERVICEABLE	1,289.24	-
1	AIR RESONATOR	CRACKED	186.40	186.40
1	FRT BRAKE PAD (NPA)	SERVICEABLE	-	-
1	REAR BRAKE PAD (NPA)	SERVICEABLE	-	-
1	A PILLAR RH	BENT	347.00	347.00
1	A PILLAR RH REINFORCEMENT NO 2	BENT	379.11	379.11
1	SPEAKER PANEL (NPA)	SERVICEABLE	-	-
1	SPEAKER PANEL TRIM (NPA)	SERVICEABLE	-	-
1	DASHBOARD (NPA)	SERVICEABLE	-	-

Report Ref No. CS/FCI18009825/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DASHBOARD LOWER (NPA)	SERVICEABLE	-	-
1	FRT DOOR OUTER HANDLE RH	SCRATCHED	298.40	298.40
1	FRT DOOR OUTER HANDLE LH	SCRATCHED	298.40	298.40
1	REAR DOOR OUTER HANDLE RH	SCRATCHED	298.40	298.40
1	REAR DOOR OUTER HANDLE LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT DOOR INNER LOCK RH	JAMMED	349.70	349.70
1	FRT DOOR INNER LOCK LH	BENT	349.70	349.70
1	REAR DOOR INNER LOCK RH (NPA)	SERVICEABLE	-	-
1	REAR DOOR INNER LOCK LH	JAMMED	341.70	341.70
1	FRT DOOR LOCK CATCH RH (NPA)	SERVICEABLE	-	-
1	FRT DOOR LOCK CATCH LH	SCRATCHED	42.10	42.10
1	REAR DOOR LOCK CATCH RH (NPA)	SERVICEABLE	-	-
1	REAR DOOR LOCK CATCH LH (NPA)	SERVICEABLE	-	-
1	FRT DOOR RH	BENT	1,221.70	1,221.70
1	FRT DOOR LH	BENT	1,221.70	1,221.70
1	REAR DOOR RH	BENT	1,127.20	1,127.20
1	REAR DOOR LH	BENT	1,127.20	1,127.20
1	FRT DOOR REGULATOR RH (NPA)	SERVICEABLE	-	-
1	FRT DOOR REGULATOR LH (NPA)	SERVICEABLE	-	-
1	REAR DOOR REGULATOR RH (NPA)	SERVICEABLE	-	-
1	REAR DOOR REGULATOR LH	BENT	189.79	189.79
1	FRT DOOR MOTOR RH (NPA)	SERVICEABLE	-	-
1	FRT DOOR MOTOR LH (NPA)	SERVICEABLE	-	-
1	REAR DOOR MOTOR RH (NPA)	SERVICEABLE	-	-
1	REAR DOOR MOTOR LH	NECESSARY	498.60	498.60
1	FRT DOOR GLASS RH (NPA)	SERVICEABLE	-	-
1	FRT DOOR OUTER CHROME RH	MISSING	155.15	155.15
1	FRT DOOR OUTER CHROME LH	CUT	155.15	155.15
1	REAR DOOR OUTER CHROME RH (NPA)	SERVICEABLE	-	-
1	REAR DOOR OUTER CHROME LH (NPA)	SERVICEABLE	-	-
1	FRT WHEEL BRAKE ROTOR RH (NPA)	SERVICEABLE	-	-
1	FRT WHEEL BRAKE ROTOR LH	SCRATCHED	311.10	311.10

Report Ref No. CS/FCI18009825/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WHEEL BRAKE ROTOR RH (NPA)	SERVICEABLE	-	-
1	REAR WHEEL BRAKE ROTOR LH (NPA)	SERVICEABLE	-	-
1	FRT WHEEL CALIPER RH (NPA)	SERVICEABLE	-	-
1	FRT WHEEL CALIPER LH (NPA)	SERVICEABLE	-	-
1	REAR WHEEL CALIPER RH (NPA)	SERVICEABLE	-	-
1	REAR WHEEL CALIPER LH (NPA)	SERVICEABLE	-	-
1	FRT BRAKE DISC RH (NPA)	SERVICEABLE	-	-
1	FRT BRAKE DISC LH (NPA)	SERVICEABLE	-	-
1	REAR BRAKE DISC RH (NPA)	SERVICEABLE	-	-
1	REAR BRAKE DISC LH (NPA)	SERVICEABLE	-	-
1	RH ROCKER PANEL (NPA)	SERVICEABLE	-	-
1	LH ROCKER PANEL	BENT	374.80	374.80
1	FRT DOOR STICKER RH	NECESSARY	68.71	68.71
1	FRT DOOR STICKER LH	NECESSARY	68.71	68.71
1	REAR DOOR STICKER RH	NECESSARY	67.84	67.84
1	REAR DOOR STICKER LH	NECESSARY	67.84	67.84
1	FRT DOOR FRAME GARNISH RH	SCRATCHED	79.70	79.70
1	FRT DOOR FRAME GARNISH LH	SCRATCHED	79.70	79.70
1	REAR DOOR FRAME GARNISH RH	SCRATCHED	68.30	68.30
1	REAR DOOR FRAME GARNISH LH	SCRATCHED	68.30	68.30
1	REAR SIDE END PANEL LH (NPA)	SERVICEABLE	-	-
1	A PILLAR RH	BENT	347.50	347.50
1	A PILLAR RH REINFORCEMENT NO 2 (NPA)	REPEATED	-	-
1	B PILLAR LH	BENT	347.50	347.50
	LESS 25% DISCOUNT		-12,750.80	-10,013.75
			38,252.41	30,041.23
	SPECIAL NETT ITEMS			
4	WHEEL TYRE (70%) (SN)	PUNCTURE-3PCS ONLY	720.00	378.00
4	WHEEL TYRE RIM (SN)	SCRATCHED-3PCS ONLY	2,200.00	1,650.00
10	FRONT BUMPER CLIPS (SN)	NECESSARY	38.90	38.90
1	FRONT NUMBER PLATE & CASING (SN)	SERVICEABLE	60.00	35.00

Report Ref No. CS/FCI18009825/R11d3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 8 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	BONNET RUBBER SEAL CLIP (SN)	NECESSARY	32.10	32.10
10	BONNET INSULATOR CLIP (SN)	NECESSARY	32.10	32.10
10	FRONT RADIATOR GRILLE TOP GARNISH CLIP (SN)	NECESSARY	38.90	38.90
10	FRONT FENDER INNER SHIELD CLIPS RH (SN)	NECESSARY	35.00	35.00
1	FRONT FENDER INNER SHIELD CLIPS LH (SN)	NECESSARY	35.00	35.00
1	BATTERY (NPA) (SN)	SERVICEABLE	-	-
1	FRONT W/S SEALANT (SN)	NECESSARY	50.00	50.00
1	FRONT STABILIZER BAR BRACKET RH (NPA) (SN)	SERVICEABLE	-	-
1	FRT FOO OUTER GLASS MOULDING (NPA) (SN)	SERVICEABLE	-	-
10	REAR BUMPER CLIP (SN)	NECESSARY	38.90	38.90
1	REAR REVERSE SENSOR (SN)	MISSING	200.00	200.00
1	REAR NUMBER PLATE & CASING (SN)	SERVICEABLE	60.00	-
1	BOOTLID LICENSE PLATE LAMP (NPA) (SN)	SERVICEABLE	-	-
10	REAR END PANEL TOP GARNISH CLIP(NPA) (SN)	SERVICEABLE	32.10	-
10	REAR FENDER INNER SHIELD CLIP RH (SN)	NECESSARY	35.00	35.00
10	REAR FENDER INNER SHIELD CLIP LH (SN)	NECESSARY	35.00	35.00
1	PRIMER (SN)	NECESSARY	50.00	50.00
1	REAR W/S PRIMER (SN)	SERVICEABLE	50.00	-
1	DECAL (SN)	NOT NECESSARY	20.00	-
1	FRT W/S SEALANT (SN)	NECESSARY	50.00	50.00
1	FRT DOOR TRIM BOARD RH (SN)	SERVICEABLE	1,333.60	-
1	REAR DOOR TRIM BOARD LH (NPA) (SN)	SERVICEABLE	-	-
1	ERP BRACKET (SN)	NECESSARY	15.00	15.00
1	REAR W/S SEALANT (SN)	NECESSARY	50.00	50.00
			5,211.60	2,798.90
	LABOUR			
	TO REPAIR AND RE-ALIGN ALL CHASSIS.	NOT NECESSARY	200.00	-
	TO R&R ENGINE WITH TRANSFER (TO FACILITATE BODYWORK REPAIRS AND TRANSFER AUTOMOTIVE TRANSMISSION ASSY).	NOT NECESSARY	350.00	-
	TO R&R FRONT AND REAR SUSPENSION AND UNDERCARRIAGE PARTS DUE TO ACCIDENT DAMAGED.		350.00	250.00

Report Ref No. CS/FCI18009825/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 9 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO R&R AND ADJUST HEAD LAMP & TAIL LAMP AND RESET HEADLAMP FOCUSING AND CHECK LIGHTING AND CHECK WHOLE WIRING AND SORT CIRUIT.		300.00	30.00
	TO FULL WHEEL ALIGNMENT, BALANCING, BRAKE BLEEDING AND ROAD TEST.		150.00	60.00
	MOUNT ON WORKBENCH.	NOT NECESSARY	350.00	-
	TO REFILL A/C GAS.		120.00	100.00
	TO R&R SEAT BELT, SEAT AND CARPET.	NOT NECESSARY	150.00	-
	TO R&R FRT WINDSCREEN.		120.00	120.00
	TO R&R REAR WINDSCREEN.		120.00	120.00
	TO SPRAY AND PUTTY FRONT ACCIDENT DAMAGED AREA (FRONT BUMPER, SUPPORT PANEL, BRACE PANEL, BONNET), FRT FENDER RH & LH, REAR FENDER RH & LH, BOOTLID, REAR BUMPER, A PILLAR, B PILLAR, ROOFTOP PANEL, REVERSE SENSOR.		3,000.00	2,800.00
	TO R&R AND WHOLE PANEL BEAT AND RE-ALIGN BODY WORKS AND ADJUST PART ON ACCIDENT DAMAGED AREA. INCLUSIVE OF THE REPAIR OF BOOTLID, ROOFTOP REINFORCEMENT NO.2, ROOFTOP REINFORCEMENT NO.4, ROOFTOP REINFORCEMENT NO.5 AND REAR DOOR OUTER HANDLE LH.		6,000.00	3,800.00
	RUST PROOFING.		100.00	100.00
	TO R&R FRT RH & LH AND REAR RH & LH DOOR AND DOOR COMPARTMENT.		400.00	180.00
	TO R&R AND JACK ROOFTOP AND ROOF LINING.		300.00	200.00
	TO R&R DASHBOARD AND RE-ALIGNMENT DASHBOARD AND R&R SPEAKER PANEL AND SPEAKER PANEL TRIM.		400.00	150.00
	TO RE-ALIGN EXHAUST PIPE AND FUEL TANK.	NOT NECESSARY	200.00	-
			12,610.00	7,910.00
	GRAND TOTAL		56,074.01	40,750.13
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			25,000.00

Report Ref No. CS/FCI18009825/R1td3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.