

Report Format :  
Lump Sum / I.B.L: (S

**Trans-cab Auto Services Pte Ltd**

AAD1805-261

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB 9909P

*Not Notified  
61 Sep @ 5300h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHB 9909P

VF1ABL15AUC273469

RENAULT

LATITUDE

27.5.2018

*4th***PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Be</i> 1,108.46	—
2	1 BUMPER LOWER REAR	\$	<i>Not</i> 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>Be</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>Be</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Be</i> 225.36	—
19	1 BOOT BADGE	\$	<i>Be</i> 225.36	—
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	

**Trans-cab Auto Services Pte Ltd**

AAD1805-261

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9909P**

30	1 DOOR PANEL REAR LH	\$	<i>R</i>	2,844.66	}
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sm</i>	671.45	
32	1 FENDER PANEL REAR LH	\$	<i>R</i>	3,299.13	
33	1 WHEELARCH REAR LH	\$	<i>Sm</i>	543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sm</i>	671.45	
35	1 FENDER PANEL REAR RH	\$	<i>R</i>	3,299.13	
36	1 WHEELARCH REAR RH	\$	<i>Sm</i>	543.47	
37	1 TAILLAMP RH	\$	<i>Sm</i>	552.55	
38	1 TAILLAMP PANEL RH	\$	<i>R</i>	986.70	
39	1 TAILLAMP LH	\$	<i>Sm</i>	552.55	
40	1 TAILLAMP PANEL LH	\$	<i>R</i>	986.70	
41	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i>	1,471.77	
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sm</i>	404.56	
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i>	2,189.88	
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Sm</i>	612.21	
45	1 EXHAUST REAR	\$	<i>R</i>	7,489.05	}
46	1 EXHAUST CAP REAR	\$	<i>R</i>	230.49	
47	1 FUEL FLAP L70Y	\$	<i>Sm</i>	343.57	
<b>TOTAL</b>		<b>\$</b>		<b>39,057.17</b>	
<b>10%</b>		<b>\$</b>		<b>3,905.72</b>	
		<b>\$</b>		<b>35,151.45</b>	

**Specical Nett**

1	1SET PARKING AID	\$	<i>Sm</i>	700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>R</i>	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>R</i>	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>R</i>	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>R</i>	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>R</i>	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>R</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>R</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>R</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sm</i>	17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>R</i>	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	<i>R</i>	30.00	—
13	1 BOOT STICKER "6555-3333"	\$	<i>R</i>	30.00	—
14	1 BOOT INNER TRIM CLIP	\$	<i>R</i>	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>R</i>	35.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1805-261

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9909P

16	1SET FENDER WHEELARCH REAR LH CLIP	\$	nn 35.00	} X
17	1 FENDER INNER TRIM CLIP LH	\$	nn 28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	nn 28.00	
19	1 TAILLAMP CLIP RH	\$	nn 5.00	
20	1 TAILLAMP CLIP LH	\$	nn 5.00	
21	2 REAR WINDSCREEN SELANT	\$	nn 80.00	
22	1 WINDSCREEN MOULDING	\$	nn 100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	su 385.00	
25	1 SPARE TYRE	\$	su 330.00	

TOTAL \$ 2,225.02

TOTAL PARTS \$ 37,376.47**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	4001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X

**Trans-cab Auto Services Pte Ltd****AAD1805-261**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9909P**

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00 X

**TOTAL \$ 12,540.00****Over All Total \$ 49,916.47****(LUMP SUM)****Repair Days****20 DAYS***2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHB9909P
Vehicle to be Exported:	Yes
Intended De-registration Date:	28 May 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000404
Chassis No.:	VF1ABL15AUC273469
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2021
PARF Rebate Amount:	\$9,373.00

**Intended COE Rebate Details**

COE Expiry Date:	29 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$54,952.00
COE Rebate Amount:	\$22,342.00
<b>Total Rebate Amount:</b>	<b>\$31,715.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 May 2018.

OK



[Home](#) e-Services (/content/policehubhome/homepage.html)

[Log in](#)

# Status of Driving Licence

## Qualified Driving Licence

### Qualified Driving Licence Number

S0121549C

### Status of Qualified Driving Licence

Valid

### Class(es) of Qualified Driving Licence

3

### Expiry Date

Valid for life unless revoked,suspended or disqualified

## Provisional Driving Licence

You are not a valid Provisional Driving Licence Holder.

[HOME \(https://www.police.gov.sg/\)](https://www.police.gov.sg/)

[ABOUT US \(https://www.police.gov.sg/about-us\)](https://www.police.gov.sg/about-us)

[SGSECURE \(https://www.police.gov.sg/sgsecure\)](https://www.police.gov.sg/sgsecure)

[I-WITNESS \(https://www.police.gov.sg/iwitness\)](https://www.police.gov.sg/iwitness)

[COMMUNITY PROGRAMMES \(https://www.police.gov.sg/community-programme\)](https://www.police.gov.sg/community-programme)

[RESOURCES \(https://www.police.gov.sg/resources\)](https://www.police.gov.sg/resources)

[NEWS & PUBLICATIONS \(https://www.police.gov.sg/news-and-publications\)](https://www.police.gov.sg/news-and-publications)

[JOIN US \(https://www.police.gov.sg/join-us\)](https://www.police.gov.sg/join-us)

[FAQS \(https://va.ecitizen.gov.sg/cfp/CustomerPages/SPF/explorefaq.aspx\)](https://va.ecitizen.gov.sg/cfp/CustomerPages/SPF/explorefaq.aspx)

[CONTACT US \(https://www.police.gov.sg/content/contact-us\)](https://www.police.gov.sg/content/contact-us)

[E-FEEDBACK \(/content/policehubfeedback/efeedback.html\)](/content/policehubfeedback/efeedback.html)

[SITEMAP \(https://www.police.gov.sg/sitemap\)](https://www.police.gov.sg/sitemap)

[Privacy Statement \(https://www.police.gov.sg/content/privacy-statement\)](https://www.police.gov.sg/content/privacy-statement) | [Terms of Use](#)

[\(https://www.police.gov.sg/content/terms-of-use\)](https://www.police.gov.sg/content/terms-of-use) . © 2018 Singapore Police Force. A Member of The Home Team

[\(https://www.mha.gov.sg\)](https://www.mha.gov.sg).

## Vic (LKKAUTO)

**From:** Vic (LKKAUTO)  
**Sent:** Monday, 6 August, 2018 3:47 PM  
**To:** Ng Wai Yin  
**Cc:** Admin A; Vic (LKKAUTO); claims@transcab.com.sg  
**Subject:** Your Ref: AAD1805-261\_ACCIDENT INVOLVING VEHICLES SLF 4866T AND SHB 9909P ON 27/05/2018  
**Attachments:** PIR.pdf

Without Prejudice

Your Ref: AAD1805-261  
Our Ref: CC3/AIG18009829/Khb3

Dear Wai Yin,

ACCIDENT INVOLVING VEHICLES SLF 4866T AND SHB 9909P ON 27/05/2018

We refer to the subject matter.

Please be informed that our principal had further reviewed the matter and based on the PIR provided, our principal is in the view that our Insured is not liable of this accident. Please refer to the attached PIR for your reference.

As such, we have our principal's instruction to deny your client's claim.

Thank you.


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contains confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## Vic (LKKAUTO)

---

**From:** Md Noor, Norsiah <Norsiah.MdNoor@aig.com>  
**Sent:** Monday, 6 August, 2018 3:07 PM  
**To:** Vic (LKKAUTO)  
**Cc:** Hsiao Tong (LKKAUTO)  
**Subject:** Claim No: 7773580546SG (003)  
**Attachments:** Police Investigation Result.pdf

Dear Vic,

Please refer to the attached a copy of Police Investigation Result.

Traffic Police has completed their investigation which revealed that the driver of SHB9909P has committed an offence of Inconsiderate Driving under Section 65(b) of the Road Traffic Act Chapter 276.

Please proceed to reject Third-party claim.

Thank you

Norsiah Md Noor  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419-1606 | Fax +(65) 6835-7417  
[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



SINGAPORE  
POLICE FORCE

TRAFFIC POLICE  
SINGAPORE POLICE FORCE  
100-1100  
100-1100  
100-1100  
100-1100

Our Ref: TP/P/24001/2018  
Date: 13 July 2018

PETER NG JUI HUAT  
BLK 281 BISHAN STREET 24  
#04-12  
SINGAPORE 570281

Dear Sir/Madam

ROAD TRAFFIC ACCIDENT INVOLVING SHB 3909 P AND SLF 4866 T ALONG PAN ISLAND  
EXPRESSWAY ON 27/06/2018 AT ABOUT 9.45AM

I refer to the above accident.

Please be informed that we have completed our investigations which revealed that the driver of  
SHB 3909 P had committed an offence of Inconsiderate Driving under Section 65(b) of the Road  
Traffic Act Chapter 275. Action has been initiated against the driver for the said offence.

Yours faithfully

HEAD INVESTIGATION  
TRAFFIC POLICE  
SINGAPORE POLICE FORCE

This is a computer-generated letter. No signature is required.

Police State the Nation

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2018 <a href="#">Edit Reg</a>		30 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$45,300.00</b> <a href="#">Edit Estimates</a>	<b>\$45,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>Josephine Chan May Hwa</b> , ID: S15655111, Tel: +6599999999									
Main Claimant: <b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: 200303878K									
Vehicle Reg. No.:	<b>SHB9909P</b>	Date of Loss:	27/05/2018 09:00 - :59 [56 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 7995893898SG</b>	Policy/Cover Note No.:	2100480676 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLF4866T</b>	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer: <b>Trans-cab Auto Services Pte Ltd (Ang Mo Kio)</b> 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Kesaval, Jaclyn-M</b> ] Jaclyn-M.Kesaval@aig.com									
Claimant's Insurer: <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 11/06/2018]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (04/06/2018): No OI GIA Report									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SHB9909P (7995893898SG)**  
**[SLF4866T]**  
**TP**  
**TRANS-CAB SERVICES PTE LTD**  
**May 27 2018 9:00AM**  
**[Josephine Chan May Hwa]**  
**Trans-cab Auto Services Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Video</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/06/18 16:54	Video - Accident from insured vehicle	Load MP4	
<b>Photos/Images</b>				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/18 17:04	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	16/07/18 17:04	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	16/07/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
4	16/07/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
5	16/07/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
6	16/07/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
7	16/07/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
8	16/07/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
9	16/07/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
10	16/07/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
11	16/07/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
12	16/07/18 17:05	General View	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/05/18 20:04	TP ESTIMATE- MARKED	Load PDF	
2	31/05/18 20:04	TP GIA REPORT	Load PDF	
3	05/06/18 09:25	Non reporting letter	Load PDF	
4	11/06/18 17:52	EMAIL FROM OI	Load PDF	
5	11/06/18 17:53	EMAIL TO AIG	Load PDF	
6	16/07/18 17:03	OID DRIVING LICENCE STATUS	Load PDF	
7	06/08/18 15:29	EMAIL FROM AIG	Load PDF	
8	06/08/18 15:29	PIR	Load PDF	
9	06/08/18 15:48	EMAIL TO TP REJECT	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/06/18 16:54	E-filed GIA report	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>			<a href="#">Reset</a>   <a href="#">Save</a>   <a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			

**Show Remarks To:** ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18009829/KHB3Q2

Date: 30/08/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100480676

Claimant Vehicle No : SHB9909P

Insured Vehicle No : SLF4866T

Date of Loss: 27/05/2018

Nature of Claim:

TP

Claim No: 7995893898SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB9909P

Make &amp; Model: RENAULT LATITUDE, 2.0 L (A)

Reg. Date: 30/08/2013 (Man. Year: 2013)

Colour: Metallic White/Red

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: M9R8839C000404

Chassis No: VF1ABL15AUC273469

Odometer: 333970 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,376.45	5,605.40	31,771.05	85.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,920.00	990.00	11,930.00	92.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>50,296.45</b>	<b>6,595.40</b>	<b>43,701.05</b>	<b>86.89</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,300.00</b>		
<b>(\$\$)</b>	50,296.45	5,300.00	44,996.45	89.46
<b>+ GST 7.00/7.00% (\$\$)</b>	3,520.75	371.00	3,149.75	89.46
<b>Nett Amount (\$\$)</b>	<b>53,817.20</b>	<b>5,671.00</b>	<b>48,146.20</b>	<b>89.46</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 30/05/2018

Date Inspected: 30/05/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.5 days

---

**Adjuster:** KENNETH KONG**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPE REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
31	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
32	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
33	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
34	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
35	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
36	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
37	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
38	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
39	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
40	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
41	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
42	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
43	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
44	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
45	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
46	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
47	1		*FUEL FLAP L70Y	Serviceable	343.57 FL	*- FL
48	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
49	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
51	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
52	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
53	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
54	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
55	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
56	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
57	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
58	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
59	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
60	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
61	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
62	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
63	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
64	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
65	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
66	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
67	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
68	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
69	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
70	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
71	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
72	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)**    **41,282.17**    **6,203.22**  
**- List Item Discount on L Items 10.00/10.00% (\$\$)**    **3,905.72**    **597.82**

**Total Parts (\$\$)**    **37,376.45**    **5,605.40**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	4,200.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
14	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
Gross Labour Cost (S\$)			12,920.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >