

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5888L - AIG**AAD1805-255***Not Notarised
L/Sing @ 5500/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5888L

VF1ABL15AUC281460

RENAULT

LATITUDE

25.5.2018

AIG**PART****LIST**

1	DOOR PANEL FRT RH	\$	<i>B</i> 2,844.66	✓
1	DOOR HINGE UPPER RH	\$	<i>R</i> 261.28	X
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55	X
1	DOOR CHECK FRT RH	\$	<i>Sn</i> 194.77	X
1	DOOR LOCK FRT RH	\$	<i>R</i> 908.75	}
1	DOOR CATCH FRT RH	\$	<i>R</i> 131.23	
1	DOOR HANDLE OUTER FRT RH	\$	<i>Sn</i> 477.76	
1	DOOR HANDLE COVER FRT RH	\$	<i>Sn</i> 13.22	
1	DOOR HANDLE MODULE FRT RH	\$	<i>Sn</i> 133.60	
1	DOOR REGULATOR FRT RH	\$	<i>R</i> 505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>Sn</i> 796.46	
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>R</i> 120.97	}
1	DOOR PANEL REAR RH	\$	<i>B</i> 2,844.66	
1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82	
1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50	X
1	DOOR HINGE LOWER RH	\$	<i>Dis</i> 300.55	✓
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sn</i> 203.06	}
1	DOOR LOCK REAR RH	\$	<i>R</i> 908.75	
1	DOOR HANDLE OUTER REAR RH	\$	<i>Sn</i> 126.49	
1	DOOR HANDLE CAP REAR RH	\$	<i>Sn</i> 35.52	
1	DOOR HANDLE COVER REAR RH	\$	<i>Sn</i> 13.22	
1	DOOR HANDLE MODULE REAR RH	\$	<i>R</i> 133.60	
1	DOOR REGULATOR REAR RH	\$	<i>R</i> 1,135.10	
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>R</i> 893.75	
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Sn</i> 12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sn</i> 6.31	
1	DOOR FINISHER REAR RH	\$	<i>Sn</i> 423.10	}
1	DOOR MOULDING REAR RH	\$	<i>Sn</i> 176.82	
1	DOOR MOULDING CLIP L70Y	\$	<i>Sn</i> 5.92	

Trans-cab Auto Services Pte Ltd**AAD1805-255**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5888L - AIG

1	DOOR MOULDING SCREW L70Y	\$	na 6.91	}
1	DOOR CASING REAR RH	\$	sn 1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	sn 30.39	
1	DOOR CASING CLIP	\$	na 12.63	
1	DOOR CASING LIGHT L70Y	\$	sn 48.74	
1	DOOR FINISHER INNER REAR RH	\$	sn 323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n 46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	n 20.33	
1	DOOR GRAB HANDLE REAR RH	\$	sn 210.96	
1	DOOR BLIND REAR RH	\$	sn 741.80	
1	DOOR WHEATHESTRIIP REAR RH	\$	sn 410.66	
1	DOOR SEAL REAR RH	\$	sn 162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	sn 229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	sn 334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	sn 115.64	
1	DOOR MIRROR ASSY RH	\$	sn 1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	sn 466.51	
1	ROCKER PANEL INNER RH	\$	n 1,024.79	
1	ROCKER PANEL CENTER RH	\$	n 990.25	

\$	22,568.20
----	-----------

10% \$	2,256.82
--------	----------

\$	20,311.38
----	-----------

Specical Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00 X
2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	na 30.00 X
1SET	WHEELARCH CLIP FRT LH	\$	na 30.50 X
1	FRONT DOOR STICKER 'Trans-cab'	\$	na 80.00 60sn
1	FRONT DOOR STICKER 'Chassis'	\$	na 50.00 15sn
1	REAR DOOR STICKER '6555 3333'	\$	na 80.00 60sn
1	DOOR CHECK BOLT	\$	na 22.69 X
1	DOOR GUIDE SCREW	\$	na 10.85 X
1	DOOR HINGE BOLT	\$	na 10.85 X

Trans-cab Auto Services Pte Ltd**AAD1805-255**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5888L - AIG

1	DOOR HINGE NUT RH	\$	<i>R</i> 14.60 <i>X</i>
1	DOOR CHECK BOLT	\$	<i>R</i> 22.69 <i>X</i>
1	DOOR CHECK NUT	\$	<i>R</i> 3.75 <i>X</i>
1	DOOR LOCK SCREW L70Y	\$	<i>Sn</i> 6.12 <i>X</i>
1	DOOR CATCH SCREW L70Y	\$	<i>Sn</i> 10.06 <i>X</i>

TOTAL	\$	462.13
--------------	-----------	---------------

TOTAL PARTS	\$	20,773.51
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 <i>500l</i>
Putty and spray painting of the affected portion.	\$	2,500.00 <i>660l</i>
To rust-proofing of the affected areas.	\$	170.00 <i>60l</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nr</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20l</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nr</i> 380.00 <i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 <i>60l</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 <i>60l</i>

Trans-cab Auto Services Pte Ltd**AAD1805-255**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5888L - AIG

Towing Fees. \$ *nn* 120.00 X

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack. \$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. \$ *nn* 380.00 X

TOTAL \$ **8,630.00**

Over All Total \$ **29,403.51**

PART-BY-PART (REPAIR DAY)*10 DAYS**4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: