

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4182R

MAKE :

MODEL : HYUNDAI SONATA

AxA

DATE 30/5/2018 11:53

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid — <i>sent</i>			\$ 1,349.50
	Boot Lid Rubber X <i>sent</i>			\$ 110.90
	Boot Lid Lock Upper X <i>sent</i>			\$ 132.10
	Boot Lid Lock Lower X <i>sent</i>			\$ 30.30
	Boot Lid Sonata Plate — <i>sent</i>			\$ 43.60
	Boot Lid Hyundai Plate — <i>sent</i>			\$ 24.20
	Boot Lid 'H' Emblem — <i>sent</i>			\$ 26.10
	Boot Lid CRDI Plate — <i>sent</i>			\$ 22.70
	Rear Bumper — <i>sent</i>			\$ 578.40
	Rear Bumper Reinforcement — <i>sent</i>			\$ 483.30
	Rear Bumper Clip — <i>sent</i>			\$ 22.00
	Rear Bumper Sponge — <i>sent</i>			\$ 137.40
	Rear Bumper Under Cover X <i>sent</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) X <i>report</i>		\$ 38.00	\$ 76.00
	Rear Panel X <i>report</i>			\$ 391.80
	Rear Panel Garnish X <i>sent</i>			\$ 95.80
	SUB TOTAL			\$ 3,709.90
	LESS 20%			\$ 741.98
	DISCOUNTED TOTAL			\$ 2,967.92
	Boot Lid Comfort Logo & Tel No. Sticker — <i>sent</i>			\$ 30.00
	Boot Lid Advertisement Logo — <i>sent</i>			\$ 100.00
	Rear Bumper Reverse Sensor X <i>sent</i>			\$ 135.70
	Rear Bumper Advertisement Logo — <i>sent</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) — <i>sent</i>		\$ 100.00	\$ 200.00
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a 'Without Prejudice' basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company			
	Acknowledged by Repairer			
	Signature: <i>Kelvin (KLP)</i>			
	Date: <i>31/5/18 1345hrs</i>			
	<i>3 Pys</i>			
	<i>After Repair photo</i>			
	Labour Charge			
	Panel Beating			\$ 850.00 <i>600</i>
	Spray Painting Charge			\$ 750.00 <i>600</i>
	Wiring Charge			\$ 50.00 <i>sent</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>sent</i>
	TOTAL LABOUR			\$ 1,820.00
	ESTIMATE TOTAL			\$ 5,303.62
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Larry Ng