



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLG 960 A

*Not authorized
 1.B.1
 Resurvey by paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s), must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Parts (a) Cost / List Price Items	\$	13,593.76
Plus/Less 25%	\$	3,398.44
Total of Cost / List	\$	10,195.32
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	45.00
Total Parts Cost	\$	10,240.32
Labour	\$	3,270.00
Total	\$	13,510.32

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 30/5/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 4-5 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : lc Date: 30/5/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLG 960 A**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **JTDKB3FU803533761**

Submit By : **Carmen Lim**
 Year Manufacture : **2016**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>Del</i>	1	\$45.00	S.N	✓
2	Front number plate garnish <i>Del</i>	1	\$45.00		✓
3	Bonnet <i>B₁</i>	1	\$812.40		✓
4	Bonnet lock <i>R</i>	1	\$130.00		X
5	Bonnet hinge LH <i>R</i>	1	\$57.80		X
6	Bonnet hinge RH <i>R</i>	1	\$57.80		✓
7	Front support panel centre <i>R</i>	1	\$338.50		X
8	Front support panel LH <i>R</i>	1	\$213.50		X
9	Front support panel RH	1	\$213.50		?
10	Headlamp panel LH <i>R</i>	1	\$89.20		X
11	Headlamp panel RH	1	\$89.20		?
12	Support panel lower	1	\$387.95		?
13	Front support panel top garnish <i>S₁</i>	1	\$285.40		X
14	Front support panel top garnish clip <i>nn</i>	10	\$35.00		X
15	Air duct	1	\$195.40		?
16	Brace panel <i>R</i>	1	\$105.20		X
17	Headlamp LH <i>S₁</i>	1	\$2,531.60		X
18	Headlamp RH <i>CMA</i>	1	\$2,531.60		✓
19	Front bumper <i>B₁</i>	1	\$450.80		✓
20	Front bumper clip <i>nn</i>	10	\$40.00		✓
21	Front bumper reinforcement - upper	1	\$711.50		?
22	Front bumper reinforcement - lower	1	\$245.30		?
23	Front bumper side retainer RH <i>D₁</i>	1	\$107.20		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

