

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 260A**AAD1805-234**

Not Authorized
Penalty B4 paid @ 3998.61

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 260A
 VF1ABL15AUC282302
 RENAULT
 LATITUDE
 25.5.2018
 III

PART	LIST
1 BUMPER COVER FRT	\$ <i>Bur</i> 1,259.42 ✓
1 BUMPER SPOILER FRT	\$ <i>Sen</i> 181.75 X
1 BUMPER ABSORBER FRT	\$ <i>Sen</i> 394.68 X
1 BUMPER RETAINER FRT RH	\$ <i>Dis</i> 150.77 ✓
1 BUMPER SUPPORT FRT	\$ <i>Sen</i> 123.88 X
1 BUMPER UNDERTRAY FRT	\$ <i>Sen</i> 472.83 X
1 BUMPER GRILLE LOWER FRT	\$ <i>Sen</i> 266.80 X
1 BUMPER FOG LAMP GRILLE RH	\$ <i>Sen</i> 207.21 X
1 BUMPER BEAM FRT	\$ <i>R</i> 914.08 X
1 HEADLAMP RH	\$ <i>Sen</i> 1,184.43 ✓
1 HEADLAMP PANEL FRT RH	\$ <i>R</i> 152.15 X
1 FENDER PANEL FRT RH	\$ <i>Bur</i> 783.83 ✓
1 WHEELARCH FRT RH	\$ <i>Sen</i> 278.84 }
1 FENDER BRACKET LOWER RH	\$ <i>Sen</i> 15.79 }
1 FENDER INSULATOR RH	\$ <i>Sen</i> 130.84 }
1 DOOR PANEL FRT RH	\$ <i>R</i> 2,844.66 }
1 RADIATOR GRILLE	\$ <i>Sen</i> 1,707.78 }
1 RADIATOR GRILLE BADGE 'RENAULT'	\$ <i>Sen</i> 225.36 }
1 RADIATOR GRILLE FRAME	\$ <i>Sen</i> 1,353.75 }
1 RADIATOR FAN COWLING	\$ <i>Sen</i> 820.54 }
1 RADIATOR FAN MOTOR LH	\$ <i>Sen</i> 967.36 }
1 RADIATOR FAN MOTOR RH	\$ <i>Sen</i> 1,479.46 }
1 FRAME FULL SUPPORT PANEL	\$ <i>R</i> 615.90 }
1 FRAME FULL SUPPORT BRACKET	\$ <i>R</i> 89.79 }
1 DOOR MIRROR ASSY RH	\$ <i>Sen</i> 1,483.40 }
1 DOOR PANEL FRT RH	\$ <i>R</i> 2,844.66 }
1 BONNET	\$ <i>R</i> 1,941.63 }
1 BONNET INSULATOR	\$ <i>Sen</i> 405.73 }
1 BONNET STRUT LH	\$ <i>Sen</i> 88.61 }
1 BONNET STRUT RH	\$ <i>Sen</i> 88.61 }

Trans-cab Auto Services Pte Ltd

AAD1805-234

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 260A

1	BONNET HINGE LH	\$	N 348.31	}
1	BONNET HINGE RH	\$	N 348.31	
1	BONNET LOCK	\$	N 305.48	
1	BONNET CABLE	\$	Sn 119.19	
1	BONNET CABLE COVER	\$	Sn 161.03	
1	BONNET SEAL OUTER	\$	Sn 92.36	
1	BONNET SEAL INNER	\$	Sn 157.28	
1	SUBFRAME OUTER FRT	\$	N 2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	N 92.36	
1	SUBFRAME BRACKET OUTER RH	\$	N 92.36	
1	ENGINE UNDERTRAY	\$	Sn 564.98	
1	A/C CONDENSER	\$	Sn 2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	Sn 39.67	
1	A/C CONDENSER GARNISH RH UPPER	\$	Sn 39.67	
1	A/C CONDENSER GARNISH LH	\$	Sn 58.81	
1	A/C CONDENSER GARNISH RH	\$	Sn 59.60	
1	LOWER ARM RH	\$	Sn 685.76	
1	KUNCKLE ARM RH	\$	Sn 846.98	
1	ABSORBER FRT RH	\$	Sn 360.54	
1	STABILIZER BAR FRT	\$	Sn 604.65	
1	DRIVESHAFT RH	\$	N 1,747.45	
1	WIPER RESERVOIR	\$	Sn 348.25	
1	WIPER RESERVOIR NECK	\$	Sn 136.11	
1	WIPER RESERVOIR MOTOR	\$	Sn 270.06	

TOTAL	\$	35,626.53
10%	\$	3,562.65
	\$	32,063.87

Special Nett

1SET	BUMPER CLIP FRT	\$	N 66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	N 12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	N 10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	N 69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	N 70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	Sn 20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	Sn 30.00	X

Trans-cab Auto Services Pte Ltd**AAD1805-234**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 260A

1SET	WHEELARCH CLIP FRT RH	\$	<i>nn</i> 30.50 X
6	BONNET INSULATOR CLIP L70Y	\$	<i>nn</i> 7.30 X
2	BONNET STRUT L70Y	\$	<i>nn</i> 88.61 X
2	BONNET CABLE CLIP L70Y	\$	<i>nn</i> 6.31 X
2	BONNET CABLE COVER SCREW L70Y	\$	<i>nn</i> 10.85 X

TOTAL	\$	421.08
--------------	-----------	---------------

TOTAL PARTS	\$	32,484.95
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <i>4000</i>
Putty and spray painting of the affected portion.	\$	4,000.00 <i>4401</i>
To rust-proofing of the affected areas.	\$	170.00 <i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1805-234

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 260ATo replace, refix and top up coolant for radiator \$ *nn* 170.00 *X*To vacuum, replace, refix and recharge Air
Intercooler \$ *nn* 170.00 *X***TOTAL** \$ 11,090.00**Over All Total** \$ 43,574.95**LUMP SUM (REPAIR DAY)**~~15 DAYS~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: