

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3062K

DATE 31/5/2018 11:48

MAKE :

MODEL : HYUNDAI i40

pbyP
AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille ✓			\$ 1,480.00	
	Front Bumper Cover ✓			\$ 1,052.20	
	Front Bumper Sponge ?			\$ 142.20	
	Front Bumper Reinforcement ?			\$ 526.10	
	Front Bumper Bracket Top (LH/RH) - ?		\$ 22.40	\$ 44.80	
	Front Bumper Bracket (LH/RH) - ?		\$ 24.60	\$ 49.20	
	Headlamp (RH) ✕			\$ 1,388.00	
	SUB TOTAL			\$ 4,682.50	
	LESS 20%			\$ 936.50	
	DISCOUNTED TOTAL			\$ 3,746.00	
	Front Number Plate ✓			\$ 25.00	Nett
	Front No Plate Trim Cover ✓			\$ 30.00	Nett
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 380.00 ²⁰⁰	
	Spray Painting Charge			\$ 250.00 ²⁰⁰	
	Wiring Charge			\$ 50.00 ✕	
	TOTAL LABOUR			\$ 680.00	
	ESTIMATE TOTAL			\$ 4,481.00	
Kali 10/11/14 31/5/18 1420hs. 2 Rys P/P Before Paint photo					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will