

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.
Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SKM 9801 Y.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,849.00	de ✓
2	FRONT BUMPER FIXING PARTS	\$ 222.00	? X
3	FRONT BUMPER AIR GRILLE - LH/RH	2 \$ 258.00	de ✓
4	FRONT BUMPER TRIM - LOWER CENTRE	\$ 322.50	de ✓
5	RADIATOR GRILLE	\$ 673.50	ma ✓
6	FRONT BUMPER CLOSING ELEMENT - LOWER	\$ 204.00	? X
7	FRONT BUMPER FOAM	\$ 109.00	de ✓
8	FRONT REINFORCEMENT BEAM	\$ 1,239.00	? X
9	FRONT GRILLE SENSOR SUPPORT - LH/RH	2 \$ 116.20	? 58.10
10	FRONT PARKING AID SENSOR	4 \$ 848.00	? 424.
11	FRONT BUMPER WIRING SET	\$ 576.50	? X
12	HEADLIGHT MOUNTING - LH/RH	2 \$ 218.00	109
13	FRONT BUMPER TOP COVER	\$ 109.00	de ✓
14	HEADLIGHT BRACKET - LH/RH	2 \$ 139.00	LH new, RH-?, 69.50
15	FRONT BUMPER GUIDE - LH/RH	2 \$ 74.00	de ✓
16	HEADLIGHT - LH/RH	2 \$ 4,762.00	LH-ua, RH-? 2,381
17	HEADLIGHT SEALING FRAME - LH OUTER	\$ 55.80	ma ✓
18	GAS DISCHARGE BULB CONTROL UNIT - LH	\$ 1,018.00	? } X
19	GAS DISCHARGE BULB - LH	2 \$ 787.00	? }
20	POWER MODULE FOR GAS DISCHARGE LIGHT - LH	\$ 1,210.00	? }
SUB-TOTAL SPARE PARTS CHARGES		\$ 14,790.50	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.
Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SKM 9801 Y.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	HEADLIGHT SEAL - LH	\$ 38.10	neu ✓
22	TOW EYE COVER	\$ 49.90	mis ✓
23	FRONT BUMPER SECURING STRIP - LH/RH	2 \$ 59.80	? } X
24	FRONT FENDER BRACE - LH/RH	2 \$ 211.00	? } X
25	HEADLIGHT WASHER COVER - LH/RH	2 \$ 97.80	? } X
26	HEADLIGHT WASHER JET - LH/RH	2 \$ 481.00	? 240.50
27	HEADLIGHT WASHER SECURING BRACKET - LH/RH	2 \$ 49.60	? X
28	RADIATOR GRILLE ' QUATTRO ' EMBLEM	\$ 107.50	neu ✓ X
29	FRONT FENDER - LH/RH	2 \$ 1,860.00	LH - bt ✓, RH - Rp 930
30	FRONT FENDER BRACKET - LH/RH FRT	2 \$ 100.00	LH - 50
31	FRONT FENDER ATTACHMENT PARTS	\$ 97.60	? X
32	FRONT FENDER RIVET SET	\$ 23.20	neu ✓
33	FRONT FENDER BRACKET - LH/RH REAR	2 \$ 100.00	? } X
34	FRONT FENDER CLOSING ELEMENT - LH/RH	2 \$ 847.00	? } X
35	FRONT LOCK CARRIER AIR GUIDE - LH/RH	2 \$ 50.80	? } X
36	FOG LAMP - LH/RH	2 \$ 448.00	? } X
37	FRONT NO. PLATE	S/N \$ 25.00	bt ✓
38	SUNDRIES	\$ 150.00	? 19.40
TOTAL SPARE PARTS CHARGES		: \$ 19,586.80	— 7,868.50
TOTAL LABOUR CHARGES		: \$ 3,390.00	— 2,240. X
GRAND TOTAL		: \$ 22,976.80	—

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

\$ 10,108.50
L/S \$ 7K