



陳林隆摩私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SCN338S
Date of Accident : 29 May 2018

Mr Loh Buck Hien

TP AXA.
Xiao Tong

Date : 31 May 2018

Estimate To Repair SLH3741R - NISSAN NOTE 1.2 CVT ABS D/AIRBAG 2WD
Chassis No : JN1TAAE12Z0972465

S/No	Quantity	Description	Amount
		NETT ITEMS	
01	1 pc	right front door <i>Distorted</i>	\$ 981.20 ✓
02	1 pc	right front door window glass channel weatherstrip <i>new</i>	\$ 178.40 ✓
03	1 pc	right front door outer weatherstrip moulding <i>new</i>	\$ 129.40 ✓
04	1 pc	right front door handle <i>new</i>	\$ 275.50 ✓
05	1 pc	right front door handle extension garnish <i>new</i>	\$ 43.00 ✓
06	1 pc	right front door handle inner base <i>new</i>	\$ 65.10 ✓
07	1 pc	right front door handle power window motor <i>new</i>	\$ 598.00 ✓
08	1 pc	right front door regulator <i>new</i>	\$ 130.80 ✓
09	1 pc	right front door weatherstrip <i>new</i>	\$ 84.60 ✓
10	1 pc	right front door side mirror - motor assy <i>new</i>	\$ 560.90 ✓
11	1 pc	right front door side mirror motor cover <i>new</i>	\$ 169.30 ✓
12	1 pc	right front door inner lock <i>new</i>	\$ 166.70 ✓
13	1 pc	right front door inner lock stricker <i>new</i>	\$ 34.80 ✓
14	1 pc	right front door window frame matt black tape - rear <i>new</i>	\$ 32.70 ✓
15	1 pc	right front door window frame matt black tape - front <i>new</i>	\$ 36.00 ✓
16	1 pc	right front door inner trimboard <i>new</i>	\$ 569.70 ✓
17	1 pc	right front door hinge top <i>new</i>	\$ 69.10 ✓
18	1 pc	right front door checker/arrestor <i>new</i>	\$ 44.80 ✓
19	1 pc	right rear door <i>Basic Dental</i>	\$ 981.20 ✓
20	1 pc	right rear door hinge bottom <i>new</i>	\$ 69.10 ✓
21	1 pc	right rear door checker/arrestor <i>new</i>	\$ 44.80 ✓
22	1 pc	right rear door window glass channel weatherstrip <i>new</i>	\$ 178.40 ✓
23	1 pc	right rear door outer weatherstrip moulding <i>new</i>	\$ 129.40 ✓
24	1 pc	right rear door wndow frame matt tape black front <i>new</i>	\$ 32.70 ✓
25	1 pc	right rear door wndow frame matt tape black rear <i>new</i>	\$ 36.00 ✓
26	1 pc	right rear door weatherstrip <i>new</i>	\$ 84.60 ✓
		2269	\$ 5,726.20
		Less 10 %	\$ 572.62
		2042.10	\$ 5,153.58
		SPECIAL NETT ITEMS	
27	1 set	right front door weatherstrip seal <i>new</i>	\$ 250.00 ✓ 120.
28	1 set	right front door audio speaker <i>new</i>	\$ 500.00 ✓
29	1 set	right rear door bump stopper	\$ 80.00 ✓
			\$ 830.00
		LABOUR & MISC. CHARGES	
01		To rust-proofing of the affected areas.	\$ 80.00 ✓ 40
02		To check steering geometry and computer wheel alignment.	\$ 150.00 ✓



陳林祥摩打有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SCN338S

Date of Accident : 29 May 2018

Mr Loh Buck Hien

Date : 31 May 2018

Estimate To Repair SLH3741R - NISSAN NOTE 1.2 CVT ABS D/AIRBAG 2WD
Chassis No : JN1TAAE12Z0972465

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
03		To transfer of both right door fittings and perform water seepage test.	\$ 220.00 160
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00 500
05		Putty and spray painting of the affected portion.	\$ 1,200.00 900
		1600	\$ 2,450.00
		Total	\$ 8,433.58

Adrian Lij
01/06/18. P/P.
05 days.
total: 3762.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: