

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 30Y

VF1ABL15AUC281227

RENAULT

LATITUDE

25.5.2018

ATA

Not Authorized
11 Sep @ 9900h

AAD1805-248

PART			LIST		
1	1	BUMPER COVER FRT	\$	<i>R</i> 1,259.42	<i>X</i>
2	1	BUMPER SPOILER FRT	\$	<i>S</i> 181.75	<i>X</i>
3	1	BUMPER ABSORBER FRT	\$	<i>S</i> 394.68	
4	1	BUMPER RETAINER FRT LH	\$	<i>S</i> 151.41	
5	1	BUMPER SUPPORT FRT	\$	<i>S</i> 123.88	
6	1	BUMPER RETAINER FRT RH	\$	<i>S</i> 150.77	
7	1	BUMPER SUPPORT FRT	\$	<i>S</i> 123.88	
8	1	BUMPER UNDERTRAY FRT	\$	<i>S</i> 472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	<i>S</i> 266.80	
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>S</i> 207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>S</i> 207.21	
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	<i>X</i>
13	1	TOW COVER FRT	\$	<i>S</i> 28.61	
14	1	RADIATOR GRILLE	\$	<i>S</i> 1,707.78	
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>S</i> 225.36	
16	1	RADIATOR GRILLE FRAME	\$	<i>S</i> 1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22	
20	1	HORN	\$	<i>S</i> 314.17	
21	1	HORN BRACKET	\$	<i>R</i> 40.45	
22	1	HEADLAMP LH	\$	<i>S</i> 1,184.43	<i>X</i>
23	1	HEADLAMP RH	\$	<i>S</i> 1,184.43	
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	
26	1	BONNET	\$	<i>R</i> 1,941.63	
27	1	BONNET INSULATOR	\$	<i>S</i> 405.73	
28	1	BONNET STRUT LH	\$	<i>S</i> 88.61	
29	1	A/C CONDENSER	\$	<i>S</i> 2,020.37	

Trans-cab Auto Services Pte Ltd
AAD1805-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

30	1	BONNET STRUT RH	\$	Sn	88.61	
31	1	BONNET HINGE LH	\$	R	348.31	
32	1	BONNET HINGE RH	\$	R	348.31	
33	1	BONNET LOCK	\$	R	305.48	X
34	1	BONNET CABLE	\$	Sn	119.19	
35	1	BONNET CABLE COVER	\$	Sn	161.03	
36	1	BONNET SEAL OUTER	\$	Sn	92.36	
37	1	BONNET SEAL INNER	\$	Sn	157.28	
38	1	FENDER PANEL FRT LH	\$	R	783.83	
39	1	FENDER PANEL FRT RH	\$	R	783.83	
40	1	WHEELARCH FRT LH	\$	Sn	278.84	
41	1	WHEELARCH FRT RH	\$	Sn	278.84	
42	1	FENDER BRACKET LOWER LH	\$	Sn	15.79	
43	1	FENDER BRACKET LOWER RH	\$	Sn	15.79	
44	1	FENDER INSULATOR LH	\$	Sn	130.84	
45	1	FENDER INSULATOR RH	\$	Sn	130.84	
46	1	BUMPER COVER REAR	\$	Bu	1,108.46	✓
47	1	BUMPER LOWER REAR	\$	Dis/DA	768.84	✓
48	1	BUMPER BRACKET CTR REAR	\$	Diy	113.47	✓
49	1	BUMEPR BRACKET SIDE RH REAR	\$	Sn	135.97	X
50	1	BUMEPR RETAINER RH REAR	\$	Sn	44.99	X
51	1	BUMPER REFLECTOR RH	\$	CM	43.61	✓
52	1	BUMEPR BRACKET SIDE LH REAR	\$	Sn	135.97	X
53	1	BUMEPR RETAINER LH REAR	\$	Sn	44.99	X
54	1	BUMPER REFLECTOR LH	\$	CM	43.61	✓
55	1	BUMPER BEAM REAR	\$	B	777.52	✓
56	1	BUMPER BEAM BRACKET LH REAR	\$	R	225.95	X
57	1	BUMPER BEAM BRACKET RH REAR	\$	Diy	225.95	✓
58	1	BOOT REAR	\$	B	2,872.68	✓
59	1	BOOT FINISHER	\$	wap	470.06	✓
60	1	BOOT WHEATERSTRIP	\$	Sn	323.05	X
61	1	BOOT REFLECTOR LAMP LH	\$	CM	493.35	✓
62	1	BOOT REFLECTOR LAMP RH	\$	CM	493.35	✓
63	1	BOOT BADGE 'RENAULT'	\$	Ru	225.36	✓
64	1	BOOT BADGE	\$	Ru	225.36	✓
65	1	BOOT STRUT LH	\$	Sn	276.08	X
66	1	BOOT STRUT RH	\$	Sn	276.08	X
67	1	BOOT HINGE LH	\$	R	367.84	X

Trans-cab Auto Services Pte Ltd**AAD1805-248**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

68	1	BOOT HINGE RH	\$	R	367.84	
69	1	BOOT INNER TRIM	\$	Sn	586.45	
70	1	BOOT SWITCH	\$	Sn	168.13	
71	1	BOOT LOCK	\$	R	202.67	
72	1	BOOT LOCK CATCH	\$	R	74.40	
73	2	LICENCE PLATE LAMP	\$	Sn	50.52	
74	2	BOOT RUBBER PLUG	\$	Sn	221.81	
75	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	
76	1	FENDER PANEL REAR LH	\$	R	3,299.13	
77	1	WHEELARCH REAR LH	\$	Sn	543.47	
78	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
79	1	FENDER PANEL REAR RH	\$	R	3,299.13	
80	1	WHEELARCH REAR RH	\$	Sn	543.47	
81	1	FENDER PANEL REAR LH	\$	R	3,299.13	
82	1	WHEELARCH REAR LH	\$	Sn	543.47	
83	1	TAILLAMP RH	\$	my car	552.55	✓
84	1	TAILLAMP PANEL RH	\$	R	986.70	X
85	1	TAILLAMP LH	\$	my car	552.55	✓
86	1	TAILLAMP PANEL LH	\$	R	986.70	X
87	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
88	1	OUTER PANEL REAR (End Panel)TRIM	\$	CM	404.56	✓
89	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
90	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
91	1	EXHAUST REAR	\$	R	7,489.05	X
92	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	59,887.17
10%	\$	5,988.72
	\$	53,898.45

Specical Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	na	52.00	
2	1SET	BUMPER CLIP FRT	\$	na	66.00	
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	

Trans-cab Auto Services Pte Ltd**AAD1805-248**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
7	1	TOW COVER FRT	\$	sn	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
13	1	Windscreen moulding	\$	na	100.00	
14	1SET	Front licence plate with holder	\$	na	80.00	455na
15	1SET	PARKING AID	\$	short	700.00	600na
16	1SET	REAR BUMPER CLIP	\$	na	66.00	—
17	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
18	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	na	10.00	X
19	1SET	BUMEPR RETAINER RH CLIP RR	\$	na	20.00	X
20	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
21	1SET	BUMEPR RETAINER CLIP LH RR	\$	na	20.00	X
22	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
23	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
24	1	EXHAUST MOUNTING REAR	\$	sn	17.82	X
25	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
26	1	BOOT STICKER "Trans-cab"	\$	na	30.00	—
27	1	BOOT STICKER "6555-3333"	\$	na	30.00	—
28	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
29	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
30	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
31	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	X
32	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	X
33	1	TAILLAMP CLIP RH	\$	na	5.00	—
34	1	TAILLAMP CLIP LH	\$	na	5.00	—
35	2	REAR WINDSCREEN SELANT	\$	na	80.00	X
36	1	WINDSCREEN MOULDING	\$	na	100.00	X
37	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
38	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	X
39	1	SPARE TYRE	\$	sn	330.00	X
			\$		2,787.52	

Trans-cab Auto Services Pte Ltd

AAD1805-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

TOTAL PARTS \$ 56,685.97

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6001 5,400.00
Towing Fees.	\$	na 120.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 8801
To rust-proofing of the affected areas.	\$	170.00 801
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00 601
To check steering geometry and computer wheel alignment	\$	na 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00 X
To lift-up engine with gear box and refit.	\$	na 440.00 X

Trans-cab Auto Services Pte Ltd**AAD1805-248**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To remove and refit air bag system and reset.	\$	nn 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00 X
To replace, refix and top up coolant for radiator	\$	nn 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To Rust-Proofing Of The Affected Areas.	\$	Renew 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 601
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1805-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 30Y

To supply and re-do rear luggage floor panel insulation padding. \$ *nn* 380.00 X

To transfer of rear fender fittings, attachment and perform water seepage test. \$ *nn* 380.00 X

To transfer of rear windscreen fittings and conduct water seepage test. \$ *nn* 170.00 X

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

TOTAL \$ 18,740.00

Over All Total \$ 75,425.97

(LUMP SUM) Repair Days~~20 DAYS~~*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: