



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDP9818S

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No **23766**
Reg No/Reg Date **SDP9818S / 29/05/2015**
Date In/Mileage **/ 0**
Chassis No **WDD2221652A149925**
Engine No **27682430164851**
Make/Model **MB/S 400 L BlueEFFICIENCY SE**
Colour/Trim **028 890 Cavansit B1/ 048 801 Black**

Account No	Terms	Date/Time Printed	CSE	Operator		
WC000668	Credit	30/05/2018/ 08:53	VS	356 / Vincent Seah		
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : DMPCSN1524151702 // 16.05.18 DRIVE IN/EXCESS : 18.05.18 // DATE IN/DATE SURVEY: BY/AUTHORIZED ON :						
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT						✓ 480.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR. NETT LHR DOOR						✓ 600.00
S BPNSUB SUPPLY & INSTALL 1 PC REAR WINDSCREEN GLASS SOLAR FILM. NETT SUPPLY & INSTALL 1 PC LHR DR QTR GLASS SOLAR FILM. NETT						? 400.00
A BPILAB REMOVE & REPLACE REAR GLASS WITH INSTALL . NETT					0.12	? 640.00
A BPILAB REMOVE & REFIT LUGGAGE COMPARTMENT, TRIM, GARNISH- CARPET FOR NECESSARY REPAIR.						960 1440.00
A BPILAB REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.					photo	960? 1440.00
S BPNSUB TRANSFER RIM AND BALANCING TYRE. NETT LHR RIM						✓ 60.00
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT						✓ 540.00
A BPILAB DISASSEMBLE AND REPLACE LEFT REAR DOOR, LEFT REAR FENDER ,LHF DOOR						Fender - Repair - 3360 5760.00
A BPIRES RESPRAY ON LEFT FRONT DOOR, LEFT REAR DOOR, LEFT REAR FENDER, END PANEL						Replace - 5280 3000.00
M LHR DOOR BOTTOM SELF-ADHESIVE TRIM			1.00	6.33	00.00	1800 net 6.33

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDP9818S

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No **23766**
Reg No/Reg Date **SDP9818S / 29/05/2015**
Date In/Mileage **0**
Chassis No **WDD2221652A149925**
Engine No **27682430164851**
Make/Model **MB/S 400 L BlueEFFICIENCY SE**
Colour/Trim **028 890 Cavansit B1/ 048 801 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	30/05/2018/ 08:53	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LEFT REAR DOOR TOP SELF-ADHESIVE TRIM	1.00	16.05	00.00	16.05
M LHR DOOR ORNAMENTAL MOLDING	1.00	193.24	00.00	193.24
M LHR DOOR SEALING FRAME	1.00	28.10	00.00	28.10
M LHR DOOR BOTTOM COVER STRIP	1.00	59.38	00.00	59.38
M LHR DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
M LEFT REAR DOOR	1.00	3597.70	00.00	3597.70
M LHR DOOR WINDOW RUN	1.00	376.15	00.00	376.15
M LHR FENDER LINEAR	1.00	251.28	00.00	251.28
M LEFT REAR VENTILATION FLAP	1.00	12.81	00.00	12.81
M REAR LEFT FENDER - aluminium.	1.00	5318.83	00.00	5318.83
M DISK WHEEL-LHR	1.00	788.73	00.00	788.73

ESTIMATE

Tanpin 97495749
Ex \$1500
Not Authorise
31/5/18 R 1700
sur @ lkkauto.com
Resurvey before first
10-12 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

7% GST on **Nett 25,289.32**
25289.32 1770.25

Authorized signatory and company stamp

Total Payable 27,059.57

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg