

WENG KEE MOTOR

84	Spare tyre panel sealant	1	30.00	250	220m
85	Spare tyre side panels sealant	2	30.00		X 2 1m
86	Exhaust silencer gasket	1	45.00		X 1m
87	Reverse sensor	1	300.00		220m
Sub-total 1			678.00		
Parts total			22,009.04		

Labour

88	To straighten and panel beating front frame members, front fender panels. To cut/weld front bumper reinforcement, support panel. To remove and refit above parts.	1	800.00	600
89	To putty, re-spray painting and polish front affected areas.	1	800.00	600
90	To rust proof affected front areas.	1	80.00	60
91	To straighten and panel beating rear frame member, rear tail lamp panel LH/RH. To cut/weld rear fender panel LH/RH, spare tyre panel, spare tyre side panels, spare tyre bottom bracket, rear end panel. To remove and refit above parts.	1	1,300.00	1100
		3790		
92	To putty, re-spray painting and polish rear affected areas.	1	1,600.00	900
93	To rust proof affected rear areas.	1	120.00	100
94	To check and rectify wiring system for front and rear	1	80.00	30
95	To remove and replace rear windscreen	1	180.00	120
96	To remove and refit upholstery to facilitate repair.	1	280.00	100
97	To remove and replace rear exhaust silencer.	1	60.00	
98	To remove and replace reverse sensor	1	120.00	60
99	To remove and transfer rear boot lid components.	1	100.00	60
Labour total			5,520.00	
Parts & Labour total			27,529.04	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

28232.72

Repair

Hp 90010068

14 days

4/5

01/06/18 @ 1515

Resurvey after repair

6/6/18