



EUROKARS HABITAT PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD		NAME :	MS SHI YING	WIP :	19132
8 SHENTON WAY		ADDRESS :	60 CHESTNUT AVE	EXCESS :	
#24-01 AXA TOWER			#21-06 TREE HOUSE	DATE:	28-May-18
SINGAPORE 068811			SINGAPORE 679517		
ATTN. :	MOTOR CLAIMS	TEL :	96231115		
FAX :					

VEH NO :	SJR3637E	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6360 2446
CHASSIS NO :	WMWXS120602E79802	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MINI COOPER F55	DATE REG.:	30-Mar-17	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	FRONT BUMPER	1	M51.11.7.379.432	DE ✓	\$ 737.06
2	FRONT BUMPER GASKET	4	M51.11.7.380.443	re ✓	\$ 94.00
3	RADIATOR GRILLE	1	M51.13.7.335.529	CRA ✓	\$ 229.75
4	RADIATOR GRILLE FRAME	1	M51.13.7.300.589	CRA ✓	\$ 126.38
5	FRONT BUMPER COVER	1	M51.11.7.337.790	SC ✓	\$ 137.00
6	AIR INLET LH	1	M51.11.7.355.239	at ✓	\$ 47.13
7	AIR INLET RH	1	M51.11.7.355.240	out ✓	\$ 47.13
8	FRONT BUMPER LOWER GRILLE	1	M51.11.7.337.793	CRA ✓	\$ 86.94
9	FRONT BUMPER LOWER GRILLE CHROME	1	M51.11.7.355.238	re ✓	\$ 172.75
10	FRONT BUMPER SPOILER	1	M51.11.7.301.622	DE ✓	\$ 200.38
11	FRONT WHEEL ARCH LH	1	M51.77.7.300.819	?	\$ 169.63
12	AIR DUCT LH	1	M51.74.7.301.609	at ✓	\$ 51.50
13	AIR DUCT RH	1	M51.74.7.301.610	out ✓	\$ 51.50
14	FRONT BUMPER REINFORCEMENT	1	M51.11.7.301.577	re ✓	\$ 422.25
15	REINFORCEMENT DEFORMATION LH	1	M51.11.7.406.389	re ✓	\$ 113.69
16	REINFORCEMENT DEFORMATION RH	1	M51.11.7.406.390	re ✓	\$ 113.69
17	FRONT BUMPER BRACKET	2	M51.11.7.337.802	re ✓	\$ 41.50
18	FRONT BUMPER SPONGE	1	M51.64.7.301.589	CRA ✓	\$ 32.63
19	FRONT BUMPER LOWER REINFORCEMENT	1	M51.11.7.301.578	SC ✓	\$ 164.44
20	LOWER CROSSLINK	1	B51.11.7.301.605	?	\$ 151.69
21	LOWER CROSSLINK DEFORMATION LH	1	M51.11.7.301.587	?	\$ 96.50
22	LOWER CROSSLINK DEFORMATION RH	1	M51.11.7.301.588	?	\$ 96.50
23	CROSSLINK DEFORMATION BAR LH	1	M51.11.7.368.481	?	\$ 101.81
24	CROSSLINK DEFORMATION BAR RH	1	M51.11.7.368.482	?	\$ 101.81
25	EXPANDING RIVET	2	M51.11.1.908.077	re ✓	\$ 1.26
26	HEXAGON SCREW	4	B07.12.9.908.636	re ✓	\$ 25.24
27	BLIND RIVET	4	B07.14.6.984.985	re ✓	\$ 4.52
28	HEX BOLT	2	M07.11.9.906.123	re ✓	\$ 5.62
29	HEADLAMP TRIM RING LH	1	M51.13.7.300.631	re ✓	\$ 68.94
30	HEADLAMP TRIM RING RH	1	M51.13.7.300.632	re ✓	\$ 68.94
31	MINI EMBLEM	1	M51.14.7.316.703	re ✓	\$ 73.88
32	TEMPERATURE SENSOR	1	M65.81.9.321.559	at ✓	\$ 100.13
33	AIRCON CONDENSER	1	M64.50.9.271.204	re ✓	\$ 1,172.75
34	RADIATOR	1	B17.11.7.617.639	re ✓	\$ 900.31

35	RADIATOR BRACKET RH	1	B17.11.8.630.445	na ✓	\$ 35.31
36	RADIATOR BRACKET LH	1	B17.11.8.617.884	na ✓	\$ 35.31
37	RADIATOR FASTENING HOLDER	2	B17.11.8.668.715	na ✓	\$ 25.88
38	RADIATOR GASKET	1	B17.11.8.600.126	na ✓	\$ 58.56
39	CHARGE AIR COOLER	1	B17.51.7.617.597	PA ✓	\$ 686.00
40	CHARGE AIR COOLER BRACKET	2	B17.11.8.617.880	na ✓	\$ 70.62
41	RADIATOR FAN HOUSING	1	B17.42.7.617.610	?	\$ 1,144.94
42	REAR BUMPPER	1	M51.12.7.380.024	DE ✓	\$ 825.25
43	REAR BUMPPER SPOILER	1	M51.12.7.380.030	DE ✓	\$ 271.88
44	REAR BUMPPER FOG LAMP CHROME	1	M51.12.7.365.737	?	\$ 95.94
45	REAR BUMPPER SENSOR HOLDER RH	1	M51.12.7.403.266	na ✓	\$ 52.13
46	REAR BUMPPER SENSOR HOLDER LH	1	M51.12.7.403.267	na ✓	\$ 52.13
47	REAR BUMPPER GUIDE LH	1	M51.12.7.318.755	?	\$ 108.94
48	REAR BUMPPER GUIDE RH	1	M51.12.7.318.756	?	\$ 108.94
49	REAR BUMPPER BREATHER COVER	1	M51.12.7.302.547	DE ✓	\$ 58.44
50	REAR BUMPPER BLIND RIVET	4	M07.14.7.411.141	na ✓	\$ 14.52
51	REAR BUMPPER CLIP	4	M07.14.2.754.954	na ✓	\$ 6.24
52	REAR BUMPPER REINFORCEMENT	1	M51.12.7.300.788	PA ✓	\$ 505.94
53	REINFORCEMENT GASKET	2	B51.12.7.300.789	na ✓	\$ 10.88
54	REAR WHEEL ARCH LH	1	M51.77.7.318.829	X	\$ 101.81
55	EMBLEM "ONE"	1	M51.14.2.755.615	na ✓	\$ 66.50
56	HEAT INSULATOR	1	M51.48.7.375.659	PA ✓	\$ 63.50
57	REAR FOG LIGHT	1	M63.24.6.946.904	?	\$ 155.50
58	REAR EXHAUST	1	M18.30.8.615.432	PA ✓	\$ 916.94
59	TAILPIPE CHROME	1	M18.30.8.606.004	SCA ✓	\$ 131.13
60	REAR EXHAUST RUBBER MOUNT	2	B18.30.7.616.850	X	\$ 42.50
61	REAR EXHAUST CLAMP	1	M18.30.7.560.777	na ✓	\$ 67.88
62	EXHAUST SILENCER	1	M18.30.8.616.381	?	\$ 1,101.63
63	ULTRASONIC SENSOR GASKET	4	B66.20.9.283.203	na ✓	\$ 25.24
64	ULTRASONIC SENSOR	2	B66.20.9.274.428	na ✓	\$ 621.80
65	RADIATOR COOLANT	2	B83.51.2.355.290	na ✓	\$ 39.50
TOTAL PARTS					\$ 13,511.03
					\$ -
TOTAL PARTS COST					\$ 13,511.03
Labour Description					
1	TO REPLACE FRONT BUMPER. TO REPAIR BONNET AND ALL AREAS AFFECTED BY THE ACCIDENT.			1680	\$ 2,000.00
2	TO RESPRAY FRONT BUMPER AND BONNET.			1600	\$ 1,900.00
3	TO REPLACE REAR BUMPER. TO REPAIR TAILGATE & REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.			85 2520	\$ 2,800.00
4	TO RESPRAY REAR BUMPER, TAILGATE AND REAR END PANEL.			2400	\$ 2,700.00
5	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.			250	\$ 350.00
6	TO CARRY-OUT BODY CAVITY PRESERVATION.			150	\$ 250.00

7	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	400	\$ 500.00
8	TO REMOVE & REPLACE TURBO COOLER, RADIATOR, CONDENSER AND RADIATOR FAN ASSY.	1680	\$ 1,900.00
9	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	NETT	\$ 500.00
10	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	1260	\$ 1,900.00
11	TO TRANSFER THE REVERSE SENSORS.	400	\$ 500.00
12	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	NETT	\$ 70.00
13	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
14	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250	\$ 350.00
15	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT	\$ 200.00
16	SUNDRIES.	NETT 50	\$ 100.00
		TOTAL LABOUR	\$ - \$ 16,270.00
		TOTAL PARTS	\$ - \$ 13,511.03
		TOTAL	\$ - \$ 29,781.03
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Passer
Hp 90010068
15 days
01/06/18 @ 1200
Resing by paint